

Work Order	Plant	Plant Description	Status	Type	Work Description	Finish Date
WO2029	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	STARTER FAULT - NEED TO REPLACE.	7/18/2019
WO2147	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	REPLACE SKIN ON THE FEEDER WINGS	4/16/2020
WO2183	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	GENERAL ALL OVER CHECK AND MAINTIAN	7/23/2019
WO2227	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	06.08.19 NEED NEW PINS FOR LATCH ON LHS OF	10/5/2019
WO2275	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	13.08.19 250 Hour Service for CP07	10/5/2019
WO2276	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	13.08 - LATCH IS BROKEN LHS ENGINE **Closed Double up**	10/10/2019
WO2174	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	5668HRS PRODUCT BELT BRACING CRACKED TO BE REPAIRED	7/30/2019
WO2413	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	03.09.19 - Latch is broken on side engine door.	10/5/2019
WO2445	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	PRODUCT BELT REDUCTION GEAR BOX TO BE REPLACED	9/9/2019
WO2446	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	BOLTS TO BE FITTED TO LIFTING EYELETS ON MAIN	10/5/2019
WO2444	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	SEAL UP FEEDER TO THE BACK OF THE JAW BOX	5/19/2020
WO2441	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	REPAIR STOCK PILE LEVEL SENSOR	5/21/2020
WO2443	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	BOLT CRUSHER TO MAIN FRAME, ATT LES AND FREDDY	5/21/2020
WO2448	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	PRODUCT BELT BRACING TO BE MADE TO SUPPORT PRODUCT	5/27/2020
WO2442	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	REPAIR HAMMER PINS/BUSHING	5/29/2020
WO2447	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	FEEDER COUPLING TO BE CHANGED OUT WITH OEM	10/22/2020
WO2737	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	REQUIRES MAIN DRIVE PRESSURE SENSOR @5879hrs	10/9/2019
WO2805	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	10.10.19 INSPECT JAW OVERLOAD FAULT	10/10/2019
WO2836	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	CHANGE BATTERIES N150 X2	10/16/2019
WO2847	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	15.10.19 LOAD TEST BATTERIES	10/15/2019
WO2863	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	2000 Hour Service for CP07	11/12/2019
WO3019	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	12.11.19 TRACK PRODUCT BELT	11/11/2019
WO3018	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	12.11.19 NEED TO SEAL UP BETWEEN THE FEEDER	5/27/2020
WO3047	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	12.11.19 TRACK PRODUCT BELT	11/12/2019
WO3053	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	14.11.19 TORN BELT - REPLACE SKIRTS	11/15/2019
WO3130	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	21.11.19 WELD IN NEW PLATE BELOW JAW.	11/19/2019
WO3172	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	12/3/2019
WO3209	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	29.11.19 MAKE UP SCRAPER	11/29/2019
WO3174	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	12/3/2019
WO3230	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07	1/15/2020
WO3231	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	12/10/2019
WO3297	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	11.12.19 BOGGED PRODUCT BELT	12/11/2019
WO3300	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	11.12.19 REPAIR OVER CENTRE VALCE BLOCK	6/17/2020
WO3330	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	17.12.19 IMPACT BED NEEDS FIXING.	5/21/2020
WO3275	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	12/30/2019
WO3374	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	12/31/2019
WO3396	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	12/31/2019
WO3446	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	PRODUCT BELT MAJOR REPAIRS	1/8/2020
WO3427	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	1/28/2020
WO3484	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	09.01.20 LEAK IN ENGINE AREA	5/12/2020
WO3488	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	HYDRAULIC TANK TEMPERATURE/HARNESS ISSUES	1/11/2020
WO3472	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	1/28/2020
WO3473	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	500 Hour Service for CP07	1/15/2020
WO3512	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	2/18/2020
WO3573	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	2/18/2020
WO3595	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	2/18/2020
WO3650	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	2/18/2020
WO3748	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	17.02.20 TRACK GUIDE FELL OFF	2/17/2021
WO3706	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	2/18/2020
WO3805	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	2/24/2020
WO3975	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	03.03.20 CHARGE PRESSURE TRANSDUCER	3/3/2020
WO3887	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	3/19/2020
WO3965	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	3/19/2020
WO3999	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	3/19/2020
WO4167	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	REPLACE RHS TAIL DRUM BEARING	3/25/2020
WO4031	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	4/21/2020
WO4067	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	4/21/2020
WO4136	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	4/21/2020
WO4149	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	4/21/2020
WO4411	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	16.4.20 - PRODUCT CONVEYOR REDUCTION GEARBOX	4/16/2020
WO4218	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	4/21/2020
WO4230	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	4/21/2020
WO4231	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07	5/7/2020
WO4301	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	5/21/2020
WO4655	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	5/21/2020
WO4711	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	5/26/2020
WO4886	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	25.5.20 REPLACE FAN BELTS	5/29/2020

WO4835	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	5/29/2020
WO4942	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	E-stop fault at platform	5/29/2020
WO4864	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	5/29/2020
WO4975	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	6/10/2020
WO5144	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	12.6.20 UNBRIDGE JAW	6/12/2020
WO5070	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	6/11/2020
WO5159	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	1000 Hour Service for CP07	6/25/2020
WO5236	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Feeder leaking, Rubber needs changing under feeder	9/28/2020
WO5160	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	6/24/2020
WO5241	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	7/20/2020
WO5430	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	hammer repairs	7/20/2020
WO5395	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	7/10/2020
WO5329	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY	7/20/2020
WO5608	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	20.07.20 NEEDS PRESTART HOLDER.	6/9/2021
WO5639	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Rock jammed in jaw	7/22/2020
WO5497	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/13/2020
WO5671	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	BIG ROCK STUCK IN JAW	7/24/2020
WO5681	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	24.7.20 REQUIRES NEW GUIDE ROLLER ON PODUCT BELT	1/29/2021
WO5583	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07	9/10/2020
WO5711	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	28.07.20 FEEDER REQUIRES WELDING REPAIRS	9/28/2020
WO5732	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	30.7.20 CHANGE SKIRTS LHS	12/21/2020
WO5759	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	31.7.20 WELD CUTTING EDGE BACK IN UNDER JAW	7/31/2020
WO5697	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/13/2020
WO5821	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	7.8.20 OIL LEAK FROM PRESSURE TRANSDUCER	8/7/2020
WO5824	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	7.8.20 BREATHER BROKEN OFF	8/27/2020
WO5852	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/13/2020
WO5960	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Bottom plate fell out, needs rewelding	8/21/2020
WO6079	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	31.8.20 REPLACE MAIN CRUSHER DRIVE HOSES	8/31/2020
WO5984	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/13/2020
WO6134	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Welding repairs under jaw	9/4/2020
WO6038	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	500 Hour Service for CP07	9/21/2020
WO6141	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/13/2020
WO6317	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Requires a new head drum scraper,	12/21/2020
WO6387	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Machine keeps stopping,	3/16/2021
WO6338	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/13/2020
WO6574	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Engine has developed a miss	10/6/2020
WO6573	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Magnet belt tail drum bearing engine side failed	6/10/2021
WO6554	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	Sublet Delaite steel -FEEDER BIN REPAIRS	7/15/2021
WO6526	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/13/2020
WO6675	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	16.10.20 INSPECT & MAINTAIN AIR INLET HEATER	10/16/2020
WO6618	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07	1/4/2021
WO6795	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	22.10.20 HYDRAULIC PUMP UNDER LOAD ON START	6/9/2021
WO6796	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	22.10.20 ROCK LEAKING BETWEEN FEEDER & JAW.	6/9/2021
WO6798	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	22.10.20 IMPACT BED (RUBBER) IN FEEDER NEEDS	6/9/2021
WO6867	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Replace injector harness, due to miss	10/28/2020
WO6699	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	11/26/2020
WO7025	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	10.11.20 PATCH X3 HOLES IN FINES CHUTE	11/10/2020
WO6914	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	11/26/2020
WO7174	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MR	20.11.20 MAJOR REPAIRS *SEE NOTES*	11/20/2020
WO7099	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	2/18/2021
WO7291	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	2/18/2021
WO7571	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Toggle cylinders are in bypass, need replacing	1/29/2021
WO7394	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	2000 Hour Service for CP07	2/10/2021
WO7490	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	2/18/2021
WO7641	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	2/18/2021
WO7873	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	19.1.21 PRODUCT BELT WONT RUN	1/20/2021
WO7867	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Inspect tail drum bearings	1/29/2021
WO7755	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	1/20/2021
WO7903	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	22/1/21-WEEKLY SERVICE	1/28/2021
WO7992	CP07	Telesmith TJ3258 Jaw Crusher	Complete	OE	29/1/21-Damage	2/3/2021
WO8002	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	28.01.21 FEEDER RUBBER NEEDS TO BE CLEANED	6/9/2021
WO8123	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	2/2/21-Replace head drum scraper	2/2/2021
WO8124	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	2/2/21-Repair fuel pump leak	2/2/2021
WO8001	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	28.01.21 WEAR PLATE WHERE FEEDS ONTO BELT	6/16/2021
WO8000	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	28.01.21 WEAR PLATE ABOVE JAW NEEDS REPLACING	7/9/2021
WO7919	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	2/18/2021
WO8043	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION.	2/18/2021
WO8167	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	04.02.21 MISSING 2 TRACK BOLTS FUEL TANK SIDE	12/12/2021

WO8235	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION.	2/18/2021
WO8236	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	2/18/2021
WO8598	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	18.02.21 REPLACE HYD FILTER AT TANK PUMP CRANK	7/14/2021
WO8597	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	18.02.21 BROKEN BOLTS IN FILTER HOUSING.	7/25/2022
WO8469	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION.	2/18/2021
WO7999	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CI	28.01.21 FRAME TO STABILISE CONVEYOR	7/22/2021
WO8798	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	3/2/2021
WO8643	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	2/25/2021
WO8924	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Replace bearing for magnet belt i	7/14/2021
WO9033	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	3/17/2021
WO8996	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	3/17/2021
WO9174	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Hole in side under feeder, needs welding	3/17/2021
WO9255	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	3/25/2021
WO9527	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection	3/31/2021
WO9531	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Serv fault-oil leak under feeder bin	7/22/2021
WO9275	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	3/31/2021
WO9556	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	GENERAL REPAIRS-April	5/4/2021
WO9587	CP07	Telesmith TJ3258 Jaw Crusher	Complete	OE	Damage-Remote ran over	4/7/2021
WO9643	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection	4/6/2021
WO9647	CP07	Telesmith TJ3258 Jaw Crusher	Complete	GE	insection 6/4/21 NEEDS FIX SIDE JAW LINER REPLACED	4/7/2021
WO9698	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	LANYARDS NOT WORKING	4/9/2021
WO9777	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	4/13/2021
WO9598	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	4/14/2021
WO9821	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	E stop faulty on remote	4/26/2021
WO9940	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	4/20/2021
WO9974	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	22.4.21 FIX AUTO GREASER FAULT	4/22/2021
WO10068	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Weekly inspection	4/27/2021
WO9844	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	4/28/2021
WO10141	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	28/4/21-Breakdown-Hydraulic pump failure	5/7/2021
WO9845	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	GENERAL REPAIRS - MAY	5/28/2021
WO10216	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	5/10/2021
WO10392	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	INSPECTION - SCIRT RUBBER NEEDS REPLACING	7/26/2021
WO10393	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	INSECTION- ACCESS GATE NEEDS AJUSTING	7/26/2021
WO10394	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	INSPECTION - TRACK BOLTS MISSING	7/26/2021
WO10396	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Replace hydraulic filters	6/1/2021
WO10237	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	7/22/2021
WO10442	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	reduction gear box drive repair/replace	5/26/2021
WO10476	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07	6/16/2021
WO10586	CP07	Telesmith TJ3258 Jaw Crusher	Complete	OE	Damage-repair shakre box drive cover	5/20/2021
WO10478	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	6/7/2021
WO10620	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	GENERAL REPAIRS-June	7/14/2021
WO10877	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	REMOVE RUBBER BED IN FEEDER	6/7/2021
WO10841	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKY INSPECTION-9th June	6/17/2021
WO10761	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	6/17/2021
WO10936	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace rubber with need ware plate in feed bin	6/16/2021
WO11024	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inpsection	6/24/2021
WO10972	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	7/22/2021
WO11059	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	GENERAL REPAIRS	7/29/2021
WO11444	CP07	Telesmith TJ3258 Jaw Crusher	Complete	OP	Replace gear box oil	7/15/2021
WO11446	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Repair faults	7/15/2021
WO11445	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Sublet-Rapid hose-grease lines	7/20/2021
WO11283	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/1/2021
WO11470	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace head drum bearing and caseing on mag belt	7/14/2021
WO11382	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Sublet- A & S-500 Hour Service for CP07	7/15/2021
WO11513	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	7/29/2021
WO11708	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	PRESTART - OIL NEEDS TOPPING UP IN ENGINE	5/3/2022
WO11734	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Magnet hyd mtr u/s	12/21/2021
WO11948	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	8/2/2021
WO11821	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	GENERAL REPAIRS	8/11/2021
WO11872	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	8/2/2021
WO12073	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	8/13/2021
WO12335	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	8/20/2021
WO12296	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	8/20/2021
WO12422	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace rubber under grizzly bars	8/20/2021
WO12444	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	8/24/2021
WO12529	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace broken sight glass with brass plug	8/25/2021
WO12567	CP07	Telesmith TJ3258 Jaw Crusher	Complete	OP	REFIT SIDE BELT-27/8/21	8/27/2021
WO12562	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Breakdown-Jaw liner loose-27/8/21	8/31/2021

WO12593	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	REMOVE SIDE BELT-30/8/21	8/31/2021
WO12590	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	9/1/2021
WO12480	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	GENERAL REPAIRS	8/27/2021
WO12481	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	9/8/2021
WO12754	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	REPLACE TAIL DRUM BEARINGS-6/9/21	9/6/2021
WO12755	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	9/6/2021
WO12781	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Breakdown-Snubber return roller at tail drum u/s-	9/7/2021
WO12729	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07	9/20/2021
WO12730	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	9/30/2021
WO13022	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	9/20/2021
WO13159	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	will need rubber replaced in chute asap	9/30/2021
WO13163	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	9/30/2021
WO13080	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	9/30/2021
WO13349	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	GENERAL REPAIRS	9/30/2021
WO13230	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	cracks in outer base of feed hopper /weld repair	10/6/2021
WO13229	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	bent steps	10/12/2021
WO13305	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	rebuild deflection plate under jaw	10/1/2021
WO13312	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	fit rubber curtain over verible feeder oil covers	10/8/2021
WO13309	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	weld repairs under variable feeder and repair work	10/11/2021
WO13311	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	make cover for hydraulic leavers	10/11/2021
WO13308	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	weld in small rock box plates at the end of grizzly and	10/27/2021
WO13310	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace skirt rubber on main conveyor-28/10/21	10/29/2021
WO13408	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	10/6/2021
WO13418	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	REPLACE FIXED SIDE LINER jm to plan	5/17/2022
WO13514	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	10/12/2021
WO13674	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	x 3 grease lines need repair	10/15/2021
WO13382	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	10/12/2021
WO13771	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	10/19/2021
WO13827	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	19.10.21 Replace head drum scraper on out feed	10/19/2021
WO13826	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Taildrum bearing failed	11/9/2021
WO13579	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	1000 Hour Service for CP07	11/19/2021
WO13988	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace rubber wear mat in chute	10/25/2021
WO13981	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	WEEKLY INSPECTION	10/26/2021
WO14107	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	small coolant leak from pump	11/30/2021
WO13896	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS FORTNIGHTLY	11/3/2021
WO14154	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	29.10.21 TOGGLE TENSION CYLINDERS LEAKING RHS	12/3/2021
WO14427	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	reweld ware plates on in feed bin	11/9/2021
WO14431	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace impact bed in feed bin	6/27/2022
WO14474	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace rubber wear sheets under grizzlies	11/11/2021
WO14526	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	11/15/2021
WO14532	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	replace/repair greese line r/s at the tail drum end	11/18/2021
WO14650	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Sublet Rapid hose-Fab and fit new pin-22/11/21	12/21/2021
WO14727	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CANCEL	11/23/2021
WO14741	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	replace engine belts at next service x 2	3/25/2022
WO14754	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	25.11.21 ROCK STUCK IN SKIRT	11/30/2021
WO14763	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Replace prod belt spd sensor & screws-25/11/21	4/4/2022
WO14769	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Top up motor with oil ?	11/29/2021
WO14787	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection	12/10/2021
WO14885	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	replace hydraulic rams x 2 (near tir rams)	12/2/2021
WO14698	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Sublet AOEM-250 Hour Service for CP07	1/31/2022
WO14990	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	fix skirt on belt and track	12/8/2021
WO15003	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	grease lines x2 on tail drum need replacing	1/14/2022
WO15226	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MR	Machine Audit-4/1/22	2/18/2022
WO16393	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DM	23.2.22 HAMMER STICK CYLINDER TO BE RESEALED	6/30/2022
WO16404	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	24.2.22 PRODUCT BELT DRIVE MOTOR LEAKING	2/24/2022
WO16425	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Sublet AOEM-Adjust scrapers-1/3/22	3/22/2022
WO16519	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Sublet - VICTECH - Check rock leaking under feeder-2/3/22	3/2/2022
WO16544	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Prestart-check e stop operation-10/12/21	10/12/2022
WO16592	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Repair scraper and refit -8/3/22	3/8/2022
WO16623	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Sublet-Rapid hose-Damage-9/3/22	5/23/2022
WO16759	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Prestart-LHS track loose, needs adjusting-15/3/22	3/16/2022
WO16865	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection	3/17/2022
WO16955	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Relocate hammer pin correctly-22/3/22	3/22/2022
WO16964	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Refit support arm pin -23/3/22	3/24/2022
WO17061	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection-28/3/22	3/28/2022
WO17059	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Tighten bolts, remove wing roller plates-25/3/22	3/29/2022
WO15455	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Sublet - VICTECH - 500 Hour Service for CP07	4/6/2022
WO17088	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Needs new rubber under grizzly,s -29/3/22	5/16/2022

WO17152	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Sublet - VICTECH - Prestart-mag belt not working-1/4/22	4/8/2022
WO17154	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	Prestart -using alot of oil-1/4/22	4/13/2022
WO17168	CP07	Telesmith TJ3258 Jaw Crusher	Complete	OE	Damage -GEAR COVER ON FEEDER BROKEN-1/4/22	4/4/2022
WO17196	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Replace wing arm pin - 4/4/22	4/4/2022
WO17244	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Prestart-hammer pin weld cracked-7/4/22	6/30/2022
WO17246	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Prestart-hammer not working -7/4/22	6/30/2022
WO17242	CP07	Telesmith TJ3258 Jaw Crusher	Complete	DF	Prestart-hyd leak behind ist step on left-7/14/22	10/11/2022
WO17230	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	BROKEN TRACK IDLER BOLT ON RHS REAR	11/18/2022
WO17633	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Repair/Replace grease lines	5/9/2022
WO17689	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Prestart - Feeder sump missing 3 bolt and leaking oil	9/12/2022
WO17789	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Inspect and track magnet belt 2/5/22	5/2/2022
WO17784	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Prestart - missing nut of right side step	5/17/2022
WO17804	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection - 3/5/22	5/3/2022
WO17904	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection ws 9/5/22	5/11/2022
WO17915	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Fire Extinguisher needs changing	6/17/2022
WO17917	CP07	Telesmith TJ3258 Jaw Crusher	Complete	GE	Skirts under product conveyer feeder wearing	9/12/2022
WO17916	CP07	Telesmith TJ3258 Jaw Crusher	Complete	GE	Feed Hopper - Cracks inside wings	1/5/2023
WO17914	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	GE	3 x Track roller bolts broken RH side	
WO17842	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Sublet - VICTECH - 250 Hour Service for CP07-SS027	5/24/2022
WO18216	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly inspection WS30/5/22	6/1/2022
WO18229	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Sublet- Victech-Serv Fault-Requires new fan/alternator belts	9/15/2022
WO18324	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CM	Weekly inspection WS 6/6/22	6/9/2022
WO18326	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection - 13/6/22 MISSED	6/23/2022
WO18389	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 20/6	6/21/2022
WO18453	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Straighten Mag Belt.Nathan 20-6-22	6/20/2022
WO18487	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 27/6	6/29/2022
WO18603	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Serv Fault - Belt has some cuts and is worn on LHS	9/19/2022
WO18580	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 4/7	7/4/2022
WO18745	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	2000 Hour Service for CP07-SS027	7/14/2022
WO18682	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection	7/14/2022
WO18870	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Serv Fault - Exhaust flex to be replaced	10/3/2022
WO18831	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 18/7	7/21/2022
WO18934	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 25/7	7/26/2022
WO19092	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Sublet - Rapid hose - Oil leak at hammer	7/27/2022
WO19096	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Insp Fault - Skirt under jaw wearing	8/10/2022
WO19193	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Belt stopped rock stuck in tail drum	8/2/2022
WO19222	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Hydraulic fault-Hammer ?	1/3/2023
WO19128	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 1/8	8/2/2022
WO19336	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Repair head drum adjuster and track belt	8/5/2022
WO19337	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Cut and fit side deflector plates under jaw	8/22/2022
WO19297	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 8/8	8/9/2022
WO19750	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Will not start - wiring repair	8/18/2022
WO19538	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection 15/8	8/17/2022
WO19710	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection - 22/8	8/24/2022
WO19858	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027, 29 Aug	8/30/2022
WO20004	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Sublet - VICTECH - 250 Hour Service for CP07-SS027	9/13/2022
WO19920	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Serv Fault - Belt tracks to right	9/12/2022
WO19941	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027 - 5 Sept	9/7/2022
WO19986	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Replace bolts that hold feeder to frame	9/7/2022
WO20016	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027, 12 Sept	9/14/2022
WO20094	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Prestart - Oil leak	10/11/2022
WO20142	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Fit new return roller and brackets	9/13/2022
WO20157	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027, 19/Sept	9/21/2022
WO20222	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027, 26/Sept	10/5/2022
WO20349	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027, 3 Oct	10/4/2022
WO20385	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MR	Product belt stalled - replace gear box	10/5/2022
WO20476	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027, 10 Oct	10/10/2022
WO20515	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Sublet - Victech - Replace injector harness	10/11/2022
WO20571	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS031 A, 17Oct	10/17/2022
WO20611	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Sublet - Victech - 500 Hour Service for CP07-SS027	10/24/2022
WO20641	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07- Hammer not working	10/18/2022
WO20642	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Sublet - Victech - steps on both sides bent	10/25/2022
WO20638	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07 - cracking around tips of grizzlys	11/18/2022
WO20640	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07 - monitor condition of skirts as new deflector	1/3/2023
WO20643	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07 -magnet belt will not run without stalling the	1/3/2023
WO20639	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07- shacker box under feeder leaking (loose missing bolts)	1/30/2023
WO20644	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Sublet - JBE- CP07 -Safety stop lanyards not working	4/4/2023
WO20636	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	MI	CP07 - weld repair cracks around outside of hopper both	

WO20637	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	MI	CP07 - wear plates lifting inside of feeder	
WO20645	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	AUTO GREASER FAULT	10/18/2022
WO20664	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027 A, 24 Oct	10/26/2022
WO20714	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	ENGINE SHUT DOWN FAULT NO CRANK	10/24/2022
WO20817	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027 A, 31Oct/Nov	11/3/2022
WO20845	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07 - Track belt & replace x 3 feeder frame bolts	10/27/2022
WO20890	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027 A, 7Nov	11/9/2022
WO21022	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	REPLACE PB GUIDE ROLLERS X2	11/9/2022
WO21016	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027 A, 14Nov	11/17/2022
WO21062	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	CP07- swap speed sensor roller to run on top of belt	11/11/2022
WO21154	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS031 A, 21Nov	11/23/2022
WO21267	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS027 A, 28Nov	11/29/2022
WO21298	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Motor missing - change injector	12/5/2022
WO21357	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Blown hose and toggle plate fell out	12/5/2022
WO21361	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07-SS027	12/7/2022
WO21377	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Weekly Inspection -SS031 A, 5Dec	12/20/2022
WO21544	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07- Weekly Inspection CP07-SS0027 A, 12Dec	12/20/2022
WO21557	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Gearbox Failed	1/3/2023
WO21572	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	CA	Serv Fault - Mag belt bearing housing cracked	
WO21607	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Tail drum roller + sensor	1/3/2023
WO21628	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Feeder stopping - knocking noise while running	1/3/2023
WO21654	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Impact head not working	1/3/2023
WO21681	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Snubber bearings	12/16/2022
WO21670	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection CP07-SS0027A, 19Dec	1/5/2023
WO21721	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Jaw position fault	2/7/2023
WO21739	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Skirt change/fix	2/2/2023
WO21787	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-weekly inspection, 2Jan	1/4/2023
WO21868	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07- Weekly Inspection, 9Jan	1/11/2023
WO21912	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Insp fault - Conveyor head drum, extend both sides grease	4/4/2023
WO21911	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	MI	Insp fault - RH / LH drive sprocket broken teeth	
WO21943	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Replace brackets and refit return roller under machine	1/13/2023
WO21944	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07- Check ram hydraulic pressures x 2	5/30/2023
WO21996	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 16Jan	1/19/2023
WO21977	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	CI	Install new tracking roller	
WO22016	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Prestart - leaking gear oil	2/1/2023
WO22037	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07- Re-install R/H side track pin	1/12/2023
WO22056	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Insp fault - 2 x cheek bolt broken/missing	1/24/2023
WO22088	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	Sublet - victech - 1000 Hour Service for CP07-SS027	1/27/2023
WO22092	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Replace LH side shaker box curtain	1/17/2023
WO22098	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Reposition product belt and track pin	1/17/2023
WO22120	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07- Weekly inspection, 23Jan	1/24/2023
WO22130	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	FEEDER KEEPS CUTTING OUT	4/3/2023
WO22227	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 30Jan	2/1/2023
WO22338	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Bottom Cheek plates worn out	4/3/2023
WO22378	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 6Feb	2/14/2023
WO22432	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PR	Jaw keeps cutting out	2/24/2023
WO22473	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 13Feb	2/15/2023
WO22490	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Auto greaser - fit grease fitting and adjust	2/10/2023
WO22525	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	Weld in deflector plates	2/17/2023
WO22591	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 20Feb	2/28/2023
WO22581	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07-SS027	3/28/2023
WO22653	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07-Replace both snubber roller bearings-UC211-203D	2/17/2023
WO22696	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 27Feb	2/28/2023
WO22774	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Cone not auto zeroing - actually CR3	4/3/2023
WO22802	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 6Mar	3/9/2023
WO22973	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 13Mar	3/21/2023
WO23027	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Repair relay for auto greaser	4/3/2023
WO23067	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 20Mar	3/22/2023
WO23088	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Prestart - head drum scraper needs adjusting	7/27/2023
WO23168	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07- Weekly Inspection, 27Mar	4/5/2023
WO23173	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07-Repair guarding	3/22/2023
WO23252	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	500 Hour Service for CP07-SS027	4/11/2023
WO23291	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Hydraulic oil filter housing broken	3/29/2023
WO23276	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 3Apr	4/5/2023
WO23353	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	CA	Swing stock cracked	
WO23428	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07- Weekly Inspection, 10Apr	4/13/2023
WO23453	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	No drive at head drum	4/11/2023
WO23495	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 17Apr	4/18/2023

WO23519	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Sublet- Rapid hose- hydraulic line behind jaw damaged	4/23/2023
WO23570	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Roller popped out and snapped drive bolt	4/20/2023
WO23586	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Conveyor lanyards not working, JB	5/23/2023
WO23587	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	OE	Steps bent	
WO23612	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 24Apr	4/27/2023
WO23648	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY, 24Apr	5/5/2023
WO23661	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY, 01May	5/5/2023
WO23660	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 01May	5/11/2023
WO23674	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	REPLACE SNUBBER ROLLER AND BEARINGS AT TAIL DRUM	4/27/2023
WO23831	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Gearbox on headdrum not working - replaced	5/2/2023
WO23951	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 08May	5/18/2023
WO23939	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Do up swing side liner	5/30/2023
WO24018	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY, 15May	5/16/2023
WO24019	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 15May	5/23/2023
WO23901	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY 08 May	5/18/2023
WO24126	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Jaw opening up when trying to adjust, replace jaw cylinders	7/13/2023
WO24180	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	250 Hour Service for CP07-SS027	7/7/2023
WO24232	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY, 22May	5/26/2023
WO24231	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 22May	6/8/2023
WO24331	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 29May	6/1/2023
WO24332	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY, 29May	6/8/2023
WO24408	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Auto greaser leaking out of over flow	7/27/2023
WO24531	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 5June	6/8/2023
WO24466	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE TIR CYLINDERS WEEKLY, 5June	6/8/2023
WO24598	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 12June	6/14/2023
WO24599	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE JAW CYLINDERS WEEKLY, 12June	6/14/2023
WO24629	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Repair skirt - track belt	6/13/2023
WO24640	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Replace speed sensor on product belt	6/15/2023
WO24661	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Insp fault - Tail drum cylinder leaking - taildrum not level	7/18/2023
WO24670	CP07	Telesmith TJ3258 Jaw Crusher	Complete	OE	CP07- Repair guard under product conveyor	6/14/2023
WO24709	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly Inspection, 19June	6/20/2023
WO24697	CP07	Telesmith TJ3258 Jaw Crusher	Complete	MI	CP07-Tighten right side cheek plate	6/22/2023
WO24710	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE JAW CYLINDERS WEEKLY, 19June	6/26/2023
WO24806	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE JAW CYLINDERS WEEKLY, 26June	6/26/2023
WO24805	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 26June	7/11/2023
WO24996	CP07	Telesmith TJ3258 Jaw Crusher	Complete	BD	Hyd pump failed	7/13/2023
WO25085	CP07	Telesmith TJ3258 Jaw Crusher	Complete	GE	Flip liner - Fixed Liner damaged- Replace	7/21/2023
WO25136	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	2000 Hour Service for CP07-SS027	7/10/2023
WO25216	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 17July	7/17/2023
WO25217	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Cycle Jaw cylinders	7/17/2023
WO25342	CP07	Telesmith TJ3258 Jaw Crusher	Complete	CA	Hydraulic hose leak	7/19/2023
WO25363	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection	7/26/2023
WO25364	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE JAW CYLINDERS WEEKLY, 24July	7/26/2023
WO25484	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CP07-Weekly inspection, 31July	8/3/2023
WO25485	CP07	Telesmith TJ3258 Jaw Crusher	Complete	PM	CYCLE JAW CYLINDERS WEEKLY, 31July	8/3/2023
WO25613	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	CI	Needs lighting	
WO25658	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	PM	CP07-Weekly inspection, 7Aug	
WO25659	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	PM	CYCLE JAW CYLINDERS WEEKLY, 7Aug	
WO25669	CP07	Telesmith TJ3258 Jaw Crusher	Complete	GE	Repair vibrating feeder outer casing	8/3/2023
WO25722	CP07	Telesmith TJ3258 Jaw Crusher	In Progress	CA	Prestart- Skirts leaking near tail drum	
WO25742	CP07	Telesmith TJ3258 Jaw Crusher	Planned	PM	CP07-Weekly inspection, 14Aug	
WO25743	CP07	Telesmith TJ3258 Jaw Crusher	Planned	PM	CYCLE JAW CYLINDERS WEEKLY, 14Aug	