

Number	Type	Date Open	Date Closed	Kilometres	Clc Fault	Repairer / Notes	Cost / Invoice
R-8624	Glass	06/05/2025	11/11/2025	245,805	10511	Internal Workshop - Night Shift Left hand side glass missing bolt and flapping around letting dust in cab. REPLACED ALL BOLTS THAT HOLD REAR WINDOWS SHUT. Internal Workshop - Night Shift REPLACED ALL WHHEL BEARINGS AND SEALS. REPLACED BRAKES SHOES ON REAR. REPLACED GEARBOX CABLES. REAPLCED TURBO AND GASKETS. REPLACED INTAKE PIPES FOR TURBO.	\$0.00
S-7288	D - 120k	09/11/2025	11/11/2025	245,805	7,133	REBUILT STEERING BOX	\$0.00
R-8833	Machinery inspection	08/27/2025	08/27/2025	245,701		PASSED MACHINERY.	\$0.00
S-7075	A - 10K	07/01/2025	02/07/2025	245,570	1,341	Internal Workshop - Night Shift REPLACED ALL FAILED GREASE NIPPLES.. Internal Workshop - Night Shift REPLACED BOTH INDERCATOR LENSES ON BOTH DOORS. REPLACED WHOLE CAB LOCK MECHANISM.	\$0.00
S-6586	A - 10K	10/14/2024	15/10/2024	244,229	869	REPLACED FRONT BUMPER.	\$0.00
R-7392	Air con	04/10/2024	07/29/2024	243,360	7991	A Grade Auto Repair A GRADE AUTO REPLACED CONDENSOR AND FAN AND GASED SYSTEM Internal Workshop - Night Shift SERVICE COMPLETED BY TYSON E. REPLACED ENGINE OIL IN TRUCK AND HONDA WATER PUMP. TOPED UP POWER STEERING OIL.	\$0.00
S-6442	A - 10K	07/29/2024	29/07/2024	243,360	1,351	REPLACED LHS LED MARKER LIGHT AMBER/RED.	\$0.00
I-40	Machinery Inspection	03/22/2024	03/20/2024	242,074		Certificate of Inspection as per attached.	\$0.00
R-7330	Pre-machinery check	03/25/2024	03/12/2024	242,049		Replaced a steering wheel. Replaced d/s seat supplied by seats r us. Replaced d/s seat belt. Replaced blinkers in doors. Replaced both front parker lenses.	\$0.00
S-6111	A - 10K	03/06/2024	06/03/2024	242,009	3,304		\$0.00
R-6933	Air Conditioning	11/24/2023	11/24/2023	239,995		A Grade Auto Repair Replaced a/c fan supplied and fitted by A grade. Internal Workshop - Night Shift replaced 3 actuators on rear off tank due to old ones being seized done by Jarrod	\$0.00
R-6681	Actuator	10/18/2023	10/10/2023		0		\$0.00
S-5824	A - 10K	09/28/2023	28/09/2023	238,705	33		\$0.00
R-6471	Fuel Primer	07/19/2023	09/08/2023			Internal Workshop - Night Shift Replaced as per Jay Audit 8/9/23	\$0.00
R-6470	Tyre	07/19/2023	09/08/2023			Internal Workshop Replaced as per Jay Audit 8/9/23 A Grade Auto Repair Wired up water tank, replaced stereo, replaced tail lights on water tank, rewired power from battery to water pump. A grade invoice attached.	\$0.00
R-6887	Electrical	08/30/2023	08/30/2023	238,704			\$0.00
R-5538	Number plate lights	12/08/2022	07/19/2023	238,672		Internal Workshop - Night Shift Replaced number plates.	\$0.00

R-5072	Wipers	08/30/2022	07/19/2023	238,672		5265	Replaced wipers. Repair leaking valve stem on RH steer tyre - clean up rust and change d-ring on stem Degrease oil leaks R&R air dryer element R&R all belts	\$0.00
S-5670	D - 60k	07/18/2023	07/19/2023	238,672	4,349		R&R tailgate booster and make attachment for booster	\$0.00
R-3735	Power Steering, Wiring	01/11/2022	01/11/2022	234,323			Fit new reservoir tank for power steering, fill back up with ATF fluid. Repaired wiring for reverse lights. Repaired wiring for RH tail light. Replaced blown globe for number plate light. Repaired tail gate locks. Repair air leak at rear of truck. Fit new bearings to steer axle packed with new grease. Adjusted brakes.	\$0.00
R-3734	Bearings	01/10/2022	01/10/2022	234,323			Tightened exhaust stack.	\$0.00
R-3732	Bearings	12/16/2021	12/16/2021	234,323			Removed front wheel bearings and cleaned ready for new bearings to be fitted. Replaced wiper blades x 3 with new and blow out jets. Power steering box leaking from top seal. Power steering leaking at reservoir tank bottom fitting. Front wheel bearings too tight. No reverse lights and bad earth RH rear tail light. No number plate light.	\$0.00
S-4139	D - 60k	12/13/2021	12/14/2021	234,323	234,323		Rear tail gate locks not working.	\$0.00
R-2465	UHF	01/20/2021	08/23/2021			1209	Internal Workshop Checked and repaired. Jay signed off spreadsheet.	
R-2382	UHF	01/22/2021	01/28/2021	231,781		1302	Internal Workshop Troy confirmed UHF is now operational 28/01/2020	