

Vehicle History Summary

Fleet #	BLL1453
Registration	855SXU
Make	UD
Model	CW
VIN / Chassis	JNBCWB4DA00W00247
Build Date	2012

Number	Date	Km	Hours	Type	Repairer Notes	Repairer
R-1175	2025-07-08	8135		Fuel	Found hand primer leaking at seals. Replaced fuel filter housing, primer and filter. Test drive. OK	Fez
R-1128	2025-06-27	6270		Radiator	Replaced header tank. Removed rust from brackets and paint. Top up coolant and pressure test. OK	Fez
T-222	2025-06-19	4347		Puncture	1 X PUNCTURE REPAIRS	
S-1175	2025-06-19	1234302	0	A - CHECK OVER	Transmission output seal leaking. Input seal front diff leaking. Needs 4 rear shock absorbers. Air bags cracking.	Fez
I-132	2025-06-19	434		NHVR Heavy Vehicle Inspection		Fez
R-920	2025-05-26	1234302		Fuel	Replaced instrument cluster (Last odo reading 1234302km, now showing 6km) Replaced rear cab airbags. Replaced fuel sender and fitted electrical connector to suit. Test drive.	
R-920	2025-05-21	0	0	Cab		
T-197	2025-05-20	1234302		Steer	2 X NEW TYRES	Internal Workshop
R-882	2025-05-16	1234301		Lights	most right side break lights not working	
R-978	2025-05-09	1233240	0	Gearbox	TRUCK BEING SOLD Very hard to get into 3rd and 7th gear	
R-766	2025-04-22	1229233	0	Suspension	noted at last service 3 shocks need replacing	All Sorts Heavy Mechanical
T-167	2025-04-10			Truck Drive	4 NEW TYRES REAR AXLE	Internal Workshop
R-855	2025-03-12	1221991		Gearbox	Call out to 24 Henry Street Loganholme. Inspected why driver could not get gears. Found gear shifter linkage to be broken. Replaced with new one and adjust. Test. OK. Return to depot.	All Sorts Heavy Mechanical
T-153	2025-02-12	1217081		Puncture	puncture repair	Goodyear Gatton
R-793	2025-02-03	1215778		Lights	Removed left rear taillight assembly and bent back flat. Tighten bolts on taillight bracket. Fit and rewire new taillight and clearance light.	All Sorts Heavy Mechanical
R-770	2025-01-28	0	0	Chassis	TRUCK BEING SOLD NOTED AT LAST SERVICE Front pinion seal leaking and second diff pinion seal leaking.	

S-1016	2025-01-28	1214884		B - MINOR	Notes. 3 shocks need replacing. Output seal leaking on transmission. Headboard needs replacing full of rust. Engine and transmission mounts need replacing. Front pinion seal leaking and second diff pinion seal leaking.	All Sorts Heavy Mechanical
R-769	2025-01-28	0	0	Chassis	TRUCK BEING SOLD NOTED AT LAST SERVICE Engine and transmission mounts need replacing	
R-768	2025-01-28	0	0	Cab	TRUCK BEING SOLD NOTED AT LAST SERVICE Headboard needs replacing full of rust.	Cranemech
R-767	2025-01-28	0	0	Gearbox	TRUCK BEING SOLD noted at last service Output seal leaking on transmission	
T-142	2025-01-17	1207880		Steer		Internal Workshop
T-135	2024-12-17	1207880	0	Fault, Steer		Internal Workshop
R-704	2024-12-17	1207613		Battery	Repairs for Rego: 855SXU BLL1453 Odometer/hours: 1207613km Faults/Defects: No start Description of work carried out: Travel to Iplex. Diagnose no start issue. Replaced batteries. Checked charging system. OK	All Sorts Heavy Mechanical
R-658	2024-12-03	1205581		Suspension	Replaced both V Stays and pinion seal on rear diff	All Sorts Heavy Mechanical
R-672	2024-11-22			Tray	* Remove & replaced leaking override valve * Function tested crane * Crane functioned fine	Cranemech
R-671	2024-11-22			Tray	* Replaced rear centre bolster pocket * Replaced floor needed around bolster pocket * Painted	Cranemech
R-594	2024-09-26	1191522		Chassis	Removed back bar and straightened Refit and replace left tail light and clearance light	All Sorts Heavy Mechanical
R-503	2024-09-20			Air Conditioner		All Sorts Electrical
R-497	2024-09-05	1189583	0	Windscreen		Internal Workshop
R-469	2024-08-21	1186956		Suspension	Replace front shackle pins, bushes and swinging shackles. Use of Oxy to remove seized pins	All Sorts Heavy Mechanical
R-411	2024-08-08	1185267		Cab		All Sorts Heavy Mechanical
R-374	2024-07-17			Suspension		All Sorts Heavy Mechanical
R-338	2024-07-12	1181655	0	Suspension		All Sorts Heavy Mechanical
R-317	2024-07-12			Air Conditioner	A/C not cold. Checked over A/C, found compressor O-rings were leaking. Replaced O-rings and serviced system. Test operation. Test ok.	All Sorts Electrical

R-401	2024-07-04			Suspension	re-align axle swing arm to drop hanger on passenger side, install new bolts and replace drivers side bolts as they too were loose. Swing arm did hit fuel tank and tank was inspected and did not appear to be leaking.	Cranemech
I-90	2024-06-13	1178504		NHVR Heavy Vehicle Inspection		All Sorts Heavy Mechanical
S-686	2024-06-13	1178504	0	D - ANNUAL		All Sorts Heavy Mechanical
R-165	2024-06-10	1178121	0	Air Conditioner		All Sorts Heavy Mechanical
R-164	2024-06-10	1178121	0	Lights		Internal Workshop
T-59	2024-06-10	1178496		Truck Drive	puncture repair	Internal Workshop
R-275	2024-05-31	1176871	0	Chassis		All Sorts Heavy Mechanical
R-66	2024-03-05	1163171	0	Fuel		Internal Workshop
T-8	2024-02-20	1161116	0	11R 225		Internal Workshop
S-373	2024-01-17	1154893		B - MINOR		Internal Workshop
S-104	2023-10-10	1145890		B - MINOR		Internal Workshop
R-25	2023-06-22	0	0	Engine	Cleared faults. Road tested and pump now holding pressure.	VCV Australia
S-103	2023-06-12	1142180		D - ANNUAL		Internal Workshop
T-5	2023-06-01	1130857	0	New		Internal Workshop
T-5	2023-06-01	1118761	0	New		Internal Workshop
R-24	2023-05-21	1126051	0	Radiator	New one ordered, Minto. Truck is going to have heater core repaired at pinkinba. Bypassed heater core so could get truck back to the yard. by passed washed and road tested all ok.	VCV Australia
S-139	2022-12-08	1142180		B - MINOR		Internal Workshop