

Date	Notes
22/07/2021	#312 - 2,525Hrs. Remove final drive cover and tap out holes. Refit cover.
22/07/2021	#312 - Manufacture mudscraper & fit to machine. Repair greaseline mount. Replace auto grease connec
23/07/2021	#312 - 2,525Hrs. Repair to silt bucket. Remove and replace pump door
23/07/2021	#312 - Repairs to silt bucket
24/07/2021	#312 - 2,525Hrs. Repair to silt bucket. Remove and replace pump door
24/07/2021	#312 - Refurbish silt bucket
27/07/2021	#312 - Check bucket measurements and load onto float
13/08/2021	Purchase Ad Blue
17/08/2021	Grease + Adblue
03/09/2021	Service
03/09/2021	2,750Hrs. Repair grease line
12/09/2021	Repair 2 x grease lines
16/09/2021	Gouge and weld cracks in digging bucket
17/09/2021	Load digging bucket for transport to Broadbent
22/09/2021	2,870Hrs. Remove broke fitting and refit. Check grease fitting
25/09/2021	Repair oil leak on stick cylinder relief valve
06/10/2021	Organise oils & filters for 1000Hr Service
14/10/2021	3,000Hrs Service
14/10/2021	Service with DW
15/10/2021	Add Adblue
04/11/2021	Check oil leak on hitch and drop off grease
20/11/2021	3,250Hrs. Service
20/11/2021	Held up with DW Service
22/11/2021	3,250Hrs. Fill out SOS samples
17/12/2021	Town - Fuel & Adblue
13/01/2022	Service
13/01/2022	3,500Hrs Service
15/01/2022	3,500Hrs. Fill out SOS Samples
15/01/2022	Fix greaselines
04/02/2022	GPS Calibration
07/02/2022	3,624Hrs. Remove and turn bucket edge and refit
07/02/2022	Rotate cutting edge
01/03/2022	Service with Fitter
01/03/2022	3,750Hrs service. Check fault. Fill out SOS samples
14/03/2022	Walk to be floated out. + DE-ESTABLISH FEE
18/03/2022	Repairs to silt bucket
18/03/2022	Maintenance
14/04/2022	3,825Hrs. Fit cutting edge to mud bucket
22/04/2022	Break down - Auto grease lines
04/05/2022	4,000Hrs service
05/05/2022	4,000Hrs service
19/05/2022	4,008Hrs. Check fault codes and do manual burn. Test
25/06/2022	4,250Hrs. Check drive plate & price parts
04/07/2022	4,250hrs. Complete Service.
05/07/2022	4,268Hrs. Load onto float at Westrac. Unload at Depot. Reload. Top up grease and fuel
06/07/2022	Check fault codes
08/07/2022	Westrac - Fill Adblue
16/07/2022	Fit GPS aerial and test
30/07/2022	4,428hrs. Check engine oil level and damper level
02/08/2022	Maintenance
02/08/2022	Assist Westrac - DPF Burn

17/08/2022 Travel to Jobsite. Clean down for transport  
17/08/2022 Clean down. Load onto float for transport back to depot  
18/08/2022 4,520Hrs - 250hr Service - DPF burn  
19/08/2022 Fuel. Grease  
07/09/2022 4,640Hrs. Drain and refill RH final drive  
12/09/2022 4,660Hrs. Perform DPF regen  
26/09/2022 4,705Hrs. Check and calibrate DEF systems. Regenerate. Clean mud from tracks  
10/10/2022 4777Hrs. - 250Hr Service  
10/10/2022 7444Hrs. Assist wth 250Hr Service  
17/10/2022 Troubleshooting fault codes  
05/11/2022 Shovel down  
25/11/2022 4,915Hrs. Plug computer in. Perform manual DPF burn  
12/12/2022 4,957Hrs. Check fault codes and test. Check boom cylinder movement  
13/12/2022 Assist HN remove DPF  
13/12/2022 Repairs to DPF. Pack up for transport to Rocklea  
13/12/2022 Wash  
13/12/2022 4,958Hrs. Remove DPF Filter  
16/12/2022 4,957Hrs. Assemble DPF to machine  
16/12/2022 4,952Hrs. Replace DPF injection. Refit DPF filter  
17/12/2022 4,957Hrs. Check fault codes and check over  
16/01/2023 5000Hr part service. Fill out SOS samples  
17/01/2023 Assist DW with Service  
17/01/2023 5,073Hrs Service with DW  
17/01/2023 Continue 5000Hr service. Blow out coolers and check A/C operation  
03/03/2023 5279.9Hr Service  
06/03/2023 Help HN with hydraulic oil change  
06/03/2023 5,280Hrs. Replace hydraulic oil and filters  
08/03/2023 5280Hrs. Finish changing hydraulic oil and screen  
08/03/2023 Reassemble hyd tank and refill with oil. Bleed system and test  
09/03/2023 5280Hrs. Drain hyd oil. Pull hose off to clean. Remove filter  
09/03/2023 Check over fault and remove hyd pump Dismantle and order parts  
10/03/2023 Clean up parts and refit hoses. Clean out hyd tank and replace filters  
13/03/2023 Run through diagnostics with Westrac  
15/03/2023 5281Hrs. Load up parts and oil. Reassemble hyd pump and drive. Bleed air from system. Test run. Che  
16/03/2023 5283Hrs. Clean out grease system diverters. Fill with greas. Check noise in boom mount  
18/03/2023 5295Hrs. Check grease unit and lines  
20/03/2023 5295Hrs. Check and repair bucket cyl rod.  
31/03/2023 Grease  
31/03/2023 5,343Hrs. Check and tighten hose at hyd tank  
11/05/2023 5,410Hrs. Check start fault and Turn E Stop  
30/05/2023 5500Hrs Service  
02/06/2023 Fill Adblue tank  
05/06/2023 5560Hrs. Top up grease unit  
08/06/2023 Attempt to update machine  
09/06/2023 Software update machine  
14/06/2023 Diganose GPS with Westrac  
15/06/2023 Flip receivers  
11/07/2023 5755.2Hrs. Service  
03/08/2023 5903Hrs. Check grease system. Clean out diverter valve at link. Repair grease line and prime system  
10/08/2023 Check stick fault. Remove stick cylinder for repairs  
24/08/2023 Assist DW with Ram repairs  
24/08/2023 5940Hrs. Load up stick cylinder. Refit seals. Assemble cylinder to machine. Top up oil. Test

## Wilde Civil Pty Ltd TWC Pty Ltd

08/09/2023 6000Hrs Service  
11/09/2023 6000Hrs Complete Service. Fill out SOS  
09/11/2023 Fill grease unit  
02/12/2023 Diagnose issues  
05/12/2023 6138Hrs. Check hyd inputs and change settings. Test  
12/12/2023 Blow out radiator. Cleandown. Get ready to float  
19/12/2023 6213Hrs. Check and measure bucket teeth. Order parts  
08/01/2024 6223Hrs. Fill up grease unit  
11/01/2024 6250Hrs Service  
19/02/2024 Bring into Workshop. Oxy cut boots off mud bucket  
20/02/2024 Bring into Workshop. Oxy cut boots off mud bucket  
21/02/2024 Weld mud bucket - holes & stress cracks. Oxy boot pins out of dig bucket.  
21/02/2024 Remove pins  
29/02/2024 6429.3Hrs. Diagnose GPS issues. Find gease leak  
01/03/2024 6429.3Hrs. Try to diagnose GPS issues. Repairs to greaseline  
02/03/2024 Add Adblue  
04/03/2024 6429.3Hrs. Diagnose GPS issues. Find gease leak  
07/03/2024 Inspect coolant leak. Find failed water pump  
08/03/2024 Remove water pump  
09/03/2024 Instal water pump.  
11/03/2024 Wash  
12/03/2024 Assist with re-install of quick hitch  
12/03/2024 Remove hitch and grind up. Weld cracks on hitch. Refit and fix grease lines  
13/03/2024 Wash out radiator Clean cab Paint Quick hitch and Grind burs on pins  
13/03/2024 Fix and fill grease system.  
21/03/2024 Part service  
22/03/2024 6508 Hrs. Service  
29/04/2024 6692Hrs. Adjust eng bay door catch. Remove guard  
13/05/2024 6728Hrs. Check off parts. Repairs to IMU sensor  
14/05/2024 6728Hrs. Part Service. Remove and replace broken IMU sensor. Refit. Clean dirt from track motor hos  
15/05/2024 6728Hrs. Refit IMU unit and brackets. Check calibration  
16/05/2024 6728Hrs. Calibrate GPS sensors  
28/05/2024 6750Hrs. Complete Service. Fill out SOS samples  
24/06/2024 6947Hrs. Check grease operation  
25/06/2024 Inspect quick hitch not disconnecting  
25/06/2024 6942Hrs. Check grease operation. Repair line. Clean out diverter. Order parts. Check quick hitch op  
26/06/2024 Source GPS issues/problem  
27/06/2024 Remove grease lines and manually grease pins.  
28/06/2024 6963Hrs. Check fault codes. Clean stick sensor and cable connectors. Check connectivity  
01/07/2024 6971Hrs. Check and clean out GPS connectors. Clean grease diverters  
02/07/2024 6974Hrs. Check and replace can terminators Check operation.  
03/07/2024 6983Hrs. Part service. Remove and replace grease diverter. Check fault codes for adblue sysemt  
24/07/2024 Add grease in to auto greaser  
13/08/2024 Check fault codes. Check tank breather and clamps and hoses  
13/08/2024 Problem - Issue with Derate  
19/08/2024 7095Hrs. Check and repair grease lines. Remove and clean out valves  
19/08/2024 Diagnose Adblue Issues and broken grease lines  
20/08/2024 Test issues with DPF / Exhaust  
20/08/2024 7095Hrs. Remove and replace arm sensor cable. Check movement in boom pins  
20/08/2024 Make and maintain Grease lines.  
20/08/2024 Attempt to remove boom  
23/08/2024 7095Hrs. Check parts and shims for boom pin

28/08/2024 7095Hrs. Clean dirt from tracks  
18/09/2024 7192Hrs. Fill up add blue tank  
18/09/2024 7195Hrs. Calibrate tilt bucket and GPS auto function  
19/09/2024 7198Hrs. Prestart and top up Adblue  
30/09/2024 Clean down ready for Transport  
30/09/2024 Diagnose DPF fault. Codes, clear, clean connectors  
23/10/2024 Fuel. Add Adblue. Grease  
06/11/2024 7,250Hrs. Part service and fill out SOS samples  
07/11/2024 Assist DW with service  
07/11/2024 7,250Hrs Complete service  
25/11/2024 Issue with hyd flow  
25/11/2024 Diagnose issue with no hyd power. Remove pressure bypass and arrange replacement  
26/11/2024 Check hyd pressures and operations  
27/11/2024 7,400Hrs. Check and clean GPS cable connectors. Check and change back what Shane changed. Test  
09/12/2024 Prestart + Adblue  
11/12/2024 Prestart + Adblue  
06/01/2025 Inspect counter weight brakcets  
07/01/2025 Prestart. Check over  
15/01/2025 7,500Hrs - SOS Samples  
16/01/2025 7500 hrs - Service  
16/01/2025 Service  
20/01/2025 7511Hrs - Clean dirt off tracks  
29/01/2025 Repairs to A/C System  
29/01/2025 7513Hrs - Check A/C  
30/01/2025 Inspect auto greaser line and repair  
15/04/2025 8,000Hrs - Part Service  
15/04/2025 Prep for transport to Gunyerwarildi  
08/05/2025 7,583Hrs. Repair grease line and check over  
13/05/2025 7,612Hrs. Check grease pump operation. Top up grease tank. Check operation  
23/05/2025 7,652Hr. Replace cutting edge  
04/07/2025 7800Hrs - Service  
12/08/2025 Prestart. Add adblue. Fix auto grease line  
20/08/2025 Unload off float  
25/08/2025 7,912Hrs. Prestart. Fuel. Blow out cooling system. Load onto float  
25/08/2025 Install new GPS cable  
25/08/2025 Assist load onto float  
13/10/2025 Assist CW with R&M  
13/10/2025 Diagnose adblue fault  
22/10/2025 7,983Hrs. Check grease unit  
22/10/2025 Assist DW with R&M  
24/10/2025 8,000Hrs Service - Repair grease line  
02/12/2025 Inspect  
03/12/2025 Prestart Checks. Check over engine. Attempt to bleed hyd system  
16/12/2025 Check and repair grease line  
27/01/2026 Attempt to repair tube - keeps blowing  
27/01/2026 Continual issue with blowing air intake manifold hose  
28/01/2026 Replace tubing