

Date	Name	Duration	Notes
28/02/2018	Dawson, Dale - TWC Mechanic	3.50	Remove counter weights, remove & relocate hydraulic control valve bank.
28/02/2018	Knapman, Kenneth - TWC MECHANIC	3.50	To Scott Stewarts to view cushion hitch mounting & hyd. bracket location & return. Remove hyd. coup
28/02/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove drawbar & shift control valve. Look at cushion hitch.
07/03/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	Fit GPS wiring & controls. Replace air filters.
07/03/2018	Knapman, Kenneth - TWC MECHANIC	5.00	Make brackets for laser boxes. Make laser screen mount brackets.
08/03/2018	Knapman, Kenneth - TWC MECHANIC	4.00	Manufacture laser screen mount bracket.
08/03/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	Fit GPS & laser wiring & valves.
09/03/2018	Knapman, Kenneth - TWC MECHANIC	4.00	Manufacture brackets for Laser controls & paint.
19/03/2018	Dawson, Dale - TWC Mechanic	4.50	Move machine into w'shop for investigation & possible modification of driveshaft shield.
20/03/2018	Dawson, Dale - TWC Mechanic	1.00	Remove drive shaft from engine.
20/03/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & remove uni-joint on input shaft.
21/03/2018	Dawson, Dale - TWC Mechanic	8.50	Fit new uni joint to driveshaft & fir guard. Refit bonnet & guards. Fit new fuel supply hose at art
21/03/2018	Knapman, Kenneth - TWC MECHANIC	0.50	Assist with removal of counterweight.
26/03/2018	Knapman, Kenneth - TWC MECHANIC	9.50	Fit cushion hitch assy. Commence manufacture of Oversize signage mounting brackets.
26/03/2018	Dawson, Dale - TWC Mechanic	3.50	Fit counterweight & weights & start making brackets to fit 'Oversize" signage.
26/03/2018	Wilde, David - TWC WORKSHOP MANAGER	5.50	Fit replacement cushion hitch & hoses.
27/03/2018	Knapman, Kenneth - TWC MECHANIC	9.50	Finish making O/Size sign mounts & fit mounts & signs to machine. Start manufacture of steps for fr
27/03/2018	Wilde, David - TWC WORKSHOP MANAGER	6.00	Fit & test run GPS & laser systems.
28/03/2018	Knapman, Kenneth - TWC MECHANIC	9.50	Continue with manufacture of steps & grad rails.
28/03/2018	Wilde, David - TWC WORKSHOP MANAGER	9.00	Continue with fitting & calibration of GPS & Laser systems.
29/03/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Setting up electrics/hydraulics for bucket.
29/03/2018	Wilde, David - TWC WORKSHOP MANAGER	7.00	Test run GPS & laser system & adjust as required.
03/04/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Replace floor mat, secure harness etc. Fit components to secure machine to float. Load machine onto
05/04/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	7,486HRS: Chk hyd. fault & calibrate remotes. Chk wiring.
06/04/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	Chk remote wiring for short circuits & repair - test run.
07/04/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	7,500HRS: Service.
09/04/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	R & R blown hose. Test run.
11/04/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk wiring to cushion hitch.

14/04/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	7,579HRS: Replace seat suspension & repair wiring.
17/04/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace seat cushion. Chk electrical fault.
18/04/2018	Dawson, Dale - TWC Mechanic	4.00	Source parts for seat repairs. Strip down seat base & commence rebuild.
19/04/2018	Dawson, Dale - TWC Mechanic	1.50	Finish assembly of seat base.
03/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	Repairs
08/05/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	Repairs
10/05/2018	Wilde, David - TWC WORKSHOP MANAGER	7.50	R & R lift cylinder & bushes. Replace bucket hyd. hoses. Remove tractor hoses & have replacements
11/05/2018	Dawson, Dale - TWC Mechanic	1.00	Fit hoses & clamps.
11/05/2018	Wilde, David - TWC WORKSHOP MANAGER	6.50	Fit new hyd. hoses & chk rear wiring harness. Calibrate Cross leveller.
14/05/2018	Wilde, David - TWC WORKSHOP MANAGER	7.00	Refit hyd. hoses & test run. Repairs to auto hyd. system.
15/05/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Remove rear outer dual wheels & move machine into w'shop.
15/05/2018	Wilde, David - TWC WORKSHOP MANAGER	5.50	Repair & calibrate hyd. system. Remove rear dual wheels.
16/05/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Remove outer dual wheels & taper locks.
16/05/2018	Dawson, Dale - TWC Mechanic	1.00	R & R hoses & final drive seals.
16/05/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove rear wheels & taper locks, clean bolts & remove rear diff seal.
17/05/2018	Knapman, Kenneth - TWC MECHANIC	1.50	7,756HRS: Remove damaged drain plug from L/H rear diff.
17/05/2018	Dawson, Dale - TWC Mechanic	2.00	7,746HRS: Remove leaking hoses.
17/05/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	7,756HRS: Chk rear diff for metal. Repairs to seal area.
18/05/2018	Dawson, Dale - TWC Mechanic	4.50	Install hoses on rear diff & refit guards etc. R & R pressure sender on diff lube line
21/05/2018	Dawson, Dale - TWC Mechanic	0.50	Follow up on order of seal spacers from supplier.
28/05/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	7,756HRS: Repair axle seals.
29/05/2018	Dawson, Dale - TWC Mechanic	2.00	Repair seals on final drives.
30/05/2018	Dawson, Dale - TWC Mechanic	2.00	Reseal final drive, remove R/H side tyre & instal seal on axle.
30/05/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Remove wheel weights etc.
30/05/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Refit wheel wedges & wheels.
31/05/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	Refit rear wheel & tension nuts.
01/06/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove rear wheels ready for seal replacement.
01/06/2018	Dawson, Dale - TWC Mechanic	6.00	Fit rear outer dual tyre set up. Fit new seal to L/H front axle shaft. Remove front dual tyre set u
04/06/2018	Dawson, Dale - TWC Mechanic	7.50	7,757HRS: Fit new seal to front R/H axle. Refit front dual wheels, fit bucket to tractor, check lea
07/06/2018	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace coolant tank cap.
08/06/2018	Dawson, Dale - TWC Mechanic	2.00	BUCKET: Fit new steel tubes, move bucket to shed & disconnect from tractor. Commence welding repair

12/06/2018	Dawson, Dale - TWC Mechanic	2.00	BUCKET: Repairs to laser bracket clamps - weld on brackets etc. Organise steel for cable covers
13/06/2018	Dawson, Dale - TWC Mechanic	0.50	BUCKET: Assist with assembly of pipes etc.
15/06/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Repair towball/hitch.
15/06/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	Repairs to towball & connect to tractor. Make up & fir new cables.
21/06/2018	Wilde, David - TWC WORKSHOP MANAGER	9.50	Prestart, chk GPS control connectivity. Replace radio & receivers & test run.
21/06/2018	Dawson, Dale - TWC Mechanic	1.00	Travel to airport site & remove Laser bucket GPS unit.
21/06/2018	Dawson, Dale - TWC Mechanic	4.00	Investigate GPS faults, repair leaking hoses, prep machine for transport to Breeza jobsite.
30/06/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	repair a/c & heater. Look up parts.
03/07/2018	Dawson, Dale - TWC Mechanic	1.50	7,484HRS: R & R #3 & #4 hyd. control switches in cab.
03/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Look up & order parts. Chk wiring diagram.
05/07/2018	Dawson, Dale - TWC Mechanic	0.50	Fit pins back into rams on bucket hitch.
10/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	7,908HRS: Replace bucket hub & wheel.
13/07/2018	Dawson, Dale - TWC Mechanic	0.50	Chains on wheels (bucket).
16/07/2018	Dawson, Dale - TWC Mechanic	1.00	BUCKET: R & R tyre.
21/07/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	8,000HRS: Part service.
25/07/2018	Dawson, Dale - TWC Mechanic	2.00	R & R all filters - part of 1,000hr service. Drain hyd. & diff oils & refill. Investigate GPS fault
27/07/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	8,054HRS: R & R #3 switch & calibrate. Replace eng. breather.
30/07/2018	Dawson, Dale - TWC Mechanic	2.00	Strip down hyd. cylinder, inspect, repair & re-seal.
02/08/2018	Dawson, Dale - TWC Mechanic	3.50	Strip down hyd. cylinder, insoect, reseal & reassemble. Reseal laser bucket hubs.
03/08/2018	Dawson, Dale - TWC Mechanic	1.50	34,582HRS: R & R GPS harness, fit wear strips to bucket, fill tyres with water.
09/08/2018	Dawson, Dale - TWC Mechanic	1.50	641HRS: R & R leaking bucket hub, fit new stauff clamps to steel piping & hoses. Fit new bolts to G
10/08/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Disassemble & replace bearings & seals. Reassemble.
14/08/2018	Dawson, Dale - TWC Mechanic	3.50	Assist remove rear half of laser bucket from #250 & load onto float for transport to jobsite.
15/08/2018	Dawson, Dale - TWC Mechanic	4.50	8,175HRS - Laser Bucket: Remove broken rear half of bucket, effect weld reapirs to bucket & fit rep
15/08/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	BUCKET: Dismantle floor from broken frame.
16/08/2018	Knapman, Kenneth - TWC MECHANIC	7.00	LASER BUCKET: Commence repairs/remanufacture of rear bucket frame - Purchase & cut steel.
16/08/2018	Wilde, David - TWC WORKSHOP MANAGER	5.50	Dismantle & commence repairs to bowl frame.
16/08/2018	Dawson, Dale - TWC Mechanic	1.00	Laser Bucket: Remove bowl from frame for repairs to broken frame.
17/08/2018	Dawson, Dale - TWC Mechanic	2.50	Bucket Frame: Assist with repairs to frame arms.
17/08/2018	Knapman, Kenneth - TWC MECHANIC	6.50	Laser Bucket: Reman. rear frame side arms assy's.

18/08/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Make up steel plates & continue frame repairs.
18/08/2018	Knapman, Kenneth - TWC MECHANIC	6.00	Laser Bucket: Reman. rear frame side arms assy's.
20/08/2018	Knapman, Kenneth - TWC MECHANIC	9.00	Laser Bucket: Reman. rear frame side arms assy's.
20/08/2018	Wilde, David - TWC WORKSHOP MANAGER	6.00	Laser Bucket: Assist with repairs to rear frame arms etc. - R & R bushes.
21/08/2018	Dawson, Dale - TWC Mechanic	0.50	Laser Bucket: Press bushes into bucket.
21/08/2018	Knapman, Kenneth - TWC MECHANIC	8.00	Laser Bucket: Reman. rear frame side arms assy's.
21/08/2018	Wilde, David - TWC WORKSHOP MANAGER	8.50	Continue assist with repairs to bucket frame
22/08/2018	Knapman, Kenneth - TWC MECHANIC	9.50	Laser Bucket: Continue with repairs/reman of bucket.
22/08/2018	Wilde, David - TWC WORKSHOP MANAGER	7.00	Continue assist with repairs to bucket frame
23/08/2018	Knapman, Kenneth - TWC MECHANIC	9.00	LASER BUCKET: Continue with reman/repair of bucket frame arms etc.
23/08/2018	Dawson, Dale - TWC Mechanic	2.50	Assist with bucket frame repairs & prime frame.
23/08/2018	Wilde, David - TWC WORKSHOP MANAGER	8.00	LASER BUCKET: Assist with repairs to rear frame arms & prime new sections.
24/08/2018	Knapman, Kenneth - TWC MECHANIC	4.50	LASER BUCKET: Remain/repair mould board.
27/08/2018	Dawson, Dale - TWC Mechanic	1.50	8,244HRS: 250hr service.
28/08/2018	Dawson, Dale - TWC Mechanic	0.50	8,252HRS: R & R furl filters.
29/08/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Assemble bucket.
29/08/2018	Dawson, Dale - TWC Mechanic	2.00	Investigate faults, order parts for repairs.
29/08/2018	Dawson, Dale - TWC Mechanic	0.50	LASER BUCKET: Assist with repairs.
29/08/2018	Knapman, Kenneth - TWC MECHANIC	2.00	Fit bowl to frame - remove from shed.
30/08/2018	Dawson, Dale - TWC Mechanic	6.50	Assemble laser bucket.
30/08/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	BUCKET: Assemble bucket.
04/09/2018	Dawson, Dale - TWC Mechanic	5.00	8,300HRS: R & R intercooler in front radiator assy. R & R hyd. fan drive motor.
24/09/2018	Dawson, Dale - TWC Mechanic	2.00	Collect draw bar hitch for laser bucket. Strip down, clean & inspect.
24/09/2018	Wilde, David - TWC WORKSHOP MANAGER	2.25	Remove broken towball assy. Price parts.
24/09/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Remove hitch assy for replacement.
25/09/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Refit towball & replace bolts.
27/09/2018	Knapman, Kenneth - TWC MECHANIC	1.00	BUCKET: Repair ripper for replacement.
27/09/2018	Knapman, Kenneth - TWC MECHANIC	1.50	BUCKET: Repair ripper/tyne assy.
27/09/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Travel to machine & repair rippers.
02/10/2018	Knapman, Kenneth - TWC MECHANIC	4.00	Repairs to ripper bars.
05/10/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Make template for bucket ripper supports & purchase steel for bucket repairs.
10/10/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,469HRS: Replace lift cylinder & chk tyre pressures. Price & order 2 new tyres.
26/11/2018	Dawson, Dale - TWC Mechanic	0.50	Laser Bucket: Paint new hitch.
12/12/2018	Dawson, Dale - TWC Mechanic	4.00	500hr service. Replace hitch, replace a/c hose, recharge.

13/12/2018	Wilde, David - TWC WORKSHOP MANAGER		2.00	Clean up ball & deliver To Scott Stewart.
14/12/2018	Wilde, David - TWC WORKSHOP MANAGER		7.00	Chk towball for clearance, repair & test run. Chk cushion hitch accumulator for charge. R & R GPS c
17/12/2018	Wilde, David - TWC WORKSHOP MANAGER		2.50	8,498HRS: Remove tow ball cap & replace - test run.
07/01/2019	Dawson, Dale - TWC Mechanic		4.00	Investigate steering fault - slow steering response - Remove steer valve, inspect & reassemble - al
08/01/2019	Dawson, Dale - TWC Mechanic		5.00	Remove steer cylinders from machine & strip down - reseal 1 cylinder & refit to machine. 2nd cylind
09/01/2019	Dawson, Dale - TWC Mechanic		3.00	R & R L/H steer ram. Investigate & repair fault with cushion hitch.
14/01/2019	Wilde, David - TWC WORKSHOP MANAGER		2.00	Prestart & chk bucket hub oil levels.
14/01/2019	Dawson, Dale - TWC Mechanic		0.50	Fill rear tyres with water.
16/01/2019	Knapman, Kenneth - TWC MECHANIC		3.00	Manufacture mount for GPS box.
17/01/2019	Dawson, Dale - TWC Mechanic		0.50	Investigate/repair headlight fault.
17/01/2019	Wilde, David - TWC WORKSHOP MANAGER		2.50	Replace headlight bulbs & GPS cable. Repair bonnet.
05/02/2019	Dawson, Dale - TWC Mechanic		0.50	Install new cushion jitch.
09/02/2019	Wilde, David - TWC WORKSHOP MANAGER		3.00	8,642HRS: Replace bucket tyre & grease nipples. Chk out a/c - pressure clean system.
13/02/2019	Dawson, Dale - TWC Mechanic		0.50	Tighten stub on apron.
15/02/2019	Wilde, David - TWC WORKSHOP MANAGER		1.00	8,703HRS: Change cutting edges & blow out filters.
23/02/2019	Wilde, David - TWC WORKSHOP MANAGER		2.50	8,750HRS: Service. R & R bucket hose.
02/03/2019	Dawson, Dale - TWC Mechanic		1.00	Clean out radiators. R & R filters.
05/03/2019	Dawson, Dale - TWC Mechanic		0.50	Clean out radiators/filters.
09/04/2019	Dawson, Dale - TWC Mechanic		0.50	Prestart on Laser bucket.
10/04/2019	Dawson, Dale - TWC Mechanic		3.50	Set up laser on bucket & investigate fault - R & R EM400 mast - only raising & not lowering.
30/04/2019	Wilde, David - TWC WORKSHOP MANAGER		1.50	Repair rippers & replace idler pulley.
14/05/2019	Wilde, David - TWC WORKSHOP MANAGER		3.00	Remove, chk & repair flashing light wiring. Replace lights.
16/05/2019	Dawson, Dale - TWC Mechanic		2.00	Split tractor from bucket & remove ripper assy.
20/05/2019	Dawson, Dale - TWC Mechanic		2.50	250hr service.
21/05/2019	Dawson, Dale - TWC Mechanic		6.50	Investigate foreign noise in eng. bay. Remove idler pulleys for replacement. R & R 2 steering hoses.
22/05/2019	Dawson, Dale - TWC Mechanic		1.00	BUCKET Commence repairs to bucket.
23/05/2019	Dawson, Dale - TWC Mechanic		2.00	BUCKET: Repairs to rippers.
24/05/2019	Knapman, Kenneth - TWC MECHANIC		7.00	BUCKET: Repairs to rippers/tynes.
27/05/2019	Knapman, Kenneth - TWC MECHANIC		9.00	BUCKET: Weld repairs to bucket, fabricate ripper mounts & weld on.
27/05/2019	Wilde, David - TWC WORKSHOP MANAGER		8.00	9,008HRS: Rotate tyres.
28/05/2019	Knapman, Kenneth - TWC MECHANIC		9.00	BUCKET: Straighten tynes, replace ripper mounts, straighten ripper guide mounts.
28/05/2019	Wilde, David - TWC WORKSHOP MANAGER		4.00	9,000HRS: Investigate coolant leak - replace heater hoses.

29/05/2019	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Straighten tynes, replace ripper mounts, straighten ripper guide mounts.
30/05/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	BUCKET: Assemble ripper, adjust & tighten. Connect tractor to bucket & connect hoses. test run.
03/06/2019	Dawson, Dale - TWC Mechanic	1.50	Repairs - fit clamps to hoses & a/c hoses.
07/06/2019	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
11/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check operation.
10/07/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	Remove & repair accumulator hitch. Repair oil leaks. Repairs to a/c
12/07/2019	Wilde, David - TWC WORKSHOP MANAGER	7.00	Replace tip cylinder, dysassemble & order parts, remove bonnet, repair hubs & tilt hoses.
15/07/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove bonnet & guards, tilt brackets & pins.
16/07/2019	Knapman, Kenneth - TWC MECHANIC	6.50	Repairs to apron.
16/07/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk camshaft & look up & price parts.
17/07/2019	Knapman, Kenneth - TWC MECHANIC	6.00	Repairs to apron. Repairs to walking beam assy.
18/07/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	BUCKET: Repairs to apron & cross leveller beam.
19/07/2019	Knapman, Kenneth - TWC MECHANIC	9.00	BUCKET: Repairs to apron.
22/07/2019	Knapman, Kenneth - TWC MECHANIC	5.50	BUCKET: Repair to walking beam & deliver to machinist for machining. Collect steel & begin reman. o
22/07/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Assemble eng. bay guards etc.
23/07/2019	Knapman, Kenneth - TWC MECHANIC	8.50	Weld repair bonnet mount, support bracket. Cut plates for cross leveller box & manufacture componen
24/07/2019	Dawson, Dale - TWC Mechanic	1.00	Assist fitting bucket onto machine.
24/07/2019	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Continue repairs to walking beam & cross leveller.
25/07/2019	Knapman, Kenneth - TWC MECHANIC	9.00	BUCKET: Continue with repairs/reman of walking beam & cross leveller.
26/07/2019	Dawson, Dale - TWC Mechanic	2.00	BUCKET: Fit rams, walking beam & rear tyres.
26/07/2019	Knapman, Kenneth - TWC MECHANIC	5.00	BUCKET: Continue with repairs/reman of walking beam & cross leveller.
26/07/2019	Wilde, David - TWC WORKSHOP MANAGER	4.00	BUCKET: Assemble bucket tilt bar & wheels & apron.
29/07/2019	Dawson, Dale - TWC Mechanic	5.00	Install support bar from GPS pole frame to pull bar. Connect GPS/laser harnesses. Finish fitting ba
29/07/2019	Knapman, Kenneth - TWC MECHANIC	6.00	BUCKET: Continue with manufacture of cross leveller box.
30/07/2019	Knapman, Kenneth - TWC MECHANIC	6.00	BUCKET: Continue with manufacture of cross leveller box.
30/07/2019	Dawson, Dale - TWC Mechanic	3.50	BUCKET: Strip down & reseal lift ram. Assemble rocker box & walking beam dual tilt system.
07/08/2019	Dawson, Dale - TWC Mechanic	2.00	BUCKET: Fit clamps, collect pins for walking beam etc. Get spare hyd. cyling from storage & other p
08/08/2019	Dawson, Dale - TWC Mechanic	7.00	Remove battery covers to charge flat batteries. Instal dual tilt assy, measure up hud. hoses & fit
19/08/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Inspect bucket for hyd. line mount protection.

21/08/2019	Knapman, Kenneth - TWC MECHANIC	9.50	BUCKET: Finish manufacture of guards for hyd. hoses on cross leveller. Begin manufacture of hungry
22/08/2019	Knapman, Kenneth - TWC MECHANIC	5.00	BUCKET: Manufacture & fit hungry boards.
23/08/2019	Knapman, Kenneth - TWC MECHANIC	8.00	BUCKET: Manufacture & fit hungry boards.
28/08/2019	Dawson, Dale - TWC Mechanic	1.50	BUCKET: Prep & paint covers for hose lines.
29/08/2019	Dawson, Dale - TWC Mechanic	1.50	Fit new hydraulic hose guards, tap out threads in frame of laser bucket for mounting bolts.
09/09/2019	Dawson, Dale - TWC Mechanic	2.50	Remove batteries & have load tested - tested O/K. Refit & recharge batteries (flat)
09/09/2019	Knapman, Kenneth - TWC MECHANIC	3.50	BUCKET: Manufacture of walking beam.
10/09/2019	Knapman, Kenneth - TWC MECHANIC	9.50	BUCKET: Manufacture of walking beam.
11/09/2019	Knapman, Kenneth - TWC MECHANIC	9.50	BUCKET: Continue manufacture of L/H walking beam & fitting of hungry boards.
12/09/2019	Knapman, Kenneth - TWC MECHANIC	9.50	BUCKET: Continue with manufacture of bucket extensions.
12/09/2019	Dawson, Dale - TWC Mechanic	1.00	BUCKET: Repair oil leak & fit guards.
13/09/2019	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Continue with manufacture/welding of bucket extensions. Weld front ripper/side cutter mounts
16/09/2019	Dawson, Dale - TWC Mechanic	1.50	BUCKET: prep new pivot wheel bar for install/painting
17/09/2019	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Finish bucket repairs/refurbishment etc.
17/09/2019	Dawson, Dale - TWC Mechanic	8.00	BUCKET: Remove L/H frame assy & paint, fit new tilt ram assy, wheels & hubs. Paint new hungry board
18/09/2019	Knapman, Kenneth - TWC MECHANIC	3.00	Chk & adjust tyre pressures on tractor & bucket. Chk & top up bucket wheel hubs as needed.
20/09/2019	Knapman, Kenneth - TWC MECHANIC	2.50	Gouge out bearings on old walking beam. Gouge & press apart bucket walking beam axles & deliver to
24/09/2019	Dawson, Dale - TWC Mechanic	0.50	R & R door strut, take SOS, fit stinger to side of bucket.
26/09/2019	Dawson, Dale - TWC Mechanic	1.75	R & R flat tyre on laser bucket & fit new ripper boots. Deliver tyre to tyre shop on return to work
27/09/2019	Knapman, Kenneth - TWC MECHANIC	1.50	BUCKET: replace wheel hub. Repair both apron rollers, grease points.
11/10/2019	Dawson, Dale - TWC Mechanic	3.00	BUCKET: Repair failed grease points, fit cutting edge, repair rippers.
11/10/2019	Knapman, Kenneth - TWC MECHANIC	0.50	BUCKET: Obtain cutting edge & bolts for machine.
18/10/2019	Dawson, Dale - TWC Mechanic	3.00	Change engine oil, carry out repairs to bucket, tighten rippers, grease etc.
04/11/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	9,170HRS: R & R fuel transfer pump, Repair bonnet catch & steering pin. Replace bucket ripper.
13/11/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	Clean out radiators & coolers. Replace fuel filters. Chk fault codes. Chk over.
14/11/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	9,209HRS: Replace ripper bar & bolt in ball. Chk & tighten hyd. pipes. Lower draw bar.
15/11/2019	Dawson, Dale - TWC Mechanic	1.00	Test boost pressure on engine - only producing 3PSI of boost.
15/11/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	9,211HRS: Replace ripper bar & chk low level oil pressure fault.

18/11/2019	Dawson, Dale - TWC Mechanic	2.00	BUCKET:: R & R stub axle, test operation.
20/11/2019	Dawson, Dale - TWC Mechanic	2.00	9,250HRS: 250hr service. Inspect turbo for wear on impellar side of wheel.
28/11/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & remove hitch relays & order parts.
30/11/2019	Dawson, Dale - TWC Mechanic	5.50	Strip down engine bay, remove bonnet/guards, remove tappet cover. Investigate fuel system fault - f
02/12/2019	Dawson, Dale - TWC Mechanic	2.50	Fit air cleaner, frame box assy, fill with coolant & move machine to welding bay.
02/12/2019	Knapman, Kenneth - TWC MECHANIC	9.50	BUCKET: Weld repairs to bowl.
03/12/2019	Dawson, Dale - TWC Mechanic	9.50	R & R seals on all injectors. Assist Kenway & Clark technician with engine valve set/tune up. Refit
06/12/2019	Dawson, Dale - TWC Mechanic	3.50	R & R turbo on engine, test boost.
09/12/2019	Dawson, Dale - TWC Mechanic	3.00	Investigate a/c fault - found compressor faulty + condensor not big enough to cool system down in h
10/12/2019	Dawson, Dale - TWC Mechanic	3.00	9,302HRS: R & R a/c compressor, vac down system & re-charge. R & R Reveiver/Dryer
10/12/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace 2 tyres.
08/01/2020	Dawson, Dale - TWC Mechanic	0.50	Investigate hitch fault - adjust sensors etc.
21/01/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Remove seat assy to access & clean a/c evaporator. Remove broken stud. Weld on tabs to signs. Gouge
21/01/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	9,386HRS: Chk a/c operation & order parts. General chk over of machine.
22/01/2020	Knapman, Kenneth - TWC MECHANIC	9.00	Weld repairs to bucket hitch and sundry other cracks.
23/01/2020	Knapman, Kenneth - TWC MECHANIC	4.00	Repair and paint bucket frame, locate & repair rotating beacon faults.
23/01/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & clean wiring to cushion sensors.
30/01/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk cushion sensor & pick up parts.
05/02/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Repair rotating beacon.
06/02/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Fit cushion hitch sensor.
06/02/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Check and replace hitch sensor and check over
10/02/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	1750hrs Service
15/02/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	1,765HRS: Calibrate trans solenoids. Chk air induction - Test run.
05/03/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over for rego & grease.
13/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	2,014HRS: Remove & replace air cleaner, dusut ejector pipe & hoses.
20/04/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & change eng. oil.
29/04/2020	Wilde, David - TWC WORKSHOP MANAGER	2.50	1,151HRS: Repair light wiring & rear inner wheel loc.
19/06/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Change eng. oil & chk over.
24/06/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R tip cylinder & test run.
25/06/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Dismantle & ispect tip cylinder - have barrel replaced.

26/06/2020	Wilde, David - TWC WORKSHOP MANAGER		2.00	2,193HRS: R & R fan hyd. hose. Chk & repair hitch relay.
01/07/2020	Wilde, David - TWC WORKSHOP MANAGER		1.00	R & R ripper bar.
03/07/2020	Wilde, David - TWC WORKSHOP MANAGER		1.00	Replace hitch relay & test run. Calibrate trans. solenoids.
06/07/2020	Wilde, David - TWC WORKSHOP MANAGER		1.00	Prestart/FGR.
07/07/2020	Knapman, Kenneth - TWC MECHANIC		2.00	Reman. co0rner tips for bucket.
08/07/2020	Wilde, David - TWC WORKSHOP MANAGER		1.50	2,229HRS: Change eng. oil & chk over.
03/08/2020	Knapman, Kenneth - TWC MECHANIC		1.00	Assemble tilt ram.
27/08/2020	Wilde, David - TWC WORKSHOP MANAGER		2.00	Disconnect bucket from tractor & partial wash down.
28/08/2020	Knapman, Kenneth - TWC MECHANIC		2.00	Assist access fuel injectors. Remove air filter assay etc. Fit test tooling.
28/08/2020	Wilde, David - TWC WORKSHOP MANAGER		4.00	Remove bonnet & engine covers. Inspect injectors for leaks.
31/08/2020	Knapman, Kenneth - TWC MECHANIC		4.00	Remove rocker assy & injectors, swap over injectors to test for fault.
31/08/2020	Wilde, David - TWC WORKSHOP MANAGER		3.00	Repair eng. fuel system, price parts.
18/09/2020	Knapman, Kenneth - TWC MECHANIC		3.00	Clean injector seats & fit No.6 injector. Purchase cleaning tools.
18/09/2020	Wilde, David - TWC WORKSHOP MANAGER		1.00	Assist with engine repairs.
21/09/2020	Knapman, Kenneth - TWC MECHANIC		7.50	Remove cooling & air - air systems
21/09/2020	Wilde, David - TWC WORKSHOP MANAGER		3.50	Fit new injectors & pressure test. Change eng. oil. remove radiator & coolers. price parts.
22/09/2020	Knapman, Kenneth - TWC MECHANIC		7.50	Remove fan & fan motor from radiator assy. Clean radiator & air cooler. replace serpentine pulley b
22/09/2020	Wilde, David - TWC WORKSHOP MANAGER		2.50	Assist with repairs to coolong system. price & order parts.
23/09/2020	Knapman, Kenneth - TWC MECHANIC		7.50	Clean radiator. Fit water pump & fan cowling & drive motor. Connect hydraulic lines.
23/09/2020	Wilde, David - TWC WORKSHOP MANAGER		4.00	Assist with repairs to coolingsystem.
24/09/2020	Knapman, Kenneth - TWC MECHANIC		5.00	Replace radiator etc. Disassemble fan motor. Drain overflow bottle.
24/09/2020	Wilde, David - TWC WORKSHOP MANAGER		2.00	Reassemble radiator & coolers to machine.
25/09/2020	Knapman, Kenneth - TWC MECHANIC		9.00	Weld/straighten bonnet mounts. Fit bonnet & guards, fit air filters & header tank. Connect lines &
25/09/2020	Wilde, David - TWC WORKSHOP MANAGER		7.25	Assemble machine & test run.
28/09/2020	Wilde, David - TWC WORKSHOP MANAGER		7.00	2,286HRS: Prestart/FGR. Repalce lift & tip cylinders & bushes. Load & secure onto float.
28/09/2020	Knapman, Kenneth - TWC MECHANIC		8.50	BUCKET: Weld harness protector to to laser frame. Replace L/H lift ram top bush. Fit chain to wheel
07/10/2020	Knapman, Kenneth - TWC MECHANIC		1.00	Repair bucket tilt cylinder.
			942.00	
			942.00	