

Date	Name	Duration	Notes
24/06/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	Make up cables & fir isolation switches/Remove & replace handbrake switch,replace horn wiring, wash
26/06/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	Make up cables & fir isolation switches/Remove & replace handbrake switch,replace horn wiring, wash
28/06/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	Make up cables & fir isolation switches/Remove & replace handbrake switch,replace horn wiring, wash
30/06/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	Make up cables & fir isolation switches/Remove & replace handbrake switch,replace horn wiring, wash
01/07/2010	Wilde, David - TWC WORKSHOP MANAGER	2.00	Check & repair light wiring/Replace flashing light bulb,shovel mud from machine & wash down.
02/07/2010	Wilde, David - TWC WORKSHOP MANAGER	4.50	Check & repair light wiring/Replace flashing light bulb,shovel mud from machine & wash down.
09/07/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	Check & repair hitch wiring, test run./test for misfire in eng.
13/07/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	Check & repair hitch wiring, test run./test for misfire in eng.
20/07/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	Check oil leak at control valve & replace batteries
05/08/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	4403 hrs - check oil leak & replace seal/ Remove blown tyre
09/08/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	4403 hrs - check oil leak & replace seal/ Remove blown tyre
02/09/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair to Hyd. over ph./4459 hrs, replace leaking seals on control valve.(Q988C)/Check bucket for I
03/09/2010	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repair to Hyd. over ph./4459 hrs, replace leaking seals on control valve.(Q988C)/Check bucket for I
06/09/2010	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repair to Hyd. over ph./4459 hrs, replace leaking seals on control valve.(Q988C)/Check bucket for I
17/09/2010	Wilde, David - TWC WORKSHOP MANAGER	1.50	4487hrs: 500 hr service, check for coolant leaks
20/09/2010	Wilde, David - TWC WORKSHOP MANAGER	1.00	remove and replace O rings on aftercooler lines,tighten bonnet cable, top up coolant , test run.
20/01/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Remove hubs from bucket & send to T'worth/ Travel to T'worth, replace apron in bucket, chk eng. noi
25/01/2011	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove hubs from bucket & send to T'worth/ Travel to T'worth, replace apron in bucket, chk eng. noi
07/03/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	14750hrs: 250hr service, refit starter motor & test run, chk electrical connectors.
29/03/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	R & R laser cables & refit
01/04/2011	Wilde, David - TWC WORKSHOP MANAGER	6.50	Wash down, check & adjust valves, remove exhaust manifold for repairs./ Refit manifold & test run.
02/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Wash down, check & adjust valves, remove exhaust manifold for repairs./ Refit manifold & test run.
18/04/2011	Wilde, David - TWC WORKSHOP MANAGER	1.50	Remove engine
19/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove engine
29/04/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Clean battery leads & refit batteries, chk charging system, chk & adjust valves./wash down parts/Re
30/04/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean battery leads & refit batteries, chk charging system, chk & adjust valves./wash down parts/Re
02/05/2011	Wilde, David - TWC WORKSHOP MANAGER	9.50	Clean battery leads & refit batteries, chk charging system, chk & adjust valves./wash down parts/Re
03/05/2011	Knapman, Kenneth - TWC MECHANIC	6.50	Bowl repairs & assist fit final drive to machine, tension whell nuts
03/05/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	Clean battery leads & refit batteries, chk charging system, chk & adjust valves./wash down parts/Re
04/05/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Clean battery leads & refit batteries, chk charging system, chk & adjust valves./wash down parts/Re
05/05/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R 4 brake pads/14804hrs - 250hr service, replace A/c filter, remove articulation bar & replace
06/05/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R 4 brake pads/14804hrs - 250hr service, replace A/c filter, remove articulation bar & replace
07/05/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	R & R 4 brake pads/14804hrs - 250hr service, replace A/c filter, remove articulation bar & replace
08/05/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R 4 brake pads/14804hrs - 250hr service, replace A/c filter, remove articulation bar & replace
12/05/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Remove alternator from 256 to put in 250
12/05/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Load parts, chk & replace laser cable, R & R alternator, cap off hoses.
27/05/2011	Knapman, Kenneth - TWC MECHANIC	1.50	Remake & hardsurface corner tips./Locate alarm fault in electrical system, chk cutting edges for lo

01/06/2011	Knapman, Kenneth - TWC MECHANIC	2.50	Remake & hardsurface corner tips./Locate alarm fault in electrical system, chk cutting edges for lo
02/06/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Arrange parts for dash switch for bucket control & cutting edges.
16/07/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Clean up engine parts/Clean & assemble engine
18/07/2011	Wilde, David - TWC WORKSHOP MANAGER	3.50	Clean up engine parts/Clean & assemble engine
20/07/2011	Knapman, Kenneth - TWC MECHANIC	4.00	Repairs/ engine rebuild
20/07/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Clean up engine parts/Clean & assemble engine
27/07/2011	Knapman, Kenneth - TWC MECHANIC	5.00	Commence rebuild of engine & rim reconditioning for bucket.
28/07/2011	Knapman, Kenneth - TWC MECHANIC	8.00	Fit rear eng. oil seal & engine mount, install cylinder liners./Source parts/Collect parts
01/08/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Fit rear eng. oil seal & engine mount, install cylinder liners./Source parts/Collect parts
01/08/2011	Wilde, David - TWC WORKSHOP MANAGER	6.00	Clean up parts & assemble engine
03/08/2011	Knapman, Kenneth - TWC MECHANIC	0.50	Fit rear eng. oil seal & engine mount, install cylinder liners./Source parts/Collect parts
06/08/2011	Knapman, Kenneth - TWC MECHANIC	7.50	Continue engine rebuild
08/08/2011	Knapman, Kenneth - TWC MECHANIC	5.00	Continue engine rebuild
08/08/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Clean parts & contine engine assembly/dismantle & clean oil cooler
09/08/2011	Knapman, Kenneth - TWC MECHANIC	7.00	Continue engine rebuild
09/08/2011	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean parts & contine engine assembly/dismantle & clean oil cooler
10/08/2011	Knapman, Kenneth - TWC MECHANIC	5.00	Continue engine rebuild
11/08/2011	Knapman, Kenneth - TWC MECHANIC	3.50	Continue engine rebuild
11/08/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Continue engine rebuild
12/08/2011	Wilde, David - TWC WORKSHOP MANAGER	5.50	Continue engine rebuild
13/08/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Continue engine rebuild
15/08/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Continue engine rebuild
15/08/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Part 1000 hr service/15,000 hrs service, R & R lift cylinder hose.
16/08/2011	Wilde, David - TWC WORKSHOP MANAGER	3.00	Part 1000 hr service/15,000 hrs service, R & R lift cylinder hose.
23/08/2011	Knapman, Kenneth - TWC MECHANIC	2.00	Resume engine assembly
24/08/2011	Knapman, Kenneth - TWC MECHANIC	8.50	Resume engine assembly
25/08/2011	Knapman, Kenneth - TWC MECHANIC	9.00	Continue reassembly of engine
29/08/2011	Knapman, Kenneth - TWC MECHANIC	8.50	Continue reassembly of engine
01/09/2011	Knapman, Kenneth - TWC MECHANIC	1.50	Fit engine to tractor
01/09/2011	Bell, Daniel - TWC Manager	1.00	Fit engine.
16/09/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair to driveshaft.
19/09/2011	Knapman, Kenneth - TWC MECHANIC	5.00	Remove driveline & have bearing pressed off in Dalby, return & commence reassembly./Complete drivel
20/09/2011	Knapman, Kenneth - TWC MECHANIC	1.00	Remove driveline & have bearing pressed off in Dalby, return & commence reassembly./Complete drivel
03/11/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to rear diffand draw bar (5181hrs)
05/11/2011	Bell, Daniel - TWC Manager	1.00	Load up tooling etc.
07/11/2011	Wilde, David - TWC WORKSHOP MANAGER	8.50	Repairs to rear diffand draw bar (5181hrs)
08/11/2011	Wilde, David - TWC WORKSHOP MANAGER	4.50	Repairs to rear diffand draw bar (5181hrs)
11/11/2011	Griffin, Reece - Plant Mechanic	5.50	Strip down old diff for parts.

18/11/2011	Bell, Daniel - TWC Manager	4.50	Remove bucket wheel hubs from spare bucket & take to Gundy.
21/11/2011	Wilde, David - TWC WORKSHOP MANAGER	5.00	250hrs service, chk wiring to GPS, R & R oil cooler./Dismantle 3 hubs & have repaired
23/11/2011	Griffin, Reece - Plant Mechanic	2.50	Strip down wheel hubs from laser bucket.
23/11/2011	Wilde, David - TWC WORKSHOP MANAGER	2.50	250hrs service, chk wiring to GPS, R & R oil cooler./Dismantle 3 hubs & have repaired
24/11/2011	Griffin, Reece - Plant Mechanic	2.00	Rebuild laser bucket hub.
30/11/2011	Griffin, Reece - Plant Mechanic	4.00	Rebuild laser bucket hub.
07/12/2011	Wilde, David - TWC WORKSHOP MANAGER	4.00	Dismantle, inspect & reassemble final drives.
15/12/2011	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk for repairs to rear tyres
02/03/2012	Wilde, David - TWC WORKSHOP MANAGER	4.50	Travel to jobsite, 5303hrs: R & R bucket wheel, chk for cracks & hub leaks.
02/03/2012	Bell, Daniel - TWC Manager	7.00	Carry out 250hr service. travel from Dalby to Wongoan & return.
20/05/2012	Bell, Daniel - TWC Manager	5.00	Escort float to workshop check over machine repairs.
21/05/2012	Bell, Daniel - TWC Manager	5.00	Escort float to workshop check over machine repairs.
24/05/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Fit new alternator belts, replace various hoses.
28/05/2012	Knapman, Kenneth - TWC MECHANIC	2.50	Fit new alternator belts, replace various hoses.
30/05/2012	Knapman, Kenneth - TWC MECHANIC	2.00	replace crankshaft alternator drive pulley fill with coolant, replace bonnet stay.
30/05/2012	Wilde, David - TWC WORKSHOP MANAGER	3.50	5363hrs. Replace alternator pulleys and belts, bonet stops, radiator clamps. Check brake pads . Tra
31/05/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace bucket hubs x 2. 5363hrs
04/06/2012	Wilde, David - TWC WORKSHOP MANAGER	5.50	Replace bucket hubs x 2. 5363hrs
05/06/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace bucket hubs x 2. 5363hrs
06/06/2012	Knapman, Kenneth - TWC MECHANIC	6.00	Rebuild bucket hubs
07/06/2012	Knapman, Kenneth - TWC MECHANIC	3.50	Remove bucket hubs & replace 2, disassemble remaining hubs & repair 1./ rerace hubs, travel to Bee
07/06/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R 4 bucket hubs.
08/06/2012	Knapman, Kenneth - TWC MECHANIC	5.00	Remove bucket hubs & replace 2, disassemble remaining hubs & repair 1./ rerace hubs, travel to Bee
15/06/2012	Griffin, Reece - Plant Mechanic	2.00	Repairs to hubs?
15/06/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Dismantle & replace bearings & reassemble bucket hubs./ Travel to Beela, refit clamps to bucket pip
18/06/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Dismantle & replace bearings & reassemble bucket hubs./ Travel to Beela, refit clamps to bucket pip
19/06/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Travel to Beela, remove cab door & return to w'shop./ Weld on door hinge, travel to jobsite, fit do
19/06/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Dismantle & replace bearings & reassemble bucket hubs./ Travel to Beela, refit clamps to bucket pip
20/06/2012	Knapman, Kenneth - TWC MECHANIC	1.50	Travel to Beela, remove cab door & return to w'shop./ Weld on door hinge, travel to jobsite, fit do
20/06/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Dismantle & replace bearings & reassemble bucket hubs./ Travel to Beela, refit clamps to bucket pip
26/06/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	5385hrs: Travel to jobsite (Glen Prairie) chk & repair laser wiring, return to w'shop.
06/08/2012	Wilde, David - TWC WORKSHOP MANAGER	1.00	Pump up tyre & return to w'shop.
20/08/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Disassemble seat & order parts./ Remove seat from machine./ Repair seat, travel to jobsite (Ellemat
21/08/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Disassemble seat & order parts./ Remove seat from machine./ Repair seat, travel to jobsite (Ellemat
22/08/2012	Knapman, Kenneth - TWC MECHANIC	5.50	Disassemble seat & order parts./ Remove seat from machine./ Repair seat, travel to jobsite (Ellemat
29/08/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	Travel to/from jobsite (Tarcoola), remove & replace tyne & bucket hub.
03/09/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Travel to jobsite (Tarcoola), repair laser cable & return to w'shop./ 5503hrs: Travel to tarcoola,
05/09/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Travel to jobsite (Tarcoola), repair laser cable & return to w'shop./ 5503hrs: Travel to tarcoola,

## 250 - Service History

07/09/2012	Dawson, Dale - TWC Mechanic	3.50	Load service gear onto service truck & travel to jobsite, carry out 250hr service, change tyre on l
09/09/2012	Bell, Daniel - TWC Manager	2.50	Travel to/from Tarcoola & replace blown bucket tyre.
10/09/2012	Wilde, David - TWC WORKSHOP MANAGER	3.00	Travel to/from jobsite x 2, Replace ripper bar & boot, change laser transmitter.  6558: Travel to j
11/09/2012	Wilde, David - TWC WORKSHOP MANAGER	2.00	Travel to/from jobsite x 2, Replace ripper bar & boot, change laser transmitter.  6558: Travel to j
12/09/2012	Wilde, David - TWC WORKSHOP MANAGER	2.50	Travel to/from jobsite x 2, Replace ripper bar & boot, change laser transmitter.  6558: Travel to j
13/09/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Replace alternator & roll pin of bonnet pivot.  Weld repairs to broken tynes, assist with L/H hub a
13/09/2012	Wilde, David - TWC WORKSHOP MANAGER	1.50	Clean down bucket & replace hyd. hose.  Wash off control valve, remove, reseal & refit to machine.
14/09/2012	Wilde, David - TWC WORKSHOP MANAGER	6.00	Clean down bucket & replace hyd. hose.  Wash off control valve, remove, reseal & refit to machine.
15/09/2012	Wilde, David - TWC WORKSHOP MANAGER	4.50	Clean down bucket & replace hyd. hose.  Wash off control valve, remove, reseal & refit to machine.
17/09/2012	Knapman, Kenneth - TWC MECHANIC	8.50	Replace alternator & roll pin of bonnet pivot.  Weld repairs to broken tynes, assist with L/H hub a
17/09/2012	Griffin, Reece - Plant Mechanic	4.00	Reseal L/H front hub.  Drained trans. & cleaned filter, drained final drives & diffs & refilled, co
17/09/2012	Wilde, David - TWC WORKSHOP MANAGER	7.00	Clean down bucket & replace hyd. hose.  Wash off control valve, remove, reseal & refit to machine.
18/09/2012	Griffin, Reece - Plant Mechanic	5.00	Reseal L/H front hub.  Drained trans. & cleaned filter, drained final drives & diffs & refilled, co
18/09/2012	Knapman, Kenneth - TWC MECHANIC	1.00	Replace alternator & roll pin of bonnet pivot.  Weld repairs to broken tynes, assist with L/H hub a
19/09/2012	Griffin, Reece - Plant Mechanic	4.50	Reseal L/H front hub.  Drained trans. & cleaned filter, drained final drives & diffs & refilled, co
19/09/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Replace alternator & roll pin of bonnet pivot.  Weld repairs to broken tynes, assist with L/H hub a
27/09/2012	Knapman, Kenneth - TWC MECHANIC	2.00	Fit drive shaft guards & remake toggle switch mount & replace seat.   Collect tyre for bucket.
03/10/2012	Knapman, Kenneth - TWC MECHANIC	0.50	Fit drive shaft guards & remake toggle switch mount & replace seat.   Collect tyre for bucket.
18/12/2012	Knapman, Kenneth - TWC MECHANIC	5.00	Travel to jobsite (Ellematta), chk machine & escort to new jobsite (Abilene- Canada)
09/01/2013	Knapman, Kenneth - TWC MECHANIC	4.50	5670hrs: Travel to/from jobsite, chk laser & load equipment & laser trailer, chk over tractor, loca
11/01/2013	Knapman, Kenneth - TWC MECHANIC	7.00	Remove apron cylinder & battery from 237, travel to jobsite, replace apron stub & bearing, replace
18/01/2013	Knapman, Kenneth - TWC MECHANIC	3.50	Travel to jobsite, inspect articulation, order parts, return to w'shop.
21/03/2013	Knapman, Kenneth - TWC MECHANIC	5.00	Disconnect from bucket, & remove upper articulation bar, grease bucket, replace grease nipples./ Re
22/03/2013	Knapman, Kenneth - TWC MECHANIC	9.00	Disconnect from bucket, & remove upper articulation bar, grease bucket, replace grease nipples./ Re
25/03/2013	Knapman, Kenneth - TWC MECHANIC	1.50	Disconnect from bucket, & remove upper articulation bar, grease bucket, replace grease nipples./ Re
02/05/2013	Wilde, David - TWC WORKSHOP MANAGER	3.50	Travel to Auscott, test receiver cable & replace receiver, return to w'shop.
06/05/2013	Griffin, Reece - Plant Mechanic	1.00	5750HRS: Complete 250hr service & general chk of machine.
06/05/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase filters for service.
10/05/2013	Griffin, Reece - Plant Mechanic	3.00	9,938HRS: 2,000hr service.
10/05/2013	Dawson, Dale - TWC Mechanic	3.00	5938HRS: Complete 2,000hr service./ Organise parts, locate start fault - starter U/S
13/05/2013	Dawson, Dale - TWC Mechanic	1.00	5938HRS: Complete 2,000hr service./ Organise parts, locate start fault - starter U/S
31/05/2013	Knapman, Kenneth - TWC MECHANIC	1.50	5960HRS: Replace starter motor & seat./ Collect parts.
05/06/2013	Knapman, Kenneth - TWC MECHANIC	0.50	5960HRS: Replace starter motor & seat./ Collect parts.
06/06/2013	Dawson, Dale - TWC Mechanic	2.00	Install seat in cab, repair wiring for seat operation.
06/06/2013	Griffin, Reece - Plant Mechanic	2.00	Install seat into cab & repair seat wiring./ Remove 24V seat motor & install 12V motor.
07/06/2013	Griffin, Reece - Plant Mechanic	1.00	Install seat into cab & repair seat wiring./ Remove 24V seat motor & install 12V motor.
07/06/2013	Knapman, Kenneth - TWC MECHANIC	0.50	Collect parts.
19/06/2013	Dawson, Dale - TWC Mechanic	6.00	Prepare & load gear for repairs 1.5hrs, R & R l/h rear final drive seal, R & R cab seat.

19/06/2013	Wilde, David - TWC WORKSHOP MANAGER	6.50	R & R l/h rear wheel seal, fir cab seat.
06/08/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	Tighten water pump belt, replace corner tips, repair decelerator & return to w'shop.
09/08/2013	Dawson, Dale - TWC Mechanic	2.00	R & R hyd. cylinders on laser bucket, start to reassemble final drive assy.
13/08/2013	Wilde, David - TWC WORKSHOP MANAGER	3.00	16,053HRS: Travel to Humphries jobsite. Repair apron stubs & bolts.
20/08/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit ripper ram & test run. Return to w'shop.
01/11/2013	Dawson, Dale - TWC Mechanic	2.00	6054HRS: Travel to jobsite, chk over machine & a/c performance, return to w'shop.
06/11/2013	Knapman, Kenneth - TWC MECHANIC	2.50	6063HRS: Collect parts & travel to jobsite, rectify fault, replace bolt in cross leveller retainer,
08/11/2013	Dawson, Dale - TWC Mechanic	1.00	Travel to jobsite (Norwood); 6084HRS: Inspect & repair wiring fault - apron failing to raise & lowe
08/11/2013	Griffin, Reece - Plant Mechanic	2.50	Travel to jobsite (Norwood); Assist repair fault with apron door, replace hyd. hose on laser bucket
28/11/2013	Griffin, Reece - Plant Mechanic	0.50	6240HRS: Blow out air filters & radiator.
30/11/2013	Wilde, David - TWC WORKSHOP MANAGER	2.50	6251HRS: Chk & adjust tyre pressures, chk over bucket.
03/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.00	Change Flat Tyre
03/12/2013	Wilde, David - TWC WORKSHOP MANAGER	1.50	Escort Tractor to Laurella
03/12/2013	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove and replace apron switch
16/12/2013	Dawson, Dale - TWC Mechanic	1.50	6750HRS: Complete 250hr service.
16/12/2013	Griffin, Reece - Plant Mechanic	1.50	6750HRS: Complete 250hr service.
08/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Clean down.
09/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk batteries & jumpstart./ 6433HRS: Tap out holes & replace nipples. Chk over./ Repair decelerator
10/01/2014	Dawson, Dale - TWC Mechanic	2.75	6421HRS: Locate fault in a/c - Fan motors U/S & replaced.
11/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk batteries & jumpstart./ 6433HRS: Tap out holes & replace nipples. Chk over./ Repair decelerator
13/01/2014	Knapman, Kenneth - TWC MECHANIC	4.00	Bucket: Gouge out & replace bowl cylinder lug mount.
15/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk batteries & jumpstart./ 6433HRS: Tap out holes & replace nipples. Chk over./ Repair decelerator
16/01/2014	Dawson, Dale - TWC Mechanic	1.00	6480HRS: Fit new batteries & test charging rate, clean radiator./ 6500HRS: Complete 500hr service.
16/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove battery & leads.
17/01/2014	Dawson, Dale - TWC Mechanic	1.75	6480HRS: Fit new batteries & test charging rate, clean radiator./ 6500HRS: Complete 500hr service.
21/01/2014	Griffin, Reece - Plant Mechanic	0.50	6527HRS: Chk all tyre pressures
31/01/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over machine./ 6599HRS: Replace bucket corner tip./ Chk laser fault & replace speed control.
01/02/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk over machine./ 6599HRS: Replace bucket corner tip./ Chk laser fault & replace speed control.
05/02/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk over machine./ 6599HRS: Replace bucket corner tip./ Chk laser fault & replace speed control.
06/02/2014	Dawson, Dale - TWC Mechanic	1.00	Measure laser system & discuss with Aaron.
06/02/2014	Griffin, Reece - Plant Mechanic	1.50	Reseal spare ram.
06/02/2014	Griffin, Reece - Plant Mechanic	0.50	Measure up laser harness length.
11/02/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Wash down machine./ Repairs to accelerator.
12/02/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Wash down machine./ Repairs to accelerator.
13/02/2014	Dawson, Dale - TWC Mechanic	2.50	Remove laser harness assy for installation of GPS.
13/02/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove old cables & fit GPS cables./ Remove old cables & fit GPS cables Test run & make up cable./
14/02/2014	Dawson, Dale - TWC Mechanic	4.50	Install GPS system to unit.
14/02/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Adapt bracket to suit laser box.

14/02/2014	Wilde, David - TWC WORKSHOP MANAGER	8.50	Remove old cables & fit GPS cables./ Remove old cables & fit GPS cables Test run & make up cable./
15/02/2014	Wilde, David - TWC WORKSHOP MANAGER	8.00	Remove old cables & fit GPS cables./ Remove old cables & fit GPS cables Test run & make up cable./
27/02/2014	Griffin, Reece - Plant Mechanic	1.00	6748HRS: Carry out 250hr service.
14/03/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	6857HRS: R & R 2 fuel lines & blow out radiator & filters./ Adjust alternator belts & replace bucke
19/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	6857HRS: R & R 2 fuel lines & blow out radiator & filters./ Adjust alternator belts & replace bucke
20/03/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	6896HRS: Clean out air & cab filters./ Fit GPS cables & aerials.
21/03/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	6896HRS: Clean out air & cab filters./ Fit GPS cables & aerials.
28/03/2014	Dawson, Dale - TWC Mechanic	8.00	Measure machine brackets for mounting of GPS ECU. Cut, drill & mount bracket & mount ECU. Run & plu
28/03/2014	Griffin, Reece - Plant Mechanic	2.00	Mount AS400 on bucket. Attach chains to bucket tyres.
29/03/2014	Dawson, Dale - TWC Mechanic	0.50	Measure machine brackets for mounting of GPS ECU. Cut, drill & mount bracket & mount ECU. Run & plu
29/03/2014	Dawson, Dale - TWC Mechanic	1.00	Laser Bucket: Fit chains to tyres.
29/03/2014	Griffin, Reece - Plant Mechanic	1.00	Mount AS400 on bucket. Attach chains to bucket tyres.
01/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to decelerator.
05/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Connect GPS cables & test run./ Chk & pump up tyres./ Dig mus from bucket, chk & repair bucket elec
07/04/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Connect GPS cables & test run./ Chk & pump up tyres./ Dig mus from bucket, chk & repair bucket elec
09/04/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Connect GPS cables & test run./ Chk & pump up tyres./ Dig mus from bucket, chk & repair bucket elec
15/04/2014	Wilde, David - TWC WORKSHOP MANAGER	4.00	7024HRS: Repairs to laser & GPS system./ 7000Hrs service.
16/04/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	7024HRS: Repairs to laser & GPS system./ 7000Hrs service.
23/04/2014	Dawson, Dale - TWC Mechanic	4.00	Remove rear left tyres from tractor for repair & refit. Set up GPS, calibrate sensors & locate powe
08/05/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	7125HRS: Dig mud from bucket. Replace valve coil & calibrate valves./ R & R apron ram./ Dig mud fro
10/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	7125HRS: Dig mud from bucket. Replace valve coil & calibrate valves./ R & R apron ram./ Dig mud fro
11/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	7125HRS: Dig mud from bucket. Replace valve coil & calibrate valves./ R & R apron ram./ Dig mud fro
15/05/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R broken exhaust bend.
19/05/2014	Knapman, Kenneth - TWC MECHANIC	3.00	Make striker latch. measure dimensions of cross leveller box, obtain quotes for same (including com
25/05/2014	Dawson, Dale - TWC Mechanic	1.50	Locate running fault - machine shutdown in middle of work area & would not start - Found no fuel su
02/07/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Source & order parts
02/07/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	Wash down & chk over.
03/07/2014	Dawson, Dale - TWC Mechanic	3.00	Remove HMU from machine, clean, reseal & refit./ Disconnect bucket, remove guards, panels & split t
07/07/2014	Dawson, Dale - TWC Mechanic	7.00	Remove HMU from machine, clean, reseal & refit./ Disconnect bucket, remove guards, panels & split t
08/07/2014	Dawson, Dale - TWC Mechanic	8.00	Remove HMU from machine, clean, reseal & refit./ Disconnect bucket, remove guards, panels & split t
09/07/2014	Dawson, Dale - TWC Mechanic	7.50	Remove HMU from machine, clean, reseal & refit./ Disconnect bucket, remove guards, panels & split t
10/07/2014	Dawson, Dale - TWC Mechanic	2.50	Install new blinker housings (3) & fit new blinker flasher cam unit & test./ Attach laser bucket to
11/07/2014	Dawson, Dale - TWC Mechanic	2.00	Install new blinker housings (3) & fit new blinker flasher cam unit & test./ Attach laser bucket to
30/07/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Drill out broken stud.
31/07/2014	Knapman, Kenneth - TWC MECHANIC	7.50	BUCKET: Tap out thread for apron bar retainer pin bolt. Heat & straighten sidewing of bowl. Remove
01/08/2014	Knapman, Kenneth - TWC MECHANIC	5.50	BUCKET: Tap out thread for apron bar retainer pin bolt. Heat & straighten sidewing of bowl. Remove
11/08/2014	Knapman, Kenneth - TWC MECHANIC	6.00	Build up & straighten ripper tynes. Build up ripper tynes & replace locator pin.
12/08/2014	Knapman, Kenneth - TWC MECHANIC	3.00	Build up & straighten ripper tynes. Build up ripper tynes & replace locator pin.

13/08/2014	Wilde, David - TWC WORKSHOP MANAGER	3.50	Reassemble rippers to machines
13/08/2014	Knapman, Kenneth - TWC MECHANIC	5.50	Build up & straighten ripper tynes. Build up ripper tynes & replace locator pin.
14/08/2014	Knapman, Kenneth - TWC MECHANIC	5.00	Set ripper bars & time. Chk bucket wheel hubs & add lube. Remove & disassemble cross leveller cylin
14/08/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Assemble rippers & test run./ Repairs to apron pins.
18/08/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Set ripper bars & time. Chk bucket wheel hubs & add lube. Remove & disassemble cross leveller cylin
19/08/2014	Knapman, Kenneth - TWC MECHANIC	1.00	Set ripper bars & time. Chk bucket wheel hubs & add lube. Remove & disassemble cross leveller cylin
19/08/2014	Wilde, David - TWC WORKSHOP MANAGER	2.00	Assemble rippers & test run./ Repairs to apron pins.
20/10/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk laser system & get fire ext. tested.
22/10/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Fit tappet covers & move machine out of w'shop.
22/10/2014	Dawson, Dale - TWC Mechanic	0.75	Remove tappet covers & clean down engine ready for valve set.
06/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	7,149HRS: Chk over machine, tighten breather on tappet cover, repair throttle./ 7250HRS service. Ch
08/11/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	7,149HRS: Chk over machine, tighten breather on tappet cover, repair throttle./ 7250HRS service. Ch
12/11/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Deliver coolant to jobsite.
12/11/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	7,149HRS: Chk over machine, tighten breather on tappet cover, repair throttle./ 7250HRS service. Ch
15/11/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	R & R bonnet catch./ Chk trans oil leaks. R & R 2 hoses. Fit drive shaft & test run. Price parts./
17/11/2014	Knapman, Kenneth - TWC MECHANIC	5.00	Purchase seals, travel to jobsire, replace input shaft seal in transmission. Return to w'shop for c
17/11/2014	Wilde, David - TWC WORKSHOP MANAGER	4.50	R & R bonnet catch./ Chk trans oil leaks. R & R 2 hoses. Fit drive shaft & test run. Price parts./
18/11/2014	Knapman, Kenneth - TWC MECHANIC	3.50	Complete transmission removal & commence installation of transmission from #256
18/11/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R bonnet catch./ Chk trans oil leaks. R & R 2 hoses. Fit drive shaft & test run. Price parts./
19/11/2014	Knapman, Kenneth - TWC MECHANIC	9.00	Purchase seals, travel to jobsire, replace input shaft seal in transmission. Return to w'shop for c
19/11/2014	Wilde, David - TWC WORKSHOP MANAGER	3.00	R & R bonnet catch./ Chk trans oil leaks. R & R 2 hoses. Fit drive shaft & test run. Price parts./
20/11/2014	Knapman, Kenneth - TWC MECHANIC	8.50	Chk & top up trans oil, clean up blocks etc. R & R r/h side apron stub & roller.Move out of shed &
20/11/2014	Wilde, David - TWC WORKSHOP MANAGER	2.50	Reassemble trans. to machine. Clean up w'shop, replace hyd. pump hose./ Chk & repaircharging fault.
21/11/2014	Knapman, Kenneth - TWC MECHANIC	4.50	Chk & top up trans oil, clean up blocks etc. R & R r/h side apron stub & roller.Move out of shed &
22/11/2014	Knapman, Kenneth - TWC MECHANIC	8.50	Chk & top up trans oil, clean up blocks etc. R & R r/h side apron stub & roller.Move out of shed &
24/11/2014	Knapman, Kenneth - TWC MECHANIC	7.00	Chk & top up trans oil, clean up blocks etc. R & R r/h side apron stub & roller.Move out of shed &
24/11/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Reassemble trans. to machine. Clean up w'shop, replace hyd. pump hose./ Chk & repaircharging fault.
25/11/2014	Knapman, Kenneth - TWC MECHANIC	3.50	Chk & top up trans oil, clean up blocks etc. R & R r/h side apron stub & roller.Move out of shed &
26/11/2014	Knapman, Kenneth - TWC MECHANIC	6.50	Chk & top up trans oil, clean up blocks etc. R & R r/h side apron stub & roller.Move out of shed &
27/11/2014	Knapman, Kenneth - TWC MECHANIC	6.50	Assemble trans, set shaft end plays, fit seal rings & tension end hubs. Fit yokes & set end float s
27/11/2014	Knapman, Kenneth - TWC MECHANIC	1.50	Replace apron cylinder & top up hydraulics.
01/12/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Assemble trans, set shaft end plays, fit seal rings & tension end hubs. Fit yokes & set end float s
05/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to apron switch. R & R broken apron stub bolt.
06/12/2014	Knapman, Kenneth - TWC MECHANIC	0.50	Fit O rings to remaining plugs.
06/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace laser receiver./ 7,434HRS: R & R apron switch./ Replace alternator belts. Repair electrical
09/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace laser receiver./ 7,434HRS: R & R apron switch./ Replace alternator belts. Repair electrical
10/12/2014	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace laser receiver./ 7,434HRS: R & R apron switch./ Replace alternator belts. Repair electrical
12/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.75	Replace alternator belts./ 7,454Hrs: Blow out radiators

15/12/2014	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace alternator belts./ 7,454Hrs: Blow out radiators
09/01/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	LASER BUCKET: R & R flat tyre.
12/01/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	7,552HRS: R & R exhaust elbow & clamp.
16/01/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & clean laser cable connectors.
03/02/2015	Knapman, Kenneth - TWC MECHANIC	1.00	7,688HRS: Chk batteries & alternator, remove earth lead, clean terminals & replace./ Inspect. Remov
04/02/2015	Dawson, Dale - TWC Mechanic	1.50	Assembly of tractor after diff had broken off mount bolts.
04/02/2015	Knapman, Kenneth - TWC MECHANIC	6.50	7,688HRS: Chk batteries & alternator, remove earth lead, clean terminals & replace./ Inspect. Remov
05/02/2015	Dawson, Dale - TWC Mechanic	4.00	Remove drive shaft from spare tractor for install in this machine. Assembly of 9380 after diff moun
09/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & repair broken wiring in joy stick control.
14/02/2015	Knapman, Kenneth - TWC MECHANIC	1.00	Replace centre bearing on drive shaft. /
16/02/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk wiring to taco. / Chk hyd. system.
17/02/2015	Dawson, Dale - TWC Mechanic	3.50	Tacho failure - test alternator & wiring back to cab - all ok. Found power going from cab harness t
17/02/2015	Knapman, Kenneth - TWC MECHANIC	0.50	LASER BUCKET: Weld in apron retainer pin.
18/02/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk wiring to taco. / Chk hyd. system.
23/02/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & top up rear diff oil.
27/02/2015	Knapman, Kenneth - TWC MECHANIC	1.00	take flat tyre to Jukes & Son for repair & return to jobsite & fit to 250 bucket..
04/03/2015	Knapman, Kenneth - TWC MECHANIC	1.50	Replace RHS bucket lift cylinder
05/03/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	Repairs to laser system. Chk over & blow out radiator.
09/03/2015	Knapman, Kenneth - TWC MECHANIC	0.50	BUCKET: Disassemble lift cylinder. Deliver shaft to McManus for remanufacture. Assist with bonnet i
10/03/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repairs to laser system. Chk over & blow out radiator.
11/03/2015	Knapman, Kenneth - TWC MECHANIC	1.00	BUCKET: Disassemble lift cylinder. Deliver shaft to McManus for remanufacture. Assist with bonnet i
11/03/2015	Knapman, Kenneth - TWC MECHANIC	0.50	Unload bonnet & set up for repairs.
12/03/2015	Knapman, Kenneth - TWC MECHANIC	4.50	Commence work on bonnet repairs - weld reapirs to splits in bonnet sides. / Continue bonnet repair
13/03/2015	Knapman, Kenneth - TWC MECHANIC	6.50	Commence work on bonnet repairs - weld reapirs to splits in bonnet sides. / Continue bonnet repair
17/03/2015	Dawson, Dale - TWC Mechanic	0.50	Inspect quick hitch fault - requires charging.
18/03/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove & get hitch acc repaired. Refit & test.
26/03/2015	Dawson, Dale - TWC Mechanic	0.50	Investigate satrtng fault - found starter relay U/S. / Inspect rippers - not working. R & R apron
27/03/2015	Dawson, Dale - TWC Mechanic	2.00	Investigate satrtng fault - found starter relay U/S. / Inspect rippers - not working. R & R apron
10/04/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Clean dirt from bucket & chk over. / Fit GPS & laser masts. Replace lift coil & repair wiring on b
11/04/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	Clean dirt from bucket & chk over. / Fit GPS & laser masts. Replace lift coil & repair wiring on b
15/04/2015	Dawson, Dale - TWC Mechanic	1.50	Remove broken parts from machine - tractor/bucket separation.
16/04/2015	Dawson, Dale - TWC Mechanic	4.50	Fit new laser bucket hitch to bucket. Fit hoses to tractor & join tractor to bucket. Fit new harnes
16/04/2015	Knapman, Kenneth - TWC MECHANIC	2.00	Gouge apart towball in hitch.
16/04/2015	Wilde, David - TWC WORKSHOP MANAGER	5.50	Repairs to ball hitch & wiring. Refit hoses. / 8,124HRS: Chk & repair wiring & refit cables. Test r
17/04/2015	Dawson, Dale - TWC Mechanic	4.00	Fit new laser bucket hitch to bucket. Fit hoses to tractor & join tractor to bucket. Fit new harnes
17/04/2015	Wilde, David - TWC WORKSHOP MANAGER	4.00	Repairs to ball hitch & wiring. Refit hoses. / 8,124HRS: Chk & repair wiring & refit cables. Test r
28/04/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace 1 rear tyre. Change apron switch wiring.
05/05/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk rear diff oil level.

## 250 - Service History

11/05/2015	Dawson, Dale - TWC Mechanic	1.00	8,266HRS: 250hr service. / Fit new air & a/c air filters.
12/05/2015	Dawson, Dale - TWC Mechanic	0.50	8,266HRS: 250hr service. / Fit new air & a/c air filters.
14/05/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit cross slope wiring & brackets.
14/05/2015	Dawson, Dale - TWC Mechanic	2.00	Travel to jobsite, install cross slop harness switches, box for cross slop system, return to w/shop
15/05/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	Travel to jobsite, Remove slop box & get updated. Return to w/shop.
18/05/2015	Wilde, David - TWC WORKSHOP MANAGER	2.50	R & R drive shaft & test run. Pack up parts & send away.
29/05/2015	Dawson, Dale - TWC Mechanic	5.50	Get hubs out of storage, strip down hubs, obtain parts required for rebuild, clean, inspect, rebuild
15/06/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,370HRS: Clean out grease points on bucket. Fit cross leveller control & test run.
16/06/2015	Dawson, Dale - TWC Mechanic	2.00	Drill, tap & helicoil threads in laser bucket hitch.
16/06/2015	Knapman, Kenneth - TWC MECHANIC	2.50	Make tool to tighten retaining nut for ball. Fit & tension ball.
22/06/2015	Dawson, Dale - TWC Mechanic	7.50	R & R rear final drives with rebuilt hubs.
22/06/2015	Knapman, Kenneth - TWC MECHANIC	1.50	Remove, remanufacture & replace ripper bar.
23/06/2015	Dawson, Dale - TWC Mechanic	6.00	eChk over machine & bucket. Chk, drain & refill hubs. Repair hyd. leaks & hose mounts. R & R hyd. f
24/06/2015	Knapman, Kenneth - TWC MECHANIC	6.00	Separate tractor from bucket. Remove cushion hitch mount. Gouge out cracks in mount. prep for weldi
01/07/2015	Knapman, Kenneth - TWC MECHANIC	4.00	Press in new bushes, weld lugs & supports to cushion hitch cylinder mounts. Fit tractor to bucket.
01/07/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit cushion hitch. Connect to bucket, test run.
02/07/2015	Wilde, David - TWC WORKSHOP MANAGER	1.50	8,370HRS: Chk & repair wiring to Navman.
07/08/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Remove GPS radio & cable. Fit rego label
12/08/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	R & R mast, test run.
01/09/2015	Knapman, Kenneth - TWC MECHANIC	0.50	8,424HRS: Chk fluid levels, chk tyre pressures & run machine.
29/09/2015	Dawson, Dale - TWC Mechanic	1.00	R & R R/H apron stub for hyd. cylinder.
30/09/2015	Dawson, Dale - TWC Mechanic	1.00	8,500HRS: Complet 500hr service.
30/09/2015	Knapman, Kenneth - TWC MECHANIC	3.00	BUCKET: Remove 4 broken bolts from apron stub. Clean out grease track.
15/10/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
16/10/2015	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
20/10/2015	Wilde, David - TWC WORKSHOP MANAGER	4.50	Chk & replace starter solenoid. Clean out a/c system. Repair throttle control, replace apron stub.
21/10/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	BUCKET: Repairs to apron stubs.
30/10/2015	Wilde, David - TWC WORKSHOP MANAGER	1.00	8,618HRS: Repairs to apron stub. Replace ripper bolts.
24/11/2015	Dawson, Dale - TWC Mechanic	0.50	BUCKET: R & R corner tips.
09/12/2015	Knapman, Kenneth - TWC MECHANIC	2.00	R & R steering wheel - make 1 from 3.
09/12/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	8,763HRS: Prestart & fuel up. Fit oversize signs .5hrs. R & R steering column & test run 1.5hrs.
10/12/2015	Wilde, David - TWC WORKSHOP MANAGER	2.00	8,750HRS: Service. Unload waste oil & filters.
13/01/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & grease. Chk a/c operation. Chk tractor & bucket tyre pressures.
21/01/2016	Dawson, Dale - TWC Mechanic	1.00	Wash machine.
22/01/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace bucket tyre.
25/01/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk & clean out a/c system. Chk & adjust all tyre pressures. Clean mud from bowl.
02/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.75	Fit chains to bucket tyres.
05/02/2016	Dawson, Dale - TWC Mechanic	3.50	Deceleration not working correctly - repair. Laser Bucket: R & R steel tubing mounts on side of bu

05/02/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	Replace lift cylinder & bushes. Replace pipe clamps.
11/02/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Order a/c blower assy & switch. Chk components & remove parts for replacement & replace covers.
12/02/2016	Dawson, Dale - TWC Mechanic	0.50	Load spare tyres on & load up gear.
12/02/2016	Dawson, Dale - TWC Mechanic	3.50	R & r bucket tyre. R & R a/c fan motor & assy. Fit new switch to a/c control on dash. Remove fan mo
15/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Blow out radiators & air filters
16/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	6,886HRS: Chk a/c operation.
16/02/2016	Dawson, Dale - TWC Mechanic	0.50	Strip down hyd. cylinder.
22/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	R & R tilt switch.
23/02/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace seal on apron cylinder. Clean out & test isolator.
24/02/2016	Dawson, Dale - TWC Mechanic	1.00	Rebuild & reassemble hyd. tilt cylinder.
26/02/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Fuel machine.
29/02/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	8,946HRS: Replace steering hose. Replace exhaust tubes.
02/03/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace 2 apron hoses & test run.
04/03/2016	Knapman, Kenneth - TWC MECHANIC	3.50	8,981HRS: Escort machine to 'Bellaree' & carry out 2,000Hr service.
04/03/2016	Wilde, David - TWC WORKSHOP MANAGER	5.75	9,000HRS: Service.
05/03/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Check tyre pressures on tractor. Repair a/c condensor tube, repalce plate.
05/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Clean out radiator & coolers, clean out a/c evaporator.
07/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace door catch & adjust.
09/03/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	9,003HRS: Remove & replace blown hyd. hose.
10/03/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Partial wash down. repair beeper.
30/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart, fit signs, repair oil leak.
31/03/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
01/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
04/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR
08/04/2016	Dawson, Dale - TWC Mechanic	3.00	Remove R/H rear final drive, clean hub, axle etc.
08/04/2016	Knapman, Kenneth - TWC MECHANIC	2.50	Fit final drive & wheels to rear R/H axle assy.
08/04/2016	Wilde, David - TWC WORKSHOP MANAGER	5.50	Remove & clean up parts. Reassemble R/H rear final drive & fit tyres.
11/04/2016	Dawson, Dale - TWC Mechanic	1.00	Strip down, clean old final drive for reseal.
13/04/2016	Knapman, Kenneth - TWC MECHANIC	4.50	Mark out & commence manufacture of new fan cowlng.
14/04/2016	Dawson, Dale - TWC Mechanic	1.00	Strip down final drive, clean for machining.
14/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fuel & grease. replace flashing light switch & test run.
15/04/2016	Dawson, Dale - TWC Mechanic	0.50	Prestart/FGR
15/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR
18/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
18/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R blown hose.
19/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
19/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R 3 hoses.
20/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR

21/04/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Remove wire & plastic from bucket hub.
21/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR
22/04/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR
26/04/2016	Dawson, Dale - TWC Mechanic	0.50	Laser Bucket: R & R corner tip.
26/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
27/04/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
27/04/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Part wash down.
28/04/2016	Knapman, Kenneth - TWC MECHANIC	5.00	BUCKET: Move unit into w'shop welding bay & set up for gouging. Gouge out cracks in bowl weld up. W
28/04/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	Part wash down.
29/04/2016	Dawson, Dale - TWC Mechanic	2.50	Rebuild spare final drive2hrs Chk & charge accumulator for hitch..
29/04/2016	Knapman, Kenneth - TWC MECHANIC	8.50	Remove Laser & GPS towers. Remove R/H side apron ram & gouge off lug for replacement. Weld replacem
29/04/2016	Wilde, David - TWC WORKSHOP MANAGER	4.50	Replace apron mount & ram. Remove GPS aerals. Replace fan shroud & belts & move unit to Woods' yar
04/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit GPS & laser aerals.
05/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit rear tyre.
07/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Chk & adjust fan & alternator belts.
13/05/2016	Dawson, Dale - TWC Mechanic	2.00	BUCKET: Strip down, clean & reseal hyd. cylinder from apron.
17/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.50	Prestart/FG. Repair apron pin. Replace ripper bolt.
18/05/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & fit chains to rear wheels.
19/05/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace alternator belts.
27/05/2016	Knapman, Kenneth - TWC MECHANIC	0.50	Deliver bucket wheel to supplier for tyre replacement.
01/06/2016	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
28/06/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	Replace seat, chk start fault, clean out bucket.
29/06/2016	Wilde, David - TWC WORKSHOP MANAGER	2.50	Chk starting fault - replace starter motor & test run.
30/06/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	BUCKET: Clean mud from unit.
18/07/2016	Dawson, Dale - TWC Mechanic	0.75	Repair failed a/c, repair oil leak in bucket.
28/07/2016	Wilde, David - TWC WORKSHOP MANAGER	4.00	Replace exhaust bend & clamps, replace radiator mounts & fan belts, chk & adjust tyre presures.
30/07/2016	Wilde, David - TWC WORKSHOP MANAGER	2.00	9,250HRS: Service & clean out cab.
16/08/2016	Wilde, David - TWC WORKSHOP MANAGER	0.75	Repair skirt mount & refit skirt.
22/08/2016	Dawson, Dale - TWC Mechanic	1.00	9,370HRS: Investigate starting fault - found broken starter motor earth lead - repaired & tested.
25/08/2016	Dawson, Dale - TWC Mechanic	1.50	Inspect & repair failed laser. Inspect & install radio for GPS - not working - remove to make brack
26/08/2016	Dawson, Dale - TWC Mechanic	0.50	Investigate & pinpoint engine oil leak - rear main seal U/S.
27/08/2016	Dawson, Dale - TWC Mechanic	0.50	Replace U/S greasenipple on bucket.
27/08/2016	Dawson, Dale - TWC Mechanic	1.00	Repair light bar bracket & remount to tank. Repair hyd. oil leak on bucket hitch.
09/09/2016	Dawson, Dale - TWC Mechanic	3.00	Mak up mount for laser control box in cab.
20/10/2016	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove rear eng. oil seal & clean up parts.
21/10/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Assist with re-assembly.
21/10/2016	Wilde, David - TWC WORKSHOP MANAGER	3.50	Refit rear oil seal, test run. Chk & adjust tyre pressures.
26/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Clean laser connectors.

30/10/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace bucket pin.
31/10/2016	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace exhaust bend, clean mud from bucket.
01/11/2016	Wilde, David - TWC WORKSHOP MANAGER	0.25	Replace grease nipples.
02/11/2016	Wilde, David - TWC WORKSHOP MANAGER	2.25	9,500HRS: Service. R& R 2 x hubs. Chk oil in 6. Replace bolts in sides, clean out cab & a/c.
20/11/2016	Knapman, Kenneth - TWC MECHANIC	1.00	Tighten rippers & change corner tips.
15/01/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Remove rear wheels & hubs. Remove tip cylinders & bushes.
15/01/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Remove tilt cylinder bushes.
16/01/2017	Knapman, Kenneth - TWC MECHANIC	1.50	BUCKET: Repair bowl.
17/01/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	9,643HRS: Refit rear wheels & tip rams. replace cutting edge support bolts. Chk uni. joints.
17/01/2017	Knapman, Kenneth - TWC MECHANIC	2.00	BUCKET: Repair bowl.
18/01/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart & grease.
28/03/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk tyre pressures.
30/03/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk & tighten all belts. Clean out a/c system & cab.
01/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	9,672HRS: Prestart/FGR. Replace 4 tip circuit hoses.
02/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace tyne bolt.
04/04/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repair door latch.
07/04/2017	Dawson, Dale - TWC Mechanic	1.00	R & R batteries, chk charge rate.
07/04/2017	Dawson, Dale - TWC Mechanic	1.50	Remove exhaust from turbo, weld up & refit with heatshield.
08/04/2017	Dawson, Dale - TWC Mechanic	1.00	250Hr service.
09/04/2017	Dawson, Dale - TWC Mechanic	1.00	Repair ripper & bolt back onto machine.
10/04/2017	Dawson, Dale - TWC Mechanic	1.00	BUCKET: R & R hub.
10/04/2017	Dawson, Dale - TWC Mechanic	2.50	Repair hyd. oil leak from suspension control valve. R & R engine mounts & fit new exhaust pipe.
18/04/2017	Dawson, Dale - TWC Mechanic	1.00	Laser Bucket: Rebuild hub.
19/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	9,792HRS: Prestart. Repair gear shift wiring.
20/04/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace apron cylinder & 2 washers on eng. mounts.
21/04/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Cut & drill plates for engine mount.
22/04/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace cushion hitch sensor & test run. Replace 1 uni joint.
23/04/2017	Wilde, David - TWC WORKSHOP MANAGER	2.50	Clean out cab, coolers & a/c filters. Repair wiring to gear switch.
13/05/2017	Wilde, David - TWC WORKSHOP MANAGER	0.25	Clean out grease track & replace nipple.
16/05/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	10,000HRS: Part service.
25/05/2017	Dawson, Dale - TWC Mechanic	1.00	Inspect over machine & access to machine due to major breakdown in borrow pit. Machine surrounded b
25/05/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	Remove rear drive shaft & hoses.
26/05/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Remove rear diff yoke from 9180 7 chk if it fits 9380 - no.
26/05/2017	Dawson, Dale - TWC Mechanic	5.50	Install 2 hoses & 8 bolts to diff rear of machine, remove machine from borrow pit to hardstand area
27/05/2017	Dawson, Dale - TWC Mechanic	3.50	Repair machine harness through drive shaft tunnel - harness in 2 pieces. Repair cushion hitch, fit
01/06/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Fit laser & GPS poles & equipment.
03/06/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Clean bowl & fit chains to wheels.
05/06/2017	Knapman, Kenneth - TWC MECHANIC	1.00	Clean bucket.

06/06/2017	Knapman, Kenneth - TWC MECHANIC	4.00	Investigate trans. electrical fault.
07/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to driveshaft, look up & order parts.
15/06/2017	Dawson, Dale - TWC Mechanic	1.00	R & R laser bucket tyre.
16/06/2017	Dawson, Dale - TWC Mechanic	1.00	10,110hrs: R & R bucket tyre, refit tyre to dual on tractor.
18/06/2017	Dawson, Dale - TWC Mechanic	1.00	Finish 250hr service.
18/06/2017	Dawson, Dale - TWC Mechanic	1.00	R & R bucket tyre, chk hub fluids.
19/06/2017	Dawson, Dale - TWC Mechanic	4.50	Investigate Trans. Code faults F24 & F27. Install new gear shift harness - faults not corrected. T/
20/06/2017	Dawson, Dale - TWC Mechanic	1.00	Rotate tyres on bucket - too much tread depth. Weld apron pin into position due to bolt broken off.
21/06/2017	Dawson, Dale - TWC Mechanic	1.00	Investigate A/c failure - recharge gas.
27/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust tyre pressures.
28/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & adjust tyre pressures.
29/06/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
30/06/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart & pump up tyre. Chk trans fault, replace bolt in rippers.
01/07/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	R & R hyd. hose. Repair cushion wiring. Test run. Tighten rear diff bolts. Refit covers.
04/07/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Refit bucket hyd. filter. Weld up hose bracket. Re-connect GPS cables.
06/07/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	R & R TX valve, drier & thermostat.
15/07/2017	Knapman, Kenneth - TWC MECHANIC	1.00	250Hr serevic e.
17/07/2017	Knapman, Kenneth - TWC MECHANIC	2.50	Chk rear axle bolts. Top up oil in rear diff & final drive. Grind off old welds on apron pivot pin
18/07/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Replace broken bolt in ripper bar assy. Chk & investigate Trans. fault code.
20/07/2017	Dawson, Dale - TWC Mechanic	4.50	Spare Engine: Continue with assembly of engine - install cylinder heads, cam , clean components etc
08/08/2017	Wilde, David - TWC WORKSHOP MANAGER	4.00	20,357HRS: Prestart/FGR. Chk trans fault. Repair solenoid wiring. Adjust clutch switch.
09/08/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	20,360HRS: Replace bolts in frame. Chk laser operation.
17/08/2017	Wilde, David - TWC WORKSHOP MANAGER	0.50	20,390HRS: Prestart & fit chain to oil filler cap.
01/09/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	20,488HRS: Chk & repair electrical fault - test run.
02/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	20,500HRS: Part service.
03/09/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	20,500HRS: Complete service.
28/09/2017	Dawson, Dale - TWC Mechanic	4.50	Make room in yard for repairs to bucket. Commence repairs - remove r/h rear final drive.
29/09/2017	Dawson, Dale - TWC Mechanic	8.00	Install r/h rear final drive, set up & fit tyres. Remove l/h rear final drive, install rebuilt fina
30/09/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	20,000HRS: Complete service.
03/10/2017	Dawson, Dale - TWC Mechanic	9.50	Strip down final drive hubs planetarys, gear housing - clean, inspect & deliver hubs for machining
03/10/2017	Wilde, David - TWC WORKSHOP MANAGER	7.50	20,634HRS: Wash down, replace belts, chk all tyre pressures. Fit laser mast. Replace bolts in cutti
04/10/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	Replace seals on oil pump. Chk a/c operation. Replace 2 flashing lights.
05/10/2017	Dawson, Dale - TWC Mechanic	6.50	Disassemble. inspect, clean & reassemble final drives.
06/10/2017	Knapman, Kenneth - TWC MECHANIC	8.50	Weld repairs to bucket: Gouge & weld cracks in bowl - both wings & rear rests. Build up mould board
06/10/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	R & R skirts & apron bar pivots.
07/10/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Prestart/FGR
18/10/2017	Wilde, David - TWC WORKSHOP MANAGER	3.00	20,677HRS: Chk & repair laser cable connector. Replace tilt switch.
27/10/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	20,750HRS: Service.

31/10/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & repair laser cable. Test run.
10/11/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Replace seals in return screen, test run.
15/11/2017	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk & clean Trans. wiring & tighten alternator belts.
22/11/2017	Dawson, Dale - TWC Mechanic	1.00	Inspect & repair GPS
24/11/2017	Dawson, Dale - TWC Mechanic	1.00	Fit new hub & wheel, chk wheel nuts tension on other hubs.
25/11/2017	Knapman, Kenneth - TWC MECHANIC	0.50	Take tyre to supplier for rim removal.
27/11/2017	Dawson, Dale - TWC Mechanic	1.00	11,000HRS: Partially complete 1,000hr service - power train service o/s.
01/12/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	R & R GPS harness & test run. R & R broken bolt in apron stub.
05/12/2017	Knapman, Kenneth - TWC MECHANIC	3.00	Weld support to cross leveller mount bracket. Weld support washers to apron stub. Chk/fill bucket w
05/12/2017	Wilde, David - TWC WORKSHOP MANAGER	3.50	Complete 1,000Hr service. Clean out a/c filters. Chk & adjust bucket tyre pressures.
06/12/2017	Knapman, Kenneth - TWC MECHANIC	1.50	Repair step.
06/12/2017	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & adjust tractor tyre pressures. Fit sensor & cable. Replace cable connector. Test run.
20/12/2017	Wilde, David - TWC WORKSHOP MANAGER	1.50	R & R bucket hub. Repair leak at cap. Blow out coolers.
10/01/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair wiring to gear switch & test run.
30/01/2018	Dawson, Dale - TWC Mechanic	4.00	Investigate GPS Fault. Investigate & repair cross level fault. Investigate GPS fault again - found
31/01/2018	Dawson, Dale - TWC Mechanic	3.50	Install main GPS harness from screen to radio, driver & receivers, test operation. Organise/obtain
06/02/2018	Dawson, Dale - TWC Mechanic	1.25	250Hr service. R & R apron roller on left side of apron door.
16/02/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	20,411HRS: Chk wheel bolt tension. Chk Bucket hub & tyre pressures.
19/02/2018	Dawson, Dale - TWC Mechanic	2.00	Investigate & repair trans. fault. Remove, repair & refit apron roller.
20/02/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk wiring & Trans. controller. Repair ripper switch & test run. Chk bucket pins.
21/02/2018	Dawson, Dale - TWC Mechanic	1.75	Remove blown hose & obtain replacement. Fit new hose, refill oil & test run.
08/03/2018	Dawson, Dale - TWC Mechanic	2.50	Investigate trans. fault with fwd & reverse. Fault intermittent but could worsen.
09/03/2018	Knapman, Kenneth - TWC MECHANIC	2.00	Disconnect bucket from machine & investigate trans. fault.
09/03/2018	Dawson, Dale - TWC Mechanic	9.50	Investigate transmission fault. Remove bucket from tractor. Found fault with Trans. input shaft 7"
09/03/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to transmission.
10/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart/FGR
16/03/2018	Wilde, David - TWC WORKSHOP MANAGER	4.50	21,500HRS: Service. Replace 1 uni joint & chk all.
19/03/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	1,520HRS: Chk & clean trans wiring & shift hoses. Clean out apron stubs & grease.
21/03/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	Replace 2 apron rollers & grease. Replace trans. filter.
24/03/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk trans fault & filter.
27/03/2018	Dawson, Dale - TWC Mechanic	1.00	Remove GPS unit from machine.
04/04/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	Disconnect tractor from bucket & remove trans.
05/04/2018	Knapman, Kenneth - TWC MECHANIC	3.50	Prep, gouge & weld up cracks in chassis.
05/04/2018	Dawson, Dale - TWC Mechanic	2.50	Install replacement transmission.
05/04/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Fit replacement transmission.
06/04/2018	Dawson, Dale - TWC Mechanic	7.50	Finish installation of replacement transmission. Fit to bucket, fit guards, fit cab back together,
06/04/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Assist with driveline installation.
07/04/2018	Dawson, Dale - TWC Mechanic	1.00	Finish installation of GPS components. Fit tilt cylinder.

07/04/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Refit GPS cables & components.
11/04/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Fit new 2way speaker & fire extinguisher.
12/04/2018	Knapman, Kenneth - TWC MECHANIC	1.50	Make new mount for proximity switches.
13/04/2018	Knapman, Kenneth - TWC MECHANIC	2.00	Make cushion hitch sensor mount & weld to Hyd. Cylinder.
14/04/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Replace hitch cylinder & repair hitch wiring.
16/04/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repair apron cylinder leak. Fit sticky pads to window for GPS
30/04/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	Effect repairs to laser system.
01/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	Effect repairs to laser system.
02/05/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Effect repairs to laser system.
03/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	Repairs
04/05/2018	Wilde, David - TWC WORKSHOP MANAGER	4.25	Repairs
08/05/2018	Wilde, David - TWC WORKSHOP MANAGER	0.00	Repairs
23/05/2018	Dawson, Dale - TWC Mechanic	2.00	Investigate fault with laser. Obtain replacement laser mast from w'shop & instal.
30/05/2018	Wilde, David - TWC WORKSHOP MANAGER	4.00	1,746HRS: Chk laser cables & remove control box for testing. Replace mast & control box - test run.
08/06/2018	Dawson, Dale - TWC Mechanic	4.00	11,762HRS: Commence 250hr service. R & R clutch cable & adjust.
08/06/2018	Wilde, David - TWC WORKSHOP MANAGER	2.00	1,750HRS: Collect parts & carry out part service.
12/06/2018	Dawson, Dale - TWC Mechanic	1.50	11,764HRS: Investigate lack of drive on trans. Found alternator to be U/S - R & R alternator.
28/06/2018	Dawson, Dale - TWC Mechanic	1.00	Drain oil from overfilled eng & trans.
17/07/2018	Dawson, Dale - TWC Mechanic	5.00	Reseal diesel leak on fuel pump, complete engine valve set.
19/07/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Remove & disassemble L/H ripper Arm.
20/07/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Top up hydraulics. Cut off pipe retainers for replacement.
20/07/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Replace leaking bucket hoses. Reseal 3 cylinders.
27/07/2018	Dawson, Dale - TWC Mechanic	2.50	R & R leaking laser bucket hubs.
31/07/2018	Dawson, Dale - TWC Mechanic	2.00	Strip down, inspect & reseal lift ram hyd. cylinder.
02/08/2018	Wilde, David - TWC WORKSHOP MANAGER	2.50	Touch up repair work on drains.
07/08/2018	Dawson, Dale - TWC Mechanic	2.50	Fit new Stauff clamps to bracket on steel piping.
14/08/2018	Knapman, Kenneth - TWC MECHANIC	2.50	Remove bowl assy from bucket.
14/08/2018	Wilde, David - TWC WORKSHOP MANAGER	3.50	Laser Bucket: Remove bowl & frame assy & load onto float for transport to breeza jobsite.
16/08/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove lift cylinder lug. Look up & order parts. Clean up parts.
16/08/2018	Dawson, Dale - TWC Mechanic	2.50	Laser Bucket: Reseal hubs. Remove clamps & wear plates.
20/08/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Laser Bucket: Remove pivot bushes.
30/08/2018	Knapman, Kenneth - TWC MECHANIC	8.50	Fit frame/bucket to front section, fit walking beams. Assemble bowl. Weld on lifting lugs. Modify b
30/08/2018	Wilde, David - TWC WORKSHOP MANAGER	5.50	BUCKET: Assemble bucket.
31/08/2018	Wilde, David - TWC WORKSHOP MANAGER	5.00	BUCKET: Continue repairs.
10/09/2018	Dawson, Dale - TWC Mechanic	4.50	LASER BUCKET: Remove steel tubes, prep rear of bucket frame & paint. Refit tubing etc.
17/09/2018	Dawson, Dale - TWC Mechanic	0.25	Prestart/FGR
19/09/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	1,841HRS: Chk & clean trans. electrical connectors. Tighten bucket bolts. Test run.
26/09/2018	Dawson, Dale - TWC Mechanic	0.50	Investigate/repair laser fault.

03/10/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	1,907HRS. Chk over machine.
25/10/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Commence 2,000HR service - eng. only - air filters.
27/10/2018	Knapman, Kenneth - TWC MECHANIC	1.00	Replace chains on bucket tyres.
31/10/2018	Dawson, Dale - TWC Mechanic	1.00	Fit GPS unit.
01/11/2018	Dawson, Dale - TWC Mechanic	0.50	Repair laser - not working due to power supply fault.
04/11/2018	Dawson, Dale - TWC Mechanic	1.50	2,045HRS: R & R diff & final drive oil - part of 2,000hr service.
10/11/2018	Wilde, David - TWC WORKSHOP MANAGER	1.00	Reapirs to apron.
10/11/2018	Dawson, Dale - TWC Mechanic	3.00	2,110HRS: Remove broken bolts from apron stub, refit to apron
11/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,129HRS: Clean out air & cab filters. Chk over.
14/11/2018	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,155HRS: Replace bowl raise switch. Chk cutting edges, replace corner tip.
16/11/2018	Wilde, David - TWC WORKSHOP MANAGER	1.50	2,179HRS: Turn cutting edges & replace corner tip.
18/11/2018	Wilde, David - TWC WORKSHOP MANAGER	3.00	2,192HRS: R & R water pump belt & idler pulley bearing.
16/01/2019	Dawson, Dale - TWC Mechanic	1.00	Install GPS components to bucket.
16/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Part wash down.
17/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	2,360HRS: Chk bucket hubs - grease. Replace bolt in wheel hub. Clean out A/c system & repair a/c mo
18/01/2019	Knapman, Kenneth - TWC MECHANIC	4.50	Repair cushion hitch sensor 2hrs. Repair wiring to cushion hitch control box - 2nd repair. 2.5hrs
19/01/2019	Dawson, Dale - TWC Mechanic	2.00	Investigate hitch failure - repaired. Test & repair a/c unit.
20/01/2019	Dawson, Dale - TWC Mechanic	0.75	Investigate powertrain noise - found R/H rear final drive damaged.
21/01/2019	Dawson, Dale - TWC Mechanic	1.25	Disconnect bucket from unit & load & secure tractor onto float
21/01/2019	Dawson, Dale - TWC Mechanic	7.00	R & R failed rear diff assy & components, fit new uni joint.
22/01/2019	Dawson, Dale - TWC Mechanic	8.00	Finish install of replacement diff/final drives, refit wheels, put spacer in articulation, change f
22/01/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	2,380HRS: Repairs to rear diff & ball joints.
23/01/2019	Dawson, Dale - TWC Mechanic	6.00	Continue with disassembly of failed diff & inspect for cause - found hemisphere gears failed.
23/01/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	Continue with disassembly/repair to failed diff.
24/01/2019	Dawson, Dale - TWC Mechanic	3.00	Disassemble diff centre & inspect wheel ends for failed components.
29/01/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk over, replace bonnet stops.
04/02/2019	Dawson, Dale - TWC Mechanic	0.50	R & R bucket corner tips.
07/02/2019	Dawson, Dale - TWC Mechanic	0.50	Tighten up laser bucket control box on seat base - vibrated loose. Chk over bucket.
09/02/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	2,436HRS: Chk Navman operstion.
13/02/2019	Dawson, Dale - TWC Mechanic	4.00	Clean parts & continue assembly of diff.
14/02/2019	Dawson, Dale - TWC Mechanic	1.00	Continue assembly of diff.
15/02/2019	Wilde, David - TWC WORKSHOP MANAGER	2.50	28,750HRS: Service. Clean out A/c system.
27/02/2019	Dawson, Dale - TWC Mechanic	2.50	Locate coolant leak - leaking hose - R & R, refill coolant.
28/02/2019	Knapman, Kenneth - TWC MECHANIC	2.00	Carry out repairs to bucket. Wash tractor & radiator.
02/03/2019	Dawson, Dale - TWC Mechanic	1.00	Clean out radiators. Change hitch accumulator.
05/03/2019	Dawson, Dale - TWC Mechanic	1.00	Clean out radiators/filters. Repairs laser mast failure.
06/03/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	2,639HRS: Partial wash down.
07/03/2019	Wilde, David - TWC WORKSHOP MANAGER	2.25	2,639HRS: Replace seals on oil pump & eng. oil line. Chk tyre pressures & uni joint.

08/03/2019	Dawson, Dale - TWC Mechanic	4.00	Effect repairs to mast - not extending. Chk & top up hubs with oil. Test operation of GPS. Test & r
14/03/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk GPS valve operation.
26/03/2019	Dawson, Dale - TWC Mechanic	2.50	BUCKET: Assist remove leaking hyd. cylinders
30/03/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	Unload from float, chk cushion hitch relays.
30/03/2019	Knapman, Kenneth - TWC MECHANIC	1.50	Unload from float & chk cushion hitch relays.
01/04/2019	Dawson, Dale - TWC Mechanic	3.00	Remove radiator from #256 and pack onto pallet for transport to S.A. jobsite
04/04/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace apron stub & bolts.
08/04/2019	Knapman, Kenneth - TWC MECHANIC	8.50	Reman corner tips for bucket.
09/04/2019	Knapman, Kenneth - TWC MECHANIC	1.50	Collect parts & re-assemble cylinder.
11/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,839HRS: Replace L/H skirt & spacer. Repair grease points.
12/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Chk cutting edges & clean electrical connectors.
15/04/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Bucket: replace corner tips & chk cutting edges.
16/04/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	2,887HRS: Clean dirt from bucket. Chk cutting edges.
17/04/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Prestart. Tighten alternator bolts.
27/04/2019	Dawson, Dale - TWC Mechanic	1.00	R & R ripper shank. Repair apron electrical circuit.
03/05/2019	Dawson, Dale - TWC Mechanic	2.00	14,000HRS: Grease machine & chk over. Adjust V belts, fix coolant leak etc. Complete part of 1,000H
04/05/2019	Dawson, Dale - TWC Mechanic	1.00	Repair leaking tyre bead - inside R/H tyre. R & R corner tips.
05/05/2019	Dawson, Dale - TWC Mechanic	1.00	R & R ripper boots, repair damaged ripper.
06/05/2019	Dawson, Dale - TWC Mechanic	1.50	Recharge accumulator, R & R ripper & boots, chk tyre pressures.
07/05/2019	Dawson, Dale - TWC Mechanic	1.00	Bucket: Grease unit, R & R broken ripper.
04/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	BUCKET: Replace corner tips & chk cutting edges.
13/06/2019	Dawson, Dale - TWC Mechanic	7.50	R & R hyd & steer pump assy. Fit new screen inside hyd. oil tank. R & R rear R/H final drive oil se
14/06/2019	Dawson, Dale - TWC Mechanic	2.50	Finish install of final drive & tyres.
20/06/2019	Dawson, Dale - TWC Mechanic	0.50	BUCKET: Fit chains to wheels.
25/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Travel to supplier, collect parts & return to jobsite.
25/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace corner tips.
26/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Replace hitch accumulator & test run.
27/06/2019	Wilde, David - TWC WORKSHOP MANAGER	1.50	BUCKET: Replace apron stub & change cutting edges.
28/06/2019	Dawson, Dale - TWC Mechanic	3.50	LASER BUCKET: Clean, strip down & fit new bearings to hubs.
29/06/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	3,202HRS: Replace 2 x hyd. hoses.
02/07/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	BUCKET: Fit chains to tyres.
08/07/2019	Knapman, Kenneth - TWC MECHANIC	4.00	BUCKET: Reman. corner tips
10/07/2019	Dawson, Dale - TWC Mechanic	1.00	Investigate cause of excessive white exhaust smoke - found No.1 cylinder overfueling.
11/07/2019	Dawson, Dale - TWC Mechanic	0.50	Repair laser bracket & grease.
15/07/2019	Dawson, Dale - TWC Mechanic	2.50	3,250hars : Complete 250hr service.
17/07/2019	Dawson, Dale - TWC Mechanic	2.00	3,268Hrs: R & R rear diff uni joint.
19/07/2019	Dawson, Dale - TWC Mechanic	1.00	Repair oil leak on hyd. pump.
20/07/2019	Dawson, Dale - TWC Mechanic	1.50	Locate & repair eng. oil leaks. Chk tappets in No.1 cylinder.

30/07/2019	Dawson, Dale - TWC Mechanic	2.50	BUCKET: Strip down, reseal/rerace hub.
04/08/2019	Knapman, Kenneth - TWC MECHANIC	0.75	Chk alternator/battery. Remove beacon light switch.
13/08/2019	Knapman, Kenneth - TWC MECHANIC	1.50	BUCKET: Remove apron roller to clear grease track & reassemble.
15/08/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Check for fuel system fault.
16/08/2019	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to fuel system.
30/08/2019	Knapman, Kenneth - TWC MECHANIC	1.00	BUCKET: Locate & repair wiring fault.
01/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	BUCKET: Repair.
01/09/2019	Knapman, Kenneth - TWC MECHANIC	0.50	Replace control box bucket lift switch.
05/09/2019	Knapman, Kenneth - TWC MECHANIC	2.00	Weld repairbracket retainer for A/C mounting.
10/09/2019	Wilde, David - TWC WORKSHOP MANAGER	3.00	3,489HRS: Part service. Chk & repair wiring to dash - test run.
16/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Repair throttle spring.
17/09/2019	Wilde, David - TWC WORKSHOP MANAGER	0.50	Chk & clean bucket solenoid.
19/09/2019	Wilde, David - TWC WORKSHOP MANAGER	2.00	Chk & repair GPS fault. Remove receivers & radio. Remove mast for repair.
09/03/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Commence rebuild of transmission (for install in #256)
09/03/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove guards & chk GPS cable. Remove for repair.
10/03/2020	Knapman, Kenneth - TWC MECHANIC	9.00	Continue trans. rebuild.
11/03/2020	Knapman, Kenneth - TWC MECHANIC	9.00	Continue trans. rebuild.
16/03/2020	Knapman, Kenneth - TWC MECHANIC	6.00	Continue with assembly of transmission.
17/03/2020	Knapman, Kenneth - TWC MECHANIC	9.00	Continue with assembly of transmission.
18/03/2020	Knapman, Kenneth - TWC MECHANIC	9.00	Continue with assembly of transmission.
06/05/2020	Knapman, Kenneth - TWC MECHANIC	2.00	Collect steel for crossleveller box manufacture & commence manufacture of box.
07/05/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Continue with manufacture of walking beam/cross leveller box for L/H side of bucket.
08/05/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Continue with manufacture of walking beam/cross leveller box for L/H side of bucket.
11/05/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Continue with manufacture of walking beam/cross leveller box for L/H side of bucket.
12/05/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Continue with manufacture of walking beam/cross leveller box for L/H side of bucket.
13/05/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Continue with manufacture of walking beam/cross leveller box for L/H side of bucket.
14/05/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Continue with manufacture of Cross leveller box & walking beam.
15/05/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Continue with manufacture of Cross leveller box & walking beam.
18/05/2020	Knapman, Kenneth - TWC MECHANIC	2.50	Purchase materials for hyd. guards. Wire guards & hungry boards on bowl.
19/05/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Make up bowl guards.
20/05/2020	Knapman, Kenneth - TWC MECHANIC	7.00	Manufacture cover/guards for bucket wiring harnesses.
21/05/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Bucket: Manufacture harness guards & attach to bucket.
21/05/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to bucket.
22/05/2020	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Manufacture & fit hungry boards.
22/05/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	BUCKET: Assist with repairs.
25/05/2020	Knapman, Kenneth - TWC MECHANIC	6.00	BUCKET: Fit hungry boards.
26/05/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Finish fitting hungry boards.
26/05/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to bucket.

27/05/2020	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Make & fit cross leveller hydraulic lines covers, clean covers ready for painting.
28/05/2020	Knapman, Kenneth - TWC MECHANIC	7.00	BUCKET: Clean off rust from manufactured walking beam parts, undercoat & apply 1st topcoat.
29/05/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Paint manufactured items. Repair/fit router mounts.
29/05/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Repairs to bucket.
01/06/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Fit cross leveller assy. Weld on router mount.
01/06/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Repairs to bucket.
02/06/2020	Knapman, Kenneth - TWC MECHANIC	8.00	BUCKET: Remove broken studs in axle retaining plate. Plumb hydraulics & fit hose covers.
03/06/2020	Knapman, Kenneth - TWC MECHANIC	4.50	Remove bonnet latch for repair. remove wheels for spacers fitted to walking beam. Weld on router mo
05/06/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Order & collect parts. repair bonnet catch on tractor. Weld on adaptorfor router tyne repair. Remov
10/06/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Collect parts etc from suppliers.
12/06/2020	Knapman, Kenneth - TWC MECHANIC	1.00	BUCKET: Heat & press cross leveller box to remove bell end.
15/06/2020	Knapman, Kenneth - TWC MECHANIC	6.00	BUCKET: Repair cross leveller box.
16/06/2020	Knapman, Kenneth - TWC MECHANIC	8.00	Set wear plates/guides for cross leveller box to walking beam. Separate, strip old paint, prime & r
17/06/2020	Knapman, Kenneth - TWC MECHANIC	5.00	BUCKET: Connect R/H Cross leveller assay to unit with new axles.
22/06/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Replace axle mount plates. Replace ripper.
23/06/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Remove apron for reconditioning - commence reconditioning.
23/06/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	BUCKET: Assist with removal of apron for repair.
24/06/2020	Knapman, Kenneth - TWC MECHANIC	8.50	Continue with repairs/reman of bucket apron.
25/06/2020	Knapman, Kenneth - TWC MECHANIC	4.50	BUCKET: Continue with reman of apron.
26/06/2020	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Continue with reman of apron.
29/06/2020	Knapman, Kenneth - TWC MECHANIC	7.50	BUCKET: Continue with reman of apron.
30/06/2020	Knapman, Kenneth - TWC MECHANIC	8.50	BUCKET: Finish apron reman. & re-install into bucket. Fit cross brace & support bar.
01/07/2020	Knapman, Kenneth - TWC MECHANIC	5.50	Replace L/H ripper ram. Fit wiring cover guards on laser frame. Repair hyd. leak on tilt system. Re
02/07/2020	Knapman, Kenneth - TWC MECHANIC	4.00	Reman. ripper bars, gouge apart worn axles & reclaim heads.
26/08/2020	Knapman, Kenneth - TWC MECHANIC	5.50	Remove oil pump & oil lines. Replace hoses, seals & gaskets. Replace A/c hose.
26/08/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk over, repair oil leaks & a/c system.
27/08/2020	Knapman, Kenneth - TWC MECHANIC	9.00	Swap out engine.
27/08/2020	Wilde, David - TWC WORKSHOP MANAGER	7.00	R & R engine.
28/08/2020	Knapman, Kenneth - TWC MECHANIC	6.50	Purchas replacement hoses & fit to machine. Fill coolant. Look for harness information.
28/08/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	Assemble engine to machine.
29/08/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Fit replacement engine into machine. Replace radiator mounts & adjust. Replace harness connectors.
29/08/2020	Wilde, David - TWC WORKSHOP MANAGER	7.50	3,606HRS: Assemble enging to machine. Repair radiator mounts. Repair a/c system.
31/08/2020	Knapman, Kenneth - TWC MECHANIC	1.50	Removed damaged diff filler plug, locate fuel leak & repair.
04/09/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk over & repair coolant leaks.
09/09/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Chk & repair Navman wiring. Chk cushion hitch & remove sensor. Tighten sump bolts.
10/09/2020	Knapman, Kenneth - TWC MECHANIC	3.50	Repair refurbish ripper thrust corner tips
24/09/2020	Knapman, Kenneth - TWC MECHANIC	1.00	Assist with reapirs to cushion hitch.
24/09/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk over & repair wiring to cushion hitch.

21/10/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Purchase fuel shut off solenoid.
22/10/2020	Knapman, Kenneth - TWC MECHANIC	7.00	3,703HRS: Replace fuel shut off solenoid. Weld detached exhaust Venturi spiggot. Weld crack in arti
23/10/2020	Knapman, Kenneth - TWC MECHANIC	2.00	Repair seat slide.
19/11/2020	Wilde, David - TWC WORKSHOP MANAGER	5.00	Wash, polish & clean out cab.
20/11/2020	Knapman, Kenneth - TWC MECHANIC	7.50	Remove cushion hitch control valve. Clean, disassemble & reseal & refit. Remove, disassemble & insp
20/11/2020	Wilde, David - TWC WORKSHOP MANAGER	5.50	Continue with wash/polish.
24/11/2020	Wilde, David - TWC WORKSHOP MANAGER	3.00	Remove stickets & polish.
25/11/2020	Wilde, David - TWC WORKSHOP MANAGER	1.00	Polish machine.
25/11/2020	Knapman, Kenneth - TWC MECHANIC	0.50	Chk over machine & move into yard.
27/11/2020	Knapman, Kenneth - TWC MECHANIC	1.50	make bracket mount for GPS receiver.
27/11/2020	Wilde, David - TWC WORKSHOP MANAGER	0.50	Make up bracket for GPS radio & mount.
30/11/2020	Wilde, David - TWC WORKSHOP MANAGER	3.50	Chk GPS Operation. Clean & replace danfos connectors. Test run.
03/12/2020	Wilde, David - TWC WORKSHOP MANAGER	1.50	Chk & clean electrical connectors & test run.
18/12/2020	Wilde, David - TWC WORKSHOP MANAGER	2.00	3,750HRS: Service & chk over.
18/12/2020	Knapman, Kenneth - TWC MECHANIC	2.00	3750 hr service add watter to inside duals
04/01/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	Refit rh outside tyre
18/01/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Check fault codes for transmission. Locate infor on fault code.
18/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	3,878HRS: Chk trans fault & clean connector on solenoids. test run.
19/01/2021	Knapman, Kenneth - TWC MECHANIC	1.00	To jobsite & investigate intermittant transmission electrical fault.
21/01/2021	Knapman, Kenneth - TWC MECHANIC	1.00	3,899HRS: Change bucket cutting edges & R/H corner tip.
21/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	3,899HRS: R & R cutting edges.
25/01/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	R & R top radiator hose & top up coolant. Test run.
27/01/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Prep & weld apron pivot pin in place. Reconnect GPS harness.
01/02/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Change corner tips, tighten ripper bolts, replace R clip in cushion hitch ram.
05/02/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Replace intercooler manifold seals. Turn cutting edges.
05/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	3,981HRS: Turn cutting edges.
06/02/2021	Knapman, Kenneth - TWC MECHANIC	4.00	Remove router mount for remanufacture.
08/02/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Fit reman. router bar to bucket.
08/02/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	3,992HRS: R & R bucket tyre. Chk cushion hitch operation. Chk raise switch.
09/02/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Change corner tips & cushion hitch charge cylinder.
09/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	3,998HRS: Change hitch accumulator & corner tips.
10/02/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	4,000HRS: Service. Tighten hyd. hoses.
13/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,033HRS: remove & replace ripper cylinder.
16/02/2021	Knapman, Kenneth - TWC MECHANIC	0.50	4,044HRS: Investigate coolant leak
16/02/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Replace corner tip.
17/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	4,054HRS: Turn cutting edges on bucket & complete service.
18/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Repairs to brakes & wiring.
19/02/2021	Knapman, Kenneth - TWC MECHANIC	4.00	Replace brake pads & handbrake pads.

20/02/2021	Knapman, Kenneth - TWC MECHANIC	6.00	Remove & replace broken brake pipe, clean out bleed screws, adjust handbrake.
20/02/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	Bleed brakes,
22/02/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Repairs to brake system, bleed.
22/02/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	Bleed brakes.
04/03/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	4,087HRS: Remove bent corner tip. Clean fuse holder for cross leveller. Repair 3 tyre leaks.
05/03/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	4091Hrs. Replace alternator belts, Check & Clean dafoss connector. Replace pin in hitch, Repair T/w
08/03/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Remanufacture router
08/03/2021	Wilde, David - TWC WORKSHOP MANAGER	0.50	BUCKET: R & R broken tyne.
10/03/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,100HRS: Refit corner tip & chk charging system.
11/03/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,107HRS: Chk & clean danfoss connectors & test run.
16/03/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Repair ripper tyne. Repair/remanufacture corner tips
17/03/2021	Knapman, Kenneth - TWC MECHANIC	4.00	Reman. corner tips for bucket.
18/03/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,123HRS: R & R ripper bar & blow up tyre.
08/04/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	4129Hrs. Check coolant for leaks. Replace top radiator hose and tighten all hoses
12/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	4136Hrs - Fit chains to bucket tyres. Check bucket oil leaks
12/04/2021	Knapman, Kenneth - TWC MECHANIC	0.50	4,163 Hrs Check bucket for oil leaks
13/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	4139Hrs - Replace hyd hose and test run
13/04/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Check Hydraulic leak
20/04/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	4157hrs. Refit centre cutting edge and check a/c operation. Order parts
23/04/2021	Wilde, David - TWC WORKSHOP MANAGER	2.50	Remove and replace condensor. Vac and check for leaks. Recharge and check for levels
07/05/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Source and purchase AM/FM Bluetooth radio
07/05/2021	Wilde, David - TWC WORKSHOP MANAGER	3.50	4162Hrs. Remove and dismantle seat suspension. Look up and order parts. Remove radio and check over
08/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.50	4162Hrs. Replace seat damper and reassemble seat
11/05/2021	Wilde, David - TWC WORKSHOP MANAGER	2.50	4162Hrs. Refit seat. Replace radio. Replace t/way aerial. Check bucket
13/05/2021	Wilde, David - TWC WORKSHOP MANAGER	1.00	4,162HRS: Charge a/c system. prestart & test run a/c.
17/05/2021	Knapman, Kenneth - TWC MECHANIC	3.50	Travel to machine location. Trace anomaly in transmission, return to w'shop.
18/05/2021	Knapman, Kenneth - TWC MECHANIC	4.00	Purchase filter, load equipment & travel to machine location. Adjust speed sensor & chk continuity
19/05/2021	Knapman, Kenneth - TWC MECHANIC	3.00	Travel to machine site. Assist moving plant . Chk harness connections for trans. Replace control pa
19/05/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	4,200HRS: Chk & clean trans wiring. replace rocker switch. Adjust fan belts. Test run. Fit chain to
20/05/2021	Knapman, Kenneth - TWC MECHANIC	3.50	Order parts. Fit filter & switch to machine.
21/05/2021	Knapman, Kenneth - TWC MECHANIC	2.50	Replace ripper, remove L/H walking beam pin, clean & rotate to take grease.
22/05/2021	Knapman, Kenneth - TWC MECHANIC	7.00	Replace cutting edges & corner tips. Locate power fault in radio. replace water filter. remove numb
24/05/2021	Knapman, Kenneth - TWC MECHANIC	4.00	Escort unit to workshop for repairs.
28/05/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Check availability of replacement windscreen. Repair gear wiring fault.
01/06/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Travel to machine site, remove routers & return to w'shop.
21/06/2021	Knapman, Kenneth - TWC MECHANIC	2.50	Escort machine back to depot. Replace apron stubs. Inspect tractor steering & articulation for wear
29/06/2021	Knapman, Kenneth - TWC MECHANIC	1.50	Remove broken gas strutt stay for door. Check light system. Clean dash assembly
30/06/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Fit door gas strut. Inspect bucket for cracks

## 250 - Service History

01/07/2021	Knapman, Kenneth - TWC MECHANIC	7.00	Locate bucket in shed. Separate from tractor. Place tractor in shed and separate front from back. Pu
01/07/2021	Wilde, David - TWC WORKSHOP MANAGER	2.00	Remove bucket from machine. Separate tractor and remove uni balls. Check housing for repair
02/07/2021	Knapman, Kenneth - TWC MECHANIC	8.50	Remove articulation bushes and bearings. Remove top plate. Gouge out and weld cracks in bucket hitc
05/07/2021	Knapman, Kenneth - TWC MECHANIC	9.50	Replace top articulation lik bar bushes. Deliver to McManus for boring. Pick up parts. Source and w
06/07/2021	Knapman, Kenneth - TWC MECHANIC	9.00	Remove steering pins. Gouge off retaining plates and deliver to McManus for remanufacture. Pick up
07/07/2021	Knapman, Kenneth - TWC MECHANIC	8.50	Manufacture & fit apron cylinder guides. Reseal danfoss valve on bucket (front). Remove RH ripper r
08/07/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Ripper cylinder shaft to McManus for remanufacture
09/07/2021	Knapman, Kenneth - TWC MECHANIC	2.00	Clean articulation components
13/07/2021	Knapman, Kenneth - TWC MECHANIC	0.50	Pickup parts. See McManus for parts eta
14/07/2021	Knapman, Kenneth - TWC MECHANIC	1.00	Remove bucket from shed
20/07/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Assemble hyd rams
23/07/2021	Wilde, David - TWC WORKSHOP MANAGER	3.00	Shift hyd hoses and pipes for machining. Assemble hyd rams

#REF!

#REF!