



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM63537
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21680314

165-14
Inspection Result:

PASS

ACILITY: MODERN DIESEL TRUCK REPAIR LTD. / S15400 INSP. TYPE: Complete INSP. START: 2026-Feb-28 09:30 AM PST
INSPECTOR: SANDHU, GURPREET / 202678 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Feb-28 11:30 AM PST
WORK ORDER #: 2026232

VEHICLE JUR: British Columbia REGI: 14145644 VIN: 2S9NE3697F1032480
PLATE #: 42036L UNIT/FLEET#: OWNER/LESSEE NAME: E2L CONSTRUCTION, LTD.
LICENCED GVW(kg): 0 BODY STYLE: Dump Trailer ADDRESS: 234-2035 GLENAIRE DR, 234-2035 GLENAIRE DR
VEHICLE YEAR: 2015 ODOMETER: North Vancouver, British Columbia
MAKE: GRAVEL PUP HUB ODOMETER: V7P1Y2, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) XL 1 & 3 BOTH SIDE DRUM BRAKE REPLACED / XL 1 RIGHT 2 LEFT SLACK ADJUSTER REPLACED
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed REPLACED HOOK EYE & BUSH
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed with Caution
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	35	5	4	10	10	
2	Clamp	30	Automatic	34	34	12	12	11	11	
3	Clamp	30	Automatic	35	35	10	10	18	18	
Comment:						Comment: XL 1 LEFT TIRE NEED TO REPLACED WITHIN THREE DAYS				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	30	Lining (Shoe)	22	22	Drum		
2	72	70	Lining (Shoe)	16	16	Drum		
3	30	30	Lining (Shoe)	22	22	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: SANDHU, GURPREET Signature:

This Inspection Report was submitted to CVSE on 2026-Feb-28 07:58 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement

NS/SED014

2/28/2026 7:58:48 PM PST