



Vehicle History Detail

Fleet #	R12
Registration	XN38MZ
Make	
Model	Volvo FE07A
VIN / Chassis #	YV2V0Y1CXKZ127260

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/05/2026		Fault R-3177 Inspected and repaired reverse alarm not working dianose faulty alarm removed and replaced alarm and tested ok			\$80.00
12/05/2026	339,393 kms	Fault R-3161 Inspected and repaired r/h lower clearance light not working remove and replaced light unit with second hand parts reassembled and tested ok	Workshop		\$37.50
05/05/2026	338,870 kms	A - A S-16548 Carried out A service as per service checklist also steam clean chassis and carried out body repairs replacing rollers			\$180.00
09/04/2026	335,193 kms	sway bar R-3115 Inspected and repaired front sway bar rubbers worn. Removed and replaced rubbers.	Workshop		\$598.75
09/04/2026	335,193 kms	A - A S-16375 Carried out A service as per service checklist			\$80.00
31/03/2026	333,704 kms	Haulmax 275/70R 22.5 T-973 Supply and fit 4 x Haulmax 275/70R22.5 Dispose 4 x Truck Tyre	Clarence Valley Tyres	1085730	\$1,832.00
24/03/2026	332,240 kms	C - C Service S-16551 Carried out C service as per service checklist also road tested vehicle and checked max road speed set to 100kms ,set ok			\$160.00
24/03/2026	332,240 kms	A - A S-16269 Carried out A service as per service checklist			\$80.00
18/03/2026		blinker R-3069 Inspected and repaired l/h front blinker fault removed and replace bulb tested ok	Workshop		\$0.00
12/03/2026	330,314 kms	C/o radiator core. R-3057 Drained coolant out of system, removed all pipes, removed condenser and removed inner cooler. Removed radiator and installed new radiator and replaced removed equipment. Filled system back up with coolant and ran truck till thermostat. Refilled with coolant.	Workshop		\$1,591.05

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
21/01/2026	323,473 kms	Satellite Tracking R-3001 Inspected and repaired satellite not working. Trouble shoot finding failed voltage protection unit. Replaced unit and fitted voltage reducer, reassembled tested - OK.	Workshop		\$237.83
21/01/2026	323,473 kms	A - A S-15971 Carried out A service as per service checklist			\$80.00
12/01/2026	321,973 kms	B - B S-15945 Carried out A B service as per service checklist. Changed engine oil and filters, changed fuel filters, greased and general inspection. Checked belts and pulleys - OK. Steam cleaned chassis.	Workshop		\$434.56
12/01/2026	321,973 kms	A - A S-15944 Carried out A service as per service checklist			\$80.00
24/12/2025	320,063 kms	water pump R-2964 Inspected and repaired coolant leak finding water pump leaking. Drained coolant and replaced water pump and coolant hoses. Reassembled engine refilled with coolant started and tested - OK.	Workshop		\$1,361.99
24/12/2025	320,063 kms	A - A S-15880 Carried out A service as per service checklist			\$80.00
10/12/2025		Fit and dispose T-890 Fit and dispose of one tyre	Clarence Valley Tyres	108074	\$77.00
08/12/2025	316,590 kms	rear tail light R-2931 Inspected l/h rear brake lights not working removed and replaced light assembly and bulbs tested ok	Workshop		\$160.00
01/12/2025	315,480 kms	A - A S-15717 Carried out A service as per service checklist			\$80.00
18/11/2025	313,366 kms	A - A S-15628 Carried out A service as per service checklist			\$80.00
18/11/2025	313,366 kms	low brake pads R-2900 Inspected and replaced low brake pads on drive axle. Removed and replaced both side brake pads adjusted and tested OK.	Workshop		\$1,404.59
18/11/2025	313,366 kms	Brake pads R-2899 Inspected and repaired low brake pads rear lazy axle. Removed and replaced brake pads. Both sides adjusted brakes to spec tested OK. Als removed and replaced some body mount bolts to chassis.	Workshop		\$429.65
11/10/2025	306,227 kms	windscreen repair R-2839 Coffs city auto glass removed and replaced windscreen	City Autoglass		\$0.00
29/09/2025	305,428 kms	A - A S-15481 Carried out A service as per service checklist			\$80.00
15/09/2025	305,223 kms	A - A S-15318 Carried out A service as per service checklist			\$80.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
12/09/2025	304,270 kms	Low front steer brakes R-2785 Inspected and repaired low brakes on steer. Jacked up, removed wheels and removed and replaced R/H & L/H front steer brake PADS and wiring indicators for low brake alarm. Adjusted brakes and tested OK.	workshop		\$315.29
26/08/2025	304,270 kms	A - A S-15317 Carried out A service as per service checklist			\$80.00
15/08/2025	302,520 kms	B - B S-14976 Carried out B Service as per service checklist. Changing engine oil and filters, changed fuel filters, inspected belt & pulleys OK. Checked coolant hoses - OK. Steam cleaned chassis.	Workshop		\$634.67
11/08/2025	302,520 kms	A - A S-15316 Carried out A service as per service checklist			\$80.00
17/07/2025		Longmarch T-761 Supply and fit one tyre , wheel balance and dispose	Clarence Valley Tyres	1074665	\$599.00
16/06/2025	295,874 kms	clearance light R-2626 Inspected and repaired clearance light not working removed and replaced l/h front top body clearance light ,tested new light ok	workshop		\$160.00
03/06/2025	295,309 kms	Oil leak R-2679 Inspected and repaired oil leak and L/H side of block behind cooler and filter housing - drained coolant and removed filter housings, fuel and oil, cleaned parts and reassembled replacing coolant hose, orings and seals and reassembling cooler mounting bolts. Refill with coolant, started and tested OK.	workshop		\$1,186.00
03/06/2025	295,309 kms	A - A S-14644 Carried out A service as per service checklist			\$80.00
22/05/2025	294,620 kms	Cab won't jack up. R-2582 Trouble shoot cab jack fault. Swap over parts from R05 to R12. Finding faulty cab jack parts ordered - refitted to truck and tested ok.	Workshop		\$2,115.15
15/05/2025	294,620 kms	tail light fault R-2572 Inspected and repaired brake light not working removed and replaced bulb as required tested ok	workshop		\$0.00
15/05/2025	294,620 kms	A - A S-14539 Carried out A service as per service checklist			\$0.00
08/04/2025	291,339 kms	A - A S-14437 Carry out A service as per service checklist also trouble shoot a/c fan not working ,diagnose faulty fan removed and replaced a/c fan tested ok			\$0.00
03/04/2025	290,812 kms	A - A S-14281 Carry out A service as per service checklist also fitted new radio Arial steam clean chassis			\$0.00
31/03/2025	290,812 kms	A - A S-14275 Carry out A service as per service checklist			\$0.00
31/03/2025	290,812 kms	C - C Service S-14362 Carry out C service as per service checklist also road test vehicle checking max speed set to 100kms ok			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/03/2025	288,544 kms	A - A S-14082 Carry out A service as per service checklist			\$0.00
05/03/2025	287,779 kms	A - A S-14071 Carry out A service	Workshop		\$0.00
05/03/2025	287,779 kms	engine oil leak R-2508 Inspected and cleaned engine oil leak monitor condition	workshop		\$0.00
28/02/2025		hazard light R-2483 Installed new anteo hazard light Part no. 00395459	Workshop		\$0.00
27/02/2025	286,363 kms	A - A S-14070 Carry out A service	Workshop		\$0.00
20/02/2025		Puncture repair T-655 Puncture repair	Clarence Valley Tyres	1068514	\$77.00
18/02/2025	285,858 kms	A - A S-14072 Carry out A Service	workshop		\$0.00
21/01/2025	281,664 kms	A - A S-13913 Carry out A service as per service checklist also inspected and repaired both side curtain rollers and replacing bearings as required			\$0.00
21/01/2025	281,664 kms	B - B S-13914 Carry out B service as per service checklist changing engine oil and filters steam clean chassis			\$0.00
14/01/2025	280,593 kms	A - A S-13911 Carry out A service as per service checklist also removed and replaced passenger side step and washer bottle reassembled to spec steam clean chassis			\$0.00
08/01/2025		rotate tyres T-635 Rotate two tyres	Clarence Valley Tyres	1066681	\$44.00
17/12/2024	276,247 kms	blinker insert R-2456 Removed and replaced l/h front side blinker assembly tested ok	Workshop		\$0.00
12/12/2024		Haulmax 275/70R 22.5 T-610 Supply and fit four new tyres and dispose of tyres	Clarence Valley Tyres	1065587	\$2,272.00
10/12/2024	275,314 kms	alternator R-2422 Trouble shoot battery light staying on dianose faulty alternator ,parts ordered removed and replaced alternator tested ok	Workshop		\$0.00
10/12/2024	275,314 kms	A - A S-13719 Carry out A service as per service checklist steam clean chassis			\$0.00
27/11/2024	273,442 kms	A - A S-13683 Carry out A service as per service checklist			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
20/11/2024	272,532 kms	A - A S-13528 Carry out A service as per service checklist also repaired rear tail light replacing glob			\$0.00
04/11/2024	269,824 kms	A - A S-13477 Carry out A service as per service checklist			\$0.00
10/10/2024	265,577 kms	A - A S-13476 Carry out A service as per service checklist			\$0.00
09/09/2024	262,907 kms	B - B S-13093 Carry out B service as per service checklist changing engine oil and filters and steam clean chassis			\$0.00
09/09/2024	262,907 kms	A - A S-13092 Carry out A service as per service checklist also removed and replaced oil temp sender wiring and plug connector tested ok			\$0.00
29/07/2024	256,878 kms	brake fault R-2265 Inspected and repaired brake fault finding wiring fault at oil temp sender repaired temporary parts ordered	Workshop		\$0.00
16/07/2024	255,234 kms	step loose R-2249 Inspected and repaired loose step tightened up and tested ok	Workshop		\$0.00
16/07/2024	255,490 kms	A - A S-12877 Carry out A service as per service checklist			\$0.00
05/07/2024	253,558 kms	golbs tail light R-2234 Inspected and repaired blown brake light globs removed and replaced as required	Workshop		\$0.00
14/06/2024	251,038 kms	A - A S-12876 Carry out A service as per service checklist also repaired stop light glob			\$0.00
11/06/2024	250,276 kms	A - A S-12875 Carry out A service as per service checklist			\$0.00
11/06/2024	249,763 kms	brake light R-2213 Inspected and repaired brake light fault finding poor connection cleaned and tested ok	Workshop		\$0.00
06/06/2024	249,499 kms	A - A S-12874 Carry out A service as per service checklist			\$0.00
28/05/2024	248,232 kms	glob tail light R-2214 Inspected and repaired tail light fault finding blown bulb replaced and tested ok	Workshop		\$0.00
20/05/2024	246,996 kms	A - A S-12603 Carry out A service as per service checklist			\$0.00
11/04/2024		Haulmax 275/70R 22.5 T-475 Supply and fit four new tyres. Dispose of two tyres	Clarence Valley Tyres	1056082	\$1,926.00
08/04/2024	241,997 kms	B - B S-12602 Carry out B service as per service checklist hanging engine oil and filters and steam clean chassis			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
08/04/2024	241,997 kms	A - A S-12601 Carry out A service as per service checklist			\$0.00
08/04/2024	241,762 kms	tail light glob R-2148 Inspected and repaired tail light fault removed and replaced glob tested ok	Workshop		\$0.00
12/03/2024	237,565 kms	A - A S-12091 Carry out A service as per service checklist			\$0.00
12/03/2024		C - C Service S-12092 Carry out C service as per service checklist also road test vehicle and check max road speed set to 100 kms set ok			\$0.00
08/03/2024	236,580 kms	tyres R-2124 Vehicle take to CVT for repair and tyres changed out as required	CVT		\$0.00
07/03/2024		Fit and dispose T-455 Fit and dispose of tyre	Clarence Valley Tyres	1054688	\$77.00
29/02/2024	233,550 kms	Broken belt R-2104 -ATTEND ROADSIDE BREAKDOWN AT CASINO. -REPORTED FAULT FAN BELT FAILURE. -INSPECTED AND DIAGNOSE AS FAN BELT FAILURE DUE TO BEING SEIZED BELT TENSIONER. -FITTED SUPPLIED TENSIONER AND BELT. -TESTED ALL OK.	Southside Truck Centre	J31546	\$1,241.22
27/02/2024	235,391 kms	A - A S-12090 Carry out A service as per service checklist			\$0.00
15/02/2024	232,549 kms	blinker fault R-2106 Inspected and repaired blinker light replacing light assembly	Workshop		\$0.00
10/01/2024		BFGoodrich 295/80R T-413 Supply and fit two tyres and wheel balance	Clarence Valley Tyres	1052253	\$1,418.00
28/11/2023	219,726 kms	B - B S-11957 Carry out B service as per service checklist changing engine oil and filters and steam clean chassis			\$0.00
28/11/2023	219,726 kms	A - A S-11956 Carry out A service as per service checklist			\$0.00
28/11/2023	218,327 kms	tail light fault R-2067 Inspected and repaired tail light fault replacing bulbs	Workshop		\$0.00
12/10/2023	211,599 kms	A - A S-11359 Carry out A service as per service checklist			\$0.00
12/10/2023	211,599 kms	golbs tail light R-1981 Inspected and repaired tail light fault removed and replaced x tail light globbs tested ok	Workshop		\$0.00
06/10/2023	209,334 kms	tail lights R-1988 Inspected and repaired as required replacing globbs	Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
04/10/2023		rotate tyres T-366 Rotate tyres	Clarence Valley Tyres	1047825	\$33.00
25/09/2023	208,258 kms	curtain repairs R-1963 Inspected and repaired curtain body replacing rivets in side curtains	Workshop		\$0.00
14/09/2023	206,719 kms	tail light globs R-1960 Inspected and repaired tail light fault ,removed and replace globs as required	Workshop		\$0.00
06/09/2023	205,651 kms	A - A S-11030 Carry out A service as per service checklist			\$0.00
30/08/2023	203,991 kms	brake light fault R-1946 Inspected and repaired brake light faults ,replaced bulbs testing ok	Workshop		\$0.00
28/08/2023	203,535 kms	A - A S-11029 Carry out A service as per service checklist			\$0.00
18/07/2023	196,513 kms	B - B S-10913 Carry out B service as per service checklist changing engine oil and filters also changing out gearbox oil and filters steam clean chassis			\$0.00
18/07/2023	196,513 kms	A - A S-10912 Carry out A service as per service checklist			\$0.00
20/06/2023	191,561 kms	reverse camera R-1887 Inspected and repaired reverse camera not working ,diagnose rear camera faulty ,removed and replaced tested ok	Workshop		\$0.00
14/06/2023	190,658 kms	A - A S-10592 Carry out A service as per service checklist			\$0.00
08/05/2023	184,297 kms	A - A S-10591 Carry out A service as per service checklist			\$0.00
17/04/2023	177,924 kms	Ad Blue fault with guage and de rates R-1838 Removed all lines, hoses and wiring and Ad Blue tank out of Chassis. Refit tank into chassis and reconnect all components. Retested - no faults. All clear.	Southside Truck Centre	647411	\$2,218.08
03/04/2023	179,078 kms	A - A S-10590 Carry out A service as per service checklist			\$0.00
08/03/2023	176,162 kms	B - B S-10589 Carry out B service as per service checklist changing engine oil and filters			\$0.00
08/03/2023	176,162 kms	A - A S-10588 Carry out A service as per service checklist			\$0.00
06/02/2023	172,990 kms	A - A S-10120 Carry out A service as per service checklist			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
06/02/2023	172,990 kms	C - C Service S-10111 Carry out C service as per service checklist			\$0.00
23/01/2023	170,971 kms	A - A S-10119 Carry out A service as per service checklist			\$0.00
11/01/2023	168,991 kms	A - A S-9793 Carry out A service as per service checklist			\$0.00
15/11/2022	158,751 kms	A - A S-9792 Carry out A service as per service checklist			\$0.00
02/11/2022	156,680 kms	A - A S-9480 Carry out A service as per service checklist			\$0.00
02/11/2022	156,680 kms	B - B S-9481 Carry out B service as per service checklist changing engine oil and filters also changed fan belt and tensioner cleaned and tested ok			\$0.00
20/10/2022	154,753 kms	A - A S-9411 Carry out A service as per service checklist also steam clean chassis			\$0.00
05/10/2022	152,189 kms	A - A S-9323 Carry out A service as per service checklist			\$0.00
29/09/2022	150,143 kms	oil leak R-1727	Southside Truck Centre	644517	\$748.78
27/09/2022	150,255 kms	air leak R-1778 Inspected air leak finding loose fitting resealed and checked for leaks ok	Workshop		\$0.00
02/09/2022	148,683 kms	A - A S-9153 Carry out A service as per service checklist also fitted new r/h side front indicator cleaned and tested			\$0.00
23/08/2022	146,129 kms	brake bulb R-1777 Removed and replace brake bulb tested ok	Workshop		\$0.00
09/08/2022	143,975 kms	air leak R-1718 Inspected and repaired air leak in air system finding loose clamps	Workshop		\$0.00
09/08/2022	143,975 kms	A - A S-8910 Carry out A service as per service checklist			\$0.00
30/06/2022	137,884 kms	B - B S-8909 Carry out B service as per service checklist changing engine oil and filters ,also steam clean chassis			\$0.00
30/06/2022	137,884 kms	A - A S-8908 Carry out A service as per service checklist			\$0.00
09/05/2022	130,497 kms	A - A S-8907 Carry out A service as per service checklist			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
19/04/2022	127,411 kms	A - A S-8366 Carry out A service as per service checklist also steam cleaned chassis			\$0.00
16/03/2022	122,248 kms	A - A S-8121 Carry out A service as per service checklist			\$0.00
01/02/2022	118,072 kms	A - A S-8120 Carry out A service as per service checklist			\$0.00
01/02/2022	118,072 kms	C - C Service S-8226 Carry out C service as per service checklist also checking max road speed limiter ok			\$0.00
11/01/2022	115,296 kms	B - B S-7808 Carry out B service as per service checklist changing engine oil and filters also steam clean chassis			\$0.00
11/01/2022	115,296 kms	A - A S-7807 Carry out A service as per service checklist			\$0.00
06/12/2021	109,574 kms	A - A S-7806 Carry out A service as per service checklist			\$0.00
03/11/2021	104,127 kms	A - A S-7506 Carry out A service as per service checklist			
05/10/2021	98,927 kms	A - A S-7384 Carry out A service as per service checklist also steam clean chassis			
07/09/2021	94,970 kms	A - A S-7329 Carry out A service as per service checklist also steam clean chassis			
31/08/2021	93,653 kms	B - B S-7229 Carry out B service as per service checklist changing engine oil and filters also steam clean chassis			
02/08/2021	89,633 kms	A - A S-7152 Carry out A service as per service checklist also steam clean chassis			
21/07/2021	87,410 kms	brake pads R-1436 Investigate noise in l/h front steer ,finding broken pad spring locator ,removing and replacing with new pads	Workshop		
02/07/2021	84,435 kms	A - A S-7082 Carry out A service as per service checklist			
02/06/2021	79,732 kms	A - A S-6861 Carry out A service as per service checklist also steam clean chassis			
13/05/2021	76,024 kms	A - A S-6782 Carry out A service as per service checklist			
21/04/2021	73,245 kms	B - B S-6696 Carry out B service as per service checklist changing engine oil and filters also truck sent to volvo for engine fault			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
06/04/2021	71,340 kms	A - A S-6649 Carry out A service as per service checklist			
19/03/2021		air leaks R-1371 Inspected and repaired air leak as required	workshop		
09/02/2021	63,853 kms	A - A S-6395 Carry out A service as per service checklist			
09/02/2021	63,853 kms	A - A S-6364 Carry out A service as per service checklist			
07/01/2021	58,864 kms	A - A S-6361 Carry out A service as per service checklist			
16/12/2020	55,642 kms	B - B S-6199 Carry out B service as per service checklist changing engine oil and filters ,also changing air cleaner ,steam clean chassis ,also changing out l/h rear tail light assembly			
16/12/2020	75,642 kms	C - C Service S-6499 Carry out C service as per service checklist also checking road speed limiter ok			
08/12/2020	54,175 kms	A - A S-6193 Carry out A service as per service checklist			
03/11/2020	48,887 kms	A - A S-6038 Carry out A service as per service checklist also stem clean chassis			
13/10/2020	45,716 kms	A - A S-5964 Carry out A service as per service checklist also steam clean chassis			
01/09/2020	39,279 kms	A - A S-5827 Carry out A service as per service checklist			
17/08/2020		brake light R-1152 Inspected and repaired brake light replacing l/h rear lower brake bulb tested ok	Workshop		
12/08/2020	36,810 kms	B - B S-5826 Carry out B service as per service checklist changing engine oil and filters			
11/08/2020	36,675 kms	A - A S-5825 Carry out A service as per service checklist			
01/07/2020	31,232 kms	A - A S-5553 Carry out A service as per service checklist			
16/06/2020	28,895 kms	A - A S-5552 Carry out A service as per service checklist			
21/05/2020		A - A S-5400			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
13/05/2020		loose exhaust guard R-1100 Inspected and listened for noise ,finding loose guard on exhaust ,tightened also inspected for air noise vehicle road tested sounds normal , under normal driving conditions if opperator still has concerns about noise will get southsides to listen to	Workshop		
05/05/2020	23,248 kms	A - A S-5361 Carry out A service as per service checklist			
02/04/2020	19,286 kms	A - A S-5360 Carry out A service as per service checklist			
18/03/2020	17,140 kms	B - B S-5152 Carry out B service as per service checklist changing eninge oil and filters			
09/03/2020	15,956 kms	blinker R-1041 inspected and repaired l/h side blinker cab ,removing and replacing testing ok	Workshop		
09/03/2020	15,956 kms	A - A S-5151 Carry out A service as per service sheet checklist			
09/03/2020	15,956 kms	headlight R-1042 Light inspected and repaired ,replacing unit due to lense broken tested light operation ok	Workshop		
04/02/2020	11,036 kms	A - A S-5086 Carry out A service as per service checklist			
28/01/2020		secure rubber R-999 secured rubber in place with glue	Workshop		
11/12/2019	3,506 kms	A - A S-4807 Carry out A service as per service checklist			
166 Records				Total:	\$24,610.11