

# Vehicle History Detail

Fleet #	YQ10VN
Registration	YQ10VN
Make	ATE
Model	
VIN / Chassis #	6X9190725KM006246

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1380	22/10/2024			Hatch Seal	Liquip sales QLD			\$691.50
S-567	19/09/2024	0	0	B - B Service	Brisbane Workshop	b service black flap at front ripped rhf shock loose air leaks, bungs and clamps air lines rubbed through under ttable. lhm inner tyre		\$750.00
T-315	18/09/2024	0	0	RUNOUT	Brisbane Workshop			\$125.00
S-485	26/07/2024	0	0	B - B Service	Brisbane Workshop	b service air leaks tyres shocks loose x 4 mudflaps		\$619.24
T-277	26/07/2024	0	0	New	Brisbane Workshop	replaced rear axle with new tyres		\$1,690.82
T-236	28/05/2024	0	0	New	Brisbane Workshop	replaced ML and MR outer tyres and matched old tread		\$845.41
S-392	28/05/2024	0	0	B - B Service	Brisbane Workshop	b service lights tyres		\$812.50
R-1239	26/04/2024	0	0	AIR LEAK	Brisbane Workshop	chnaged leaking fitting at t bar		\$62.50

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-243	30/01/2024	204871	0	C - C Service	Brisbane Workshop	carried out C service. removed cleaned bearings. found bearings to be worn replaced with grease. replaced all brake shoes and drums. replaced middle right hand shocker. replaced right hand front and left hand middle shocker bushes. kit turntable	5598276 - 5600219	\$8,521.04
S-200	05/01/2024	204871	0	B - B Service	Brisbane Workshop	fire extinguishers out of date-replaced washer on ride height valve too big-replaced		\$312.50
R-855	18/09/2023	0	0	Chassis	Brisbane Workshop	Cut huk bolts off Removed and replaced with 5/8 bolts		\$385.18
R-835	11/09/2023	169834	0	Shock Absor	Brisbane Workshop	Replaced shock on rear RH side Replaced shock on middle LH side		\$726.89
S-103	11/09/2023	0	0	B - B Service	Brisbane Workshop	Replaced LH turn table pad (Lucas Jensen) Fixed rail on RH side (Lucas Jensen)		\$187.50
R-273	05/04/2023	100219	0	Road Worthy Certificate Repairs, Road Worthy Inspection	ALL MAITENANCE TRUCK SPECIALISTS	Brake Roller Test Per Axle HVRAS Rego Assessment Certificate of Inspection (HT-3.1198315-5)	219999	\$1,294.21
<b>14 Records</b>							<b>TOTAL:</b>	<b>\$17,024.29</b>