

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
6598

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Quarterly Inspection - Elevated Work Platform - Mechanical Check / Service				
History Description	Quarterly Inspection - Elevated Work Platform - Mechanical Check / Service				
	-	Inspection Completed			
	-	Safety Checks Completed			
	-	Structural Checks Completed			
	-	Machine Greased			
	-	Oil Levels Checked			
	-	Underbody Inspected			
	-	Components Check Completed			
	-	Function Checks Completed			
Downtime	1.50	Hours	Estimated Costs		Actual Costs
Repair Time	1.50	Hours	Labour	\$240.00	\$180.00
Date Complete	7/08/2024		Material	\$0.00	\$0.00
Component Code	GS		Other	\$0.00	\$0.00
Account Code	45860		Total	\$240.00	\$180.00
Job Type	INSP				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Ibarra Baylin	3/07/2024	0.00	15/07/2024	1.50
HDF		3/07/2024	2.00		0.00

Tasks

No	Description	Completed	Type	Reading	Contact Name
1	Transmission Belt - Check	☒			
2	Differentials Oil - Check	☒			
3	Wheel Reduction Gears Oil - Check	☒			
4	Turret Rotation Slewing Ring Gear - Check Reduction Gear Oil Level	☒			
5	Dropbox Oil - Check	☒			
6	Air Filters - Check - Replace If Needed	☒			

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
7545

Asset EA-EWP-EWP006

2023 - Dingli - 60ft - Diesel Rough Terrain
Articulating Boom Lift - BA20RT

Site 45860 - Project Energy
Connect (PEC)

Project Energy Connect (PEC)

Job Description

History Description removed & replaced basket beacon light
test all functions - ok

Downtime	0.00	Hours		Estimated Costs	Actual Costs
Repair Time	1.00	Hours	Labour	\$120.00	\$120.00
Date Complete	22/07/2024		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$120.00	\$120.00
Job Type	BREAK				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Ibarra Baylin		1.00	22/07/2024	1.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
9345

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Carry out 3 monthly inspection.				
History Description	Carry out 3 monthly inspection.				
	-	Inspection Completed			
	-	Safety Checks Completed			
	-	Structural Checks Completed			
	-	Machine Greased			
	-	Oil Levels Checked			
	-	Underbody Inspected			
	-	Components Check Completed			
	-	Function Checks Completed			
Downtime	1.50	Hours	Estimated Costs		Actual Costs
Repair Time	1.50	Hours	Labour	\$0.00	\$180.00
Date Complete	11/10/2024		Material	\$0.00	\$0.00
Component Code	Ins		Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$180.00
Job Type	INSP				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
LVM	Michael Coppola		0.00	11/10/2024	1.50

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
9438

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Carry out annual onboarding inspection.				
History Description	Carry out annual onboarding inspection.				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	0.00	Hours	Labour	\$0.00	\$0.00
Date Complete	2/11/2024		Material	\$0.00	\$0.00
Component Code	Ins		Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$0.00
Job Type	INSP				

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
9737

Asset P&E WORKSHOP C6 P&E WORKSHOP (TIME SHEET)
Site 45860 - Project Energy Connect (PEC) Project Energy Connect (PEC)

Job Description

History Description EWP001, EWP002, EWP003, EWP004, EWP005 & EWP006
carried out RCD testing with graham/sparky at substation

Downtime	0.00	Hours		Estimated Costs	Actual Costs
Repair Time	3.00	Hours	Labour	\$360.00	\$360.00
Date Complete	14/10/2024		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$360.00	\$360.00
Job Type	GM				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
LVM	Michael Coppola		3.00	14/10/2024	3.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
10634

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Quarterly Inspection - Elevated Work Platform - Mechanical Check / Service				
History Description	Quarterly Inspection - Elevated Work Platform - Mechanical Check / Service • Inspection Completed • Safety Checks Completed • Structural Checks Completed • Machine Greased • Oil Levels Checked • Underbody Inspected • Components Check Completed • Function Checks Completed				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	2.00	Hours	Labour	\$240.00	\$240.00
Date Complete	18/01/2025		Material	\$0.00	\$0.00
Component Code	GS		Other	\$0.00	\$0.00
Account Code	45860		Total	\$240.00	\$240.00
Job Type	INSP				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
LVM	Michael Coppola	15/10/202	0.00	18/01/2025	2.00
HDF		15/10/202	2.00		0.00

Tasks

No	Description	Completed	Type	Reading	Contact Name
1	Transmission Belt - Check	☒			
2	Differentials Oil - Check	☒			
3	Wheel Reduction Gears Oil - Check	☒			
4	Turret Rotation Slewing Ring Gear - Check Reduction Gear Oil Level	☒			
5	Dropbox Oil - Check	☒			
6	Air Filters - Check - Replace If Needed	☒			

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
14285

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Check and repair battery descent fault - Alarm is going off				
History Description	Check and repair battery descent fault - Alarm is going off				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	9.00	Hours	Labour	\$0.00	\$1080.00
Date Complete	12/04/2025		Material	\$0.00	\$0.00
Component Code	ELEC		Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$1080.00
Job Type	GM				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Ibarra Baylin		0.00	12/04/2025	9.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
14358

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Carry out 3 monthly inspection				
History Description	Carry out 3 monthly inspection				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	1.50	Hours	Labour	\$0.00	\$180.00
Date Complete	21/04/2025		Material	\$0.00	\$0.00
Component Code	Ins		Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$180.00
Job Type	INSP				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Michael Albanese		0.00	21/04/2025	1.50

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
14389

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Replace battery and isolator				
History Description	Replace battery and isolator				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	4.50	Hours	Labour	\$0.00	\$540.00
Date Complete	19/04/2025		Material	\$0.00	\$0.00
Component Code	ELEC		Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$540.00
Job Type	GM				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
LVM	Michael Coppola		0.00	15/04/2025	2.00
HDF	Michael Albanese		0.00	19/04/2025	2.50

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
16105

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Carry out general inspection on ewp				
History Description	Carry out general inspection on ewp				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	1.00	Hours	Labour	\$0.00	\$80.00
Date Complete	27/06/2025		Material	\$0.00	\$0.00
Component Code	Ins		Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$80.00
Job Type	INSP				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
TA	Daniel Roberts		0.00	27/06/2025	1.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
16274

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Yearly Inspection				
History Description	Yearly Inspection				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	4.00	Hours	Labour	\$0.00	\$480.00
Date Complete	30/06/2025		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$480.00
Job Type	INSP				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Ibarra Baylin		0.00	30/06/2025	4.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
16277

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	Yearly Onboarding Inspection				
History Description	Yearly Onboarding Inspection				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	0.00	Hours	Labour	\$120.00	\$120.00
Date Complete	10/07/2025		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$120.00	\$120.00
Job Type	INSP				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Ibarra Baylin		1.00		1.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
16846

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description					
History Description	250Hr Service				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	4.00	Hours	Labour	\$0.00	\$480.00
Date Complete	30/06/2025		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$480.00
Job Type	GM				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Ibarra Baylin		0.00	30/06/2025	4.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
19822

Asset	EA-EWP-EWP006	2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT			
Site	45860 - Project Energy Connect (PEC)	Project Energy Connect (PEC)			
Job Description	wont start				
History Description	wont start				
Downtime	0.00	Hours		Estimated Costs	Actual Costs
Repair Time	1.00	Hours	Labour	\$0.00	\$120.00
Date Complete	5/10/2025		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$120.00
Job Type	BREAK				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
HDF	Matthew Peterson	5/10/2025	0.00	5/10/2025	1.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
20476

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	battery isolator inop				
History Description	battery isolator inop				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	1.50	Hours	Labour	\$0.00	\$120.00
Date Complete	29/10/2025		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$120.00
Job Type	BREAK				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
TA	Brendan Micallef	29/10/202	0.00	29/10/2025	1.50

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
20870

Asset	EA-EWP-EWP006		2023 - Dingli - 60ft - Diesel Rough Terrain Articulating Boom Lift - BA20RT		
Site	45860 - Project Energy Connect (PEC)		Project Energy Connect (PEC)		
Job Description	beacon light in-op				
History Description	beacon light in-op				
Downtime	0.00	Hours	Estimated Costs		Actual Costs
Repair Time	1.00	Hours	Labour	\$0.00	\$120.00
Date Complete	22/11/2025		Material	\$0.00	\$0.00
Component Code			Other	\$0.00	\$0.00
Account Code	45860		Total	\$0.00	\$120.00
Job Type	BREAK				

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
LVM	Don Tuckwell	22/11/202	0.00	22/11/2025	1.00

Work Order History

Elecnor Australia

26-Jun-2026



Work Order No
22329

Asset EA-EWP-EWP006

2023 - Dingli - 60ft - Diesel Rough Terrain
Articulating Boom Lift - BA20RT

Site 45860 - Project Energy
Connect (PEC)

Project Energy Connect (PEC)

Job Description

History Description 500HR Service
- 90 day inspection
- Annual inspection

Downtime 0.00

Hours

Estimated Costs

Actual Costs

Repair Time 6.00

Hours

Labour

\$0.00

\$480.00

Date Complete 9/03/2026

Material

\$0.00

\$0.00

Component Code

Other

\$0.00

\$0.00

Account Code 45860

Total

\$0.00

\$480.00

Job Type PM

Trades Information

Trade Code	Name	Due Start	Est Duration	Date Started	Act Duration
TA	Nick Boromeo		0.00	9/03/2026	6.00