

For Maintenance Recorded Between: 1/01/2006 and 21/05/2026

Asset ID	Asset Description	Date Acquired	Maintenance Date	Maintenance Performed By	Maintenance Description	Maintenance Cost
312	305E Excavator	3/11/2014	3/07/2015	Doug Armistead	First Service @ 366Hrs as per Maintenance Manual	\$451.00
			17/12/2015	Doug Armistead	Service @ 616 hours	\$475.00
			10/05/2016	Doug Armistead	Service @ 860 hours	\$492.00
			18/07/2016	William Adams Cat	1 x Cap Fuel	\$109.20
			2/08/2016	Colac Hydraulic Hose	Hydraulic hose repairs	\$318.19
			22/08/2016	Lucky & Steven	Change engine & final drive oils, did sos.	\$806.01
			22/08/2016	Phillip Kurzman & Steven Kurzman	1000hr service @ 981.1hrs. Replaced final drive oils and engine oil. Did SOS samples. Replaced air filters outer and inner, cabin air filter, fuel air filter and accumulator filter.	\$360.00
			22/08/2016	Phillip & Steven Kurzman	Change Final Drive Oils, Change Engine Oil and do SOS Samples	\$400.00
			25/08/2016	William Adams	Supply parts - Element and engine oil filter.	\$70.33
			25/08/2016	William Adams	Supply parts - SOS - oils sample kit	\$682.00
			1/09/2016	GM Risk assessment services	Risk Assessment Report	\$148.50
			28/07/2017	William Adams	Hydraulic ram rod and seal kit.	\$1,648.60
			29/07/2017	Lewie EE 3hrs + parts	Repair bucket ram - replace ram rod and seals.	\$1,854.10
			4/08/2017	William Adams	Filter supply - PRO70152814	\$77.22
			8/08/2017	Steven	Service @ 1293hrs 250hr interval service - Replaced filters, oil and greased. Safety check.	\$197.60
			7/01/2018	Colac Hydrohose	Replace broken hydraulic hose	\$151.39
			7/01/2018	Colac Hydrohose	Replace broken hydraulic hose	\$151.39
			13/04/2018	Steven	250hr service @ 1561hrs - Replace oil, filters, greased and cleaned.	\$196.41
			28/05/2018	Tyrone	Repairs to quick hitch.	\$205.50
			12/09/2018	Tyrone	250hr Service @ 1884hrs. Replaced engine oil & filter. Grease machine. Rotate pins and welded wear points on hitch and mud bucket. Tyrone 8hrs.	\$600.25
			20/09/2018	Burson	Supply of replacement radio.	\$181.63
			27/11/2018	William Adams	Invoice # PRO70167470 - parts supply - filter element	\$30.24
			17/01/2019	William Adams	Invoice # PR070168917 - Replacement relay assembly	\$132.40
			17/01/2019	Tyrone	Replaced air con relay and cleaned and inspected machine. Tyrone 4hrs	\$274.00
			22/03/2019	Wal Miller	250hr service @ 2028hrs. Wal 8hrs	\$548.00
			29/03/2019	William Adams	Invoice#PR070171402 - Filter	\$34.66
			15/07/2019	GM Risk Assessments	Machine Risk Assessment	\$128.50
			11/09/2019	MaxiParts	Invoice#PR070176455 - Roller	\$383.02
			14/11/2019	Simon McKenzie	Replaced support roller. Simon McKenzie 4hrs	\$274.00
			17/04/2020	Warren Miller	Repairs Woll 2hrs	\$200.00
			21/05/2020	Phillip Kurzman	Wash and grease.	\$300.00
			9/07/2020	William Adams	Invoice#PR070185640- Filter 1R-0739	\$15.54
			5/08/2020	Warren Miller	Service @ 2500hrs - 500hr interval service carried out - Replaced engine oil & filter, fuel filter. Checked track rollers and all fluid levels - ok. Woll 4hrs	\$454.00
			10/09/2020	Otway Touring Solutions	Machine Risk Assessment - annual assessment.	\$137.50
			8/10/2020	Otway Touring Solutions	Machine risk assessment and fire extinguisher check.	\$154.00
			16/10/2020	William Adams	Invoice#PR070188583 - Support roller	\$433.85
			19/10/2020	Warren Miller	Replaced support roller. Woll 1hr	\$100.00
			26/10/2020	William Adams	Invoice#PR070188782 - Filter	\$20.99
			8/07/2021	Warren Miller	Service @ 3000hrs. Woll 4hrs	\$400.00
			12/07/2021	William Adams	Invoice#P2PR0011203 - Filters for service.	\$73.44
			16/07/2021	JB Attachments	New tilt hitch attachment - JBA PowerLatch Tilt Hitch 5	\$9,735.00
			26/08/2021	Burson	Parts supply - 12V accessory plug for flashing light.	\$20.90

26/08/2021	Otway Touring Solutions	Mobile plant static risk assessment carried out.	\$132.00
30/08/2021	Warren Miller	Fixed boom work lights wiring per risk assessment identified fault.	\$100.00
21/09/2021	Colac Hydrhose	Replacement hydraulic hose connector	\$177.69
21/09/2021	Colac Hydrhose	Replacement hydraulic hose.	\$663.19
21/09/2021	Colac Hydrhose	Replacement hydraulic hose connector	\$184.38
22/09/2021	Warren Miller	Repaired boom hose and washed machine. Topped up oil levels. Wolll 6hrs	\$690.00
19/10/2021	William Adams	Invoice#P2PR005365 - Side mirror	\$136.90
22/10/2021	Warren Miller	Fitted new side mirror.	\$100.00
4/05/2022	ITR Victoria	Parts supply - replacement rubber tracks.	\$3,685.00
2/06/2022	Warren Miller	Replaced rubber tracks. Checked final drives and undercarriage.	\$400.00
5/07/2022	Colac Hydrhose	Replacement hydraulic hose	\$199.31
2/08/2022	Warren Miller	Service @ 3500hrs. Carried out logbook service. Replaced engine oil and filters. Repaired roof light. Woll 4hrs	\$442.25
4/08/2022	William Adams	Invoice#P2PR0172173 - Parts supply: filters and seals.	\$295.82
5/08/2022	William Adams	Invoice# P2PR0172746 - Parts supply: Pin assemblies	\$1,042.25
15/08/2022	Phillip Kurzman	Replaced teeth on 400mm & 600mm digging buckets.	\$455.00
22/08/2022	Pirtek Ballarat	Replaced hydraulic hose	\$628.49
26/08/2022	Warren Miller	Replaced pins and bushes. Woll 9hrs Lucky 5hrs	\$1,400.00
3/10/2022	Otway Touring Solutions	Machine static risk assessments and fire extinguisher check.	\$142.95
3/10/2022	Otway Touring Solutions	Machine static risk assessments and fire extinguisher check.	\$142.95
10/10/2022	ITR	Cutting edge for mud bucket	\$220.00
23/10/2022	RB Rural	Line boring of machine buckets for larger pins.	\$226.62
24/10/2022	William Adams	Emergency parts delivery charge	\$13.20
25/10/2022	William Adams	Invoice#P2PR0202807 - 2 x pins	\$246.05
27/10/2022	William Adams	Invoice# P2PR0203854 - Pins Part# 580-8465	\$492.10
27/10/2022	William Adams	Emergency supply service fee	\$72.60
27/10/2022	William Adams	Invoice# P2PR0203857 - Pin	\$123.02
29/10/2022	RB Engineering	Line boring of 5 tonner buckets	\$3,179.00
31/10/2022	William Adams	Invoice# P2PR0204694 - Pin Part# 580-8465	\$123.02
14/12/2022	Bunnings	Bolts and nuts for hitch repairs.	\$15.04
7/03/2023	Hydrhose	Fittings for hydraulic hose repair.	\$76.45
7/03/2023	Warren Miller	Repaired blown hydraulic hose. Woll 3hrs	\$300.00
13/04/2023	Warren Miller	Replaced fan belt, greased, fitted new pins to teeth on bucket.	\$500.00
14/04/2023	William Adams	Invoice#P2PR0268999 - V-Belt	\$52.95
19/04/2023	William Adams	Invoice#P2PR0270682 - Pin set for bucket teeth.	\$55.04
14/05/2023	William Adams	Invoice#P2PR0269564 - Belt 9L-1126	\$50.08
25/05/2023	Warren Miller	Filed service callout to re-fit track onto machine.	\$400.00
25/05/2023	William Adams	Parts supply - front glass window	\$613.89
29/05/2023	Warren Miller	Repaired blown hydraulic hose - Woll 1.5hrs	\$150.00
29/05/2023	Colac Hydrhose	Replacement hydraulic hose	\$204.50
30/05/2023	Warren Miller	Replaced broken windscreen, fan belt and fixed panel damage. Woll 7hrs	\$700.00
31/05/2023	Colac Windscreens	Fitted glass to window frame.	\$110.00
31/05/2023	Wqarren Miller	Service @ 4000hrs Carried out 500hr interval service. Replaced oil and filters. Fitted new windscreen and struts. New battery and starter motor repaired, New fan belts fitted. Replaced hydraulic hose. Fitted new retaining pin to boom. Woll 2hrs	\$794.90
31/05/2023	William Adams	Parts supply - front window strut/damper x 2	\$407.90
1/06/2023	Warren Miller	Removed and refitted repaired starter motor. Woll 6hrs	\$600.00
5/06/2023	Colac Electric Motor Co	Rebuild of starter motor.	\$164.00
6/06/2023	Burson	Replacement battery	\$195.80
7/06/2023	William Adams	Parts supply - Bearing sleeve, links and bushings.	\$1,744.60

16/10/2023	Otway Touring Solutions	Machine risk assessment and fire extinguisher check	\$137.50
16/10/2023	Otway Touring Solutions	Machine risk assessment and fire extinguisher check	\$137.50
17/10/2023	Warren Miller	Replaced head light globe and hazard light. Woll 1hrs	\$100.00
19/10/2023	Burson Auto Parts	Narva amber flashing light	\$154.00
20/10/2023	William Adams	Parts supply - seal O rings Part 6V-8398	\$3.27
27/10/2023	William Adams	Parts supply - Pipe assembly 283-2054	\$667.29
9/11/2023	Kevin Peucker Hydraulic Service	Hydraulic hose repair	\$286.67
13/11/2023	Warren Miller	Repaired hydraulic hose on boom.	\$200.00
12/01/2024	William Adams	Parts supply - fuel cap	\$165.33
24/01/2024	Warren Miller	Service @ 4567hrs. Replaced engine oil, oil filter, fuel filter. Cleaned air elements and cabin filter. Woll 2hrs Patrick 2hrs	\$345.40
10/04/2024	Tyrepower	Replacement battery	\$185.00
30/04/2024	William Adams	Parts supply - Filters Invoice#P2PR0411059	\$113.30
30/04/2024	William Adams	Filter and element partsInv No. P2PR0411059	\$113.30
7/05/2024	Warren Miller	Service @ 4867hrs. Carried out 500hr interval service. Changed engine oil and filter, fuel filters and hydraulic filter. Checked all other filters and oils.	\$417.90
7/06/2024	William Adams	Parts supply - Filters for serviceP2PR0426176	\$94.11
27/06/2024	William Adams	Parts supply - Seal kit	\$589.38
13/12/2024	Warren Miller	Service @ 5617hrs - Carried out 500hr interval service. Replaced engine oil and oil filter. Changed fuel filter. Topped up hydraulic oil. Woll 4hrs	\$440.00
16/12/2024	Colac Hydrhose	Replacement hydraulic hose	\$289.55
20/01/2025	Brylee Sheedy	Re-gassed aircon. Brylee 2hrs	\$176.00
13/02/2025	Brylee Sheedy	Removed and cleaned evaporator. Brylee 2.5hrs	\$220.00
11/03/2025	William Adams	Parts supply - Filters for next service	\$218.23
12/08/2025	Brylee and Patrick	Service @ Carried out 500hr interval service. Changed engine oil, oil filter, fuel filter. Changed hub oils. Checked cabin filters, air cleaner and battery terminals.	\$1,227.60
21/10/2025	Otway Touring Solutions	Machine risk assessment	\$159.50
31/10/2025	William Adams	Emergency parts order fee	\$45.10
28/11/2025	William Adams	Parts supply - Door roller- centre	\$322.63
5/01/2026	William Adams	Parts supply - front glass	\$644.68
6/01/2026	William Adams	Parts supply - 2 x rollers part# 250-1639	\$67.47
14/01/2026	Colac Windscreens	Fitted glass to frame	\$220.00
14/01/2026	Brylee Sheedy	Removed front window for glass replacement	\$200.00
22/01/2026	Brylee Sheedy	Refitted fron window assembly	\$100.00
18/03/2026	William Adams	Replacement fuel cap	\$163.88
18/03/2026	William Adams	Parts supply - filters for servicing	\$451.33
18/03/2026	William Adams	Infield replacement of air filters and fuel cap.	\$480.00
22/04/2026	Brylee Sheedy	Removed and refitted repaired starter motor.	\$300.00

*Sum Of MaintenanceCost:*

*\$54,551.22*