



CROSSIRON TRUCK & EQUIPMENT LTD.
 4153 ROAD 38 HARROWSMITH
 ONT CANADA K0H 1V0
 PARTS & SERVICE 613-372-6269
 AFTER HOURS 613-217-8600

INVOICE W 7791
 Date 06/30/25
 Date Open 05/16/25

Sold To : 453-7878 613	Ship To :
<div style="background-color:black; width:100%; height:15px; margin-bottom:5px;"></div> <div style="background-color:black; width:100%; height:15px; margin-bottom:5px;"></div> <div style="background-color:black; width:100%; height:15px; margin-bottom:5px;"></div>	

Written By BECKY	Terms CHGLST	Time 14:20:33	Customer Po #	Promised	Phone	Ship Via	
Unit # GREEN	Plate # BY72420	Year 2006	Make INTERNATION	Model EAGLE	Kilometer/Hrs 109723/39524.0	VIN 2HSCNAPR27C289319	Engine

Qty	Description	Price	Amount
	PERFORM ANNUAL SAFETY INSPECTION AS PER THE NEW ONTARIO DRIVE ON STANDARDS PULLED TRUCK IN SHOP AND ENTERED INFO TO TABLET, LOOKED TRUCK OVER, JACKED UP AND SET ON STANDS, REMOVED WHEELS AND DRUMS, INSPECTED AND RECORDED BRAKE AND TIRE MEASUREMENTS TO TABLET, FINISHED GOING THROUGH INSPECTION LIST AND ENTERED IN DEFECTS FOUND, PUT DRUMS AND WHEELS BACK ON AND ADJUSTED BRAKES, REMOVED STANDS AND TORQUED WHEELS, ENTERED REPAIRED ITEMS TO TABLET, PRINTED STICKER AND PUT ON, PUT RE TORQUE TAGS IN CAB. <i>Tech 486 # 6 Id 486</i>		660.00
1.000	NPN-CMVI CERTIFICATION STICKER # 71U0AC46	20.00	20.00
2.000	BOS19CA 19" WIPER BLADE	14.47	28.95
1.000	TEC101117B GLAD HAND SEAL BLUE -POLY W/SCREEN	4.56	4.56
1.000	TEC101117R GLAD HAND SEAL - POLY RED W/ SCREEN	4.56	4.56
	SubTotal		718.07
	REPLACE WORN REAR DRIVE AIR BAGS BOTH REAR DRIVE AIR BAGS WERE CUT TO CORDS, DUMPED SUSPENSION, DISCONNECTED AIR LINES AND CAPPED OFF, AIRED UP, UNBOLTED BAGS AND REMOVED, BOLTED NEW BAGS IN PLACE, DUMPED SUSPENSION, SWAPPED FITTINGS AND HOOKED LINES UP, AIRED UP. <i>Tech 486 # 6 Id 486</i>		132.00

I authorize the above repair work, including sublet work, to be done along with necessary materials. Crossiron Truck & Equipment LTD. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. Crossiron Truck & Equipment LTD. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.
 WHEEL NUTS MUST BE RE TORQUED WITHIN 150KM AFTER INSTALLATION
 NO RETURNS ON SPECIAL ORDER OR ELECTRICAL COMPONENTS
 20% RE STOCKING FEE ON RETURNED PARTS WITHIN 10 DAYS
 HST#73244 5291 RT0001

Parts..... 1013.65
 Labor..... 1815.00

TERMS: DUE UPON RECEIPT, 4% Interest per month on invoices past 30 days
 No returns after 10 days or on special order parts
 No returns

Sub Total 2828.65
 Sales Tax.... 367.72

Authorized By _____

TOTAL Continued



CROSSIRON TRUCK & EQUIPMENT LTD.
 4153 ROAD 38 HARROWSMITH
 ONT CANADA K0H 1V0
 PARTS & SERVICE 613-372-6269
 AFTER HOURS 613-217-8600

INVOICE W 7791
 Date 06/30/25
 Date Open 05/16/25

Sold To : 453-7878 613

Ship To :

[REDACTED]				[REDACTED]			
[REDACTED]				[REDACTED]			
[REDACTED]				[REDACTED]			

Written By BECKY	Terms CHGLST	Time 14:20:33	Customer Po #	Promised	Phone	Ship Via
---------------------	-----------------	------------------	---------------	----------	-------	----------

Unit # GREEN	Plate # BY72420	Year 2006	Make INTERNATION	Model EAGLE	Kilometer/Hrs 109723/39524.0	VIN 2HSCNAPR27C289319	Engine
-----------------	--------------------	--------------	---------------------	----------------	---------------------------------	--------------------------	--------

Qty	Description	Price	Amount
2.000	RIG9875RT AIR SPRING	139.84	279.68
2.000	WUR884.1469-6B AIR BRAKE 90 ELBOW 3/8T X 1/4P	5.11	10.22
	SubTotal		421.90
	REPAIR LIGHTS OUT RIGHT HEADLIGHT WAS FLASHING WITH SIGNAL, REMOVED HEADLIGHT AND FOUND BAD GROUND CONNECTION, REPAIRED WITH BUTT CONNECTOR AND SHRINK TUBE, REVERSE LIGHT AND RIGHT TAIL LIGHT WERE OUT, FOUND ROTTEN WIRES AND REPAIRED, DASH LIGHTS WERE NOT WORKING, REMOVED SWITCH PANEL UNPLUGGED LIGHT SWITCH AND TESTED POWER, WHEN I PLUGGED BACK IN LIGHTS STARTED WORKING, REPLACED 2 LIGHT BULBS IN LEFT SIDE GAUGES. Tech 486 # 6 Id 486		165.00
2.000	WUR720.194000 14V-3.78W MINI T3 1/4 WEDGE N194	1.08	2.17
	SubTotal		167.17
	REPAIR LOOSE DASH PANEL DASH PANEL THAT BRAKE VALVE IS MOUNTED TO WAS BROKEN AND LOOSE, REMOVED PANEL, CUT PIECES OF ALUMINUM TO FIT IN DASH DRILLED HOLES AND SECURED TO DASH TO SECURED PANEL BACK TO DASH AND TO THE ALUMINUM PIECES WERE THE DASH WAS BROKEN. Tech 486 # 6 Id 486		247.50
9.000	WUR032.10.1 10-24X1 UNC MACH SCR PAN	0.20	1.80

I authorize the above repair work, including sublet work, to be done along with necessary materials. Crossiron Truck & Equipment LTD. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. Crossiron Truck & Equipment LTD. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.
 WHEEL NUTS MUST BE RE TORQUED WITHIN 150KM AFTER INSTALLATION
 NO RETURNS ON SPECIAL ORDER OR ELECTRICAL COMPONENTS
 20% RE STOCKING FEE ON RETURNED PARTS WITHIN 10 DAYS
 HST#73244 5291 RT0001

Parts..... 1013.65
 Labor..... 1815.00

TERMS: DUE UPON RECEIPT, 4% Interest per month on invoices past 30 days
 No returns after 10 days or on special order parts
 No returns

Sub Total 2828.65
 Sales Tax.... 367.72

Authorized By _____

TOTAL Continued



CROSSIRON TRUCK & EQUIPMENT LTD.
 4153 ROAD 38 HARROWSMITH
 ONT CANADA K0H 1V0
 PARTS & SERVICE 613-372-6269
 AFTER HOURS 613-217-8600

INVOICE W 7791
 Date 06/30/25
 Date Open 05/16/25

Sold To : 453-7878 613

Ship To :

[Redacted]				[Redacted]			
------------	--	--	--	------------	--	--	--

Written By BECKY	Terms CHGLST	Time 14:20:33	Customer Po #	Promised	Phone	Ship Via
---------------------	-----------------	------------------	---------------	----------	-------	----------

Unit # GREEN	Plate # BY72420	Year 2006	Make INTERNATION	Model EAGLE	Kilometer/Hrs 109723/39524.0	VIN 2HSCNAPR27C289319	Engine
-----------------	--------------------	--------------	---------------------	----------------	---------------------------------	--------------------------	--------

Qty	Description	Price	Amount
6.000	WUR373.1024 #10-24 NYLON LOCKNUT GR2	0.05	0.29
6.000	WUR403.10 10X0.500X0.049 MACH SCR WASHER	0.66	3.98
6.000	WUR214.12.1 DRILL PT SCREW	0.14	0.83
	SubTotal		254.40
	REPLACE AIR GOVERNOR AIR DRIER WOULD NOT BLOW OFF AFTER BUILDING AIR, DISCONNECTED LINE GOING TO GOVERNOR AND SUPPLIED SHOP AIR TO IT AND DRIER BLEW OFF, REMOVED GOVERNOR FROM COMPRESSOR, SWAPPED FITTINGS TO NEW ONE AND BOLTED IN PLACE, HOOKED UP LINES AND TESTED OPERATION. Tech 486 # 6 Id 486		82.50
1.000	BENBX5010669N GOVERNOR - AIR	132.26	132.26
	SubTotal		214.76
	REPAIR CORRODED CONNECTIONS ON FIREWALL POWER CABLES AND MEGA FUSE ON PASSENGER SIDE FIRE WALL WERE VERY CORRODED AND ABOUT TO ROT OFF, REMOVED POSITIVE CABLE FROM FUSE TO SOLENOID, REMOVED FUSE AND HOLDER AND INSTALLED NEW ONE, CUT CABLE END OFF CABLE GOING INTO CAB AND CRIMPED NEW END ON, MADE NEW CABLE TO GO FROM FUSE TO SOLENOID AND INSTALLED. Tech 486 # 6 Id 486		99.00

I authorize the above repair work, including sublet work, to be done along with necessary materials. Crossiron Truck & Equipment LTD. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. Crossiron Truck & Equipment LTD. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.
 WHEEL NUTS MUST BE RE TORQUED WITHIN 150KM AFTER INSTALLATION
 NO RETURNS ON SPECIAL ORDER OR ELECTRICAL COMPONENTS
 20% RE STOCKING FEE ON RETURNED PARTS WITHIN 10 DAYS
 HST#73244 5291 RT0001

Parts..... 1013.65
 Labor..... 1815.00

TERMS: DUE UPON RECEIPT, 4% Interest per month on invoices past 30 days
 No returns after 10 days or on special order parts
 No returns

Sub Total 2828.65
 Sales Tax.... 367.72

Authorized By _____

TOTAL Continued



CROSSIRON TRUCK & EQUIPMENT LTD.
 4153 ROAD 38 HARROWSMITH
 ONT CANADA K0H 1V0
 PARTS & SERVICE 613-372-6269
 AFTER HOURS 613-217-8600

INVOICE W 7791
 Date 06/30/25
 Date Open 05/16/25

Sold To : 453-7878 613

Ship To :

[Redacted]				[Redacted]			
[Redacted]				[Redacted]			
[Redacted]				[Redacted]			

Written By BECKY	Terms CHGLST	Time 14:20:33	Customer Po #	Promised	Phone	Ship Via
---------------------	-----------------	------------------	---------------	----------	-------	----------

Unit # GREEN	Plate # BY72420	Year 2006	Make INTERNATION	Model EAGLE	Kilometer/Hrs 109723/39524.0	VIN 2HSCNAPR27C289319	Engine
-----------------	--------------------	--------------	---------------------	----------------	---------------------------------	--------------------------	--------

Qty	Description	Price	Amount
1.000	PIC970311 150A BOLT ON FUSE	10.29	10.29
1.000	WUR776.034 DUAL WALL SHRINK TUBE WITH GLUE	3.08	3.08
1.000	WUR557.1542 2/0 WIRE END LUG COPPER 3/8" HOLE	5.00	5.00
2.000	WUR557.1552 1/0 WIRE END LUG COPPER 3/8 HOLE	2.31	4.62
1.000	WUR772.011 RED 1GA WIRE	9.23	9.23
1.000	GRO82-MGGA-FB FUSE BLOCK HOLDER MEGA	41.96	41.96
	SubTotal		173.18
	INSTALL HYDRAULIC LINE FOR TRAILER SWAPPED FITTING ON LINE THAT WAS ALREADY ON TRAILER TO MALE END AND HOOKED UP TO TRAILER, INSTALLED FEMALE END ON EACH SIDE OF NEW HOSE AND INSTALLED ON RETURN SIDE, HOOKED UP TO TRAILER, TESTED OPERATION OF HYDRAULICS <i>Tech 486 # 6 Id 486</i>		165.00
1.000	NLC471TC-16-RL HOSE	331.19	331.19
	SubTotal		496.19
	REPLACE LEAKING RIGHT FORWARD BRAKE CHAMBER REMOVED AND REPLACED LEAKING BRAKE CHAMBER, SWAPPED FITTING OVER TO NEW CHAMBER, AIRED UP SYSTEM AND CHECKED FOR LEAKS... OK, SET BRAKE ADJUSTMENT... <i>Tech 486 # 6 Id 486</i>		132.00

I authorize the above repair work, including sublet work, to be done along with necessary materials. Crossiron Truck & Equipment LTD. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. Crossiron Truck & Equipment LTD. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.
 WHEEL NUTS MUST BE RE TORQUED WITHIN 150KM AFTER INSTALLATION
 NO RETURNS ON SPECIAL ORDER OR ELECTRICAL COMPONENTS
 20% RE STOCKING FEE ON RETURNED PARTS WITHIN 10 DAYS
 HST#73244 5291 RT0001

Parts..... 1013.65
 Labor..... 1815.00

TERMS: DUE UPON RECEIPT, 4% Interest per month on invoices past 30 days
 No returns after 10 days or on special order parts
 No returns

Sub Total 2828.65
 Sales Tax.... 367.72

Authorized By _____

TOTAL Continued



CROSSIRON TRUCK & EQUIPMENT LTD.
 4153 ROAD 38 HARROWSMITH
 ONT CANADA K0H 1V0
 PARTS & SERVICE 613-372-6269
 AFTER HOURS 613-217-8600

INVOICE W 7791
 Date 06/30/25
 Date Open 05/16/25

Sold To : 453-7878 613

Ship To :

[Redacted]				[Redacted]			
[Redacted]				[Redacted]			
[Redacted]				[Redacted]			

Written By BECKY	Terms CHGLST	Time 14:20:33	Customer Po #	Promised	Phone	Ship Via
---------------------	-----------------	------------------	---------------	----------	-------	----------

Unit # GREEN	Plate # BY72420	Year 2006	Make INTERNATION	Model EAGLE	Kilometer/Hrs 109723/39524.0	VIN 2HSCNAPR27C289319	Engine
-----------------	--------------------	--------------	---------------------	----------------	---------------------------------	--------------------------	--------

Qty	Description	Price	Amount
1.000	TRPSB3030PKLC PIGGYBACK KIT 3030 LONG	93.57	93.57
1.000	WUR553.3305 DUAL CABLE TIE 19IN	5.41	5.41
	SubTotal		230.98
1.000	E TEST PERFORMED EMISSION TEST, PASSED TEST Tech 481 # 1 Id 481 NPN-EMISSIONS TEST CERTIFICATE # 25A0AB73	20.00	20.00
	SubTotal		152.00

I authorize the above repair work, including sublet work, to be done along with necessary materials. Crossiron Truck & Equipment LTD. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. Crossiron Truck & Equipment LTD. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.
 WHEEL NUTS MUST BE RE TORQUED WITHIN 150KM AFTER INSTALLATION
 NO RETURNS ON SPECIAL ORDER OR ELECTRICAL COMPONENTS
 20% RE STOCKING FEE ON RETURNED PARTS WITHIN 10 DAYS
 HST#73244 5291 RT0001

Parts..... 1013.65
 Labor..... 1815.00

TERMS: DUE UPON RECEIPT, 4% Interest per month on invoices past 30 days
 No returns after 10 days or on special order parts
 No returns

Sub Total 2828.65
 Sales Tax.... 367.72

Authorized By _____

TOTAL 3196.37