



Crossiron Truck & Equipment Ltd.
 4153 ROAD 38 HARROWSMITH
 ONT CANADA K0H 1V0
 PARTS & SERVICE 613-372-6269
 AFTER HOURS 613-217-8600

INVOICE W 5704
 Date Closed 06/26/23
 Date Open 06/07/23

Sold To : 453-7878 613

Ship To :

<div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div>	
---	--

Written By JORDAN	Terms CHG	Time 09:26:53	Customer Po #	Promised	Phone	Ship Via
----------------------	--------------	------------------	---------------	----------	-------	----------

Unit # EZE	Plate # X3257P	Year 2007	Make TRAIL EZE	Model	Kilometer/Hrs 1/1.0	VIN 1DA722C7357C018870	Engine
---------------	-------------------	--------------	-------------------	-------	------------------------	---------------------------	--------

Qty	Description	Price	Amount
	COMPLAINT LIGHTS NOT WORKING ON TRAILER CHECKED WIRING ON TRAILER, FOUND ONE LIGHT 1/2 OUT AND IN THE WRONG POSITION AT REAR OF TRAILER. SWAPPED LIGHTS AND INSTALLED ONE NEW BULB, CHECKED OPERATION OF ALL LIGHTS, SIGNALS AND BRAKES ARE ON THE SAME LINE WHICH THEY SHOULD NOT BE, CHECKED OUTPUT AT TRAILER CORD, IT IS THE SAME, THE PROBLEM LIES IN THE TRUCK, TOOK UNIT OUT AND DROPPED TRAILER, PULLED UNIT IN, REMOVED COVER FROM JUNCTION BOX AND CHECKED WIRES, THEY ARE HOOKED UP RIGHT BUT WIRING IS NOT CORRECT, FOLLOWED WIRING THROUGHOUT UNIT, FOUND 3RD LIGHT HARNESS GOING TO THE REAR OF THE UNIT. CHECKED FOR POWER, HAS POWER ON BRAKES AND MARKERS NO POWER TO SIGNALS, WENT UNDER AND FOUND SECTION WHERE IT HAD BEEN CUT OUT, TESTED FOR POWER, GOOD, CUT TIES DOWN FRAME RAIL AND REMOVED THE CORD GOING TO THE REAR OF THE UNIT AND RAN UP TO TRAILER CORD. CAN USE THIS CORD DIRECT FOR TRAILER. THE OTHER 2 HARNESSES NEED TO BE RELOCATED AS THEY RUN OVER A CROSS MEMBER AND UNDER THE 5TH WHEEL, THE SECOND CORD IS NOT NEEDED. REPLACED TRAILER RECEPTACLE, WIRED IN PLUG, NOW UNIT HAS SEPARATE BRAKE LIGHT FEED, CUT OUT OTHER 2 CABLES AND RAN THE ONE BACK AND TIED UP PROPERLY, REWIRED BACK LIGHTS, TEST OK CHECKED ON TRAILER NOW ALL OVAL LIGHTS COME ON WITH BRAKES EXCEPT WHEN SIGNALS ON, THE INSIDES STAY BRAKE LIGHTS AND THE OUTSIDES FLASH. ALSO INSTALLED TEE INTO PTO SWITCH SO THAT THE PUMP IS LIVE ONE THE PTO SWITCH IS TURNED ON. <i>Tech 484 # 2 Id 484</i>		687.50

I authorize the above repair work, including sublet work, to be done along with necessary materials. Crossiron Truck & Equipment LTD. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. Crossiron Truck & Equipment LTD. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.
 WHEEL NUTS MUST BE RE TORQUED WITHIN 150KM AFTER INSTALLATION
 NO RETURNS ON SPECIAL ORDER OR ELECTRICAL COMPONENTS
 20% RE STOCKING FEE ON RETURNED PARTS WITHIN 10 DAYS
 HST#73244 5291 RC0001

Terms: Net 30 days 4% interest per month on over due accounts
 No returns after 10 days or on special order parts
 No returns on electrical co

Parts.....	83.09
Labor.....	687.50
Shop Supplies	34.38
Sub Total	804.97
Sales Tax....	104.65

Authorized By _____

TOTAL Continued



Crossiron Truck & Equipment Ltd.
 4153 ROAD 38 HARROWSMITH
 ONT CANADA K0H 1V0
 PARTS & SERVICE 613-372-6269
 AFTER HOURS 613-217-8600

INVOICE W 5704
 Date Closed 06/26/23
 Date Open 06/07/23

Sold To : 453-7878 613

Ship To :

<div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div>	
---	--

Written By JORDAN	Terms CHG	Time 09:26:53	Customer Po #	Promised	Phone	Ship Via
----------------------	--------------	------------------	---------------	----------	-------	----------

Unit # EZE	Plate # X3257P	Year 2007	Make TRAIL EZE	Model	Kilometer/Hrs 1/1.0	VIN 1DA722C7357C018870	Engine
---------------	-------------------	--------------	-------------------	-------	------------------------	---------------------------	--------

Qty	Description	Price	Amount
1.000	TRL6058 LED SIGNAL STAT ST-T	38.56	38.56
7.000	WUR553.9706 14-16 GA BUTT CONN UNINSULATED SEAMLESS	0.45	3.14
5.000	WUR775.0316 DUAL WALL SHRINK TUBE 3/16X6	1.89	9.43
2.000	WUR553.9705 18-22 GA BUTT CONN UNINSULATED SEAMLESS	0.24	0.49
36.00	WUR0502.98181 WIRE TIE 0.30"X15"	0.26	9.25
1.000	PHI15-720 SOCKET 7 PIN	17.93	17.93
1.000	WUR778.01 DUAL WALL SHRINK TUBE 1"	4.29	4.29
	SubTotal		770.59

--	--

I authorize the above repair work, including sublet work, to be done along with necessary materials. Crossiron Truck & Equipment LTD. employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. Crossiron Truck & Equipment LTD. will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.
 WHEEL NUTS MUST BE RE TORQUED WITHIN 150KM AFTER INSTALLATION
 NO RETURNS ON SPECIAL ORDER OR ELECTRICAL COMPONENTS
 20% RE STOCKING FEE ON RETURNED PARTS WITHIN 10 DAYS
 HST#73244 5291 RC0001

Terms: Net 30 days 4% interest per month on over due accounts
 No returns after 10 days or on special order parts
 No returns on electrical co

Parts.....	83.09
Labor.....	687.50
Shop Supplies	34.38
Sub Total	804.97
Sales Tax....	104.65

Authorized By _____

TOTAL 909.62