

Work Order

CORNWALL

Number: 1069

Unit N° 365

PA84527

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 1FUJGED57GLHE2270

Make: FRHT

Model:

Year: 2016

Kilometer: 1358278

Engine hours: 4590

Date opened: 2026-03-12

Date closed: 2026-04-10

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	PMA			Ordered an ACM wiring harness since this one has been repaired a couple of times						
	INS	PMA			*****						
	INS	PMA			*****						
	REP	DEF	PTS5		DEF MAINTENANCE						
	REP	DEF			>> TTALENT 2026-03-13 17:32:07:79						
	REP	DEF			@NOT525:ACM wiring harness ordered for tomorrow						
	REP	DEF			TALENT TAMBAOGA, 2026-03-13						
	REP	DEF			Corrections						
	REP	DEF			removed and replaced ACM wiring harness and initiated regen completed						
	REP	DEF			replaced piggy back 1st rear axle driver's side and adjusted brakes						
	REP	DEF			performe A service						
	REP	DEF			*****						
	REP	DEF	BRAKE CHAMBER PIGGY		BRAKE CHAMBER PIGGY BACK		PTS5		1.00		
	REP	DEF	720.744		12V-21W MINI LAMP 1.75AMP NO.744Q(W21W)		PTS5		2.00	4.310	8.620
	REP	003			TALENT TAMBAOGA, 2026-03-17						
	REP	003			Corrections						
	REP	003			replaced wiper blade						

Comment:

END OF SHIFT

Signature : _____

Date : _____

Subtotal-parts:

8.62 +

Subtotal labor:

451.35

Shop supply:

67.70

TOTAL (\$):

527.67

Hrs.

5.31

Work Order		CORNWALL		Number: 1069	
VIN: 1FUJGED57GLHE2270 Make: FRHT Model: Year: 2016		Unit N° 365 Plate: PA84527		05. WORK FINISHED ☐ SCHEDULED WORK	
Engine hours: 4590 Kilometer: 1358278		Date opened: 2026-03-12 Date closed: 2026-04-10			

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	003			*****						
	REP	003			(14758) >> TTALENT 2026-03-17 11:30:26:50						
	REP	003			wiper blades (14758) (14758) >> OK						
	INS	PMA	TTALENT		TALENT TAMBAOGA				0.13	85.00	11.05
	REP	DEF	TTALENT		TALENT TAMBAOGA				5.15	85.00	437.75
	REP	003	TTALENT		TALENT TAMBAOGA				0.03	85.00	2.55

Comment: END OF SHIFT	Subtotal-parts:	8.62 +	0.00
	Subtotal labor:	451.35	0.00
	Shop supply:	67.70	
	TOTAL (\$):	527.67	Hrs. 5.31

Signature : _____	Date : _____
-------------------	--------------

Work Order

CORNWALL

Number: 905

Unit N° 365

PA84527

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 1FUJJGED57GLHE2270

Make: FRHT

Model:

Year: 2016

Kilometer: 1353153

Engine hours: 4473

Date opened: 2026-02-17

Date closed: 2026-02-19

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	045			(12502) >> TTALENT 2026-02-17 17:55:08:01						
	REP	045			replace remote disconnect switch (12502) (12502) >> OK						
	REP	045			(12503) >> TTALENT 2026-02-17 17:55:09:01						
	REP	045			replace PNBD module (12503) (12503) >> OK						
	REP	045			TALENT TAMBAOGA, 2026-02-17						
	REP	045			Corrections						
	REP	045			replaced PNBD and disconnect switch						
	REP	045			leds kept on flushing and blowing out SAM cab fuse						
	REP	045			traced switch to module wiring and found corroded pins , no stock but ordered						
	REP	045			cleaned connector for now						
	REP	045			Installed all wiring back and fault was resolved						
	REP	045			*****						
	REP	045	TTALENT		TALENT TAMBAOGA				0.17	85.00	14.45

Comment:

OTHER ELECTRIC OR ELECTRONIC SYSTEMS

Signature :

Date :

Subtotal-parts:

Subtotal labor:

Shop supply:

TOTAL (\$):

Hrs.

0.17

Work Order

CORNWALL

Number: 368

VIN: 1FUJGED57GLHE2270

Unit N° 365

05. WORK FINISHED

Make: FRHT

Plate: PA84527

☐ SCHEDULED WORK

Model:

Kilometer: 1347240

Date opened: 2025-12-09

Year: 2016

Engine hours: 4331

Date closed: 2025-12-30

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
☒	INS	SAFETY	PTS1		SAFETY						
☒	INS	SAFETY			(3425) >> TTALENT 2025-12-09 15:01:07:96						
☒	INS	SAFETY			Back up alarm not working (3425) (3425) >> OK						
☒	INS	SAFETY			(3426) >> TTALENT 2025-12-09 15:01:09:03						
☒	INS	SAFETY			Back up light not working (3426) (3426) >> OK						
☒	REP	045	DDE A4700781710		INJECTOR TUBE				1.00	116.090	116.090
☒	REP	045	DDE A4700781810		INJECTOR TUBE				1.00	116.090	116.090
☒	REP	045			>> BVOLPI 2025-12-09 23:27:07:45						
☒	REP	045			@NOT328:Pass through seals						
☒	REP	045			Pass through seal 3 and 5 were leaking						
☒	REP	045			Changed both with new kits.						
☒	INS	016			CHRIS CHITAMBARA, 2025-12-10						
☒	INS	016			Corrections						
☒	INS	016			Cut off left rear shock absorber mounting bolt						
☒	INS	016			*****						
☒	REP	016	85724HD		TRUCK SHOCK				2.00	69.730	139.460
☒	REP	016			>> BVOLPI 2025-12-10 03:51:45:80						
☒	REP	016			@NOT330:Shocks						

Comment:

ANNUAL SAFETY

Signature : _____

Date : _____

Subtotal-parts: 1395.47

Subtotal labor: 1394.00

Shop supply: 209.10

TOTAL (\$) : 2998.57

Hrs. 16.40

+

0.00

0.00

Work Order		CORNWALL	Number: 368
VIN: 1FUJGED57GLHE2270 Make: FRHT Model: Year: 2016		Unit N° 365 Plate: PA84527	05. WORK FINISHED ☐ SCHEDULED WORK
Kilometer: 1347240		Engine hours: 4331	Date opened: 2025-12-09 Date closed: 2025-12-30

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	016			Driver side had shocks that are not matching to what the truck takes.						
	REP	016			Had to cut back one out with a torch.						
	REP	016			New shocks installed on driver side.						
	REP	016			Anti seize applied to the bolt before fastening to shock.						
	REP	016			Shocks are secured.						
	REP	016			BLAKE VOLPI, 2025-12-10						
	REP	016			Comment / Request						
	REP	016			Power Steering filter change						
	REP	016			Corrections						
	REP	016			Drain power steering fluid from tank						
	REP	016			Remove filter						
	REP	016			Change filter with new						
	REP	016			Fill with new Power steering fluid						
	REP	016			*****						
	REP	016	HF35387		HYDRAULIC FILTERS				1.00	12.770	12.770
	REP	016	BRAKE CLEAN		BRAKE KLEAN				2.00		
	REP	016	POWER STEERING FLUID		POWER STEERING FLUID				4.00		
	REP	016			>> BVOLPI 2025-12-10 05:47:49:94						

Comment: ANNUAL SAFETY	Subtotal-parts: 1395.47 + 0.00	
	Subtotal labor: 1394.00 0.00	
	Shop supply: 209.10	
	TOTAL (\$): 2998.57 Hrs. 16.40	

Signature : _____	Date : _____
-------------------	--------------

Work Order

CORNWALL

Number: 368

Unit N° 365

PA84527

☐ SCHEDULED WORK

05. WORK FINISHED

VIN: 1FUJGED57GLHE2270

Make: FRHT

Model:

Year: 2016

Kilometer: 1347240

Engine hours: 4331

Date opened: 2025-12-09

Date closed: 2025-12-30

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	016			@NOT331:Power steering						
	REP	016			Power steering was completely drained						
	REP	016			Filter was changed with new filter.						
	REP	016			Filled with new power steering fluid.						
	INS	SAFETY			TALENT TAMBAOGA, 2025-12-10						
	INS	SAFETY			Comment / Request						
	INS	SAFETY			safety						
	INS	SAFETY			Causes						
	INS	SAFETY			annual safety due						
	INS	SAFETY			Corrections						
	INS	SAFETY			installed tablet docking station and charging harness						
	INS	SAFETY			replaced DEF filter, air dryer filter and steering filter						
	INS	SAFETY			Repaired reverse wiring and replaced reverse switch						
	INS	SAFETY			replaced rear left axle shocks						
	INS	SAFETY			completed annual safety						
	INS	SAFETY			*****						
	INS	SAFETY	20363		REVERSE SWITCH		PTS1		1.00		
	INS	SAFETY	GREASE PREMALUBE		GREASE PREMALUBE		PTS1		1.00		

Comment:

ANNUAL SAFETY

Signature : _____

Date : _____

Subtotal-parts:

1395.47

+

0.00

Subtotal labor:

1394.00

+

0.00

Shop supply:

209.10

TOTAL (\$):

2998.57

Hrs.

16.40

Work Order

CORNWALL

Number: 368

Unit N°

365

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 1FUJGED57GLHE2270

Make: FRHT

Model:

Year: 2016

Plate: PA84527

Kilometer: 1347240

Engine hours: 4331

Date opened: 2025-12-09

Date closed: 2025-12-30

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	SAFETY	UF106		DEF FILTER		PTS1		1.00	127.800	127.800
	INS	SAFETY	T1808G		POWER STEERING FILTER		PTS1		1.00	12.770	12.770
	INS	SAFETY	5005037		AD-9 AIR DRYER KIT		PTS1		1.00	57.430	57.430
	INS	SAFETY	432 421 033 0		AIR DRYER		PTS1		1.00	813.060	813.060
	INS	SAFETY			(6649) >> TTALENT 2025-12-10 09:23:49:19						
	INS	SAFETY			repair back up lamp wiring (6649) (6649) >> OK						
	INS	SAFETY			(6650) >> TTALENT 2025-12-10 09:23:55:03						
	INS	SAFETY			Replace back up switch (6650) (6650) >> OK						
	INS	SAFETY			(6651) >> TTALENT 2025-12-10 09:23:53:44						
	INS	SAFETY			Mismatched rear shocks drivers side (6651) (6651) >> OK						
	INS	SAFETY			(6652) >> TTALENT 2025-12-10 09:23:52:40						
	INS	SAFETY			Air leaks (6652) (6652) >> OK						
	INS	SAFETY			(6653) >> TTALENT 2025-12-10 09:23:51:55						
	INS	SAFETY			Passthrough seals (6653) (6653) >> OK						
	INS	SAFETY			(6654) >> TTALENT 2025-12-10 09:23:50:69						
	INS	SAFETY			replace air dryer filter and kit (6654) (6654) >> OK						
	INS	SAFETY			(6655) >> TTALENT 2025-12-10 09:23:49:67						
	INS	SAFETY			Install tablet bracket (6655) (6655) >> OK						

Comment:

ANNUAL SAFETY

Signature :

Date :

Subtotal-parts:

1395.47

Subtotal labor:

1394.00

Shop supply:

209.10

TOTAL (\$):

2998.57

Hrs.

16.40

+

0.00

0.00

Work Order

CORNWALL

Number: 368

Unit N° 365

05. WORK FINISHED

VIN: 1FUJGED57GLHE2270

PA84527

☐ SCHEDULED WORK

Make: FRHT

Plate: PA84527

Model: 2016

Engine hours: 4331

Date opened: 2025-12-09

Date closed: 2025-12-30

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS	SAFETY				(6656) >> TTALENT 2025-12-10 09:24:42:51						
INS	SAFETY				Lubricated vehicle as required (6656) (6656) >> OK						
INS	SAFETY	SAUBIN			SEBASTIEN AUBIN				5.44	85.00	462.40
INS	SAFETY	TTALENT			TALENT TAMBAOGA				6.14	85.00	521.90
REP	045	BVOLPI			BLAKE VOLPI				0.25	85.00	21.25
REP	016	BVOLPI			BLAKE VOLPI				4.54	85.00	385.90
INS	016	CCHITAMBARA			CHRIS CHITAMBARA				0.03	85.00	2.55

Comment:

ANNUAL SAFETY

Subtotal-parts:

1395.47

+

0.00

Subtotal labor:

1394.00

0.00

Shop supply:

209.10

SIGNATURE

DATE

TOTAL (\$)

2998.57

Hrs.

16.40