



Vehicle History Summary



Fleet #	PM10
Registration	BMR014
Make	Western Star
Model	2021 Prime Mover
VIN / Chassis #	5KKJBEBG1NPNP8787
Build Date	2021

Date	Reading / Units	Type / Repairer Notes	Repairer
30/06/2026	1,038,480 kms	Truck Wash R-3204 see attached job card	BMR Logistics
19/06/2026	1,032,831 kms	Fault R-3165 FOUND 3X 5C PIECES IN THE SOCKET NOT ALLOWING CONTACT, REMOVED COINS AND CHANGED FUSE	BMR Logistics
18/06/2026	1,032,831 kms	Fault R-3167 REPLACED FUSE IN FRIDGE ALL WORKING NOW	
01/06/2026		Driveline R-3093 see attached invoice for details	Primary Mechanical Repairs
01/06/2026		Fault R-3064 repaired in service	
20/05/2026	1,014,537 kms	B - 40k S-1412 CARRIED OUT B SERVICE AS PER JOBCARD REPLACED OIL AND FILTERS COMPLETESD REPAIRS	BMR Logistics, Primary Mechanical Repairs
01/05/2026		PUNCTURE T-1348 qtr tyres repaired see attched invoice	Barry Tyres
23/04/2026		Driveline R-3013 replace all 10 wheel studs lhs	MaxiParts
31/03/2026	968,445 kms	A - 10k S-1353 SIDE TO SIDE STEER TYRES 10 X PRESSURE CHECKS REPLACE BROKEN WHEEL STUD REFIT LHS TOP REAR WING REPLACE LH TAIL BRAKE LIGHT WITH 2ND HAND SPARE READJUST EXHAUST STACK HEAT SHEILDS REPLACE FUSE FOR BRAKE LIGHTS SLEEPER AIR LOW ON OIL TOPPED UP DRAG LINK HAS MOVEMENT WILL REQUIRE REPLACING DIFF WEEPING/ WET UNSURE OF WHERE OR CAUSE LEVELS ARE ALLGOOD	BMR Logistics
13/03/2026		Glass R-2882	
13/03/2026	957,670 kms	STEER TYRES T-1291 TYRES WORN OUT REPOLACED WITH NEW TYRES PRESSURE 105PSI	BMR Logistics
10/03/2026	954,520 kms	Runout T-1285	BMR Logistics
10/03/2026	952,182 kms	B - 40k S-1319 REMOVE, CLEAN AND REFIT DRIVE FRONT RHS WHEEL SEAL(FIT NEW SEAL ADJUST BEARINGS REFIT LOCKING RING TOP UP DIFF) JOHN 8X DRIVE ROTATIONS/ 4 X INNER FLIP ON RIMS	BMR Logistics
23/02/2026		COMPRESSOR R-2688	BMR Logistics
13/02/2026	931,264 kms	PUNCTURE T-1229 9 x Pressure check 1 x Puncture repair	BMR Logistics
29/01/2026	915,950 kms	Main/inspect T-1178	BMR Logistics

Date	Reading / Units	Type / Repairer Notes	Repairer
		SEE ATTACHED TYRE JOBCARD - PRESSURE CHECKS X 10. NO KLMS RECORDED. I ADDED 915950.	
09/01/2026	900,649 kms	Main/inspect T-1119	BMR Logistics
		SEE ATTACHED TYRE JOBCARD - 1 RUNOUT REQUIRED & 9 PRESSURE CHECKS.	
09/01/2026	900,649 kms	B - 40k S-1200	BMR Logistics
		SEE ATATCHED SERVICW JOBCARD - REKIT TURNTABLE JAW & LOCKING PIN. REPLACED AIR DRIER. FLUSHED ADBLUE SYSTEM. REPACL IDLER BEARINGS WITH GREASE. REPLACED 2X WHEEL STUD & NUTS, PASSENGER STEER. * *COMPRESSOR LEAK AIR WHEN DECOMPRESSION VALVE IS ACTIVE & KEEPS BLOWING OFF AIR DRIER, NEEDS TO GO TO CUMMINS FOR WARRANTY**NEW REPAIR TO BE CREATED** BREAKDOWN MECHANICS TIMES: NATHAN 6HR MIKAYLA 4HR	
06/01/2026		SERVICE CALL/FIT T-1109	BRENNANS TYREPOWER
		SEE ATTACHED INVOICE 204489 PAID BY EFTPOS.	
31/12/2025		Chassis R-2349	BMR Logistics
		SERVICE JOBCARD 1157 SAYS AWAITING PARTS, LEFT OPEN.	
18/12/2025	883,767 kms	TURNTABLE R-2604	BMR Logistics
		SEE ATTACHED REPAIR JOBCARD-REPLACED R/H TEFLON PAD ON TURNTABLE. MECHANICS BREADOWN TIMES: NATHAN 0.25 MIKAYLA 0.25	
11/12/2025		Glass R-1988	
11/12/2025	875,113 kms	A - 10k S-1157	BMR
		SEE ATTACHED SERVICE JOBCARD 1157. MECHANIC TIME BREAKDOWN: NATHAN 0.5 MIKAYLA 1HR	
11/12/2025		Cab R-2116	BMR Logistics
		SERVICE JOBCARD 1157 SAYS"WORKED DURING SERVICE" REPAIR JOBCARD NOW CLOSED.	
11/12/2025		Glass R-2041	
		SERVICE JOBCARD 1157 - DEFERRED.	
09/12/2025		Chassis R-2512	Penske
		MAXIPARTS- PDP844 POWERDOWN SHOCK ABSORBERS X 4-PO1930-SEE ATTACHED INVOICE 6600316. PENSKE-SS MUDGUARD SMOOTH X 2 & CABLE HOOD RESTRAINT X 1-PO1931-SEE ATTACHED INVOICE DTH109877T. PENSKE LYTTON QUOTE NDH5443N FOR DRAGLINK. PENSKE TSV QUOTE DTH40576T FOR DRAGLINK.	
08/12/2025	868,018 kms	Lights R-2513	KENNYS AUTO ELECTRICAL TSV
		JAS(BAXTERS)-15W WORK SPOT BEAMS x 2 - SEE ATTACHED QUOTATION 6735197-PO 1932. ARRIVAL HERE ON SITE MONDAY 1/12/25 FROM BNE. SEE ATTACHED INVOICE 5733820. PRINTED JOBCARD AND ATTACHED TO SPOTS. SEE ATTACHED REPAIR JOBCARD FROM KENNYS 5/12/25. WAITING ON KENNYS INVOICE WITH PO, SEE INVOICE 62452.	
29/11/2025		Battery R-2444	BMR Logistics
		SEE ATTACHED A1 BATTERYPRO INVOICE 706739. NOT FITTED TO THIS VEHICLE USED FOR ANOTHER TRUCK. 28/11-NEW ORDER 4 X BATTERIES FROM A1 BATTERY PRO. (PO1929). SEE ATTACHED INVOICE 708886. SEE ATTACHED SERVICE JOBCARD S1122.	
29/11/2025		Chassis R-2421	Penske
		PENSKE LYTTON PO (Brian) for truck seat set WSP2297-\$125.00. SEE ATTACHED REPAIR JOBCARD FOR COOLANT & INSPECT TRACK SEAT, WAITING ON NEW TRACK SEAT KIT FROM PENSKE. TRACK SEAT KIT ARRIVED. SEE ATTACHED SERVICE JOBCARD S1122.WITH FAULT FIXED.	
29/11/2025	862,633 kms	C - 100k/Annual S-1122	BMR Logistics
		SEE ATTACHED COMPLETED SERVICE JOBCARD. *NEEDS NEW DRAG LINK* 1/12-PENSKE TSV FOR A DRAGLINK QUOTE.	
29/11/2025		Radiator R-2352	BMR Logistics
		SEE ATTACHED SERVICE JOBCARD S1122.	
29/11/2025		Cab R-2259	BMR Logistics

Date	Reading / Units	Type / Repairer Notes	Repairer
29/11/2025		Engine R-2464 SEE ATTACHED SERVICE JOBCARD S1122.	BMR Logistics
29/11/2025	862,633 kms	Cab R-1983 17/11-awaiting quote from Penske. see attached quote DTH38931T. SEATBELT ARRIVED. SEE ATTACHED PENSKE INVOICE DTH109499T. REPAIRED ON SERVICE JOBCARD 1122 (SEE ATTACHED).	Penske
29/11/2025		Engine R-2202 SEE ATTACHED SERVICE JOBCARD.	BMR Logistics
17/11/2025	849,394 kms	SERVICE CALL/FIT T-1012 SEE ATTACHED INVOICE 1007902	TYREPOWER SARINA
17/11/2025	812,949 kms	Chassis R-2304 SEE ATTACHED INVOICE, PENSKE PO#1711-DTH108346T FOR PARTS WITH NO RECORDED TRUCK DETAILS. AWAITING CREDIT ADJUSTMENT!!!! SEE ATTACHED INVOICE, PENSKE PO#1711-DTH108357T FOR PARTS WITH TRUCK DETAILS ON IT. SEE ATTACHED INVOICE, PENSKE PO#1711-DTH108350T FOR ISOLATOR-RADIATOR TIEROD X 5. SEE ATTACHED CUMMINS INVOICE PO#1710-1796707, WAITING ON APPROVAL FROM MATT &/OR FRANCIS TO INPUT INTO XERO A/C'S. APPROVAL FROM MATT VIA EMAIL.	BMR Logistics, Cummins, Penske
11/11/2025	844,210 kms	Air Conditioner Cabin Truck dash R-2442 SEE ATTACHED COMPLETED REPAIR JOBCARD 2442.	BMR Logistics
07/11/2025	839,980 kms	Glass R-2435 SEE ATTACHED COMPLETED REPAIR JOBCARD 2435	BMR Logistics
31/10/2025	833,022 kms	Chassis R-2407	BMR Logistics
29/10/2025	2,451 hrs	Air Conditioner Cabin Truck dash R-2383 PO1779 SENT TO KENNYS. SEE ATTACHED INVOICE 62090	KENNYS AUTO ELECTRICAL TSV
24/10/2025	826,385 kms	Driveline R-2385 SEE ATTACHED REPAIR JOBCARD 2385	BMR Logistics
01/10/2025		Engine R-2291 see attached repair job card - NO KILOMETRES RECORDED.	BMR Logistics
24/09/2025	811,266 kms	Cab R-2258 TRUCKLINE - MIRROR SPOTTER - PO 1673. SEE ATTACHED INVOICE 10360012 SEE ATTACHED REPAIR JOBCARD.	BMR Logistics
28/08/2025	790,902 kms	Cab R-2118 SEE ATTACHED REPAIR JOBCARD.	BMR Logistics
18/08/2025	783,663 kms	Lights R-2086 SEE ATTACHED REPAIR JOBCARD.	BMR Logistics
15/08/2025		Electrical R-2032	
12/08/2025		Chassis R-2005 Cummins arrived on site to repair. REFER TO ATTACHED INVOICE 1699280.	Cummins
12/08/2025	176,775 kms	Driveline R-1984 SEE ATTACHED DETAILED INVOICE 1140.	Primary Mechanical Repairs
12/08/2025	781,488 kms	Electrical R-2052 SEE ATTACHED INVOICE WTCST15947.	Penske
06/08/2025	779,393 kms	Electrical R-2025 SEE ATTACHED REPAIR JOBCARD.	KENNYS AUTO ELECTRICAL TSV
05/08/2025		Cab R-2083	KENNYS AUTO ELECTRICAL TSV

Date	Reading / Units	Type / Repairer Notes	Repairer
		SEE ATTACHED INVOICE 61281. SEE ATTACHED SERVICE 1122.	
23/07/2025		Cab R-1968 NO leak found on inspection	
23/07/2025		Driveline R-1838 At time of inspection, all working	
23/07/2025		Driveline R-1976 Removed inspection plate, blew out clutch with compressed air, grease clutch, test drove, all ok	
23/07/2025		Mudflaps R-1970 Guards inspected and tightened - monitor cracks	
23/07/2025		Chassis R-1839 Monitor - not require as RW Item	
23/07/2025		Cab R-1969 No leak found on inspection	
16/07/2025		Lights R-1833 No fault found	
16/07/2025	573,101 kms	A - 10k S-935	BMR Logistics
16/07/2025		Brakes R-1931	
16/07/2025		Brakes R-1910	
16/07/2025		Mudflaps R-1832	
16/07/2025		Lights R-1745 Refit missing driver mirror light. Found fuse in wrong location	
15/07/2025	760,112 kms	Driveline R-2002 repair notes as per attached	Penske
04/07/2025	762,961 kms	Pressure Check T-900 Pressure check	BMR Logistics
04/07/2025	762,961 kms	Chassis R-1889 Inspect rattle in rear when driving. Found walk plates front two bolts loose and would be jumping up and down. Found bolts hard to turn. Free up bolts with oil then tighten down walk plate. Retighten rear bolts too.	
17/06/2025	760,654 kms	Rotate T-857 Side to side steer rotation Pressure Check	BMR Logistics
11/06/2025	759,676 kms	Electrical R-1746 Open dash panel. Found all gauges linked in series. Clean all gauge connections and plugs. Could not recreate fault after.	
11/06/2025	759,676 kms	A - 10k S-895	
11/06/2025	759,676 kms	Chassis R-1783 Replaced both shock absorbers over steer	
21/05/2025	744,132 kms	Chassis R-1699 Found mounting bolts for driver mirror loose and one top bolt missing and one bolt holding broken off piece of bracket. Removed bolt holding broken off piece and used it to re-secure top bracket and stabilizer arm. Ensured all bolts are tightened for driver and passenger mirrors. Refit step brackets for L/H rear bottom step then fit new step brackets.	
20/05/2025	744,132 kms	C - 100k/Annual S-872	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Small movement in driveshaft spline (non-greaseable) - Monitor	
16/05/2025		Brakes R-1616	
07/05/2025	736,014 kms	New T-792 1x new steer tyre Pirelli R01 Left Front 1x Puncture repair left front outer driver	BMR Logistics
07/05/2025	736,014 kms	Brakes R-1595 Cut out suzi coils tangled with electrical leads. Replace broken lights plug on truck end of lead. Fit new suzi leads and tie together nicely. Untangle electrical leads and tie together nicely. Tighten bolts on sleeper air cover.	
30/04/2025		Glass R-1229	
30/04/2025		Cab R-1235	
30/04/2025		Chassis R-1233	
30/04/2025		Chassis R-1232	
22/04/2025	727,141 kms	Engine R-1504 Found batteries too low to start truck and icepack. Trued to jump icepack with lights test battery but didn't work. Used BMR032 with jumper leads to kick over icepack. Charged batteries with both for 5min before truck engine would start. Run truck for 2hr before it left for jobs.	BMR Logistics
17/04/2025	726,393 kms	Brakes, Lights R-1231 Remove R/H revers and indicator lamp. Refit R/H Tail light with longer washers. Refit lamps.	
02/04/2025		New T-658 Breakdown at Deeragun New steer tyre	BMR Logistics
31/03/2025		Chassis R-1234	
31/03/2025		Air Conditioner Cabin Truck dash R-1113	BMR Logistics
31/03/2025		Cab R-1230	
30/03/2025	715,764 kms	Driveline R-1401 Inspect driveline, found movement in transmission output shaft. Unbolt and remove driveshaft from trans. Tighten transmission yoke lock nut as tight as can go, chisel edge of lock nut in 3 places to ensure nut won't come loose. Refit driveshaft. Test drive with driver and vibration is gone.	BMR Logistics
26/03/2025	714,317 kms	Brakes R-1365 Removed hose and took to 24hr hose, had replacement hose made and returned. Fit new hose through chassis and tighten ends, test operation and truck now gets to full air pressure. Zip tie hose throughout chassis. Check airbags for leaks, found 2 bags with major leaks and 2 with minor. Replaced all 4 airbags and ride height valve due to constantly inflating and exhausting bags. Tightened cab panhead bushes due to movement.	BMR Logistics
24/03/2025	714,316 kms	Chassis R-1347 Grab new signs and bolts, take tools to truck in yard, remove remaining sign, drill new bolt holes and fit new signs. Organise and complete all outstanding paperwork.	BMR Logistics
21/03/2025	713,459 kms	Repair T-718 Cracked Rim replace - STOCK Left Front Steer Pressure Check	BMR Logistics
17/03/2025	710,653 kms	Battery R-1287 Inspect charge rate and all cables in battery box and engine bay, remove all cables from batteries and test each battery individually, found 3x batteries @ 13.5v and one @ 10.3v, remove and replaced bad battery with spare battery from last change out. Test and started good.	BMR Logistics
12/03/2025	708,737 kms 2 hrs	Driveline R-1267	BMR Logistics

Date	Reading / Units	Type / Repairer Notes	Repairer
		Remove UNI off trans yoke, tighten yoke nut then refit, Started to remove UNI on front input, advised to drop and check oils and replace yoke nuts. Cut open and clean container then drain and check diff oil, no chunks of metal or abnormal amounts on magnet. Check transmission and get some results, undo front UNI and replace eaton yoke nut the refit UNI. Undo front drive input UNI and replace meritor yoke nut then refit UNI, Refit trans and front drive with correct gear oil.	
06/03/2025	707,857 kms	A - 10k S-785	BMR Logistics
		-Remove cover in front of windshield - Remove broken driver washer hose and replace with new hose - test operation, blow out washer jets, bend wiper arms and reposition washer jets on are, replace driver wiper and retest washer. - Drain excess oil in sleeper air and test operation - gets cold. - found plug for horn was tied up, untangled and refit - Topped up oil - Found coolant cap perished, replaced with new cap - repair weld L/H tail light bracket - Refit camera to windshield with gorilla double sided tape - Rewired L/H tail light assembly due to corrosion	
04/03/2025	707,054 kms	New T-677	BMR Logistics
21/02/2025	687,475 kms	Cab R-1007	Penske
		Repair Airline	
17/02/2025	698,185 kms	Electrical R-1134	BMR Logistics
		Drove to DC docks, found electrical 7pin plug contacts pulled in, open plug and refit in housing properly, test plug again and all lights working. Seat wouldnt slide forward for driver, removed cushion and reset slide bar lever, seat now slides as normal.	
12/02/2025	694,659 kms	Engine R-1097	BMR Logistics
		11/02/25 - Inspect truck for start issues, slow to wind then once starter gets hot engine wont crank for another 10mins, run hose constantly over starter to cool faster, couple taps with hammer and jumper leads to ute before truck would finally start and could be moved into the shop for repairs. (STARTER MOTOR STILL NEEDS REPLACEMENT) 12/02/25 - Grease all points on truck Remove and replace starter motor with new Bend/straighten L/H tail light bracket, remove both outter lenses and refit tail light assembly with larger washers to cover breaks in housing	
11/02/2025	694,441 kms	Runout T-617	BMR Logistics
11/02/2025	694,441 kms	Chassis R-1096	BMR Logistics
		Jack up front L/H steer, remove tyre and drum, remove broken hub cap, remove hub and flush bearings and hub with brake clean, refit hub and tension spindle nut to 300ft-lb, fit lock ring and new hub cap, fill hub with gear oil, refit drum and wheel and tension wheel nuts to 475ft-lb. Check and adjust steer tyre pressures to 110psi.	
22/01/2025	688,344 kms	Engine R-1015	
		Truck slow to crank then no crank at all check battery terminals and starter connections, starter was very hot and temp sensor would tell not to start, cool starter with hose then crank again, vehicle started, will most likely require replacement starter.	
21/01/2025		Electrical R-1010	BMR Logistics
		Replaced plug on suzi going into cab for lights, cleaned and inspect 7 pin socket on cab. Had power in socket and suzi, Once plugged into trailer power drops out inspect socket on trailer, believed trailer to be issue but found truck wiring to be faulty.	
17/01/2025	684,580 kms	B - 40k S-736	BMR Logistics
		R/H/R Wheel seal leaking. Remove hub, degrease hub and brakes and clean with brush, rince and repeat till done. Fit new hub seal, tension spindle nut to 500FT-lb refit axle and tighten nuts, adjust brakes. Replaced R/H bonnet rubber. Replaced suzi 7 pin plug. Drag link needs replacing. Trans output shaft needs tightening. Topped up diff oil.	
17/01/2025		Cab R-986	Andrew's Mobile Windscreens
09/01/2025		Brakes R-587	
09/01/2025		Engine R-786	BMR Logistics
		11.09.2024 -Found pressure relief valve on Air Drier constantly leaking, can see oring inside caught behind spring, fixed pressure relief but found to be opening again before operating pressure is reached, pick up new pressure relief valve and fit to drier. Unbolt and clean exhaust port, spring and valve for air drier blow off as was constantly releasing air. Drained air tanks as both tanks were close to full with water, found air system going past max pressure and not blowing off, check D2 governor, found compressor is governed by the air drier, removed 1/4 hose and run shop air up line to find compressor decompresses, found little air coming out of fitting on air drier and thought that to be issue, when blocking the fitting the drier blows off and operates as normal, disconnected the shop air from compressor line and noticed line didnt feel pressurised/air didnt blow back out line, turned off engine and run shop air through compressor line again, found Air coming out tell-tale on side of compressor head. Compressor head needs rebuild kit through it. 12.09.2024 -	

Date	Reading / Units	Type / Repairer Notes	Repairer
09/01/2025		Chassis R-759	BMR Logistics
08/12/2024	659,184 kms	Cab R-837 Removed light assembly from old tank step, mark, drill and fit light assembly to new step, bend and hammer tank strap/step mounts back straight and fit new step, plug in lights and test operation.	BMR Logistics
08/12/2024	659,184 kms	Chassis R-894 Unbolt and remove old handle, check table for further damage, noticed tab broken off behind handle lock but lock still operating as it should, fit new turntable handle and reattach extension and cable.	BMR Logistics
05/11/2024	637,383 kms	Electrical R-833 Replaced 7 pin plug for trailer lights.	BMR Logistics
05/11/2024	637,383 kms	Cab R-783 Replaced hose	BMR Logistics
01/11/2024	636,258 kms	C - 100k/Annual S-609 -Sleeper Air hours: 1621hrs Service due -Air drier needs rekit, water in system. -Air compressor not unloading, metal sound inside compressor when unloader valve is activated.	BMR Logistics
25/10/2024	634,578 kms	New T-419 2 new Jinyu JF568 Front	BMR Logistics
09/10/2024	567,403 kms	Glass R-133 Replaced job with jobcard R-382	
04/10/2024	621,632 kms	New T-400 8 x new Jinyu JD571	BMR Logistics
26/09/2024	616,685 kms	Runout T-394 1 x Runout Left Front outer Drive	BMR Logistics
11/09/2024		Cab R-786 Replaced ride height valve with new	BMR Logistics
10/09/2024	610,788 kms	Cab R-783 Press and push trim grooves back around glass, had trouble for some time as when you go around pushing it in other parts fall back out, found soapy water helps to allow grooves to slide back over glass properly without catching or pushing itself back out. Went to wash soapy water off glass and found wiper washers not working, inspect and found driver wiper hose has broken in the middle of the hose, found spare wiper with hose still attached, remove and fit hose from spare wiper but when tested again found hole in hose, cover hole with heat shrink, hose is just too short/stretches slightly in operation and has poor flow.	BMR Logistics
02/09/2024	605,233 kms 1 hrs	Runout T-381 3 x Runouts, 2 left rear, 1 right front outer	BMR Logistics
02/09/2024	605,233 kms	Brakes R-516 Brakes were adjusted last service and operate/stop as normal on truck, trailer brake fault was previously corrected and was due to a kink in suzi coils. Suzi coils were replaced and the cause for kink in lines was identified and corrected on all corresponding trailers.	BMR Logistics
28/08/2024	599,065 kms	Engine R-766 see invoice hot hose had chaffed a hole	Penske
20/08/2024	593,655 kms	Cab R-758 Replaced driver wiper blade	BMR Logistics
12/08/2024	587,811 kms	B - 40k S-525 -Crack in both windshields. -L/h lower step damaged. -Scrap along L/H front flare. -Driver seat belt fraying.	BMR Logistics
09/08/2024	586,169 kms	Chassis R-724	BMR Logistics

Date	Reading / Units	Type / Repairer Notes	Repairer
		Jack bottom of fuel tank to take weight off, unbolt strap and refit tank strap rubbers, rotate tank back to correct position and tighten down tank straps, loosen bolts for top step and realign with rear top step before tightening back down.	
03/08/2024	581,761 kms	Electrical R-710	BMR Logistics
		Top right spot light faulty, top lefts bracket is broken through, advised due to the shock impact from the position of the lights and rough road that they should be switched with Bar lights. Removed old spot lights and fit 2 spotlight bar lights. Solder in new wiring and ziptied out of the way.	
02/08/2024	580,979 kms	Cab R-712	BMR Logistics
		Remove all top bolts, refit L/h wing in correct position, refit bolts.	
31/07/2024	577,755 kms	Engine R-702	BMR Logistics
		Add 7ltrs engine oil to bring back to full.	
30/07/2024		Air Conditioner Cabin Truck dash R-698	PETER CLARKE AIRCONDITIONING
26/07/2024		Cab R-674	
26/07/2024	575,732 kms	Air Conditioner Cabin Truck dash R-689	BMR Logistics
		23/07/2024 573333km 0.25hr Inspect A/C and found pipe broken out of compressor. Inspect oil level and found oil inbetween lines on dipstick 24/07/2024 574135km .66hr Remove a/c pipe between compressor and condenser for repairs. Wire brush, clean and fit repaired a/c pipe. Driver complained of oil again with same problem but upon checking level is same as yesterday half way between low and high and does not need any attention. 26/07/2024 575732km Replaced all bonded washers for a/c pipe, peter clark vac down system to remove moisture from system and charged with R134a.	
22/07/2024		Glass R-382	
22/07/2024		Cab R-651	BMR Logistics
22/07/2024		Chassis R-651	
18/07/2024	568,218 kms	Brakes R-660	BMR Logistics
		Inspect for damage to suzi service line, no repairs will be required at this stage (suzi coils only two weeks old), driver stated he didnt have any issues driving back from Moranbah after removing the kink and squeezing the line back to round. (27B and all sister trailers to it are to have the connections moved and grouped together).	
17/07/2024	567,403 kms	A - 10k S-486	BMR Logistics
		-R/H top bull light out. -L/H lower step damaged. -Scrape on L/H front bonnet flare. -Driver seat belt tearing, needs to be replaced. -Driver window cracked through the middle. R-382	
17/07/2024	567,403 kms	Lights R-651	BMR Logistics
		Unbolt front casing, tapped behind led light, tried smacking to see if it would go out again but stayed lit.	
04/07/2024	556,706 kms	Chassis R-609	BMR Logistics
		Lift up end of tail-light bar with jack and tighten all bolts on bracket.	
04/07/2024	556,706 kms	A - 10k S-452	BMR Logistics
		L/H rear tail-light bar fallen down.	
19/06/2024	545,977 kms	Brakes R-556	BMR Logistics
		Cut zipties and untangle hoses and leads, remove and replace suzi hoses, replace female connector fitting due to crack in thread, intertwine suzi hoses and ziptie hoses and leads together neatly.	
14/06/2024	1 hrs	Main/inspect T-289	
14/06/2024	543,562 kms	B - 40k S-421	BMR Logistics
07/06/2024	537,749 kms	Chassis R-524	BMR Logistics
		Straighten rear marker sign, drill new holes in sign and mudflap, unbolt existing bolts from mudflap and refit sign to r/h rear mudflap	
31/05/2024	532,791 kms	A - 10k S-371	BMR Logistics

Date	Reading / Units	Type / Repairer Notes	Repairer
		L/H tail light bar bent. L/H Marker plate missing from L/h rear mudflap. L/H rear side marker light missing	
31/05/2024	532,791 kms	Chassis, Lights R-496 Used forklift to help bend tail light bar back in place and hammer out and damage, replaced missing clearance light and solder in wiring, replaced missing marker plate on mudflap.	BMR Logistics
28/05/2024	519,470 kms	Chassis R-381 Check over engine, chassis, brakes, suspension and cab, found wiper blades can be replaced, rear side fibreglass wings have come loose and broken at top (same issue as BMR012 earlier today) and windscreen is cracked through driver vision. - Replaced wiper blades. - Remove bolts from tops of fibreglass wings and add larger washers to cover cracks for better security.	BMR Logistics
13/05/2024	515,160 kms	Chassis R-352 Check and tighten radiator bushes and brackets. Adjusted/aligned bonnet with cab Adjusted side front tank mudguards to match with bonnet. (Previous damage from cow has bent bullbar brackets, no alignment can be made to straighten)	BMR Logistics
13/05/2024	515,160 kms	Chassis R-352 Remove sleeper air top cover, unbolt sleeper air rear cover where hanging loose, refit bolts with bigger washers and refit top cover.	BMR Logistics
08/05/2024	515,160 kms	Main/inspect T-193 2x295x80x22 8xpressure check Miss match steers used run outs from bmr017	
08/05/2024	515,160 kms	A - 10k S-334	BMR Logistics
03/05/2024		T-120	
03/05/2024	1 hrs	Pressure Check T-148	
29/04/2024	505,772 kms	Engine R-303 Icepack 1506hrs	BMR Logistics
24/04/2024		Electrical R-304	Future Adventure Auto Electrical
18/04/2024	500,334 kms	B - 40k S-260 Delete this Job, B service is replaced with C service #269	BMR Logistics
16/04/2024	500,334 kms	C - 100k/Annual S-269	BMR Logistics
10/04/2024	500,334 kms	Electrical R-243 No on going issues found with indicators	BMR Logistics
04/04/2024	491,183 kms	Lights R-249 Inspect fuses and found blown 30amp blade fuse, replaced fuse and bull lights work again. No visable signs of wear in wiring	BMR Logistics
21/03/2024	479,730 kms 1 hrs	Pressure Check T-120	
13/03/2024	476,819 kms	Pressure Check T-111	
26/02/2024		Pressure Check T-66 8x Rotate @0.25 = 2hrs 10x Pressure @0.05 = 0.5hrs	
26/02/2024	460,023 kms	Lights R-126 Replaced l/h upper bull light mounting bracket with spare on shelf, test light operation, tighten all face cover bolts and bracket bolts on all spotlights	
23/02/2024	461,867 kms	B - 40k S-163 Tyres checked by john L/h lower kingpin cap not taking grease (come out side of cap), removed cap and grind flat on wet stone, refit cap and greased kingpin without issue. (30min)	
19/02/2024	450,394 kms	Chassis R-62	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Tighten all bolts, found bolt missing/broken in gusset for R/h side, opposite bolt to be removed for reference and broken bolt to be removed from thread when suppliers are open	
09/02/2024		Electrical R-47 x1 key cut. (Paid by c/card)	Jim Roberts Locksmith
02/02/2024	445,318 kms	Cab R-35 Bend LH foot step back straight and refit bracket.	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
31/01/2024	444,438 kms	Pressure Check T-11 Check tyre pressures x10	
31/01/2024	444,438 kms	Chassis R-18 Replace 2x rear mudflaps. Fit new red/yellow marker plates LH/RH 600x150mm	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
30/01/2024	443,128 kms	Lights R-8 Check bull lights fuse, okay. Checked power at lights, no power. Checked power at fuse and nothing there. Check all fuses and found ACC Power Battery 1 fuse blown. Replaced fuse and bull lights now working okay.	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
02/12/2023	407,299 kms	C - 100k/Annual S-32 C SERVICE	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
06/09/2023	359,038 kms	B - 20k/250hrs/180d S-6 B SERVICE	Primary Mechanical Repairs

Signed: _____

Name: _____

Date: _____