

## Vehicle History Detail

Fleet #	
Registration	
Make	HAMLEX
Model	HXWD99A
VIN / Chassis #	6D9HXW1TT3MW66150

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		<b>RMS HVIS REQUIRED I-22</b>			
01/12/2025	713,000 kms	<b>RMS INSPECTION R-3836</b> INSPECTION SHEET FROM HEAVY VEHICLE INSPECTION AZ2980210			\$0.00
21/11/2025	715,000 kms	<b>B - A Service S-2677</b> REGO INSPECTION DONE HYDRAULIC HOSE FALLING OFF REPAIRED DRAWBAR SPRING MISSING REPLACED ALL TRAILER SHOCK RUBBERS WORN REPLACED TRAILER REFLECTORS MISSING REPLACED TURNTABLE MOUNTING BOLTS LOOSE REPAIRED REVERSE AND BRAKE LIGHTS INOP - REPAIRED GRAIN SHUTE LOOSE REPAIRED AIR LEAK INSIDE DRAWBAR - REPAIRED MARKER PLATES WORN REPLACED ALL TRAILER WHEEL BEARINGS EXCESSIVE MOVEMENT REPAIRED 3RD AXLE CROSS MEMBER AND SIDE BRACE CRACKED WELDS - REPAIRED.			\$0.00
24/10/2025	706,556 kms	<b>C - B Service S-2665</b>			\$0.00
11/10/2025	702,624 kms	<b>A - O Service S-2649</b>			\$0.00
27/09/2025	696,864 kms	<b>B - A Service S-2636</b>			\$0.00
05/06/2025	691,753 kms	<b>A - O Service S-2541</b>			\$0.00
10/12/2024		<b>AIR BAG, TARP R-3318</b> REPLACE AIR BAG BARRATTS. REPLACE TARP MOTOR ACL BATHURST.			\$0.00
29/11/2024		<b>WHEEL BEARINGS R-3283</b> ADJUST 1ST AND 3RD AXLE WHEEL BEARINGS AND ALSO 2ND AXLE LHS. GREASE AND ADJUST BRAKES. FIT NEW BOLT TO BALL RACE MOUNT. RE STRAIGHTEN AND FIT NEW BOLT TO FRONT TARP PULLY.		0399	\$605.00
25/11/2024		<b>RMS INSPECTION R-3287</b> CHECK OVER FOR REGO BEARINGS, BUSHES LIGHTS ETC.			\$0.00
15/10/2024	682,943 kms	<b>C - B Service S-2359</b>			\$0.00
28/09/2024		<b>TRUCK TYRES R-3203</b> REPLACE 4 TYRES STRIP FIT REPLACE. LH MUDFLAP FIX LIGHTS NOT WORKING			\$0.00

Date	Reading	Type	Repair Notes	Repaired	Invoice	Cost
21/09/2024	675,097 kms	B - A	Service S-2337			\$0.00
31/08/2024	662,531 kms	A - O	Service S-2314			\$0.00
26/07/2024	662,531 kms	C - B	Service S-2284			\$0.00
06/07/2024	654,916 kms	B - A	Service S-2260			\$0.00
22/06/2024	649,236 kms	A - O	Service S-2253			\$0.00
04/06/2024	642,475 kms	C - B	Service S-2239			\$0.00
25/05/2024	639,314 kms	A - O	Service S-2221			\$0.00
06/04/2024	627,871 kms	A - O	Service S-2184			\$0.00
09/03/2024			SHORT WIRING R-2770 REWIRE PLUG AT BACK OF TRUCK, REPLACE BRAKE LIGHT UNIT ON REAR LH DOG			\$0.00
01/03/2024	619,845 kms	C - B	Service S-2147			\$0.00
13/02/2024			AIR LINES R-2635 INSPECT WELD LEG BACK ON CHECK FOR AIR LEAKS			\$0.00
03/02/2024	609,306 kms	B - A	Service S-2116			\$0.00
20/01/2024	603,352 kms	A - O	Service S-2099			\$0.00
02/01/2024	597,058 kms	C - B	Service S-2072			\$0.00
17/11/2023	586,371 kms	B - A	Service S-2029			\$0.00
07/10/2023	580,899 kms	A - O	Service S-1965			\$0.00
13/09/2023	574,863 kms	C - B	Service S-1945			\$0.00
15/07/2023	544,990 kms	B - A	Service S-1863			\$0.00
30/06/2023	544,990 kms	A - O	Service S-1850			\$0.00
16/06/2023	544,990 kms	C - B	Service S-1834			\$0.00
22/05/2023	544,990 kms	A - O	Service S-1790			\$0.00
10/05/2023	544,990 kms	B - A	Service S-1778			\$0.00
31/03/2023	534,501 kms	C - B	Service S-1725			\$0.00
25/02/2023	521,502 kms	A - O	Service S-1690			\$0.00
11/02/2023	521,502 kms	B - A	Service S-1670 NONE			\$0.00
21/01/2023	495,047 kms	A - O	Service S-1592			\$0.00

Date	Reading	Type / Repair	Notes	Repair	Invoice	Cost
17/12/2022	495.861 kms	C - B Service	S-1635			\$0.00
07/12/2022		Tyres	R-2246 BATHURST TRUCK REPAIRS STRIP AND FIT 4 NEW TYRES ON REAR AXLE			\$0.00
15/11/2022		WHEEL BEARINGS	R-2225 TIGHTEN APPROPRIATE WHEEL BEARING GET SPARKS AND SPANNERS TO FIX LIGHT PROBLEM.			\$0.00
05/11/2022	495.861 kms	C - B Service	S-1621			\$0.00
17/10/2022		Defect	R-2277			\$0.00
16/09/2022	495.861 kms	A - O Service	S-1554			\$0.00
21/07/2022	207.992 kms	D - C Service	S-1477 CARRIED OUT C SERVICE			\$0.00
21/07/2022	207.992 kms	SHOCK BUSHES	R-1942 REPLACED			\$0.00
21/07/2022	207.992 kms	TRUNION BUSHES	R-1942 T.B.A.			\$0.00
25/05/2022	482.391 kms	C - B Service	S-1366 CARRIED OUT B SERVICE			\$0.00
02/04/2022	472.680 kms	B - A Service	S-1417 CARRIED OUT A SERVICE			\$0.00
07/03/2022	468.614 kms	A - O Service	S-1300			\$0.00
11/02/2022		DEFECT - SERVICE BRAKES	R-1809			\$0.00
11/02/2022		DEFECT CLEARANCE	R-1809 DEFECT HVN0610006 CLEARED			\$0.00
05/02/2022	463.600 kms	B - A Service	S-1306			\$0.00
26/11/2021	452.979 kms	B - A Service	S-1224			
29/10/2021	441.408 kms	A - O Service	S-1201			
11/09/2021	441.408 kms	C - B Service	S-1111			
06/08/2021	435.707 kms	A - O Service	S-1085			
11/07/2021	432.430 kms	B - A Service	S-1025			
12/06/2021	427.688 kms	A - O Service	S-1017			
18/05/2021	421.677 kms	TREAD	R-1321 Replace 6 caps with clearskins from BTW			

Date	Reading	Type / Repair / Notes	Repair	Invoice	Cost
12/05/2021		<b>C - B Service S-945</b>			
07/05/2021	420.154 kms	<b>Defect - Minor R-1308</b> cleared			
23/04/2021	403.112 kms	<b>A - O Service S-954</b> 3rd axle air bags split			
04/12/2020	409.478 kms	<b>B - A Service S-813</b>			
16/11/2020	404.359 kms	<b>Defect - Minor R-1169</b> Cleared			
22/10/2020	403.112 kms	<b>C - B Service S-800</b>			
21/08/2020	394.039 kms	<b>Defect - Minor R-1100</b> cleared			
10/08/2020	394.040 kms	<b>B - A Service S-781</b>			
14/04/2020	373.638 kms	<b>B - A Service S-534</b>			
28/02/2020	370.294 kms	<b>MUDGUARD R-953</b> Remove guard reweld and gusset cracked area			
19/02/2020	368.175 kms	<b>A - O Service S-515</b>			
11/11/2019	365.929 kms	<b>RMS HVIS REQUIRED I-76</b>			
13/08/2019	359.295 kms	<b>A - O Service S-407</b>			
19/06/2019	355.270 kms	<b>MUDGUARD R-764</b> pat thick wall tube up inside original tube weld in place rewire light.			
03/06/2019	352.083 kms	<b>B - A Service S-337</b>			
11/04/2019	348.115 kms	<b>A - O Service S-325</b>			
11/03/2019	344.011 kms	<b>C - B Service S-318</b>			
18/02/2019	340.726 kms	<b>A - O Service S-301</b>			
09/01/2019	334.959 kms	<b>B - A Service S-273</b>			
11/12/2018	331.730 kms	<b>WHEEL BEARINGS R-1340</b> Remove repack bearing and refit to tension			
12/11/2018		<b>RMS HVIS REQUIRED I-68</b>			
11/11/2018		<b>Axle R-569</b> Remove, repack bearing and refit to tension			
05/11/2018	324.600 kms	<b>C - B Service S-173</b>			

Date	Reading	Type / Repair	Notes	Repaired	Invoice	Cost
12/10/2018		<b>Tyres R-505</b>	Replace			
12/10/2018	321,774 kms	<b>TREAD R-1339</b>	cleared			
04/08/2018	310,115 kms	<b>B - A Service S-130</b>				
07/07/2018		<b>Lights R-358</b>	Replace lights unit x1			
27/06/2018	303,312 kms	<b>C - B Service S-126</b>				
22/05/2018	296,700 kms	<b>B - A Service S-285</b>				
22/05/2018	296,700 kms	<b>B - A Service S-117</b>				
02/05/2018		<b>Body R-241</b>	Replace and fit bearing RH rear.			
19/04/2018		<b>B - A Service S-108</b>				
19/04/2018		<b>A - O Service S-156</b>	O Service Grease chassis, brake and turntable components Check all lights, reflectors and marker plates Check for air leaks			
19/04/2018		<b>B - A Service S-107</b>				
28/03/2018	282,415 kms	<b>C - B Service S-72</b>				
26/02/2018		<b>A - O Service S-89</b>				
27/01/2018	272,123 kms	<b>A - O Service S-94</b>				
14/12/2017		<b>A - O Service S-157</b>	O Service Grease chassis, brake and turntable components Check all lights, reflectors and marker plates Check for air leaks			
23/11/2017		<b>TREAD R-1336</b>	Replace rear axle 4 tyres			
22/11/2017	264,870 kms	<b>OIL LEAK, Shocks R-1335</b>	Replace all shocks parts ex south coast			
26/10/2017	263,695 kms	<b>B - A Service S-28</b>				
26/10/2017	263,695 kms	<b>C - B Service S-27</b>				
<b>102 Records</b>					<b>Total:</b>	<b>\$605.00</b>