

Work Order	Plant	Plant Description	Scheduled	Status	Type	Work Description	Finish Date
WO14438	DT16	2021 Mack Superliner	11/10/2021	Complete	CI	INSTALL BUG DEFLECTOR	01/04/2022
WO14496	DT16	2021 Mack Superliner	11/15/2021	Complete	PM	250HR SERVICE DT16 @ 331 hrs	11/19/2021
WO14515	DT16	2021 Mack Superliner	11/15/2021	Complete	WA	Sublet CMV - Taking off on 3rd gear-15/11/21	12/13/2021
WO14748	DT16	2021 Mack Superliner	11/25/2021	Complete	BD	25.11.21 NO INDICATORS (FLASH RELAY FAULT)	12/13/2021
WO14937	DT16	2021 Mack Superliner	12/16/2021	Complete	PM	500HR SERVICE DT16	01/05/2022
WO15046	DT16	2021 Mack Superliner	12/13/2021	Complete	BD	Punctured tyre	12/13/2021
WO16139	DT16	2021 Mack Superliner	02/13/2022	Complete	PM	250HR SERVICE DT16	02/08/2022
WO16376	DT16	2021 Mack Superliner	02/19/2022	Complete	BD	FLASHER RELAY FAULT - ONGOING PROBLEM - ANDY	10/19/2022
WO16490	DT16	2021 Mack Superliner	03/12/2022	Complete	PM	Sublet AOEM - 1000HR SERVICE DT16	03/16/2022
WO16625	DT16	2021 Mack Superliner	03/10/2022	Complete	CI	FIT WEATHER SHIELD ON DRIVERS SIDE WINDOWS	07/06/2022
WO16740	DT16	2021 Mack Superliner	03/11/2022	Complete	DF	Sublet Goodyear - Prestart-Rotate steer tyres-11/3/22	04/07/2022
WO16741	DT16	2021 Mack Superliner	03/11/2022	Complete	DF	Prestart-Hoist cyl sometimes skips a stage coming	07/25/2022
WO16742	DT16	2021 Mack Superliner	03/11/2022	Complete	DF	Prestart-Dog lock is activated via trailer control	01/18/2023
WO16743	DT16	2021 Mack Superliner	03/11/2022	Complete	DF	Prestart-lift axles make creeking sound when	07/04/2022
WO17158	DT16	2021 Mack Superliner	04/01/2022	Complete	DF	Sublet Goodyear - Prestart-drive tyres need replacing-1/4/22	04/07/2022
WO17418	DT16	2021 Mack Superliner	04/13/2022	Complete	DF	Sublet-CMV-Spd calibration,idle timing-13/4/22	06/14/2022
WO17449	DT16	2021 Mack Superliner	04/14/2022	Complete	TY	Sublet - Goodyear - Needs new steer tyres soon. 14/4/22	06/14/2022
WO17503	DT16	2021 Mack Superliner	04/18/2022	Complete	PM	Sublet - Victech - 250HR SERVICE DT16-SS043	05/03/2022
WO17868	DT16	2021 Mack Superliner	05/05/2022	Complete	MI	Replace LH rear mud flap.	07/04/2022
WO18297	DT16	2021 Mack Superliner	06/06/2022	Complete	PM	SUBLET - VICTECH - 500HR SERVICE DT16-SS043	06/20/2022
WO18608	DT16	2021 Mack Superliner	07/01/2022	Complete	MI	Serv Fault - Requires new electric horn	09/15/2022
WO18727	DT16	2021 Mack Superliner	07/11/2022	Complete	CI	Prestart - Fit shovel under body please	07/25/2022
WO18839	DT16	2021 Mack Superliner	07/22/2022	Complete	PM	Sublet - Victech - 250HR SERVICE DT16-SS043	07/25/2022
WO18973	DT16	2021 Mack Superliner	07/22/2022	Complete	MI	Pre Start - fibreglass tarp cover broken at front	02/27/2024
WO19375	DT16	2021 Mack Superliner	08/05/2022	Complete	MI	Prestart - Front Parker Lights are out	09/19/2022
WO19948	DT16	2021 Mack Superliner	09/01/2022	Complete	CI	Fabricate and Fit Steering Column Boxes	09/01/2022
WO19966	DT16	2021 Mack Superliner	09/01/2022	Complete	PM	Sublet - Victech - 2000HR SERVICE DT16-SS043	09/15/2022
WO20083	DT16	2021 Mack Superliner	09/08/2022	Complete	TY	Sublet - Goodyear - rotate steer tyres	09/21/2022
WO20547	DT16	2021 Mack Superliner	10/11/2022	Complete	PM	Sublet - Victech - 250HR SERVICE DT16-SS043	10/18/2022
WO21030	DT16	2021 Mack Superliner	11/09/2022	Complete	TY	Sublet - goodyear - puncture repair POS3	11/09/2022
WO21106	DT16	2021 Mack Superliner	11/14/2022	Complete	PM	Sublet - Victech - 500HR SERVICE DT16-SS043	12/01/2022
WO21213	DT16	2021 Mack Superliner	11/21/2022	Complete	MI	Prestart - new wiper blades	12/02/2022
WO21476	DT16	2021 Mack Superliner	12/02/2022	Complete	CA	Serv Fault - Front wheel bearings need to be adjusted	01/17/2023
WO21518	DT16	2021 Mack Superliner	12/06/2022	Complete	PM	250HR SERVICE DT16-SS043 -	01/17/2023
WO21999	DT16	2021 Mack Superliner	01/11/2023	Complete	MI	DT16- UHF not working	01/25/2023
WO22148	DT16	2021 Mack Superliner	01/18/2023	Complete	TY	Serv Fault - rear drive tyres worn	01/31/2023
WO22235	DT16	2021 Mack Superliner	01/24/2023	Complete	PM	1000HR SERVICE DT16-SS043	02/01/2023
WO22267	DT16	2021 Mack Superliner	01/25/2023	Complete	GE	DT16- Replace driver side elec window switch	01/25/2023
WO22318	DT16	2021 Mack Superliner	02/01/2023	Complete	CA	Inspect and replace body locating rubbers	02/01/2023
WO22499	DT16	2021 Mack Superliner	02/09/2023	Complete	TY	Sublet- Goodyear - replace front drive tyres	02/10/2023
WO22702	DT16	2021 Mack Superliner	02/21/2023	Complete	PM	250HR SERVICE DT16-SS043	03/07/2023
WO22919	DT16	2021 Mack Superliner	03/06/2023	Complete	TY	Sublet - Goodyear - Tyre rotation + balance	03/07/2023
WO22941	DT16	2021 Mack Superliner	03/08/2023	Complete	MI	DT16-Weld radiator bracket	03/08/2023
WO23157	DT16	2021 Mack Superliner	03/21/2023	Complete	PM	500HR SERVICE DT16-SS043	04/05/2023
WO23201	DT16	2021 Mack Superliner	03/23/2023	Complete	MI	DT16-Replace Tarp, Cable & pulleys	03/28/2023
WO23322	DT16	2021 Mack Superliner	03/30/2023	Complete	TY	Sublet - Goodyear - Replace Steer tyres	03/31/2023
WO23327	DT16	2021 Mack Superliner	03/31/2023	Complete	CA	DT16-Exhaust manifold leaking & exhaust flex at dump	05/02/2023
WO23328	DT16	2021 Mack Superliner	03/31/2023	Complete	CA	DT16-Tipper body mount bolts require replacing x 10	05/10/2023
WO23329	DT16	2021 Mack Superliner	03/31/2023	Complete	MI	DT16-Replace belt & belt tensioner	04/24/2023
WO23559	DT16	2021 Mack Superliner	04/17/2023	Complete	CA	Sublet - L&A - Wheel alignment - 2nd May 1PM	05/16/2023
WO23584	DT16	2021 Mack Superliner	04/18/2023	Complete	PM	250HR SERVICE DT16-SS043	05/10/2023
WO23835	DT16	2021 Mack Superliner	05/04/2023	Complete	BD	Replace oil filters due to leak	05/04/2023
WO24009	DT16	2021 Mack Superliner	05/10/2023	Complete	MI	Replace mud flap over ring feeder	05/10/2023
WO24206	DT16	2021 Mack Superliner	05/17/2023	Complete	CA	Replace heater hose	05/19/2023
WO24610	DT16	2021 Mack Superliner	06/08/2023	Complete	PM	2000HR SERVICE DT16-SS043	06/16/2023
WO24739	DT16	2021 Mack Superliner	06/19/2023	Complete	MI	DT16-Replace both steering shaft uni,s	07/10/2023
WO25120	DT16	2021 Mack Superliner	07/06/2023	Complete	MI	Bracket on cooling pipe broken	07/10/2023
WO25338	DT16	2021 Mack Superliner	07/19/2023	Complete	MI	Serv-Replace turbo waste gate hose	09/04/2023
WO25900	DT16	2021 Mack Superliner	08/18/2023	Complete	MI	Change 90 deg hyd coulping	08/23/2023
WO25924	DT16	2021 Mack Superliner	08/21/2023	Complete	CA	Prestart- Front parker light not working	08/21/2023
WO25931	DT16	2021 Mack Superliner	08/21/2023	Complete	PM	250HR SERVICE DT16-SS043	08/21/2023
WO26261	DT16	2021 Mack Superliner	09/05/2023	Complete	CA	Prestart- Transmission check light on dash is on,	10/24/2023
WO26316	DT16	2021 Mack Superliner	09/07/2023	Complete	TY	Sublet- Goodyear - Rotate steer + replace POS13-16	09/07/2023
WO26363	DT16	2021 Mack Superliner	09/08/2023	Complete	TY	sublet-Goodyear - Rotate steer tyres	09/08/2023
WO26618	DT16	2021 Mack Superliner	09/21/2023	Complete	PM	500HR SERVICE DT16-SS043	10/09/2023
WO27067	DT16	2021 Mack Superliner	10/16/2023	Complete	CA	Engine exhaust brake only works sometimes	05/02/2024
WO27093	DT16	2021 Mack Superliner	10/17/2023	Complete	PM	250HR SERVICE DT16-SS043	10/30/2023
WO27246	DT16	2021 Mack Superliner	10/24/2023	Complete	CA	Prestart - Grain door needs repair (Loosing product)	02/21/2024
WO27439	DT16	2021 Mack Superliner	11/01/2023	Complete	MI	Sublet NEWS- replace r/h windscreen	11/02/2023
WO27783	DT16	2021 Mack Superliner	11/20/2023	Complete	TY	Prestart-sublet-Goodyear- replace rear drive tyres	11/29/2023
WO28005	DT16	2021 Mack Superliner	11/28/2023	Complete	PM	1000HR SERVICE DT16-SS043	12/15/2023
WO28093	DT16	2021 Mack Superliner	12/04/2023	Complete	CA	Prestart-Air con leaks water into cab passenger side	02/21/2024
WO28106	DT16	2021 Mack Superliner	12/05/2023	Complete	MI	serv-Replace ring feeder	12/06/2023
WO28353	DT16	2021 Mack Superliner	12/19/2023	Complete	CA	FLH drive axle brakes - replace	12/20/2023
WO29215	DT16	2021 Mack Superliner	02/19/2024	Complete	MI	Prestart- 2x roof clearance lights not working	04/29/2024
WO29247	DT16	2021 Mack Superliner	02/21/2024	Complete	PM	250HR SERVICE DT16-SS043	02/21/2024
WO29352	DT16	2021 Mack Superliner	02/27/2024	Complete	TY	Change drive tyres - middle axle	03/22/2024
WO29378	DT16	2021 Mack Superliner	02/29/2024	Complete	MI	serv-replace LED roof flashing light	04/29/2024

WO29618	DT16	2021 Mack Superliner	03/13/2024	Complete	MI	Prestart- L/H parker not working	03/19/2024
WO29654	DT16	2021 Mack Superliner	03/14/2024	Complete	PM	500HR SERVICE DT16-SS043	03/26/2024
WO29706	DT16	2021 Mack Superliner	03/18/2024	Complete	TY	Prestart- Replace front steer tyres	07/09/2024
WO29850	DT16	2021 Mack Superliner	03/21/2024	Complete	CA	Replace all 4 batteries	03/21/2024
WO30509	DT16	2021 Mack Superliner	04/23/2024	Complete	PM	250HR SERVICE DT16-SS043	05/01/2024
WO30855	DT16	2021 Mack Superliner	05/17/2024	Complete	PM	2000HR SERVICE DT16-SS043	06/19/2024
WO30895	DT16	2021 Mack Superliner	05/17/2024	Complete	MI	prestart- floor light out	07/11/2024
WO31348	DT16	2021 Mack Superliner	06/13/2024	Complete	MI	prestart- exhaust leak under cab	06/20/2024
WO31513	DT16	2021 Mack Superliner	06/24/2024	Complete	MI	Prestart- both wide view mirrors loose in frame	10/30/2024
WO32927	DT16	2021 Mack Superliner	08/23/2024	Complete	CA	Prestart - Replace headlight globe LHS	08/23/2024
WO33067	DT16	2021 Mack Superliner	09/10/2024	Complete	PM	250HR SERVICE DT16-SS043	09/23/2024
WO33919	DT16	2021 Mack Superliner	10/23/2024	Complete	PM	500HR SERVICE DT16-SS043	10/30/2024
WO35117	DT16	2021 Mack Superliner	12/05/2024	Complete	PM	250HR SERVICE DT16-SS043	12/13/2024
WO35760	DT16	2021 Mack Superliner	01/07/2025	Complete	TY	Sublet - Goodyear - replace rear axle drive tyres	01/08/2025
WO35820	DT16	2021 Mack Superliner	01/08/2025	Complete	BD	Tarp repairs- new tarp cable	01/08/2025
WO35958	DT16	2021 Mack Superliner	01/14/2025	Complete	BD	Leaking radiator	01/28/2025
WO35959	DT16	2021 Mack Superliner	01/14/2025	Complete	CA	Roof lights not working	01/16/2025
WO35960	DT16	2021 Mack Superliner	01/14/2025	Complete	CA	Compressor relief valve stuck open	01/16/2025
WO36132	DT16	2021 Mack Superliner	01/21/2025	Complete	CA	Replace brake air line	01/20/2025
WO36400	DT16	2021 Mack Superliner	01/29/2025	Complete	PM	1000HR SERVICE DT16-SS043	02/03/2025
WO36657	DT16	2021 Mack Superliner	02/11/2025	Complete	CA	Serv: Rear torque rod has play (twist movement)	03/19/2025
WO36658	DT16	2021 Mack Superliner	02/11/2025	Complete	CA	Serv: Bottom uni's on steering shaft have play	03/24/2025
WO36659	DT16	2021 Mack Superliner	02/11/2025	Complete	CA	Serv: Drag link has play (twist movement)	03/18/2025
WO37046	DT16	2021 Mack Superliner	03/06/2025	Complete	PM	250HR SERVICE DT16-SS043	03/24/2025
WO37562	DT16	2021 Mack Superliner	03/24/2025	Complete	MI	Ser Fault-Replace Pinion seal, thru shaft rear of front diff	04/03/2025
WO38154	DT16	2021 Mack Superliner	04/27/2025	Complete	PM	500HR SERVICE DT16-SS043	05/01/2025
WO38303	DT16	2021 Mack Superliner	04/23/2025	Complete	CA	Replace seat ride valve	05/01/2025
WO38450	DT16	2021 Mack Superliner	05/01/2025	Planned	MI	Replace steering damper	
WO38895	DT16	2021 Mack Superliner	05/31/2025	Complete	PM	250HR SERVICE DT16-SS043A - Drive Axel brakes	05/28/2025
WO39092	DT16	2021 Mack Superliner	06/06/2025	Complete	BD	Replace steering column strut	06/08/2025
WO39103	DT16	2021 Mack Superliner	06/10/2025	In Progress	MI	Prestart - LH headlight leaking water and dirt	07/21/2025
WO39522	DT16	2021 Mack Superliner	06/30/2025	Complete	BD	Intermittent stalling - low on power	06/30/2025
Work Order	Plant	Plant Description	Scheduled	Status	Type	Work Description	Finish Date
WO13830	TT16	2021 Hercules PBS 6 Axle Dog	10/19/2021	Complete	CA	realign wirers and tarps	11/18/2021
WO14527	TT16	2021 Hercules PBS 6 Axle Dog	11/15/2021	Complete	DF	Fit new slack adjuster-15/11/21	11/16/2021
WO14530	TT16	2021 Hercules PBS 6 Axle Dog	11/15/2021	Complete	PM	Grease and Adjust Brakes	11/18/2021
WO14618	TT16	2021 Hercules PBS 6 Axle Dog	11/19/2021	Complete	CI		11/30/2021
WO15043	TT16	2021 Hercules PBS 6 Axle Dog	12/13/2021	Complete	PM	Grease and Adjust Brakes	01/06/2022
WO15156	TT16	2021 Hercules PBS 6 Axle Dog	12/20/2021	Complete	DF	Prestart-axle 6 drivers side grease leak-17/12/21	01/05/2022
WO15271	TT16	2021 Hercules PBS 6 Axle Dog	01/05/2022	Complete	DM	cracks in body /warrenty	01/17/2023
WO16227	TT16	2021 Hercules PBS 6 Axle Dog	02/08/2022	Complete	PM	Grease and Adjust Brakes	02/08/2022
WO16275	TT16	2021 Hercules PBS 6 Axle Dog	02/10/2022	Complete	DF	Needs pass 1st axle slack adjuster assm-10/2/22	03/16/2022
WO16369	TT16	2021 Hercules PBS 6 Axle Dog	02/18/2022	Complete	BD	New Tyres #9 #10 #11 #12	02/18/2022
WO16744	TT16	2021 Hercules PBS 6 Axle Dog	03/11/2022	Complete	DF	Prestart-tarp buttons are on backwards-11/3/22	06/30/2022
WO16765	TT16	2021 Hercules PBS 6 Axle Dog	03/15/2022	Complete	PM	Sublet AOEM - Grease and Adjust Brakes	03/15/2022
WO16798	TT16	2021 Hercules PBS 6 Axle Dog	03/17/2022	Complete	DF	Welding repairs on RHS rear bar-17/3/22	03/17/2022
WO16917	TT16	2021 Hercules PBS 6 Axle Dog	03/21/2022	Complete	DF	Sublet Goodyear-flat tyre-21/3/22	03/23/2022
WO16969	TT16	2021 Hercules PBS 6 Axle Dog	03/23/2022	Complete	DM	PRODUCT LEAKING DOWN SIDE OF THE FLOOR	05/04/2022
WO17652	TT16	2021 Hercules PBS 6 Axle Dog	04/22/2022	Complete	PM	Sublet - Victech - Grease and Adjust Brakes	05/02/2022
WO18328	TT16	2021 Hercules PBS 6 Axle Dog	06/09/2022	Complete	PM	Sublet - VICTECH - Grease and Adjust Brakes	06/20/2022
WO18606	TT16	2021 Hercules PBS 6 Axle Dog	07/01/2022	Complete	MI	Serv fault - Crack on lift up axle	06/20/2023
WO18607	TT16	2021 Hercules PBS 6 Axle Dog	07/01/2022	Complete	MI	Serv Fault - Body mount rubbers worn	10/24/2022
WO18720	TT16	2021 Hercules PBS 6 Axle Dog	07/08/2022	Complete	MI	Sublet - Wals Auto - Tail lights staying on	07/14/2022
WO18722	TT16	2021 Hercules PBS 6 Axle Dog	07/11/2022	Complete	BD	Sublet - Goodyear - Replace rear axle tyres #6	07/11/2022
WO18964	TT16	2021 Hercules PBS 6 Axle Dog	07/21/2022	Complete	PM	Sublet - Victech - Grease and Adjust Brakes	07/25/2022
WO18974	TT16	2021 Hercules PBS 6 Axle Dog	07/22/2022	Complete	MI	Pre Start - Black Mesh Tarp damaged at front	10/10/2022
WO19176	TT16	2021 Hercules PBS 6 Axle Dog	07/29/2022	Complete	CA	Change out tow eye bush	07/29/2022
WO19376	TT16	2021 Hercules PBS 6 Axle Dog	08/05/2022	Complete	CA	Prestart - Rear RHS mudflap needs remounting	10/19/2022
WO19967	TT16	2021 Hercules PBS 6 Axle Dog	09/01/2022	Complete	PM	Sublet - Victech - Grease and Adjust Brakes	09/21/2022
WO20416	TT16	2021 Hercules PBS 6 Axle Dog	10/03/2022	Complete	MI	Replace tarp cable Both Sides	10/10/2022
WO20504	TT16	2021 Hercules PBS 6 Axle Dog	10/07/2022	Complete	MI	TT16 - Fit locking nut to turnbuckle	10/07/2022
WO20548	TT16	2021 Hercules PBS 6 Axle Dog	10/11/2022	Complete	PM	Sublet - Victech - Grease and Adjust Brakes	10/18/2022
WO21061	TT16	2021 Hercules PBS 6 Axle Dog	11/11/2022	Complete	CA	WELD DRAW BAR LEG BACK ON	12/19/2022
WO21118	TT16	2021 Hercules PBS 6 Axle Dog	11/15/2022	Complete	PM	sublet - victech - Grease and Adjust Brakes	12/01/2022
WO21248	TT16	2021 Hercules PBS 6 Axle Dog	11/23/2022	Complete	TY	Sublet - Goodyear - 8 x new tyres	11/23/2022
WO21262	TT16	2021 Hercules PBS 6 Axle Dog	11/23/2022	Complete	MI	Replace grease block - check auto greaser	01/10/2022
WO21462	TT16	2021 Hercules PBS 6 Axle Dog	12/01/2022	Complete	CI	Install safety chains	01/12/2023
WO21519	TT16	2021 Hercules PBS 6 Axle Dog	12/06/2022	Complete	PM	Grease and Adjust Brakes	01/17/2023
WO22212	TT16	2021 Hercules PBS 6 Axle Dog	01/24/2023	Complete	CA	Tarp blocks	01/24/2023
WO22234	TT16	2021 Hercules PBS 6 Axle Dog	01/24/2023	Complete	PM	Grease and Adjust Brakes	02/01/2023
WO22408	TT16	2021 Hercules PBS 6 Axle Dog	02/06/2023	Complete	TY	Prestart - 4 x tyres middle front tri	02/10/2023
WO22703	TT16	2021 Hercules PBS 6 Axle Dog	02/21/2023	Complete	PM	Grease and Adjust Brakes	03/07/2023
WO22770	TT16	2021 Hercules PBS 6 Axle Dog	02/27/2023	Complete	CA	Fitting new tarp block	02/28/2023
WO22860	TT16	2021 Hercules PBS 6 Axle Dog	03/02/2023	Complete	CA	Turn up auto greaser	03/02/2023
WO22928	TT16	2021 Hercules PBS 6 Axle Dog	03/07/2023	Complete	TY	Sublet - goodyear - tyre repair	03/07/2023
WO23158	TT16	2021 Hercules PBS 6 Axle Dog	03/21/2023	Complete	PM	Grease and Adjust Brakes	04/11/2023
WO23324	TT16	2021 Hercules PBS 6 Axle Dog	03/31/2023	Complete	CA	TT16 dolly - crack in lift axle dolly	06/16/2023
WO23325	TT16	2021 Hercules PBS 6 Axle Dog	03/31/2023	Complete	MI	TT16- A frame bushs worn, replace	04/27/2023
WO23326	TT16	2021 Hercules PBS 6 Axle Dog	03/31/2023	Complete	GE	TT16- Replace tow eye bush, 3mm of play	04/27/2023

WO23373	TT16	2021 Hercules PBS 6 Axle Dog	04/04/2023	Complete	TY	Change tyre	04/04/2023
WO23585	TT16	2021 Hercules PBS 6 Axle Dog	04/18/2023	Complete	PM	Grease and Adjust Brakes	05/10/2023
WO24336	TT16	2021 Hercules PBS 6 Axle Dog	05/25/2023	Complete	MI	TT16-Replace tarp blocks & cable	05/25/2023
WO24407	TT16	2021 Hercules PBS 6 Axle Dog	05/30/2023	Complete	CA	Replace cracked tarp blocks	07/10/2023
WO24612	TT16	2021 Hercules PBS 6 Axle Dog	06/08/2023	Complete	PM	Grease and Adjust Brakes	06/16/2023
WO24633	TT16	2021 Hercules PBS 6 Axle Dog	06/09/2023	Complete	CA	Prestart - Grease nipple broken on rear hinge	07/10/2023
WO24740	TT16	2021 Hercules PBS 6 Axle Dog	06/19/2023	Complete	GE	TT16-Replace both "A" frame bushes	07/21/2023
WO24741	TT16	2021 Hercules PBS 6 Axle Dog	06/19/2023	Complete	CA	TT16-Replace 3x reflectors that are missing	07/21/2023
WO24742	TT16	2021 Hercules PBS 6 Axle Dog	06/19/2023	Complete	CA	TT16-Replace slack adjuster return spring L/H axle 1	07/21/2023
WO25932	TT16	2021 Hercules PBS 6 Axle Dog	08/21/2023	Complete	PM	Grease and Adjust Brakes	08/21/2023
WO25948	TT16	2021 Hercules PBS 6 Axle Dog	08/22/2023	Complete	CA	Serv Fault - Axle 1 & 4 and 6 need suspension bushes	12/06/2023
WO26196	TT16	2021 Hercules PBS 6 Axle Dog	08/29/2023	Complete	TY	Sublet - Goodyear - Needs new tyres POS 9 10 11 12	08/30/2023
WO26248	TT16	2021 Hercules PBS 6 Axle Dog	09/04/2023	Complete	CA	Prestart- Replace trailer bump stops	10/09/2023
WO26361	TT16	2021 Hercules PBS 6 Axle Dog	09/08/2023	Complete	TY	Sublet-Goodyear- 4x tyres accross front of rear tri	10/06/2023
WO26619	TT16	2021 Hercules PBS 6 Axle Dog	09/21/2023	Complete	PM	Grease and Adjust Brakes	10/09/2023
WO26850	TT16	2021 Hercules PBS 6 Axle Dog	10/09/2023	Complete	CA	TT16 Prestart- Replace lost draw bar spring & cable	10/30/2023
WO27059	TT16	2021 Hercules PBS 6 Axle Dog	10/13/2023	Complete	CA	Replace tarp blocks	10/18/2023
WO27094	TT16	2021 Hercules PBS 6 Axle Dog	10/17/2023	Complete	PM	Grease and Adjust Brakes	10/30/2023
WO27463	TT16	2021 Hercules PBS 6 Axle Dog	11/02/2023	Complete	GE	serv-Replace A frame bushes	12/04/2023
WO28006	TT16	2021 Hercules PBS 6 Axle Dog	11/28/2023	Complete	PM	Grease and Adjust Brakes	12/06/2023
WO28012	TT16	2021 Hercules PBS 6 Axle Dog	11/28/2023	Complete	TY	Change tyre	11/28/2023
WO28135	TT16	2021 Hercules PBS 6 Axle Dog	12/01/2023	Complete	TY	Sublet - Goodyear - puncture repair	12/05/2023
WO28150	TT16	2021 Hercules PBS 6 Axle Dog	12/05/2023	Complete	CA	Replace tow eye bush	12/07/2023
WO29011	TT16	2021 Hercules PBS 6 Axle Dog	02/09/2024	Complete	TY	Sublet-Goodyear- fit 12 new tyres	02/16/2024
WO29256	TT16	2021 Hercules PBS 6 Axle Dog	02/21/2024	Complete	PM	Grease and Adjust Brakes	02/21/2024
WO29353	TT16	2021 Hercules PBS 6 Axle Dog	02/27/2024	Complete	TY	Change tyre	03/22/2024
WO29655	TT16	2021 Hercules PBS 6 Axle Dog	03/14/2024	Complete	PM	Grease and Adjust Brakes	03/20/2024
WO29895	TT16	2021 Hercules PBS 6 Axle Dog	03/22/2024	Complete	BD	replace missing drawbar spring DUPLICATE	03/25/2024
WO29896	TT16	2021 Hercules PBS 6 Axle Dog	03/25/2024	Complete	MI	Prestart- replace missing A frame spring	03/26/2024
WO30118	TT16	2021 Hercules PBS 6 Axle Dog	04/08/2024	Complete	TY	Prestart- Middle axle rear tri- needs tyres	04/10/2024
WO30384	TT16	2021 Hercules PBS 6 Axle Dog	04/22/2024	Complete	MI	Prestart- replace suspension air bag,	04/22/2024
WO30510	TT16	2021 Hercules PBS 6 Axle Dog	04/23/2024	Complete	PM	Grease and Adjust Brakes	05/01/2024
WO30790	TT16	2021 Hercules PBS 6 Axle Dog	05/13/2024	Complete	CA	Prestart- grain door loose	06/19/2024
WO30791	TT16	2021 Hercules PBS 6 Axle Dog	05/13/2024	Complete	CA	Prestart- L/H grease line on tipper pin rubbed through	07/11/2024
WO30856	TT16	2021 Hercules PBS 6 Axle Dog	05/17/2024	Complete	PM	Grease and Adjust Brakes	06/19/2024
WO32850	TT16	2021 Hercules PBS 6 Axle Dog	08/17/2024	Complete	PM	Grease and Adjust Brakes	09/23/2024
WO32895	TT16	2021 Hercules PBS 6 Axle Dog	08/29/2024	Complete	MI	Replace tarp cable motor bracket & Battery Charger	09/09/2024
WO33432	TT16	2021 Hercules PBS 6 Axle Dog	09/26/2024	Complete	MI	TT16-Replace nylon pads from tipper body to frame & bolts	10/30/2024
WO34291	TT16	2021 Hercules PBS 6 Axle Dog	10/29/2024	Complete	PM	Grease and Adjust Brakes	10/30/2024
WO35001	TT16	2021 Hercules PBS 6 Axle Dog	11/28/2024	Complete	CA	Vehicle accident - tail light NW	11/28/2024
WO35224	TT16	2021 Hercules PBS 6 Axle Dog	12/06/2024	Complete	PM	Grease and Adjust Brakes	12/13/2024
WO35815	TT16	2021 Hercules PBS 6 Axle Dog	01/08/2025	Complete	TY	Sublet - Goodyear - new tyres 3rd+6th axle	12/20/2024
WO36490	TT16	2021 Hercules PBS 6 Axle Dog	02/03/2025	Complete	PM	Grease and Adjust Brakes	02/03/2025
WO36656	TT16	2021 Hercules PBS 6 Axle Dog	02/11/2025	Complete	CA	Serv: Body mounts need replacing	03/13/2025
WO36995	TT16	2021 Hercules PBS 6 Axle Dog	02/26/2025	Complete	TY	Sublet - Goodyear - tyre Puncture repair pos 24	02/26/2025
WO37180	TT16	2021 Hercules PBS 6 Axle Dog	03/04/2025	Complete	PM	Grease and Adjust Brakes	03/24/2025
WO37807	TT16	2021 Hercules PBS 6 Axle Dog	04/01/2025	Complete	TY	Prestart: Pos 3 tyre scrubbing- GB T30	05/13/2025
WO38448	TT16	2021 Hercules PBS 6 Axle Dog	05/01/2025	Complete	PM	Grease and Adjust Brakes	05/01/2025
WO38473	TT16	2021 Hercules PBS 6 Axle Dog	05/07/2025	Complete	BD	Replace lift axle air bag on dolly	05/11/2025
WO38536	TT16	2021 Hercules PBS 6 Axle Dog	05/07/2025	Complete	CA	Replace 2 x ride height valves	06/15/2025
WO38939	TT16	2021 Hercules PBS 6 Axle Dog	05/29/2025	Complete	PM	Grease and Adjust Brakes- Replace brakes x 1 axel	06/11/2025
WO39251	TT16	2021 Hercules PBS 6 Axle Dog	06/16/2025	Complete	CA	Replace drawbar bushes	06/22/2025
WO39261	TT16	2021 Hercules PBS 6 Axle Dog	06/17/2025	Forecast	TY	Serv fault - Needs new tyres	
WO39262	TT16	2021 Hercules PBS 6 Axle Dog	06/17/2025	Forecast	CA	Serv fault - Body mount rubbers need replacing	
WO39521	TT16	2021 Hercules PBS 6 Axle Dog	06/30/2025	In Progress	TY	Tyre puncture repair	