

Work Order History Listing

Search: 3107

W/O ...	Asset No	Asset Description	Description
17049	303107-FEL1467	CATERPILLAR 980H	Decon unit. Washed and cleaned whole machine. Clean and blown air inside cab. Removed fire extinguishers inside & outside. 9944hrs
16611	303107-FEL1467	CATERPILLAR 980H	PM2 - Victoria Plant Pool - Caterpillar 980H unit disposed 15/1/26
15629	303107-FEL1467	CATERPILLAR 980H	Brakes getting jammed on & gears neutralizing. Checked & inspected machine brake jammed found out park brake is partially releasing due to linkages are worn. Cleaned and lubricated linkages and booster rod then adjusted park brake to last adjustment ...
15333	303107-FEL1467	CATERPILLAR 980H	Park brake jamming on. Checked and inspected machine found out park brake released are loosed at mounting. Removed front dash panel and installed parking brake release properly at mounting. Calibrated tilt & lift bucket level & sensor. Tested machin ...
15223	303107-FEL1467	CATERPILLAR 980H	PM1 - Victoria Plant Pool - Caterpillar 980H completed
15207	303107-FEL1467	CATERPILLAR 980H	Faults list. (Muffler pipe leaking, Tyres not serviceable, bucket pins need shimming & hydraulic oil leak @ hydraulic line.) Repair muffler. Cleaned & blown air control valves, hose connections. then located hyd oil leak @ supply hose. Removed and r ...
14850	303107-FEL1467	CATERPILLAR 980H	PM3 - Victoria Plant Pool - Caterpillar 980H Washed and cleaned the whole machine. Started 1000hr service PM3. Finished PM3 Service. Topped up coolant and tested for leak all good. Checked and repaired wiper washer n/w. Straighten rear steps r/h/r ...
14503	303107-FEL1467	CATERPILLAR 980H	Steps damaged. Fab steps because used 4070 set on this loader.
14396	303107-FEL1467	CATERPILLAR 980H	Replace x3 grease hose lines as leaking & Seat not adjusting. Checked and inspected seat not adjusting found out adjusting cable pulled out and lock bolt missing. Connected adjusting cable to handle and installed locking bolt. tested all good. Assis ...
14362	303107-FEL1467	CATERPILLAR 980H	Front guard damaged. Remove flap drill re bolt.
14354	303107-FEL1467	CATERPILLAR 980H	Pin noisy when lifting (lifting issues.) & Repair steps. check system, no grease to front pins, auto greaser faulty, broken lines replaced lines, replaced unit with one from 988G loader, tested all ok, manually greased all pins Repair step. Repair b ...
14149	303107-FEL1467	CATERPILLAR 980H	PM1 - Victoria Plant Pool - Caterpillar 980H
14035	303107-FEL1467	CATERPILLAR 980H	Fit cab fire extinguisher. Fit fire extinguisher in cab.
13107	Tr112 Truck	Tr112 Truck	PB 5/6/25 Replace chevrons as found on mex:12911 DV 5/6/25 spoke to PB and booked in for 1.30pm 12/6/25 PB 13.6.25 Techs to busy will have to re book. PB 25.6.25 Waiting on paperwork. Bring up truck from tipper yard. clean tailgate area & fix all ch ...
12684	303107-FEL1467	CATERPILLAR 980H	Carry out Prerelease. Conducted walk around inspection. Checked all oil levels engine, hydraulic, trans all good. Run & tested machine all good. Calibrated bucket lever sensor and linkage. Clear all faults. no active faults. 33488hrs
12427	303107-FEL1467	CATERPILLAR 980H	Fault on dash 274-4. Removed wiring harness connection. Removed and replaced atmospheric pressure sensor. then connected all wiring harness. Run & tested no faults. 32015hrs
12389	303107-FEL1467	CATERPILLAR 980H	R/DIFF Stabilizer worn needs to be repaired. Wades to repair worn trunnions 5.5.25 LM 48369 assist driving fork remove, stripe, replace and reassemble rear trunnion assembly.
12385	303107-FEL1467	CATERPILLAR 980H	Bonnet n/w up & down. Removed r/h/r mounting cover box. Removed all muds & dirt. cleaned and blown air found out switch of bonnet up/ down broken. Removed and replaced switch assy. Run and tested all good. installed back installed back all related ...
12058	303107-FEL1467	CATERPILLAR 980H	faults bucket auto level pin left side near cab cracked weld seat doesnt slide forward, requires force. Grind existing welds + re weld pins into position. Repair bucket level fault. Check and inspected operator seat jammed found out dirty and dusty. ...
11894	303107-FEL1467	CATERPILLAR 980H	PM2 - Victoria Plant Pool - Caterpillar 980H Make parts request. arranged/ ordered parts. Make parts request. Arranged/ordered parts. Conducted PM2 Service as per service sheets. Trouble shoot repair working lamp n/w r/h/f top. Tighten hose clamps @ ...
11689	303107-FEL1467	CATERPILLAR 980H	Oil leak. Checked & inspected hydraulic leak near front top axle diff. Open control valve plate cover washed & cleaned control valve assy located oil leak at check valve plug. Removed check valve & order parts. Pick up parts @ William Adams. Install ...
11608	303107-FEL1467	CATERPILLAR 980H	Hydraulic leak. Checked and inspected machine @ jobsite found out hydraulic leak under cab. Removed all side plate covers and located hose busted at pressure test line. Removed hose test line and put plug fittings. Refilled hydraulic oil. Test run a ...
11572	303107-FEL1467	CATERPILLAR 980H	A/C N/W. Stealth fixing 26.2.25 Completed by Stealth. inv.96714 Wrong fleet number its not 3107 its 3087
11321	303107-FEL1467	CATERPILLAR 980H	oil leak. lift loader arms chock. isolate. remove guarding dig out buildup of rock and glass. locate leaking pipe. dig out surrounding Debry on rest of pipe. test new pipe. fill with hydraulic fluid. 33337hrs
11306	303107-FEL1467	CATERPILLAR 980H	Cracked pin. Grind out weld + crack + weld.
11235	303107-FEL1467	CATERPILLAR 980H	Replace batteries. Stealth fixing 31.1.25 Completed by Stealth inv. 96289

Work Order History Listing

Search: 3107

Search

W/O #	Asset No	Asset Description	Description	
10636	303107-FEL1467	CATERPILLAR 980H	Bucket self-level issues & Front washers not working. Checked and calibrated bucket lift and tilt linkage position sensors. Error code 351-13 done thru computer tool. calibrated and clear the code. Run and tested all good. Reweld retainer pin to loa ...	
10259	303107-FEL1467	CATERPILLAR 980H	Exhaust loose. Checked and inspected exhaust loose found out fiber glass mounting air all cracked and damaged. Fabricated bracket plates measured and cut plates, drilled holes and bolted.	
10189	303107-FEL1467	CATERPILLAR 980H	Oil sample testing Hyd and Engine retesting required due to abnormal results 24/10/2024 as attached.	
10094	303107-FEL1467	CATERPILLAR 980H	Scales out of calibration. Checked and inspected scale n/w found out sensor linkage pulled out. Installed back sensor linkage and calibrated scales. Run and tested scales then adjusted linkage and calibrated scales all good. 33020hrs	
9969	303107-FEL1467	CATERPILLAR 980H	PM3 - Victoria Plant Pool - Caterpillar 980H Pick up parts. Carry out PM3 Service. R&R Bonnet jack pump motor assy. Cleaned and removed all dirt & Mud around ram assy l/h/s & r/h/s. R&R L/h/s bonnet ram assy. Calibrated tilt & lift bucket leveling. ...	
9768	303107-FEL1467	CATERPILLAR 980H	Reverse buzzer n/w & Warning fault on dash. Checked and inspected reverse buzzer not working found out connection wiring cable disconnected. Connected wiring cable and secured wiring cables. Checked warning fault found out code 351-13 Tilt linkage o ...	
9364	303107-FEL1467	CATERPILLAR 980H	repairs and calibration of scales & Washer's n/w. Booked for Smart tech 10/10/24 Checked and Inspected scale n/w found out sensor not functioning need Elec/Stealth tech. done it last. Checked and inspected washer's n/w found out front washer n/w. Re ...	
8940	303107-FEL1467	CATERPILLAR 980H	Scales n/w Stealth fixing 30.8.24 P/O: 102023 Completed. inv. 00093759	
8634	303107-FEL1467	CATERPILLAR 980H	Scales malfunctioning. Stealth fixing 21.08.24 P/O:101783 Completed by Stealth. inv.00093734 Radar Stealth inv.00094039 19.8.24 check weigh scales not working repair wiring to sensor, angle sensor faulty to order replacement	
8275	303107-FEL1467	CATERPILLAR 980H	Check hand brake system as reported as not working & Internal door lock issues. Checked and inspected hand brake n/w found out two much gap between brake shoes & drum. Cleaned and lubricated brake adjuster then adjusted as per required. tested and...	
7878	303107-FEL1467	CATERPILLAR 980H	washers not working Grease line to be checked Load rite scale's fault Checked and Inspected washer's front n/w. Removed waterline and blown air as well as sprayer then tested all good. Checked grease line at l/h/s bucket ram all good. Checked scale ...	
7778	303107-FEL1467	CATERPILLAR 980H	PM1 - Victoria Plant Pool - Caterpillar 980H Carry out PM1 Service.	
7663	303107-FEL1467	CATERPILLAR 980H	Leaking coolant top radiator hose (elbow) blown. Source new unit and collect. fit to machine, top up coolant and test, all ok.	
7583	303107-FEL1467	CATERPILLAR 980H	Lower front headlight L/H & R/H/S n/w. / windscreen washers n/w. / Bucket and Lift controls stop working & Swap buckets over. Remove bucket assy and installed bigger bucket assy. Take Engine oil sample as required. As per Darren's request. Supply an ...	
7565	303107-FEL1467	CATERPILLAR 980H	Warning fault on dash. / Hydraulics stop working. Checked dash couldn't find fault. tested couldn't get to fault. 32625hrs Wades PO 101388	
7430	303107-FEL1467	CATERPILLAR 980H	Hydraulic leak. Checked and inspected hydraulic leak. found out leaking coming from control valve hose line connection. Removed hose line and found out O-ring seal damaged. Replaced O-ring seal then installed back. Run & tested all hyd. Functions al ...	
5650	303107-FEL1467	CATERPILLAR 980H	Oil pressure light on. Removed and replaced oil pressure sensor. Installed Diagnostic tool and tested all parameters are in required specs. No active faults. 32517hrs	
5634	303107-FEL1467	CATERPILLAR 980H	Top r/h pin coming out. Re weld pin retainer on loader. Installed back arm pin pulled out at r/h/s Grub boiler maker to weld due to pin lock is not there anymore. so, lock it with weld.	
5501	303107-FEL1467	CATERPILLAR 980H	PM2 - Victoria Plant Pool - Caterpillar 980H & Repairs. Conducted PM2 Service as per service sheets. Removed and Replaced connection hyd hose from oil cooler to trans. Trouble shoot wiper rear n/w found out wiper motor only making noise, but n/w. Or ...	
4768	303107-FEL1467	CATERPILLAR 980H	Hydraulic leak. Collect parts for repair. Remove and replace hose and o rings. Prime hydraulic system. Wash loader. Fit new fire extinguisher and bag.	
4758	303107-FEL1467	CATERPILLAR 980H	fire extinguisher testing Replaced in May	
4161	303107-FEL1467	CATERPILLAR 980H	Not selecting gears. Stealth looking at 30.4.24 P/O:099458. Completed by stealth	
4110	303107-FEL1467	CATERPILLAR 980H	PM1 - Victoria Plant Pool - Caterpillar 980H & Repairs Carry out PM1 + Defects. Help and Assist Jamie conducting Pm1 service. Repair windscreen front washer not working. Cleaned bay. 32267hrs	
3866	303107-FEL1467	CATERPILLAR 980H	Wade's invoice PO-099132 Remove pinseals, bushes, greaselines & Install pinseals, cylinder, pins, hose.	
3829	303107-FEL1467	CATERPILLAR 980H	Transmisson shifting issue, load clunking when shifting into gears, On track recent rebuild, found faulty Transmisson shift modules. replaced and reset system, tested all ok. PO 099065	
3818	303107-FEL1467	CATERPILLAR 980H	Hydraulic leak front of artic leaking test line on lift arms, blanked off system, cleaned and tested, all ok.- Ready PO:099072. Trace hydraulic leak.	

3003	303107-FEL1467	CATERPILLAR 980H	Safety check check Steering cylinder radiator core leaking missing knobs in cab power hood lift not working lift frame pin has moved out driver step to be repaired hood loose engine divider damaged check hyd level rear door lock nt working door l..
2282	303107-FEL1467	CATERPILLAR 980H	Pins and bushes getting done on w/o: 3003
2280	303107-FEL1467	CATERPILLAR 980H	check Steering cylinder getting checked on w/o: 3003
2277	303107-FEL1467	CATERPILLAR 980H	Centre hitch replacement completed by On Track Diesel Feb 2024
2023	303107-FEL1467	CATERPILLAR 980H	Grease hose needs replacing Reddy attended to complete works
2017	303107-FEL1467	CATERPILLAR 980H	Refer Checkproof D002206 - transmission not reversing, struggling to move when in reverse MT - 27/11/2023 - valve replaced did not fix issue. Mechanics diagnose fault. MJS45496, MJS47382 & MJS45855 Reverse clutch faulty, not drive when in reverse - p...
1984	303107-FEL1467	CATERPILLAR 980H	Loader 3107 - Blown radiator hose DG 22/11/2023 - Remove blown hose & fit new one. Fill with coolant & test for leaks. No leaks. MJS45928
1936	303107-FEL1467	CATERPILLAR 980H	PM4 - Victoria Plant Pool - Caterpillar 980H Check with Dennis re Lou finished this PM4 on Monday DG 20/11/2023 - Service has been completed refer W/O 1749
1749	303107-FEL1467	CATERPILLAR 980H	PM4 - Victoria Plant Pool - Loaders DG 10/11/2023 - Start on PM4 service. MJS47494, MJS47362 & MJS45472
1676	303107-FEL1467	CATERPILLAR 980H	Loader 3107 - Hydraulic leak DG 09/11/2023 - Wash down machine & check for oil leak. Leaking from hydraulic pump & pump is cavitating. MJS45470 & MJS47360 DG 10/11/2023 - Diagnose fault with pump & order new pump. MJS47362 DG 13/11/2023 - Re...
1645	303107-FEL1467	CATERPILLAR 980H	Loader 3107 - Blown hydraulic hose DG 01/11/2023 - Remove blown hydraulic hose & have hose technician make new one. Fit new hose & blank off test port. MJS45337. Reddy PO-95958
1550	303107-FEL1467	CATERPILLAR 980H	Loader 3107 - Overheating DG 23/10/2023 - replaced hose clamp on hose to valve tap. MJS45089
1351	303107-FEL1467	CATERPILLAR 980H	Loader 3107 PM1 service. DG 27/09/2023 - complete PM1 service. MJS47298
1165	303107-FEL1467	CATERPILLAR 980H	Loader 3087 - Blown hydraulic hose. DG 06/09/2023 - Remove engine cover panels to access blown hydraulic hose. Hose fitter replaced hose. MJS47252 Reddyfix Hydraulics & Maintenance. PO-94738 Invoice 2432.
1085	303107-FEL1467	CATERPILLAR 980H	Loader 3107 - Leaking hydraulic oil.
1024	303107-FEL1467	CATERPILLAR 980H	PM2 service & defects DG 21/08/2023 - Start PM2 service. MJS44012 DG 22/08/2023 - Complete PM2 service & replace condenser. Replace wiper arm, repair wiring & reposition load frame pin. MJS44015, MJS44057 & MJS44059. DG 23/08/2023 - Replace arm..