



Time: 15:47

BRANDT TRACTOR LTD.
Service History Summary
SRT: SERNO,W0,CUST

Page: 1
(SHHIST-1)

BL19-7

SERIAL NUMBER: 1T0850LXJNF417541

MAKE: JD

MODEL: 850L

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT	TOTAL PARTS	TOTAL LABOR	TOTAL MISC	TOTAL SEG.
CUSTOMER:	53800005	INTERNAL								
1558383-01		INT	4.0			19MAY22				
1558383-02		INT	4.0		CALIBRATE CROSS SLOPE.	19MAY22				
1558383-03		INT	4.0		INSTALL GUARDING PACKAGE.	19MAY22				
1558383-04		INT	4.0		ESPAR.	19MAY22	.00	.00		
1558839-02		CHG	34.0		INSTALL RIPPER.	30JUN22	.00			.00
1558839-01		WTY	34.0		TRAVEL-F0B	30JUN22				
1558839-03		INT	34.0		REPAIR HYDRAULIC LEAK	30JUN22		.00		
1558839-04	E	INT	34.0		CHECK FOR FINAL DRIVE NOISE/VIBRATION	30JUN22	.00	.00		
1558947-02		CHG	45.0			19JUL22	.00			.00
1558947-01		WTY	45.0		TRAVEL-F0B	19JUL22				
1558947-04	E	INT	45.0		REPAIR PARK BRAKE LEAK	19JUL22	.00	.00		
1558947-03		INT	45.0			19JUL22	.00	.00		
1559209-02		CHG	195.0		O/T NOT COVERED UNDER WTY	29JUL22	.00			.00
1559209-01		WTY	195.0		TRAVEL-F0B	29JUL22				
1559209-04	E	INT	195.0		REPAIR 94.03 CODES	29JUL22	.00	.00		
1559209-03		INT	195.0			29JUL22	.00	.00		
1559694-02		CHG	401.0		O/T NOT COVERED UNDER WTY	24SEP22	.00			.00
1559694-01		WTY	401.0		TRAVEL-F0B	24SEP22				
1559694-03	E	INT	401.0		REPAIR DEAD BATTERIES	24SEP22	.00	.00		
1559825-01		INT	479.0			29SEP22				
1559826-02		CHG	479.0		ASI	29SEP22	.00			.00
1559826-01		WTY	479.0		TRAVEL-F0B	29SEP22				
1559826-04	E	INT	479.0		REPAIR LEAK	29SEP22	.00	.00		
1559826-03		INT	479.0			29SEP22	.00			
1560425-02		CHG	739.0		O/T NOT COVERED BY WTY	29NOV22	.00			.00
1560425-01		WTY	739.0		TRAVEL-F0B	29NOV22				
1560425-04	E	INT	739.0		REPAIR DEAD BATTERIES - POSSIBLE BATTERY DRAW	29NOV22	.00	.00		



BRANDT TRACTOR LTD.
Service History Summary
SRT: SERNO,W0,CUST

Page: 2
(SHIST-1)

SERIAL NUMBER: 1T0850LXJNF417541

MAKE: JD

MODEL: 850L

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT	TOTAL PARTS	TOTAL LABOR	TOTAL MISC	TOTAL SEG.
CUSTOMER:	58442730	4T CONTRACTING								
1561032-03		CHG	915.0			28JAN23	.00			.00
					TRAVEL-F08					
1561032-01	E	WTY	915.0			28JAN23				
					REPLACE LEAKING BOTTOM ROLLER #1 RH					
1561032-02	E	WTY	915.0			28JAN23				
					REPLACE LEAKING ROLLER #2 LH SIDE					
1561032-04	E	INT	915.0			28JAN23	.00	.00		
1561980-01		INT	1280.0			20APR23	.00			
					INSTALL SATELITE RADIO					
1561980-02		INT	1280.0			20APR23	.00	625.00	12.50	637.50
					TRAVEL					
1563936-02		CHG	1769.0			29OCT23	.00			.00
					TRAVEL-F08					
1563936-01		WTY	1769.0			29OCT23				
					REPAIR CROSS SLOPE					
1563936-03	E	INT	1769.0			29OCT23	.00	.00		
1564225-02		CHG	1901.0			30NOV23	.00			.00
					TRAVEL-F08					
1564225-01	E	WTY	1901.0			30NOV23				
					REPAIR 3471.05 FUEL DOSING CONTROL VALVE CIRCUIT					
1564225-03	E	WTY	1901.0			30NOV23	.00			
					REPAIR JDLINK					
1564225-04	E	INT	1901.0			30NOV23	.00	.00		
1558467-01		INT	546.0			28MAY22				
					REMOVE RIPPER FROM 850L 409897, PACKAGE FOR TRANSPORT.					
4705674-01	E	CGD	2.0			22APR22		.00	.00	
					Add diesel fuel					
4705674-02		CGD	2.0			22APR22				
					PDI					
4705674-03		CGD	2.0			22APR22	.00			
					Install blade					
4705743-01	E	INT	2.0			30APR22	.00			
					REMOVE BLADE FOR SHIPPING					

ENTRIES -

45



BRANDT TRACTOR LTD.
Service History Summary
SRT: SERVO,WO,CUST

Page: 3
(SHIST-1)

SERIAL NUMBER: 1FF2654GKHD260010 MAKE: JD MODEL: 2654G

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT	TOTAL PARTS	TOTAL LABOR	TOTAL MISC	TOTAL SEG.
CUSTOMER:	58442730	4T CONTRACTING								
1547547-03	INT		1070.0		O/T NOT COVERED BY WARRANTY	28SEP18	.00	--		
1547706-02	CHG		1100.0		TRAVEL	160CT18	.00			.00
1547706-01	WTY		1100.0		DIAGNOSE/REPAIR NO MONITOR	160CT18				
1547706-03	WTY		1100.0		DIAGNOSE/REPAIR LEAK	160CT18				
1547706-05	E INT		1100.0			160CT18	.00	.00		
1547706-04	INT		1100.0			160CT18		.00		
1548256-01	E WTY		1346.0		ASSEMBLY CHARGES	18JAN19				
1548256-02	E WTY		1346.0	18TX884A	18TX884A - DHSP PROPORTIONAL ROCK	18JAN19				
1548254-01	WTY		1347.0		PIP TRAVEL	31JAN19				
1548254-02	CHG		1347.0		FACTORY UNDERCARRIAGE - LH IDLER LEAKING	31JAN19	18.03	1,100.00	99.00	1,217.03
1548254-03	CHG		1347.0		LH IDLER - LABOR ONLY	31JAN19	.00	530.00	430.00-	100.00
1548254-04	CHG		1347.0		TRAVEL	31JAN19	18.39	720.00	64.00	803.19
1548254-05	E INT		1347.0		REPLACE SWING GREASE	31JAN19	.00	.00		
1550627-02	E CHG		2160.0			080CT19	.00			.00
1550627-03	CHG		2160.0		TRAVEL	080CT19	.00	167.25	16.72	183.97
1550627-01	E WTY		2160.0		REPLACE CUTTING EDGE	080CT19				
1550627-04	E WTY		2160.0		DIAGNOSE/REPAIR BUCKET SNAP	080CT19				
1550627-06	E INT		2160.0		DIAGNOSE/REPAIR NO MONITOR	080CT19	.00	.00		
1550627-05	INT		2160.0			080CT19	.00			
1551704-01	E WTY		2886.0		O/T NOT COVERED UNDER WARRANTY	29JAN20				
1551704-02	E CHG		2886.0		DIAGNOSE/REPAIR COOLANT LEAK	30JAN20	.00			.00
1551704-04	E INT		2886.0		TRAVEL - FOB	30JAN20	.00	.00		
1551704-03	INT		2886.0			30JAN20	.00			
1553348-03	E CHG		3375.0		O/T NOT COVERED BY WARRANTY	24SEP20	.00			.00
1553348-06	CHG		3375.0		TRAVEL-FOB	24SEP20	152.93	.00	.00	152.93
1553348-01	WTY		3375.0		ITEMS NOT COVERED UNDER WARRANTY					
					DIAGNOSE/REPAIR PILOT PUMP LEAK					