

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	235651	11/09/2024 0:00	76015	PREP FOR AUCTION, Completed by: wilson.wang@porterplant.com.au on: Sep 11, 2024	GR - GENERAL REPAIRS
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	236243	26/08/2024 0:00	76015	REPLACED BATTERY. REPAIRED PTO., REPLACED FLAT BATTERIES. LOOKED AT PTO BUT LOOKED TO BE ALL RUSTED ON EVERY CONTACT UNDERNEATH & COULD NOT, GET TO WORK. DISASSEMBLED ANTI BURST VALVE & MANUALLY LIFTED LEG. TIED UP WITH STRAP., Completed by:jackson.amendola@porterplant.com.auon:Aug 26, 2024	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	216124	14/04/2023 0:00	76015	REPAIRED WIRING MAIN SAFETY SWITCH FOR HYDRUALICS., FOUND TRUCK NOT ABLE TO BE MOVED DUE TO FRONT OUT RIGGER NOT IN STOWED POSITION (ON GROUND)., WAS UNABLE TO BE OPERATED. CHECKED OVER. FOUND SAFETY SYSTEM ACTIVATED & HYDRAULIC SYSTEM, DISABLED. FOUND MAIN SAFETY SWITCH FOR HYDRAULIC TRIPPED. CARRIED OUT & DIAGNOSED SYSTEM., FOUND CHAFED/DAMAGED WIRE ON CHASSIS RAIL FOR OUT RIGGER STOWED SWITCH. REPAIRED DANDY, & RESET SYSTEM. ALL OPERATIONAL AFTER REPAIR. PUT TRUCK IN WASH BAY.	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	204428	17/06/2022 0:00	76015	COMPLETED PRE-DELIVERY INSPECTION. GREEN TAGGED., FOUND KEYS. JUMP STARTED VEHICLE. REMOVED PORTER STICKERS. REMOVED 9kg FIRE EXTINGUISHER & BRACKET. DETAILED INTERIOR.	PD - PRE-DELIVERY INSPECTION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	202292	20/04/2022 0:00	76015	REPAIRED FRONT BUMPER & TOOLBOX, R&R FRONT BUMPER, SLIDING TOOL BOX FITTINGS, BLACK TOOL BOX FITTINGS., REPAIR FRONT BUMPER, SLIDING TOOL BOX, BLACK TOOL BOX & LH WHEEL GUARD., PAINT FRONT BUMPER, SLIDING TOOL BOX & BLACK TOOL BOX., REPLACE RH LOWER MIRROR & LH UPPER MIRROR., PO 169316 - ADROIT PANELS	GR - GENERAL REPAIRS
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	201603	01/04/2022 0:00	76015	REPAIR FRONT BUMPER, SLIDING TOOLBOX, BLACK TOOLBOX, R/H AND L/H MIRRORS, REMOVE REFIT, FRONT BUMPER, SLIDING TOOLBOX FITTINGS, BLACK TOOLBOX, REPAIR, FRONT BUMPER, SLIDING TOOLBOX, BLACK TOOLBOX, PAINT, FRONT BUMPER, SLIDING TOOLBOX, BLACK TOOLBOX, PARTS, R/H LOWER MIRROR, L/H UPPER MIRROR, AS PER SMASH REPAIRER QUOTE #2890	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	199605	10/02/2022 0:00	75873	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, REPLACED HYDRAULIC FILTER & HYD RETURN FILTER, PO 166442 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	196264	05/11/2021 0:00	75873	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST, HV WET TESTS., PO 162900 - SETCO	ET - ELECTRICAL TEST
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	195574	19/10/2021 0:00	75873	CARRIED OUT 9MTH TOWER SERVICE, PO 162149 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	194952	30/09/2021 0:00	75873	CARRIED OUT TRUCK "B" SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTER, REPLACED WIPER BLADES, PO 161452 - EPV	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	191621	30/06/2021 0:00	75873	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, PO 157518 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	190264	28/05/2021 0:00	74393	CARRIED OUT 3MTH TOWER SERVICE, PO 156178 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	188371	30/04/2021 0:00	74393	VEHICLE INSPECTION & REPAIRS, PICK UP & DELIVER TO THOMASTOWN - TOLL INCL. REPLACE MISSING CIRCLIP FROM BASKET SLIDER TOP PIN. BASKET SLIDE CYLINDER, LEAKING, WASH CYLINDER & FOUND LEAK FROM GLAND ON SLIDE CYLINDER, REMOVED ALL COVERS, PIPING & MOUNTINGS, REMOVED, CYLINDER & DISASSEMBLED, CLEAN ALL PARTS & CHECKED, REPLACED ALL WORN SEALS & REBUILD CYLINDER, PRESSURE TEST CYLINDER, & CHECKED, OK, REFIT CYLINDER & ALL REMOVED PARTS. REPLACED SEIZED/WORN GREASE NIPPLES ON UPPER LEVEL CYLINDER., BASKET LEVEL CYLINDER, LOWER BOOM PIVOT AT ELBOW & UPPER BOOM PIVOT PIN AT ELBOW. CDD ROPE CLOSE TO BASKET FRONT HAS, 3 TURNS ON DESCENDER, SHOULD BE 2, REMOVE ROPE & REFIT WITH CORRECT TURNS. REPLACE MISSING AD BLUE CAP. CDD NEEDS, ATTENTION TO RELEASE PINS, REROUTE CDD ROPE. CARRY OUT WEIGHT TEST., PO 154063 - EPV	MR - MECHANICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	188944	22/04/2021 0:00	74149	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST, HV WET TESTS., PO 154700 - SETCO	ET - ELECTRICAL TEST
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	184228	11/02/2021 0:00	74149	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, REPLACED MISSING COUNTERSUNK HEAD BOLTS FROM THE SLEW PINION GEAR., SENTRY SEAL BOLTS ON THE UPPER TURRET., LHR TELE ROLLER BEARING CAPS BROKEN, REMOVED, WASHED & INSPECTED, MANUFACTURE NEW COVER, REFIT & CHECKED, OK., RH & LH TELE ROLLER BEARINGS HAVE MOVEMENT, REMOVED COVER & INPSECTED, FOUND ROLLER BEARINGS NEED REPLACEMENT,, REMOVED & REFIT AS REQD, REFIT COVER & CHECKED, OK., CHECKED BASKET ROTATE ARM MOTOR HOSES, FOUND TO BE LEAKING, REMOVED HOSES & SENT AWAY AS SAMPLE FOR NEW HOSES, FIT NEW, HOSES & TOPPED UP HYD OIL, RECHECKED FOR LEAKS, OK., REPAIRED GOUGES THROUGH GEL COAT & TELE BOOM, CLEANED TELE BOOM INSIDE & OUT., PIECE BROKEN OUT OF BASKET CONTROLS COVER, MANUFACTURE, FIT & BOLT ON NEW PIECE AS REQD., PO 149712 - EPV	AS - ATTACHMENT SERVICES

P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	182478	01/01/2021 0:00	73153	REPAIRED BUCKET PIVOTS, CRUNCHING NOISE WHILE ARM ROTATING, BASKET COVERS CATCHING ON PIVOT, TENSION & REPROFILE ALL BASKET PIVOT COVERS, RECUT, LHS & SECURE INSIDE INSTEAD OF OUTSIDE., BASKET RUNS ON WHEN CONTROLS RELEASED, CHECKED ALL, PRESSURE TO ROTATOR CYLINDER OK, FOUND EXCESSIVE MOVEMENT IN, BASKET ROTATOR MOTOR, NEEDS NEW MOTOR., TURRET SLEW HAS EXCESSIVE BACKLASH, CARRIED OUT SLEW MOTOR ADJUSTMENT, BUT WILL NEED FURTHER WORK., BASKET ROTATOR YOKE REPLACED - REMOVE COVER FOR ACCESS, REMOVE ROTATOR & DISCONNECT HOSES, REPLACE BOLTS WHEN, REFITTING, MOUNT FRAME TO BOOM, FIT COVERS, BLEED & WASH., BASKET & GROUND REMOTES CUT OUT - UNPACK & SET UP UNIT, SYNC RADIO REMOTE TO UNIT, TEST RUN EXTENSIVELY & FOUND NOT FAULTS., REMOVED BOTH REMOTE LIDS, CHECK ALL WIRING CONNECTIONS, FOUND ALL OK, REMOVED LID FROM RECEIVER, CHECK ALL CONNECTIONS, & LED OPERATIONS, OK. PACKED UP VEHICLE & MOVED AROUND YARD, RESET UNIT & SYNC RADIO REMOTES, RETEST VIGOROUSLY, FOUND, UNIT NOT TO FAULT. NOTE - USED NEW BATTERIES WHILST TESTING., BASKET STOPS ROTATING WHEN UNIT HEATS UP, PRESSURE RELIEF VALVE BLOWING OFF & HOWLING WHEN HOT, SET UP UNIT IN TEST AREA., ADD WEIGHT TO BASKET CONTINUOUSLY FLY UNIT UNTIL IT FAILS, FOUND BASKET TO STOP OPERATING WHEN OIL WARMS UP & PRESSURE, RELIEF BLOWS OFF & HOWLS, R&R BOTH VALVES - BOTH SYSTEM PRESSURE & TOOLS PRESSURE, SET UP TEST BENCH & TEST RELIEF, PRESSURES, FOUND SYSTEM PRESSURES EXCESSIVELY HIGH, RESET TO UNIT SPECS OF 2500psi, TEST TOOLS PRESSURE & RESET TO SPECS, OF 2250psi, RETEST UNIT OPERATIONS, FOUND TO BE OPERATING AS NORMAL FOR A LONGER PERIOD THEN STARTED TO FAULT, TRACKED, HYDRAULIC SYSTEM PRESSURE IN & FLOW, FOUND DEADMAN CIRCUIT TO CONTAIN RELIEF VALVE, R&R VALVE TO BE SET BELOW SYSTEM, OPERATING PRESSURES BY A LARGE MARGIN, RESET RELIEF VALVE PRESSURE, RETEST UNIT, FOUND TO OPERATE OK, TEST FUNCTIONS &, SPEEDS OF BOTH REMOTE CONTROLS, RESET (BASKET REMOTE) BASKET SLEW SPEED BOTH FAST & SLOW, RESET REMOTE FUNCTIONS FROM, UNIT, FOUND OK., PO 147852 - EPV	MR - MECHANICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	181798	01/11/2020 0:00	71580	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST, HV WET TESTS, TRAVEL, PO 147155 - SETCO	ET - ELECTRICAL TEST
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	181414	22/10/2020 0:00	72914	REPAIRED OIL LEAK FROM TRANSFER CASE & REPLACED VALVE IN 4WD SYSTEM, OIL LEAK FROM TRANSFER CASE, REMOVED GEARBOX, BEARING COVER & TRANSFER CASE AS REQD, REPLACED ALL PINION SEALS &, TRANSFER CASE SEALS, REPLACED TRANSFER CASE OIL, REASSEMBLED ALL PARTS & ROADTESTED, OK., 4WD WON'T ENGAGE, CHECKED & FOUND 3-2-WAY PNEUMATIC VALVE STICKING, REPLACED VALVE AS REQD, ROADTESTED, OK., PO 146818 - WHITEHORSE TRUCK CENTRE	BM - BREAKDOWN - MECHANICAL
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	181294	01/10/2020 0:00	71580	REPAIRED BASKET REMOTE CIRCUIT BOARD, REMOTE DROPPING OUT OF SYNC, FOUND BASKET REMOTE VERY, SENSITIVE TO KNOCKS, CHECKED & FOUND GROUND REMOTE TO, OPERATE OK, REMOVED BASKET & GROUND REMOTE LIDS, FOUND, BASKET REMOTE CIRCUIT BOARD OUT OF POSITION & FLOPPING, AROUND, REFIT TO HOLDING SLOTS, FOUND PLUG AT MAIN CIRCUIT, BOARD IN GROUND REMOTE INSECURE, RESECURED ALL THE WAY IN., REFIT LIDS, CHECKED OPERATION, ALL OK., PO 146682 - EPV	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	179959	28/09/2020 0:00	71153	CARRIED OUT TRUCK "C" SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED AIR FILTERS, FUEL, FILTER, 2 X WIPER BLADES., PO 145372 - EPV	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	179960	28/09/2020 0:00	71153	CARRIED OUT 9MTH TOWER SERVICE, PO 145372 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	178223	25/08/2020 0:00	67036	***CANCELLED - JOB BOOKED IN ERROR***, DOWNER READ WRONG LABEL & ROBES ARE NOT DUE TO BE CHANGED, FIT NEW CDD ROPES, PO 143744 - EPV	GR - GENERAL REPAIRS
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	177415	15/07/2020 0:00	67036	REPAIRED DAMAGE TO TOWER, REPLACE MISSING WHEEL CHOCKS AS REQUESTED. KNUCKLE COVER, HAS SEVERAL BROKEN NYLON BOLTS, LOWER BOOM TO TURRET COVER, NYLON BOLTS HAVE COME ADRIFT, BOOM END COVER MISSING NYLON, BOLT, REMOVE & REPLACE BROKEN BOLTS AS REQD, RETENSION LOWER, BOOM TO TURRET COVER BOLTS. BOOM TO ARTICULATING ARM COVER, BROKEN, SEVERAL NYLON BOLTS MISSING ON BASKET COVERS, UPPER, BOOM COVER HAS A HOLE IN IT, REPAIR COVERS AS REQD & SUPPLY, & FIT NEW BOLTS., PO 141629 - EPV	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	175586	01/07/2020 0:00	67036	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, CHECK & REPAIR CUST REPORTED DEADMAN ON BOTH REMOTES NOT, OPERATING CORRECTLY, CHECKED DEADMAN OPERATION & HETRONIC., NO OPTION ON THESE REMOTES, ONLY WAY TO RECTIFY IS TO GO, BACK TO OLD STYLE HOUSING. CHECK & REPAIR IN NORMAL MODE, SNAIL BUCKET PRESSURE NEEDS TO BE REDUCED, CHECKED &, ADJUSTED ALL SPEEDS, RECHECKED OPERATION, OK. CDD TOWARDS, FRONT OF VEHICLE HAS DAMAGED PIN & CLIP IS MISSING, REPAIR, BOX & REFIT PIN WITH RETAINING WASHER. CHECK & REPAIR TOOL, HYDRAULIC PRESSURE, GUN VERY SLOW, CHECKED & FOUND RELIEF, VALVE HAD FAILED, S & F NEW VALVE & SET TO SPECIFICATION., REFIT LHS REAR/FRONT MUD GUARD. SWIVEL HOSES BOOM END, RUBBING & ALL BURST PROTECTION COMING OFF, TIDY UP & RECLAMP, AS REQD. REPLACED WORN WIPER BLADES., PO 141629 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	172654	01/05/2020 0:00	90282	REPAIRED LOOSE CONNECTION IN CONTROLLER, PROBLEM WITH CONTROLLER FOR BUCKET, MOVING BUCKET TOO FAST., CHECKED & FOUND NO POWER TO RECEIVER, MOTOR AT BASKET, RUNNING & ALARM SOUNDS, GENERATOR DUMP VALVE IS ALSO ACTIVE., LED 5 FLASHING, TRACED & FOUND LOOSE CONNECTIONS IN BOX &, JOYSTICK CONTROLLERS - POSSIBLY DUE TO DROPPING. RESECURE, CONNECTIONS & CHECKED OPERATION, OK., PO 139075 - EPV	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	172852	08/04/2020 0:00	64086	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST, HV WET TESTS, INCL TRAVEL, PO 139242 - SETCO	ET - ELECTRICAL TEST

P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	169134	17/02/2020 0:00	64086	CARRIED OUT 3MTH TOWER SERVICE & REPAIRS, CHECK & REPAIR REMOTE, KEEPS CUTTING OUT, CHECKED & FOUND, BROKEN STARTER SIGNAL WIRE FROM TOWER SYSTEM, RUN NEW WIRE, UP TO JUMP START AT THE BATTERY ISOLATOR FOR THE AUXILIARY, BATTERIES, TESTED, SYSTEM OK. TESTED AUXILIARY BATTERY, KEEP, LOSING CHARGE, CHECKED & FOUND BATTERIES FAULTY, S & F NEW, BATTERIES., PO 135800 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	169133	10/02/2020 0:00	64086	CARRIED OUT TRUCK "A" SERVICE, PO 135800 - EPV	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	167477	18/12/2019 0:00	64073	CARRIED OUT 12MTH TOWER SERVICE, WEIGHT TEST & REPAIRS, REKIT LEAKING RHS STABILISER LEG. RETENSION ARTICULATED, BASKET ARM FASTENING BOLTS & SENTRY SEAL., PO 134079 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	165461	01/11/2019 0:00	153072	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST, HV WET TESTS + TRAVEL, PO 132071 - SETCO	ET - ELECTRICAL TEST
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	165273	25/10/2019 0:00	153072	R#BUS012718099	RE - REGISTRATION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	161975	01/09/2019 0:00	153072	COMPLETED TRUCK "B" SERVICE, REFUND PROCESSED - CHARGED TWICE FOR WIPER BLADES - REFER, TO WO 161958 FOR CORRECT CHARGE, PO 128684 - EPV	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	162159	30/08/2019 0:00	153072	REPAIRED DAMAGE TO TOWER, BASKET UP & DOWN LV COVER CRUSHING & NYLON BOLTS MISSING,, REMOVE ALL UP & DOWN LV, ADJUST, CHANGE BOLTS & REFIT, TEST,, OK. JACK NOT STOWED, LIGHT LENSES DAMAGED AT JUNCTION BOX, TRAY, REMOVE DAMAGED & S & F NEW., NOTE - STABILIZER PINS MISSING X2 REAR LEG., PO 128684 - EPV	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	161958	16/08/2019 0:00	153072	CARRIED OUT 9MTH TOWER SERVICE & REPAIRS, REPLACED WIPER BLADES. CARRY OUT CDD TEST, ROPES ARE IN, DATE. COVERS ON BASKET BROKEN, MAKE COVER TO FIT. NYLON, BOLTS MISSING, S & F NEW NYLON BOLTS. HYDRAULIC OIL LOW, TOP, UP. WORK LIGHT MISSING BRACKET, FOUND BRACKET, REPLACE, BOLTS & REASSEMBLE., PO 128684 - EPV	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	160019	09/07/2019 0:00	153072	REPAIRED ISSUES WITH TOWER, TOWER STOPS WORKING INTERMITTENTLY & HARD TO GET IT STARTED, AGAIN, THEN IT STOPS, ONCE FUNCTION WORKING IT KEEPS WORKING, UNTIL FUNCTION RELEASED, THEN TRIED TO START AGAIN, ALSO, WON'T WORK FROM TURRET CONTROLS WHEN IT STOPS. CHECKED, CHANGEOVER COIL, ALL OK. OPERATED FOR OVER AN HOUR BUT, UNABLE TO GET CONSISTENT SCENARIO. TRACED HOSES & GETTING, FLOW TO TURRET ABOVE ROTATION BECAUSE TOOLS STOP THE SAME, AS THE BOOM, TRIED TO PINPOINT WHERE LOSS OF PRESSURE, OCCURING BUT UNABLE, SENT TO WORKSHOP., TESTED OPERATION OF TOWER, FOUND IT WOULD STOP OPERATING, FROM TURRET CONTROLS AFTER A SHORT PERIOD OF TIME, SHUT DOWN, TOWER & RESTARTED, OPERATED FROM CONTROLS THEN STOPPED, WORKING. INSPECTED TOWER/STABILISER CHANGEOVER AS TOWER, WORKED ONCE THE SWITCH HAD BEEN CHANGED TO STABILISER BACK, TO TOWER. INSPECTED CHANGEOVER COILS FOR POWER ONCE TOWER, STOPPED, STILL HAD POWER TO IT. FITTED FLOW & PRESSURE GAUGE, IN PRESSURE LINE AT HYDRAULIC COUPLING & TESTED, FAULT NOT, CHANGEOVER VALVE AS GAUGE WAS SHOWING GOOD OIL FLOW AT HYD, COUPLING. INSPECTED TURRET CONTROL VALVE & REMOVED BYPASS, PRESSURE COMPENSATOR CARTRIDGE WHEN CONTROLS STOPPED, WORKING, HAD A HIGH PRESSURE OF OIL BUILT UP BEHIND IT, CAUSING OIL TO DIVERT FROM DEADMAN VALVE. FITTED NEW, CARTRIDGE TO VALVE & TESTED OPERATION, TOWER UNIT DID NOT, STOP WORKING. SYNCHRONISE RADIO REMOTES & TESTED OPERATION, FROM BASKET & GROUND CONTROLS, UNIT DID NOT FAULT. ON, INSPECTION OF SYSTEM ALSO NOTED 2 RELIEF VALVES HAD BEEN, FITTED INCORRECTLY, REMOVED & FITTED BACK IN CORRECTLY., PO 126990	PI - PLANT INSPECTION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	157747	17/06/2019 0:00	153072	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST & REPAIRS, WEIGHT TEST AFTER COMP LINER REFITTED., BOOM DOES NOT WANT TO LIFT WITH SWL, ADJUSTED & TESTED., CRACKING NOISE WHEN BOOM COMING DOWN, POSSIBLE INSERT, LOOSE, CHECKED & FOUND COMP LINK BEARING HAS FAILED, FITTED, NEW. TOP UP HYDRAULIC OIL. WASHED BOOM & TURRET., PO 125134	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	148170	06/06/2019 0:00	54558	0	RE - REGISTRATION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	156507	15/05/2019 0:00	153072	REPAIRED DEADMAN CARTRDGE FROM BASE CONTROLS, TOWER STOPS WORKING INTERMITTENTLY, THEN CANNOT BE OPERATED, FROM BASE CONTROLS, REMOVED LOWER CONTROLS DEADMAN VALVE, & INSPECTED, ALL OK, REFITTED BUT PROBLEM STILL THERE, NO, PRESSURE TO TURRET VALVE BODY, WHEN UNIT WORKING & LOWER, CONTROLS USED YOU CAN ONLY RAISE NOT LOWER. TRACED SYSTEM, & FOUND OIL GONE BACK TO TANK FROM BASE CONTROL VALVE,, REMOVE DEADMAN CARTRIDGE FROM BASE CONTROLS & SET UP ON, TEST BENCH, FOUND WHEN CONTROLS GET WARM IT WILL ONLY, PARTIALLY OPEN CAUSING OIL TO RETURN TO TANK, REPLACE, CARTRIDGE & COIL & CARRY OUT FURTHER TESTING, OK., PO 124139	HR - HYDRAULIC REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	155291	06/05/2019 0:00	153072	REPLACED 2 BATTERIES, PO 123075 - BEAUREPAIRS BAYSWATER, CALLED OUT TO JUMP START & THEN REPLACED BATTERIES, CHECKED CHARGE RATE, 1 LOW & 1 FAULTY, ARRANGED BEAUS TO, ATTEND AS PER INSTRUCTIONS FROM PORTERS., PO 124079 - EPV, REPLACED 2 BATTERIES - 2 X N150MFE TRUCK/TRACTOR/BUS, FITTING CHARGE AND CALL OUT FEE, PO 123075 - BEAUREPAIRS BAYSWATER	BE - BREAKDOWN - ELECTRICAL

P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	156003	29/04/2019 0:00	153072	REPAIRS TO BASKET, REMOTE, ETC, PO 123446, REPAIRS TO BASKET, REMOTE, ETC, RAPID REMOTE INTERMITTENT OPERATION FAILURE - UPPER REMOTE, NOT WORKING & LOWER WOULD DROP OUT, SENT TO HETRONIC TWICE, FOR REPAIRS, FAULT FOUND, NOW OK. BASKET CONTROLS COVER HAS, BECOME BRITTLE & SEVERED, SECTIONS BROKEN THROUGH, ALL COVER, MOUNTS ARE LOOSE, S & F NEW COVER & SECURED OTHER COVERS., MULTIPLE GEL COAT CHIPS IN THE BASKET SWING ARM, TOUCHED UP, GEL COAT. BASKET LIFT CYLINDER 2ND STAGE GLAND HAS BAD LEAK., REMOVE BASKET FOR ACCESS, S & F SEAL KIT TO CYLINDER &, REASSEMBLED UNIT. BASKET HOSE DAMAGED, FABRICATED & FITTED, NEW HOSE.MBASNEW HOSE. BASKET LIFT FRAME BOTTOM COVER NOT FI, ON TRAY, RESECURED COVER. BOLTS MISSING AT THE ELBOW COVERS., S & F NEW BOLTS, OIL LEAK AT THE TOP OF THE HYDRAULIC SLEW, COUPLING, WASHED AREA & TIGHTENED HOSE FITTINGS IN AREA., REMOTE FAULT (CONT), BASKET REMOTE WILL NOT WORK AT ALL., REMOVED REMOTE RECEIVER FROM TURRET & SENT REMOTES &, RECEIVER FOR REPAIRS, FITTED RECEIVER TO TURRET & TESTED ALL, FUNCTIONS ON BOTH REMOTES. BASKET TOOLS MALE COUPLING, LEAKING, COUPLING REMOVED & FOUND TO BE METRIC, MODIFY HOSE, & FIT ADAPTER TO FIT UP 1/2 INCH COUPLING. FOUND HOSE AT, BASKET ARM ROTATOR HAD BEEN RUBBING ON COVERS, FITTED, SPIRAX TO BOTH HOSES TO PREVENT FURTHER RUBBING. HARNESS, POINT COVER BROKEN SIDE SECTION, REPAIRED DAMAGED COVER -, USED PLASTIC FROM DAMAGED CONTROL COVER TO MAKE REPAIR., PO 123446	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	155892	12/04/2019 0:00	153072	ELECTRICAL TEST, PO 123549, CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, BUCKET LINER TEST., PO 123549	ET - ELECTRICAL TEST
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	155739	12/04/2019 0:00	153072	3MTH SERVICE AND REPAIRS, PO 123446, CARRIED OUT 3MTH TOWER SERVICE, PO 123446	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	154128	15/03/2019 0:00	153072	TRUCK "A" SERVICE & REPAIRS, PO 122068, CARRIED OUT TRUCK "A" SERVICE & REPAIRS, REPLACED WIPER INSERTS, REPLACED RH STEER MUDGUARD AS, CRACKED AROUND MOUNT, SCRATCH IN CENTRE OF LH MIRROR BUT, STILL SERVICABLE, REPLACED AIR FILTER ELEMENT., PO 122068	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	154074	14/03/2019 0:00	153072	2 BALANCES REQUIRED, PO 122022, BALANCE TRUCK - WHEEL POSITIONS 1+2, PO 122022	WA - AXLE CORRECTION/ALIGNMENT
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	153424	04/03/2019 0:00	153072	REPLACED 2 STEER TYRES - 11R22.5 148L (16) M840 TL B5TN, TYRE ROTATION - POS 1 TO POS 3, PO 121472	TC - TYRE CHANGE/REPLACMENT
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	153250	28/02/2019 0:00	153072	REPLACED CRACKED RH MIRROR & BROKEN NUMBER PLATE MOUNT, S & F NEW MIRROR. S & F ANOTHER MOUNT PLATE, STRAIGHTENED &, REFITTED NUMBER PLATE., PO 119676	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	151557	26/02/2019 0:00	153072	REPAIRED REAR BRAKE LININGS & DRUMS, OTHER GENERAL REPAIRS, FRONT DIFF PINION SEAL LEAKING, S & F NEW SEAL & TOPPED UP, DIFF. TRANSFER CASE LEAKING, SEALED UP BOLTS IN TRANSFER, CASE & REFILLED WITH OIL. GRILL BROKEN/CRACKED - NEW GRILL, FITTED. WINDSCREEN SUN VISOR BROKEN - NEW VISOR FITTED., 2 X CUPBOARD DOORS DAMAGED/BENT, STILL OPERABLE. LH REAR, BRAKE LINING 10% MATERIAL REMAINING, S & F NEW REAR LININGS, & REAR DRUMS, S & F NEW LINING WEAR SENSORS TO LOWER REAR, SHOES., PO 119676	MR - MECHANICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	150637	14/01/2019 0:00	153072	COMPLETED WHEEL ALIGNMENT, SHAKE & REPORT, WHEEL ALIGNMENT, TYRE STRIP REFIT & BALANCE., FLIP LHF TYRE ON RIM, DRIVE ALIGNMENT., LH REAR TYRE WEARING - COMPLETE WHEEL ALIGNMENT, PO 118930	WA - AXLE CORRECTION/ALIGNMENT
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	148408	22/11/2018 0:00	59502	CARRIED OUT TRUCK A SERVICE, S & F AMBER REFLECTOR LHS, CARRY OUT TYPE A TRUCK SERVICE, REPLACE MISSING MIDDLE LHS AMBER REFLECTOR, PO 116969	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	148406	22/11/2018 0:00	59502	12 MTH TOWER SERVICE & A/I COMPLETED, WEIGHT TEST PASSED., MODERATE HYD OIL LEAKING AROUND HYD DIZZY IN TURRET., CHECKED TIGHTNESS OF FITTINGS, RETIGHTENED X 1, APPEARS TO, STILL BE WEEPING. EXTENSION BOOM D/S TOP ROLLER - HARDENED, WASHER INSTALLED TO ACT AS SUPPORT SPACER, ALSO 1 BOLT, MISSING FROM ROLLER KEEPER - REMOVED 4 CRACKED CAPS, FOUND, ALL 4 REMAINING ROLLER BOLTS LOOSE, RETIGHTENED SENTRY., SEALED, REINSTALLED DAMAGED PLASTIC CAPS. TOOL HOSES AT, BASKET SHOW SIGNS OF WEEPING., PO 116967	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	148172	15/11/2018 0:00	54558	R# BUS007927731	RE - REGISTRATION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	148252	01/11/2018 0:00	153072	CREDIT OF SUPPLIER INVOICE, P/O 116845	MR - MECHANICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	146911	17/10/2018 0:00	54553	COMPLETED 6m ELECTRICAL TEST, P/O 115650	ET - ELECTRICAL TEST
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	147229	01/10/2018 0:00	54558	REPAIRED AUX THROTTLE NOT WORKING, CHECKED REPORT OF AUX THROTTLE NOT WORKING AFTER 10-15, MINS ENGINE RPM DROPS DOWN AND WILL SOMETIMES STALL ENGINE, WHILST OPERATION EWP., FOUND PSM CONTROL MODULE HAS LOST ITS PARAMETERS. CARRIED, OUT PTO MANAGEMENT AND DISENGAGEMENT OF TRUCK, ALSO, CARRIED OUT QUICK TEST. FOUND STORED FAULT IN FR AND MR IN, RELATION TO ALTERNATOR. HAD TRUCK RUNNING AND ALSO CHECKED, AND TESTED FOR OUTPUT FROM ALTERNATOR FOUND OK., VISUALLY CHECKED WIRING AS WELL OK. PTO OPERATED BY SWITCH, NUMEROUS TIMES. HOOKED UP ENTRY AND CHECKED PARAMETERS, IN PSM FOUND PARAMETERS HAD BEEN LOST AND TORQUE LIMITATION, WAS SET TO 400 NM WHICH WAS NOT HIGH ENOUGH. TURNED OFF, TORQUE LIMIT AND RETRIED, NOW VEHICLE OK. ARRANGED FOR, CUSTOMER TO CHECK BEFORE LEAVING., PO#112921	MR - MECHANICAL REPAIR

P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	142721	08/08/2018 0:00	54553	REPAIRED SLEW FAULT, PTO DISENGAGING, REPLACE REMOTE BATTERIES AS REQUIRED. ONE IS MARKED WITH, AN X, IS FAULTY - INSTALLED NEW BATTERY, CHECKED CHARGE, OPERATION. OK., REMOTE DEADMAN BUTTON IS TOO SMALL TO USE WHEN GLOVING -, INSPECTED FAULT, DEAD MAN ARE ALSO IN TOP OF JOYSTICKS, OK, AS IS., SLEW AND LUFF WHEN LOWERING SHUDDERING AND YOU CANNOT, FEATHER THE CONTROLS, TOO FAST - OPERATE AND CHECK, SPEEDS ETC, ALL APPEAR OK AFTER ENGINE ISSUE RECTIFIED., WHEN THE FRONT WHEELS ARE IN THE AIR WITH JACK LEGS EXTENDED, THE TRUCK WILL SHUT DOWN OR GO INTO LIMP MODE, WHEELS KEEP, ROTATING, COULD BE TORQUE CONTROLLER IN TRANSFER CASE ISSUE. - SET UP WITH WHEELS ON GROUND, TESTED TOWER & FOUND, ENGINE DIES AND STALLS AFTER 15min OPERATION, THROTTLE DOES, NOT RAMP UP, CHECKED DASH & FOUND NO FAULT LIGHT BUT, CRUISE LIGHT ON, TURNED OFF CRUISE & RETESTED, STILL HAS, SAME FAULT, 'T' IN GAUGE AT PUMP TO ENSURE PUMP/PRESSURE IS, OPERATING CORRECTLY, OK. BOOM IN WITH WHITE HORSE &, DROPPED OFF, WHITE HORSE DIAGNOSED, FAULTS PERAMETERS, IN ECU HAD CHANGED CAUSING FAULT, PICKED UP FROM WHITE HORSE, BOTTOM OF BASKET REQUIRES GELCOAT REPAIRS - HOLD REPAIR, TURRET REQUIRES WASH - COMPLETED, RHF BOLTS HAVE SIGNS OF WEAR - STILL ON FOR SERVICE., TRAY ACCESS STEP BENT - STRAIGHTENED., BASKET RAISE / LOWER CYCLINDER LEANING - MINOR LEAN OK AS IS, BASKET ANTI TAPE TORN & WORN OUT - SUPPLIED AND FITTED TAPE, CDD PROCEDURE DECAL TORN / WARN - REMOVED DAMAGED DECAL, REPORT BASKET REMOTE NOT WORKING - ATTEMPTED TO SYNC, REMOTES, WON'T WORK, REMOVED REMOTES & RECEIVER AND, SENT OUT FOR REPAIRS. TESTED ON RETURN, DID NOT FAULT., REFITTED REMOTES, ALL OK, P/O 111743	MR - MECHANICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	139292	14/06/2018 0:00	52058	COMPLETED ANNUAL TOWER SERVICE, INSPECTION & WEIGHT TEST, P/O 108970	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	140190	14/06/2018 0:00	52058	REPLACED MISSING LOWER BOOM INSPECTION COVER., REPLACED FRONT LEG STABILISER REFLECTIVE TAPE BOTH SIDES, WASHED VERY MUDDY LEG, CARRIED OUT INSPECTION., REPLACED MISSING BASKET TOOL LINE LV COVER, TIGHTENED LOOSE BOLTS TO UPPER BOOM REST BRACKET MOUNT TO, HYDRAULIC TANK., REPLACED DAMAGED BASKET ARM ROTATOR TO EXTERIOR BOOM LV, COVER BOTTOM., REPLACED DAMAGED ARM ROTATOR LV COVER., PO#108970	GR - GENERAL REPAIRS
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	138435	01/06/2018 0:00	51221	COMPLETED SERVICE. REPLACED OILS & FILTERS. AIR DRIER FILTER, SERVICE & ADBLUE FILTER REPLACED., WHITEHORSE DANDENONG - P/O #108357	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	136721	01/05/2018 0:00	48327	REPLACED PTO SOLENOID DUE TO OPEN CIRCUIT., CHECKED OPERATION OF PTO. CARRIED OUT DAS SHORT TEST., FOUND CURRENT FAULT IN PSM. REMOVED LHF TRIM, CHECKED FOR, SIGNAL FROM PSM. OK. REMOVED PLUG OFF SOLENOID (AIR)., BRIDGED WIRES AND RECHECKED FOR CONTINUITY, ALL OK., CHECKED WIRING FOR ANY SHORTING, ALL OK., CHECKED RESISTANCE OF SOLENOID. SOLENOID HAD OPEN CIRCUIT., REPLACED SOLENOID, CONNECTED ELECTRICAL PLUG AND AIRLINE., CHECKED OPERATION OF PTO. ALL WORKING CORRECTLY. CLEARED, ALL FAULT CODES AND ROAD TESTED VEHICLE. ALL OK., PO#106913, NB: WORK CARRIED OUT 8/8/17, PO# ENQUIRY RECEIVED 11/4/18	MR - MECHANICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	135634	10/04/2018 0:00	48327	NO POWER TO TOWER, FOUND BOTH REMOTES WOULD NOT SYNC, CHECKED OPERATION DUE TO SHUTTING DOWN AND NOT, FUNCTIONING. LOWER BOOM WAS NOT IN THE NEST, ACTIVATING, MICRO SWITCH TO OVER RIDE PACK UP LEGS ETC AND SET UP FOR, OPERATION. LEGS OPERATED CORRECTLY BUT BOTH REMOTES WILL, NOT SYNC. TO ALLOW BOOM OPERATION., OPERATOR DECIDED TO TAKE UNIT BACK TO MELBOURNE AS THIS WAS, THE FIRST TIME IT HAS BEEN USED IN WANGARATTA., P/O 106068	BE - BREAKDOWN - ELECTRICAL
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	129800	20/02/2018 0:00	47569	FITTED NEW DRIVERS LOWER STEP, PO#101410, NB WORK COMPLETED 28NOV17 INVOICE RECEIVED 20FEB18	GR - GENERAL REPAIRS
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	132144	18/01/2018 0:00	47722	REPLACED ARROW BOARD, CONTROLLER & HARNESS, SUPPLIED & FITTED NEW ARROW BOARD TO REAR OF TRUCK. NEW, CONTROLLER & WIRING HARNESS REQUIRED FOR ARROW BOARD. RAN, NEW 7 CORE WIRE FROM CAB CONTROL TO BOARD. FITTED NEW 8 & 2, WAY DEUTSCH PLUGS. USED 12v REDUCER FOR POWER TO ARROW, BOARD AND INCAB CONTROLLER. FITTED NEW INCAB CONTROLLER TO, DASH., PO#103183	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	131154	01/01/2018 0:00	47727	DOUBLE UP, SEE W/O 132114, REPLACE ARROWBOARD LIGHTS, CONTROLLER & HARNESS, PO#102420	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	130536	12/12/2017 0:00	47561	CHECKED INTERMITTENT PTO, REPLACED BLOWN FUSES., INSPECTED AND LOCATED BLOWN FUSES. REMOVED AND CHECKED, CIRCUIT, TESTED AND FOUND DRAWING HEAVEY AMPS. THEN NOTICED, SMOKE FROM TOWER CONTROLS REMOVED TOWER CONTROL COVER, FOUND BURNED OUT COIL, NOTICED ALL THE COILS ARE 12v., CHECKED ALL TRUCK WIRING IS 24v EXCEPT THE TRAY IS 12v., TRACED WIRE AND FOUND REDUCERS FOR LIGHTS. ALL RELAYS ARE, 24v REMOTE RECEIVER/TRANSMITTER IS 10-30v WILL REQUIRE ALL, TOWER CONTROL SOLENOIDS TO BE UPGRADED TO 24v., BROUGHT TRUCK IN AND REMOVED ALL SOLENOIDS, FITTED 24v, SOLENOIDS TO TOWER CONTROLS. UPGRADED ALL FUNCTIONS TO TOWER, & BOTH REMOTES ALL FUNCTIONS OPERATE. RETESTED CIRCUIT AND, FOUND AMP DRAINAGE HAS BEEN CUT IN HALF. TESTED FUNCTIONS &, LEGS FOR 2 HOURS RECHECKED ALL OK. COILS ARE NOT GETTING HOT, AMPS ARE STILL DOWN. REFITTED COVERS., PO#101956	ER - ELECTRICAL REPAIR

P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	130475	08/12/2017 0:00	47727	SECURED LOOM AWAY FROM CIRCUIT BREAK TO STOP TRIPPING., CONNECTED XENTRY, FOUND FAULT FOR CAN HIGH TO SCR FRAME, MODULE DEFECTIVE., CHECKED WIRING DIAGRAMS FOR CAN NETWORK AND TESTED WIRING. FOR SHORT CIRCUITS. ALL OK., RESET CIRCUIT BREAKER AND FOUND WIRING LOOM BY FUSE BOX, TRIPPING CIRCUIT BREAKER., MOVED AND SECURED LOOM AWAY FROM CIRCUIT BREAKER. ALL OK., PO#101917	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	129660	22/11/2017 0:00	47561	REPLACED FAULTY COIL AND REPLACED FUSE., FOUND COIL FOR UNLOADER VALVE AT TURRET CONTROLS FAULTY., SUPPLIED AND FITTED NEW COIL & REPLACED FUSE., SUPPLIED AND FITTED DECAL FOR LOG BOOK, SUPPLIED AND FITTED DECAL "BEWARE OF OVERHEAD POWER LINES", REMOVED ELBOW COVER, REPAIRED AND FITTED BACK ON DUE TO, DAMAGED FIBREGLASS AT LHS ELBOW COVER., REPAIRED BOOM LV COVER & COVER UNDER BOOM REPAIRED, FIBREGLASS., SUPPLIED AND FITTED NEW M8 NYLON BOLTS FOR LV COVER FOR, UPPER BOOM., PO#100440	GR - GENERAL REPAIRS
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	128729	22/11/2017 0:00	47561	COMPLETED 6m TOWER SERVICE, PO#100440	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	129343	17/11/2017 0:00	47443	0	RE - REGISTRATION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	127320	06/10/2017 0:00	46828	REPAIRED ARROW BOARD, ARROW BOARD NOT OPERATING - FAULT FIND STARTING AT DASH, REPLACED MISSING INDICATOR LENS TO RH F MUD GUARD., BOARD CONTROLLER, DISASSEMBLE OF DASH CENTRE, FUSE PANEL &, FRONT BONNET GRILL TO FOLLOW WIRES FROM DASH TO BATTERIES., POWER TESTING AT VARIOUS CONNECTIONS, FUSE PANEL ALONG WITH, INSPECTING CONNECTIONS FOUND NO POWER FEED, FOLLOWING WIRING, TO REAR SIGN BOARD UPON OPENING CONTROL PANEL JUNCTION BOX, FOUND CIRCUIT BOARD BADLY RUSTED & CORRODED FROM WATER ALSO, MAIN POWER WIRE SNAPPED, TESTED WIRING FOR CONTINUITY &, FOUND WIRING ALL OK. CONTROL BOX BEYOND REPAIR, REFIT ALL, COMPONENTS REMOVED IN TESTING AND FAULT FINDING, PROCESS INCLUDING, GRILL CONTROL PANELS AND DASH PANELS., REPLACED MISSING PIP PIN., STRAIGHTENED DAMAGED TRAY BACK SQUARE DOLLY, WELDED &, GROUND METAL FLAT MASK OFF AND PAINTED TO SUIT., REPAIRED DAMAGED WIRING AT TAIL SHAFT AREA. TIED LOOM BACK, INTO POSITION., PTO NOT STAYING IN - MADE UP STEEL PLATE TO FIT PTO. DROVE &, REMOVED PTO. INSPECTED OK., RHS FRONG LEG SWITCH STICKY - REMOVED SWITCH HEAD, CLEANED., GROUND OFF SWITCH ARM DUE TO IT GETTING STUCK ON WELD., TESTED OK., REPLACED AMBER REFLECTOR FROM RHS TRAY, PO#97120	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	127328	06/10/2017 0:00	47443	REPAIRED EMERGENCY HAND PUMP, BASE CONTROLS WORKS 2 WAYS.; 1. IF ENGINE IDLING AND REMOTES ACTIVE, AS LABEL STATES., PRESS BUTTON ON SIDE OF VALVE AND OPERATE CONTROLS., 2. IF REMOTES HAVE DIED THE LOWER CONTROLS ARE ALL ALIVE., FITTED UP OF PUSH SWITCH FOR E/PUMP ON TURRET., HAND PUMP COULD BE FITTED FR WHEN LOSS OF POWER & PTO TO, MANUALLY PACK UP TOWER. 2 MAN OPERATION., PO#99122	ER - ELECTRICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	127319	26/09/2017 0:00	46828	COMPLETED 'A' SERVICE . REPLACED ENGINE OIL & FILTER, REPLACED FUEL FILTER., BRAKES: FRONT & REAR 80%, PO#97120	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	124966	29/08/2017 0:00	46828	COMPLETED 3m TOWER SERVICE., P/O 97120	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	125758	08/08/2017 0:00	45512	REPAIRED PTO FAULT, TOWER NOT WORKING, PTO DROPS OUT OR STALLS ENGINE AND NOT, WORKING ON LEGS - PACKED UP LEGS WITH E/PUMP, CHECKED AND, CHANGED HIGH PRESSURE FILTER. REMOVED AND FITTED TANK RETURN, FILTER . BOTH FILTERS WERE RESTRICTED IN OPERATION. BOTH, PARTIALLY OR ALMOST BLOCKED. REMOVED 3 NON RETURN VALVES IN, SYSTEM AND CHECKED OPERATION - OK STARTED UP TRUCK ENGAGED, PTO AND RAN FOR 20 MINS TO SEE IF NOT SLOWING REVS OR, STOPPING. OPERATED LEG SYSTEM OK. OPERATED TOWER SYSTEM OK., FILTERS HAVEN'T BEEN CHANGED AT ALL OR FOR A LONG TIME., E-STOP LABEL AT TURRET 50% MISSING - REMOVED REMAINING OLD, LABEL AS SUPPLIED., NO "CORRECT USE OF STABILISERS" LABEL - CLEANED SURFACE FIT, NEW LABEL AS SUPPLIED., LARGE AREAS OF GELCOAT MISSING FROM UNDERSIDE OF THE, TELEBOOM. - NO ACTION NEW BOOM., TOP BASKET MOUNT COVER BROKEN - MEASURED, CUT AND BEND, REPLACEMENT SECTION TRIM DAMAGED PLASTIC DRILL AND BOLTED, TOGETHER., BASKET SLIDE COVER BROKEN. BASKET TOOLS COVER BROKEN, CHIPS IN SWING ARM GELCOAT - PREPARED AREAS TO BE REPAIRED., MIXED PRODUCT AND APPLIED MULTIPLE LAYERS., SCREWED INSULATOR MISSING FROM TOP OF UPPER BOOM COVER -, UNTIL REQUIRED FINISH IS ACHIEVED., NO CDD RELEASE LABELS - CLEANED SURFACE FITTED NEW LABEL AS, SUPPLIED., NO VACUUM EXCLUSION - NO ACTION., NO EARTH WARNING LABEL - SUPPLIED AND FITTED EARTH WARNING, LABEL., NOTE PTO FAULT STILL EXISTS AS WOULD NOT ENGAGE AT START OF, SERVICE - RELEASED & TIGHTENED WIRING PLUG ON PTO & PTO, STARTED TO ENGAGE OK., FAULT NOTED AS PSM PTO FAULT 1 - UNIT SENT TO WHITEHORSE, TRUCKS FOR FAULT REPAIR., MANUAL SLEW HANDLE NOT LOCATED - NO ACTION. REMOVED FROM, BOOM BASKET., BASKET SLIDE COVER BROKEN - MEASURED, CUT AND DRILLED, PLASTIC ANGLE. TO FIT BROKEN SECTION SIKAFLEX AND ASSEMBLE, PLACE WITH NYLON BOLTS. REFITTED TO BOOM BASKET., BASKET TOOLS COVER SPLIT IN 2 LOCATIONS - REMOVED FROM, BASKET MEASURE CUT AND DRILLED PLASTIC, BEND INTO SHAPE TO, FIT REPAIRS TO BROKEN SECTIONS SIKAFLEX AND ASSEMBLED IN, PLACE WITH NYLON BOLTS. REFITTED TO BASKET., SCREW INSULATOR MISSING FROM TOP OF UPPER BROOM COVER -, USING SCISSORS LIFTED TO ACCESS CUT AND FITTED SUPPLIED CAP, TO SUIT. SECURED WITH SMALL AMOUNT OF SIKAFLEX., ARROW BOARD NOT WORKING - INSPECTED ARROW BOARD SYSTEM, FUSE, WAS BLOWN. REPLACED FUSE BUT ARROW BOARD STILL NOT WORKING., CONTROL UNIT NOT POWERING UP. INSPECTED ARROW BOARD AND FOUN, THAT CIRCUIT BOARD WAS DAMAGED. PURCHASED NEW ARROW BOARD, TESTED. WOULD NOT LIGHT UP. FOUND THAT MAIN UNIT WAS ALSO, DAMAGED., PO#97120	CD - CUSTOMER DAMAGE

P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	121392	10/05/2017 0:00	45512	REPAIRED BENT BOOM TIP & COMPLETED WEIGHT TEST, P/O 93870	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	120957	28/04/2017 0:00	45512	COMPLETE ANNUAL SERVICE, WEIGHT TEST & ELECTRICAL TEST, P/O 93545	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	119502	01/04/2017 0:00	45512	INSPECT AFTER EXTENSION BOOM PIN AT ROTATOR PULLED THROUGH, DUE TO CIRCLIP FAILURE AS REQUESTED., FOUND CIRCLIP TO BE DISTORTED AND STRETCHED FROM BEING, FORCED FROM PIN., P/O 92523, REPLACEMENT PARTS 10 WEEKS ex USA.	MR - MECHANICAL REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	116161	16/12/2016 0:00	37340	REPLACED DAMAGED INSULATION COVER TO END OF UPPER BOOM., P/O 89680	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	115920	13/12/2016 0:00	37340	COMPLETED 3m TOWER SERVICE. REPAIRED LEAKING SLEW MOTOR., P/O 89680	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	115642	07/12/2016 0:00	37340	0	RE - REGISTRATION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	115563	06/12/2016 0:00	43209	COMPLETED SERVICE. REPLACED OIL & FUEL FILTERS., REPLACED CAB FILTER. CHECKED OVER & GREASED., P/O 89371	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	116213	06/12/2016 0:00	43209	REPLACED BROKEN REAR TAIL LIGHT LENSE & MISSING SIDE MARKER, LENSE. WIRED IN AND TESTED - ALL OK., P/O 89371	CD - CUSTOMER DAMAGE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	111575	30/08/2016 0:00	37340	COMPLETED 6m INSPECTION, P/O 86242	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	111006	30/08/2016 0:00	36240	COMPLETED 18m ELECTRICAL TESTS, COMPLETED HV DRY TEST & BUCKET LINER TEST, P/O 85744	ET - ELECTRICAL TEST
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	110456	16/08/2016 0:00	37340	REPAIRED DAMAGES TO FRONT AFTER TRUCK WAS BOGGED, WASHED OFF MUD FROM WHEELS, SUSPENSION ETC. INSPECTED ALL, COMPONENTS FOR DAMAGE UNDER VEHICLE, OK. LIST COSMETIC, ITEMS THAT ARE DAMAGED., ABS LIGHT STAYS ON.; REMOVED & CLEANED CONNECTIONS, ROAD TESTD & CHECKED. OK., LHF BUMPER DAMAGED.; FITTED NEW BUMPER END & REFITTED., LIGHT ASSY., LHF STEP BROKEN & PLATE BENT.; STRAIGHTENED BOLTS & FITTED UP STEP ASSY., LHF OF FRONT WHEEL SPLASH GUARD DAMAGED.; FITTED NEW SPLASH GUARD & TIED BACK WITH BLUE CORD., PO#85418	Other
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	108228	01/06/2016 0:00	35450	REPLACED DAMAGED SUN VISOR AS REQUESTED., P/O 82451	Other
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	108014	31/05/2016 0:00	36211	COMPLETED 15m TOWER SERVICE. CHECKED OVER., REPAIRED RH TOOL BOX DOOR STRUT AS IT WS SLOW TO OPEN., P/O 83546	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	106755	31/05/2016 0:00	31186	FITTED NEW 240v INVERTER., FIT INVERTER AS REQUESTED, P/O 82453	Other
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	106748	16/05/2016 0:00	35450	COMPLETED SERVICE. REPLACED OIL, FUEL & ADBLUE FILTERS., REPLACED WIPER INSERTS. REPLACED DRYING AGENT BOX., P/O 82451, WARRANTY WORK COMPLETED: CHECKED FOR CAUSE OF VEERING TO, LEFT, FOUND RH F LEAF SPRING & HAD WHEEL ALIGNMENT COMPLETED., CHECKED BRAKE INDICATOR LIGHT FLASHING INTERMITTENTLY., REPLACED REAR BRAKE LININGS & SENSORS.	PS - PLANNED SERVICE
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	104005	29/02/2016 0:00	29320	COMPLETED ANNUAL SERVICE AND REPAIRS., REPLACED HYD FILTER & RETURN FILTER., CHECKED REPORTED FAULT WITH 240 VOLT INVERTER &, FOUND THE INVERTER TO BE CONTINUOUSLY OVERLOADED AS IT WAS, RUNNING 3 BATTERY CHARGERS & A MICROWAVE AT THE SAME TIME., COMPLETED REPAIRS TO OIL LEAK FROM SLEW MOTOR OF EWP THAT, WAS FOUND TO BE COMING FROM THE SLEW BRAKE. REMOVED SLEW, BRAKE ASSEMBLY & RESEALED SLEW BRAKE. REFITTED SLEW BRAKE, & TESTED OPERATION. REMOVED FAULTY HOUR METER FOR PTO &, SUPPLIED & FITTED NEW HOUR METER TO MAIN CONTROL BOX., FITTED NEW INSULATION COVER TO BASE OF BUCKET ROTATOR MOTOR, TO REPLACE DAMAGED INSULATION COVER. REMOVED INSULATION, COVER FROM END OF UPPER BOOM & COMPLETED PLASTIC WELDING, REPAIRS TO COVER TO THE END OF BOOM., P/O 80508	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	103358	10/02/2016 0:00	28486	COMPLETED 12m ELECTRICAL TEST., COMPLETED HV DRY TEST & BUCKET LINER TEST., P/O 80000	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	100204	24/11/2015 0:00	26101	REGO: P19-W-005 PAID	RE - REGISTRATION
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	99882	18/11/2015 0:00	26101	COMPLETED 9m TOWER SERVICE & INSPECTION., COMPELTED @ 351hrs, P/O 77651, REPAIRED HYDRAULIC OIL LEAK FROM CARTIDGE VALVE LOCATED IN, THE TURRENT OF THE EWP. REPLACED ORINGS & TESTED, TOPPED UP, HYDRAULIC OIL. CLEANED OIL FROM DECK.	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	97895	14/09/2015 0:00	21631	SUPPLIED & FITTED 1x NEW INSULATION COVER TO TOOL CIRCUIT, FITTINGS ON BASKET TO REPLACE BROKEN COVER., P/O 75744	Other
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	95959	11/09/2015 0:00	20269	CARRY OUT MODIFICATIONS TO SYSTEM REMOTE AS REQUESTED., RE CONFIGURE JOY STICK TO MATCH CUSTOMERS REQUEST., ADD ADDITIONAL DEAD MAN SWITCH AS PER CUSTOMERS REQUEST.	Other
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	95882	30/07/2015 0:00	20269	COMPLETED 6 MONTHLY ELECTRICAL TEST, P/O 74492, COMPLETED EPV TESTS (HIGH & LOW VOLTAGE) & BUCKET LINER TEST	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	95683	29/07/2015 0:00	20269	COMPLETED 6 MONTH TOWER INSPECTION @ 200hrs, P/O 74273	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	95432	16/07/2015 0:00	20269	CHECKED OVER FOR ENGINE STALLING WITH PTO ENGAGED, NO FAULT, FOUND. TESTED AND COULDN'T GET FAULT TO REPLICATE., P/O 74023	UR - UNPLANNED REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	96483	15/07/2015 0:00	20269	CHECKED PTO ISSUE, REFERRED TO DEALER SERVICEMAN FOR REPAIR, AS THEY HAVE ATTENDED FOR SAME ISSUE PREVIOUSLY., JC# 20608	UR - UNPLANNED REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	91985	01/04/2015 0:00	8432	CALLED OUT TO SITE AND REPLACE DAMAGED LIMIT SWITCH ON FRONT, BOOM REST, P/O 71397	UR - UNPLANNED REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	91983	30/03/2015 0:00	8432	COMPLETED 3 MONTH EWP INSPECTION, P/O 71396	AS - ATTACHMENT SERVICES
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	91887	03/03/2015 0:00	8432	REPLACED HYDRAULIC HOSE., INSPECTED HYDRAULIC LEAK, FOUND TO BE RUBBED THROUGH HOSE, FROM INSIDE BOOM. ARRANGED HYDRAULIC SUBLET TO COMPLETE, REPAIR., JC# 25229, VEARLY GROUP TO PAY FOR HYD REPAIR	UR - UNPLANNED REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	90496	12/02/2015 0:00	6002	LOCATED & TIGHTENED LOOSE HYDRAULIC OIL HOSE FITITNG., P/O 70176	UR - UNPLANNED REPAIR
P19-W-005	MERCEDES BENZ ATEGO 4X4 AWD	89214	13/01/2015 0:00	0	EASTLINK TOLLS - 1CU80B, 27/11 @ 14:00 MONASH FWY/PRINCES H-PRINCES HWY/CHELTHENHAM, 29/11 @ 07:56 CHELTHENHAM/PRINCES H-BORONIA/CANTERBURY, 29/11 @ 13:56 CANTERBURY/BORONIA - PRINCES HWY/CHELTHENHAM, 02/12 @ 07:07 POLICE/WELLINGTON-BURWOOD HWY/BORONIA, 02/12 @ 16:14 BORONIA/BURWOOD HWY-PRINCES HWY/CHELTHENHAM	-