

Repair Order Detail - Customer Copy

RO Number: 9191KLS

RO Status: PREASSIGNED

Customer: CIVIL-X CONTRACTING (BC) LTD

Phone(s): Contact: (250)862-7379

Main: (778)821-1399

SKINGSNORTHXCX@GMAIL.COM

Cell:

Vehicle: 1NKDL40X4LR953144

2020 T800

Service advisor: 50851

Tag number: TR953144

Payment type: CHG

Promised time: 11:00 PM

Promised date: 12/05/2023

Waiter: No

Estimate: 350.92

~~~~~  
A 045 DIAGNOSE FOR GEAR/ENGINE DAMAGE AND ADVISE  
045-TS CTAR 045 DIAGNOSE FOR 840.00  
GEAR/ENGINE DAMAGE  
AND ADVISE

Tech(s): 50339

Pts: 0.00 Lbr: 840.00 Other: 0.00 Total Line A: 840.00  
Story: 48352

~~~~~  
B** 045 REPLACE DAMAGED FRONT GEAR HOUSING ASSEMBLY
045-GEN CTRS 045 REPLACE DAMAGED 775.00
FRONT GEAR HOUSING
ASSEMBLY

Tech(s): 50339

Pts: 0.00 Lbr: 775.00 Other: 0.00 Total Line B: 775.00
Story: 48352

~~~~~  
C\*\* 044 REPLACE BROKEN FUEL LINE - BACK OF FUEL FILTER TO TO FUEL  
FILTER HEAD  
044-GEN CTRS 044 REPLACE BROKEN 0.00  
FUEL LINE - BACK OF  
FUEL FILTER TO TO  
FUEL FILTER HEAD

Tech(s):

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
Story: 48352

~~~~~  
D** 045 TROUBLESHOOT FOR METAL FOUND IN OIL PAN
045-TS CTRS 045 TROUBLESHOOT FOR 1,240.00
METAL FOUND IN OIL
PAN

Tech(s): 50339

Pts: 0.00 Lbr: 1,240.00 Other: 0.00 Total Line D: 1,240.00
Story: 48352

~~~~~  
E\*\* 045 RE & RE OIL COOLER ELEMENT, OIL FILTER BYPASS VALVE, OIL  
THERMOSTAT FOR POSSIBLE CONTAMINATION- AS PER CUMMINS PROCEDURE.  
045-GEN CTAR 045 RE & RE OIL 0.00  
COOLER ELEMENT, OIL  
FILTER BYPASS VALVE,  
OIL THERMOSTAT FOR  
POSSIBLE  
CONTAMINATION

Tech(s):

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00  
Story: 48352

# Repair Order Detail - Customer Copy

RO Number: 9191KLS

RO Status: PREASSIGNED

Customer: CIVIL-X CONTRACTING (BC) LTD

SKINGSNORTHXCXC@GMAIL.COM

Phone(s): Contact: (250)862-7379

Main: (778)821-1399

Cell:

Vehicle: 1NKDL40X4LR953144

2020 T800

Service advisor: 50851

Payment type: CHG

Waiter: No

Tag number: TR953144

Promised time: 11:00 PM

Estimate: 350.92

Promised date: 12/05/2023

~~~~~  
F** 045 RE & RE SCORED OIL PUMP
045-GEN CTAR 045 RE & RE SCORED 0.00
OIL PUMP (INSPECTED
ON PREVIOUS
CONDITION)

Tech(s):

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00
Story: 48352
~~~~~

G\*\* 045 RE + INSPECT #1 & #4 MAIN AND CONNECTING ROD BEARINGS-  
045-006-003 CTAR 045 RE + INSPECT #1 & 504.00  
#4 MAIN AND  
CONNECTING ROD  
BEARINGS- \*\*SEE  
NOTES & REFER TO  
CUMMINS PROCEDURE

Tech(s): 50339

Pts: 0.00 Lbr: 504.00 Other: 0.00 Total Line G: 504.00  
Story: 48352  
~~~~~

H** 045 REPLACE FAILED ENGINE WITH CUMMINS NEW ENGINE
045-GEN CTAR 045 REPLACE FAILED 5,040.00
ENGINE WITH CUMMINS
NEW ENGINE

Tech(s): 50339

DR7690NX 1 ENG X15 16 B 605@1950 87,221.94
XPI
FRT 1 FREIGHT IN 625.00
FRT 1 FREIGHT IN 625.00
3686344 1 TUBE,OIL FILLER 109.32
AC10900 2 O RING-#8 PKG 25 1.44
W34-1158 8 BOLT-FLANGE HEAD, M16 129.28
X 2
2866636CUM 1 GASKET, AFM DEVICE 18.97
4988280CUM 1 GASKET,HYDRAULIC PUMP 5.37
PC1462-4 1 UNION COUP DOT;1/4 T 4.20
1461-4 1 AB COMP NUT;1/4 0.42
1460-4 1 AB COMP SLEEVE;1/4 0.14
DR7690NX -1 CORE RETURN -13,914.06
MISC 1 OIL, COOLANT, MISC 1,500.00

Pts: 76,327.02 Lbr: 5,040.00 Other: 0.00 Total Line H: 81,367.02
Story: 48352
~~~~~

# Repair Order Detail - Customer Copy

RO Number: 9191KLS

RO Status: PREASSIGNED

Customer: CIVIL-X CONTRACTING (BC) LTD

SKINGSNORTHXCXC@GMAIL.COM

Phone(s): Contact: (250)862-7379

Main: (778)821-1399

Cell:

Vehicle: 1NKDL40X4LR953144

2020 T800

Service advisor: 50851

Payment type: CHG

Waiter: No

Tag number: TR953144

Promised time: 11:00 PM

Estimate: 350.92

Promised date: 12/05/2023

~~~~~  
I** 045 REASSEMBLE ENGINE CORE FOR RETURN
045-GEN CTAR 045 REASSEMBLE ENGINE CORE FOR RETURN 1,008.00
Tech(s): 50339
Pts: 0.00 Lbr: 1,008.00 Other: 0.00 Total Line I: 1,008.00
Story: 48352
~~~~~

J\*\* 026 TRANSMISSION INPUT SHAFT AND SEAL, R&R (TRANSMISSION ALREADY REMOVED)  
026-001-039 CTRS 026 TRANSMISSION INPUT SHAFT AND SEAL, R&R (TRANSMISSION ALREADY REMOVED) 387.50  
Tech(s): 50339  
308925-25 1 CLUT EP 15.5,2050 1,039.99  
TORQ,VCT DAMPR,7-SPRNG  
K2468 1 KIT-CLUTCH INSTALL 312.98  
SUBL CTRS MACHINE ENGINE 0.00  
FLYWHEEL  
Pts: 1,352.97 Lbr: 387.50 Other: 0.00 Total Line J: 1,740.47  
Story: 48352  
~~~~~

K** 015 REPLACE LEAKING POWER STEERING HOSE AT PUMP
015-GEN CTRS 015 REPLACE LEAKING POWER STEERING HOSE AT PUMP 232.50
Tech(s):
V38-1088 1 FTG-45DEG 5/8" HOSE 65.25
BEAD
NL4875-063X50 3 5/8X50FT BOXED 12.90
SILICONE HOSE
Pts: 78.15 Lbr: 232.50 Other: 0.00 Total Line K: 310.65
Story: 48352
~~~~~

L\*\* 014 REASSEMBLE AND INSTALL MISC ITEMS  
014-GEN CTRS 014 REASSEMBLE AND INSTALL MISC ITEMS 310.00  
Tech(s):  
MISC 1 MISC GRILLE 1,000.00  
Pts: 1,000.00 Lbr: 310.00 Other: 0.00 Total Line L: 1,310.00  
Story: 48352  
~~~~~

Customer Pay

Repair Order Detail - Customer Copy

Labor	10,337.00
Parts	78,758.14
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	499.99
Deductible	0.00
Total Charges	89,595.13
Less Insurance/Adjustment	0.00
Sales Tax	10,751.42
Total	100,346.55