



---

4230 Interprovincial Highway, Abbotsford  
(672) 966-1200  
summitrecreationservices@gmail.COM

September 26, 2025

ATTN: [REDACTED]

VIN# LCELV1ZG7M6002450

2021 CFMOTO ZForce 950

Verified drive problem with unit. Removed drive clutches and inspected. Replaced all sliders, bushings and weights in primary clutch. Installed new bearing assembly in primary as well. Secondary clutch did not require parts and is in good shape. Cleaned both clutches and reinstalled with new belt. Test drove unit, operates as it should. Visually inspected complete unit, no other repairs required at this time.

Sincerely,

Brandin Lafleur

Summit Recreation