

**Tridem Services Ltd.**

20345 102 Ave

Langley, BC V1M 4B4

Phone: 604-882-3877 ~ Fax: 604-513-8004

Email: tridem@telus.net

www.tridemservices.com

Tax ID# 899178552


Invoice

Plate SK 269LEA

Description 2011 Peterbilt 388 Base L6 14.9L 912CID

VIN 1XPWD49X5BD122904

Unit 843

Odometer 1,340,576

Invoice Date 7/12/2023 9:33 AM

Appointment 7/4/2023 8:31 AM

Promised 7/4/2023 8:31 AM

Work
Service Advisor Mel P
Technician Gurpreet K**Service****Commercial Vehicle Inspection**

Labour

1 Hour

\$225.00 / Hour

\$225.00 GP

DECAL - # FX95763 EXP: JAN 2024

1 Unit

\$7.00 / Unit

\$7.00 GP

Sub

\$232.00

PORTION OF ENGINE REPAIRS THAT ARE CUSTOMER'S RESPONSIBILITY

Replaced clutch, machines flywheel and replaced input shaft kit. Replaced rear motor mounts

Labour

3 Hour

\$137.00 / Hour

\$411.00 GP

308925-25 - CLUTCH EP 15.5, 2050 TORQ R20C

1 Unit

\$1,268.43 / Unit

\$1,268.43 GP

SUBLET - FLY WHEEL RESURFACE

1 Unit

\$132.49 / Unit

\$132.49 GP

003F/FUL K2468 - CLUTCH INST KIT

1 Unit

\$328.71 / Unit

\$328.71 GP

M17499 - REAR MOTOR MOUNT (PETERBILT)

2 Unit

\$324.38 / Unit

\$648.76 GP

Sub

\$2,789.39

JOB 3 - FOG LIGHTS, L/S CENTER SIGNAL AND ID LIGHT NOT WORKING. REPAIR FOR REAR LIGHT BRACKET BROKEN

Troubleshoot fog lights - found no power. Check wiring and switch - ok. Found missing 5 amp fuse. Replaced fuse, Found power to fog lights but still not working - removed and replaced fog lights and make/install new plugs. Removed old tail light bracket, drilled holes for new bracket. Installed lights, make up and install new tail light harness.

Labour

4 Hour

\$137.00 / Hour

\$548.00 GP

36070UMC - FOG LIGHT (RECTANGULAR)

2 Unit

\$86.10 / Unit

\$172.20 GP

LP560-99256 - 14 GA TERMINAL SEAL GREY

8 Unit

\$1.15 / Unit

\$9.20 GP

LP560-96900 - 16-14 GA SOCKET TERMINAL FOR
TOWER HOUSING

4 Unit

\$2.26 / Unit

\$9.04 GP

LP560-96902 - 16-14 GA PIN TERMINAL FOR SHROUD
HOUSING

4 Unit

\$2.01 / Unit

\$8.04 GP

LP560-96898 - 2 WIRE TOWER HOUSING

2 UNIT

\$4.76 / UNIT

\$9.52 GP

LP560-96895 - 2 WIRE SHROUD HOUSING

2 UNIT

\$4.58 / UNIT

\$9.16 GP

43362 - BRACKET

3 Unit

\$7.65 / Unit

\$22.95 GP

62231 - BACK UP LIGHT

1 Unit

\$17.76 / Unit

\$17.76 GP

92720 - CLOSED GROMMET

3 Unit

\$4.10 / Unit

\$12.30 GP

94993 - TRUCKLITE - PIGTAIL

3 Unit

\$3.62 / Unit

\$10.86 GP

G6002 - HI COUNT OVAL LED

2 Unit

\$33.40 / Unit

\$66.80 GP

Sub

\$895.83

JOB 4 - #1 L/S HUB CAP LEAKING

Removed and replaced #1 L/S hub cap and gasket

Labour

0.25 Hour

\$137.00 / Hour

\$34.25 GP

303-4024 - HUB CAP

1 Unit

\$49.20 / Unit

\$49.20 GP

330-3024 - HUB CAP GASKET

1 Unit

\$6.68 / Unit

\$6.68 GP

Sub

\$90.13

JOB 5 - WASHER FLUID RESERVOIR MISSING CAP

Replaced reservoir cap

Labour	0.25 Hour	\$137.00 / Hour	\$34.25 GP
C5720S - WASHER RESERVOIR CAP	1 Unit	\$2.98 / Unit	\$2.98 GP
		Sub	\$37.23

JOB 6 - L/S AIR TANK DRAIN VALVE AND R/S AIR TANK ONE WAY CHECK VALVE LEAKING

Removed and replaced tank drain valve and pressure control valve. Replaced leaking purge valve. Found air dryer leaking - replaced air dryer.

Labour	3 Hour	\$137.00 / Hour	\$411.00 GP
TV12105U - DRAIN COCK WITH CABLE	1 Unit	\$15.52 / Unit	\$15.52 GP
109477X - ADIP AIR DRYER COMPLETE	1 Unit	\$538.36 / Unit	\$538.36 GP
K022105 - BENDIX - AD-IS/IP PURGE VALVE	1 Unit	\$174.11 / Unit	\$174.11 GP
1461-4 - #4 AB COMPRESSION NUT	2 Unit	\$1.55 / Unit	\$3.10 GP
1460-4 - #4 AB COMPRESSION SLEEVE	2 Unit	\$0.70 / Unit	\$1.40 GP
RGT223-485V - PRES PRO VALVE 85-67	1 Unit	\$49.21 / Unit	\$49.21 GP
PC1469-5/32A - 5/32X1-8 90ELB CONNECTOR	3 Unit	\$6.95 / Unit	\$20.85 GP
		Sub	\$1,213.55

JOB 7 - REAR BOTH MUD FLAPS NEED TO BE REPLACED

Make up and install new mudflaps and hangers on both sides

Labour	0.5 Hour	\$137.00 / Hour	\$68.50 GP
MKR - MUD FLAP KIT, RIGHT SIDE	1 Unit	\$129.08 / Unit	\$129.08 GP
MKL - MUD FLAP KIT, LEFT SIDE	1 Unit	\$129.08 / Unit	\$129.08 GP
		Sub	\$326.66

JOB 8 - #3 R/S SLACK FAILED AND MISSING #3 L/S AND #2 R/S BRAKE STROKE INDICATORS

Removed and replaced #3 R/S slack adjuster.

Labour	1 Hour	\$137.00 / Hour	\$137.00 GP
40110143 - SLACK ADJUST	1 Unit	\$121.14 / Unit	\$121.14 GP
		Sub	\$258.14

JOB 9 - #3 BOTH SIDE SHOCKS FAILED

Removed and replaced #3 both side shocks

Labour	2 Hour	\$137.00 / Hour	\$274.00 GP
85069 - HD SHOCK	2 Unit	\$87.18 / Unit	\$174.36 GP
		Sub	\$448.36

UNIT ON CHARGE ALL DAY BUT STILL WON'T START - BATTERIES FAILED

Removed and replaced 4 batteries and red cable.

Labour	1.5 Hour	\$137.00 / Hour	\$205.50 GP
31S-1150 - 925CCA BATTERY STARTING 18M	4 Unit	\$188.12 / Unit	\$752.48 GP
909RR - BATTERY CABLE 8" RED	1 Unit	\$30.63 / Unit	\$30.63 GP
		Sub	\$988.61

ABS LIGHT CAME ON DURING FINAL ROAD TEST

Scan for codes found #1 L/S wheel speed sensor failed. Removed and replaced sensor, cleared codes.

Labour	1.5 Hour	\$137.00 / Hour	\$205.50 GP
LAPTOP - LAPTOP DIAGNOSIS	1 Unit	\$50.00 / Unit	\$50.00 GP
4410309102 - ABS SENSOR 90 DEG 2M	1 Unit	\$119.94 / Unit	\$119.94 GP
		Sub	\$375.44

Total Parts		\$5,101.34
Total Labor		\$2,554.00
Total Before Taxes & Miscellaneous Charges		\$7,655.34

(*) Shop Supplies*

(G) Canadian Goods and Services Tax (GST) 5% 7963.05

(P) BC Provincial Sales Tax (PST)*

Exemption #: SK 1058-1-2023-0

Grand Total 22502 398.15 \$8,361.20

Bronco Transportation Systems Inc. charged to 850912001 Account - 75 - Bronco Transportation Systems Inc. - Net 30 Days

**Tridem Services Ltd.**

20345 102 Ave

Langley, BC V1M 4B4

Phone: 604-882-3877 ~ Fax: 604-513-8004

Email: tridem@telus.net

www.tridemservices.com

Tax ID# 899178552

Invoice

Bill To Bronco Transportation Systems Inc.
19787 98Th Ave
Langley V1M 2X5

Phone (604) 888-8777
Email ap@brncotransportation.com

Invoice # 8529
Work Order # 41276
Service Advisor Mel P
Technician Gurpreet K

Plate SK 269LEA
Description 2011 Peterbilt 388 Base L6 14.9L 912CID
VIN 1XPWD49X5BD122904
Unit 843
Odometer 1,340,576

Invoice Date 7/12/2023 9:33 AM
Appointment 7/12/2023 8:13 AM
Promised 7/12/2023 8:13 AM

Service**HEAD AT REAR OF AIR COMPRESSOR LEAKING**

Removed and replaced air compressor with new orings for coolant fittings. Refill coolant and check for leaks - ok

Labour	5 Hour	\$137.00 / Hour	\$685.00 GP
9111530197X - AIR COMPRESSOR 85mm	1 Unit	\$1,352.51 / Unit	\$1,352.51 GP
LP96-1118611 - 9/16 ID 3/32 THICK BUNA O RING	2 Unit	\$0.45 / Unit	\$0.90 GP
LP96-1118616 - 13/16 ID 1/8 THICK BUNA O RING	1 Unit	\$0.50 / Unit	\$0.50 GP
3683814 - O RING SEAL	2 Unit	\$5.51 / Unit	\$11.02 GP
	Sub		\$2,049.93

Total Parts	\$1,364.93
Total Labor	\$685.00
Total Before Taxes & Miscellaneous Charges	\$2,049.93

(*) Shop Supplies*		\$65.08 GP
(G) Canadian Goods and Services Tax (GST)	5 %	\$105.75
(P) BC Provincial Sales Tax (PST)*		\$0.00
Exemption #: SK 1058-1-2023-0		
Grand Total		\$2,220.76



Bronco Transportation Systems Inc. charged \$2,220.76 to Account - 75 - Bronco Transportation Systems Inc. - Net 30 Days

Thanks for the Business!

Please note: If your wheels have been removed during service, you must get your lug-nuts retorqued within 100 kilometers. Keeping your tires properly inflated, rotated & torqued will assist in maximizing tire wear life and vehicle handling.

I acknowledge my indebtedness for the amount of this invoice and acknowledge and agree that in the event of non-payment that the repairer is entitled to liens under any available Repair Liens or Storage Liens Legislation. This information and any other information we have in our data base is restricted to authorized personnel only. This information will be used solely for the current and future service of your vehicle, warranty registration, and any other use required by law.

Customer Signature: _____

CU Date 071223

65000 2115.01

22502 105.75

Approval _____

Driver CB No Yes _____