

Jan-22		Brandt			
12-Jan-22	4726343	Hydraulixy, shim, disk, bushing, seal, hydraul, waste de	6,777.12		
		Deep Basin Shop			
11-Jan-22		Ordered parts loaded truck with filters and oil	Derek	2	250.00
12-Jan-22	8037hrs	removed lift cyclinder, servied. Installed new lift cyclinder	Derek	8	1000.00
		pull new hose through remove other hoses, tighten ends, install gaurds, fill up with hyd			
25-Jan-22	8111	oil run up test for leaks	Alex	7	875.00
		Resource			
21-Jan-22	1163708	1/2" dr 3/8" deep imp/socket, 3/4" dr 1 1/2" imp socket	65.32		
		Shaws			
21-Jan-22	3221609	bruiser bit	956.00		
		Shawn Pandachuck			
		Travel, check out hyd lesk. Removed hose from valve under cab to control valve at cirle			
24-Jan-22	8110hrs	drive. Order new hose. Repair wiring harness along top neck.	1,075.00		
		Climb Machining			
		Tear apart & inspect cylinder. Rod is bent. Barrel is scored. Gland is smashed up.			
26-Jan-22	3982	Machine & weld new rod, new barrel, new gland. Install new seals. Assemble & test.	3,103.44		
Feb-22		Deep Basin Shop			
		Remove lift cylinder on snow wing. Remove keeper and top piece of pin. Install new			
		pin, line base up with come alone. Pound new pin through, install keeper and lift			
		cylinder. Install pitch bolt. Remove door, take to glass shop. Run door back out and			
9-Feb-22	8165hrs	install.	Alex	10	1250.00
22-Feb-22	8204	replace fan hose x3 top up hyd oil, replace wing edgex2	Alex	5	625.00
25-Feb-22	8230	replace wiring edges, install nut on wing bolt check air filters	Alex	2	250.00
		The Glass Shop			
9-Feb-22	4244	cut in install door glass	450.00		
		Brandt			
9-Feb-22	4729412	Pin weldxy	363.66		
22-Feb-22	4730695	2 hydraulixy,	402.20		
24-Feb-22	4730977	3 filter E, 2 air filter, fuel fil	760.38		
		Resource			
24-Feb-22		teri pls wipper, windex trigger ind, spray nine	48.46		
Mar-22		Brandt			
2-Mar-22	4731628	Lamp, wiper	378.62		
8-Mar-22	4732168	Returned seals, disks, shims	(730.70)		
24-Mar-22	4733532	Diesel xy, core, break, waste, break.	51,272.99		
		Factory Engine			
11-Apr-22	8267hrs	replaced articalation sensor assembly. Replace bushing shafts and sensors	Derek	5	625.00
11-Apr-11		remove hold down bolts order new bolts nuts.	Alex	10	1250.00
12-Apr-22		LH shim pack off beat shims straight and install,	Alex	5	625.00
		Brandt			
5-Apr-22	4734266	V belt, bulk hose, clamp.	284.76		
9-Apr-22	4734545	Insert , insert, sensor, module, snap rin bushing armarm, keykey, cap scre	2,160.52		
12-Apr-22	4734632	cap scre, nutnut	98.20		
25-Apr-22	4735314	Return engine core	(4,477.00)		
		Triple "S" Tire			
11-Apr-22	BL234111	Call out, change over 6 tires on grader	621.30		