

Pacific Coast Heavy Truck Group



☒ **Sold From:**
Chilliwack
44250 Progress Way
Chilliwack, BC
V2R 0W3
604-426-1086

Our Locations:

Langley: 604-888-5577
Annacis Island: 604-526-2231
Chilliwack: 604-426-1086
Kamloops: 250-374-3883

Invoice

R103015250:01

Date Invoiced: 03/18/2024

PO No:

Asist Case: 18084156

Terms: **NET30**

Our Unit# 110106

Cust Unit# 2104

GST No. 129757167RT

Bill To:

Owner:

www.PCHTG.caYour ACCOUNT Number: Customer Phone: 

Make: VOLVO	Year: 2014	VIN: 4V5RC9EH7EN154779
Model: VAH	Series:	Mileage In: 907,419 KM
DateCreate: 03/06/2024	Promised Time: 2024-03-06 12:00:00AM	Mileage Out: 907,419 KM
Writer: 521 (HG)	Reviewed: 350 (AR)	Engine Hours: 18,235
Posted By: 350 (AR) @ 2024-03-18 2:17:27PM	LastTimePunch: 2024-03-14 12:32:54PM	Tag: 20

Operation: 1

SalesType: SRET

Complaint TRUCK KEEPS GOING IN AND OUT OF DERATE, PLEASE DIAGNOSE AND ADVISE

PLEASE NOTE WAS AT LANGLEY (GOT THEM TO DIAGNOSE, I HAVE ATTACHED THERE NOTES)

Correction: CHECK CODES, NO ENGINE CODES, CHECK PRODUCT HISTORY VIEWER AND FOUND CODES WERE JUST CLEARED, UNIT HAD P20EE00 AND P207F00 BOTH ACTIVE. PRESSURE TEST CAC SYSTEM FOUND TEMP SENSOR IN THE CAC PIPE LEAKING. SENSOR NUT IS TIGHT BUT NOT CLAMPING SENSOR. REPLACE SENSOR. CHECK EGR OUTLET- OK. RUN EGR FUNCTION TEST, EGR SYSTEM WORKING OK. REMOVE SCR DOSER HEAT SHIELDS AND FLOW TEST THE DEF DOSER, WITHIN SPEC. RUN A CRYSTAL SUBLIMATION AND THEN A NOX CONVERSION. FOUND THE OUTLET NOX SENSOR START UP READINGS ERRATIC AND SENSOR READING SLIGHTLY HIGH. PERFORM A ROAD TEST AND MONITOR NOX LEVELS, FOUND WHILE CRUISING THE OUTLET NOX ARE IN THE 280-300 PPM RANGE, THEY SHOULD BE IN THE MID TO HIGH DOUBLE DIGITS. UNIT REQUIRES AN OUTLET NOX SENSOR AND A SCR CAT. (COMPLETED ON OPERATION 6)

Operation: 2

SalesType: SRET

Complaint GREASE 5TH WHEEL**Correction:** GREASED 5TH WHEEL**Operation: 3**

SalesType: SRET

Complaint THE OIL PAN, ON THE DS THERE IS A RUBBER HOSE AND THE CLAMP IS LOOSE, PLEASE TIGHTEN**Correction:** TIGHTEN HOSE CLAMP ON OIL FILL HOSE. COMPLETED

Description:		Extd Price
Labor		40.20
Operation	Prepay: \$0.00	Labor: \$40.20
	Parts: \$0.00	Sublet: \$0.00
	Misc: \$0.00	Total: \$40.20

Operation: 4

SalesType: SRET

continued on page 2

Bill To:

Owner:

Invoice**R103015250:01****Complaint** DEDUCTIBLE**Correction:** ON JOB 6**Operation: 6**

SalesType: SRET

Complaint FOUND ON OPERATION 1 UNIT REQUIRES AN OUTLET NOX SENSOR AND SCR CAT

Correction: UNIT HAD P20EE00 AND P207F00 BOTH ACTIVE. PRESSURE TEST CAC SYSTEM FOUND TEMP SENSOR IN THE CAC PIPE LEAKING. SENSOR NUT IS TIGHT BUT NOT CLAMPING SENSOR. (HAD TO REPLACE SENSOR TO STOP BOOST LEAK). CHECK EGR OUTLET- OK. RUN EGR FUNCTION TEST, EGR SYSTEM WORKING OK. REMOVE SCR DOSER HEAT SHIELDS AND FLOW TEST THE DEF DOSER, WITHIN SPEC. RUN A CRYSTAL SUBLIMATION AND THEN A NOX CONVERSION. FOUND THE OUTLET NOX SENSOR START UP READINGS ERRATIC AND SENSOR READING SLIGHTLY HIGH. PERFORM A ROAD TEST AND MONITOR NOX LEVELS, FOUND WHILE CRUISING THE OUTLET NOX ARE IN THE 280-300 PPM RANGE, THEY SHOULD BE IN THE MID TO HIGH DOUBLE DIGITS. UNIT REQUIRES AN OUTLET NOX SENSOR AND A SCR CAT.

Qty:	Item:	Description:	Unit Price:	Extd Price
		Labor		2,010.00
2	103M/21021850	5" DPF CLAMP	73.92	147.84
2	103M/21095726	5" DPF GASKET	37.84	75.68
1	103M/21164792	EGR TEMPERATURE SENSOR 2	181.90	181.90
1	103V/21311951	MUFFLER SCR	8,468.90	8,468.90
1	103M/21376801	SEAL - SCR DOSAGE MODULE	51.34	51.34
1	103V/22303391	SENSOR POST NOX	1,075.36	1,075.36
-1	103V/22303391-CORE	Dirty Core	174.00	-174.00
4	103M/984733	M8 X 1.25 X 16 FLANGE BOLT	1.95	7.80
15	1031/WUR55359001	HD CABLE TIE 15` `	0.28	4.20
1	103V/22303391-CORE	Clean Core Charge	174.00	174.00

Operation	Prepay: \$0.00	Labor: \$2,010.00	Parts: \$10,013.02	Sublet: \$0.00	Misc: \$0.00	Total: \$12,023.02
------------------	-----------------------	--------------------------	---------------------------	-----------------------	---------------------	---------------------------

Operation: 7

SalesType: SRET

Complaint NOTE: PORTION OF PAYMENT FOR PREMIUM 2000+
\$ 8068.61

Please remit payment to:
Pacific Coast Heavy Truck Group
9758- 203rd Street, Langley, BC
V1M 4B9
ar@pactrucks.com

Authorized By: _____

Printed Name: _____

Date: _____

Parts:	10,013.02
Labor:	2,050.20
Sublet:	0.00
Misc Supplies:	184.52
Misc Diag:	0.00
Misc Charges:	0.00
Prepay:	0.00
Subtotal:	12,247.74
GST:	612.39
PST-1059-8306	12.92
WorkOrder Total:	12,873.05

Terms: NET 30 days 2% per month (26.824% per annum) on overdue amounts