

**Pioneer Parts Rebuilding LTD.**9184 National Place
Prince George, B.C.
V2N 5T1Ph. (250) 561-0122
Fax. (250) 562-2398
E-mail: accounts@pioneerparts.com

Invoice

Date	Invoice
22/05/2024	R24575

Invoice ToDaniel Albertson
BC**Ship To**

Customer P.O. No.	Reference	Terms	Ship Via	W.O. No.
				W15580
02515 Hitachi Main Pump	HPV102GW-RH23A		John Deere 270 DLC	

Description	Ordered	Shipped	B/O	Price	Total
No warranty					
Parts and Labour					5,423.52
HPV102 Head - In-line ports - Aftermarket	1.0	1.0		1,496.00	1,496.00
HPV102/105 - Valve Plate LH - Aftermarket	1.0	1.0		348.00	348.00
HPV102/105 - Valve Plate RH - Aftermarket	1.0	1.0		348.00	348.00
HPV102/118 Servo Pintle/Piston Pin - Aftermarket	2.0	2.0		20.79	41.58
HPV102 Hitachi Pilot Pump Seal Kit	1.0	1.0		111.55	111.55
HPV102/118 Pump Seal Kit	1.0	1.0		246.75	246.75
HPV102/118 Various Common Seals (not included in the Seal Kit)	1.0	1.0		26.10	26.10
HPV102/118 Gear Case Gasket Seal Kit	1.0	1.0		132.00	132.00
HPV102,118,145 Regulator Seal Kit - Idler Side	1.0	1.0		29.40	29.40
HPV102,118 Regulator Seal Kit - Drive Side	1.0	1.0		54.14	54.14
Shop Labour	16.0	16.0		130.00	2,080.00
Shop Supplies	1.0	1.0		75.00	75.00
Testing	3.0	3.0		145.00	435.00
Additional Seals					33.79

Sub Total	\$5,457.31
PST 7%	\$382.01
G.S.T 5%	\$272.87
Total	\$6,112.19

PAY BY INVOICE**No statement issued**

GST/HST No. 104208764

TERMS: THERE IS NO WARRANTY EXCEPT AS EXPRESSLY STATED HEREIN AND, IN ANY EVENT, OUR LIABILITY IS LIMITED TO REPAIR OR REPLACEMENT AT OUR PREMISES AND DOES NOT INCLUDE THE COST OF REMOVAL, INSTALLATION, SYSTEM CLEANING, TRAVEL OR LOSS OF USE. NET 30 DAYS. PAST DUE INVOICES SUBJECT TO A SERVICE CHARGE OF 2% PER MONTH (24% PER ANNUM)