CARD CARD TYP DATE TIME 5429 11:50:01 RECEIPT NUMBER C84045233-001-001-202-0 PURCHASE TOTAL

Vignment and Truck Repairs Ltd.

| <i>95 Ave</i> | |
|------------------------|---------------|
| BC | - 00 L |
| :8 | , 4.1 |
| ax # 604-628-74 | |
| @gmail.com | 223.00 |
| | Z4- |

Invoice

| Date | Invoice # |
|------------|-----------|
| 2023-08-01 | 28446 |

NOTE: Retorque U-Bolt after 7 days.

| Vin # | LICENCE | Make | P.O. No. | Milage | Rep |
|---------|---------|------|----------|--------|-------|
| GJ98309 | 7689-8P | KW | | | JAGDI |

100

APPROVED

AUTH# 00063Z 01-027 THANK YOU

CARDHOLDER COPY

A 'MPORTANT - RETAIN THIS COPY FOR YOUR RECORDS

IMPORTANT - RETAIN THIS COPY FOR YOUR RECORDS

| | Description | Rate | Amount | 1 | Tax |
|---|--|--------|----------|----|-----|
| 4 | Roadlux R516 11R22.5 | 270.00 | 1,080.00 | G | |
| 4 | Levy on tire | 14.00 | 56.00 | ĪĠ | • |
| 4 | Stem& Valve | 12.00 | 48.00 | G | |
| 2 | Oil Add | 4.50 | 189.00 | s | • |
| 5 | Levy on Oil | 1.25 | 6.25 | lG | |
| | Lube Filter | 55.65 | 55.65 | Ğ | |
| | Fuel Filter | 63.85 | 63.85 | lG | |
| | Paccar Fuel Element | 73.25 | 73.25 | ÌG | |
| | Labour- Reℜ Oil Change and Filters (Sandeep) | 110.00 | 110.00 | G | |
| | Air Spring | 190.00 | 380.00 | lG | |
| | CONN Dot; 3/8 TX3/8 MPT | 5.50 | 5.50 | lG | |
| 1 | 110-DC 1/2" X 3/8" Brass reducer bushing | 2.25 | 2.25 | lG | |
| 2 | Labour- Reℜ Air Bag | 110.00 | 220.00 | G | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | 1 | |

Customer Bus. No.

The undersigned hereby acknowledge: That the understand is indebted the above named company in the amount set out on this work order together with interest of 20% per month, 24th per annum computed from the date of this work order.

That until payment in full for this work order is received, a lien under the Repair and Storage Lien Act of BC on vehicle described herein in respect of the material supplied, all disbursement and service rendered under this work order for the full amount charged therfore and furthe rthat the said lien shall continue in force at all times whether the vehicle is in my possession of the debtor.

That we, or our balliff or agent may seize and resume possession at anytime if the amount of the indebtedness is not paid on due date and relize the amount of such indebtedness together with all costs and disbursements of the resuming possesion

NOTE: Nut Retorque after 100 to 150 KM.

Thank you for you business

Customer Signature:_____

| Subtotal | \$2,289.75 |
|-------------------|---|
| Sales Tax Summary | GST@5.0% 114.49 PST (BC)@7.0% 13.23 Total Tax |
| Total | \$2,417.47 |
| Payment | -\$2.417.47 |
| Balance Due | \$0.00 |

TORQUE TECH TRUCK & TRAILER REPAIR LTD.

7583 VANTAGE PLACE DELTA BC V4G 1.45 Telephone (604) 498-1462 FAX (604) 498-1692 torquetechrepair@gmail.com/torquetechrepair.ca



Invoice #: 10402

Invoice Date: Sep 29, 2023

Due Date: Sep 29, 2023

GST #: 741019483RT0001

CUSTOMER INFORMATION VEHICLE INFORMATION Plate No.: 7689-8P Mileage: 503,182KM Make: KENWORTH Unit #: 1309 Vehicle ID: 1XKYD49X2GJ981309 Year: 2016 Reg. No.: P.O #: Model: Hours:

Telephone: (206) 218-7482 Cell: (604)

Attn: MR. ROY

MVI Decal: Eng. Serial #: MVI Expiry: Mar 31,2024

PST: 2048

| | LABOUR DETAIL | | |
|-------|--|----------|----------|
| HOURS | DESCRIPTION | PER HOUR | AMOUNT |
| 1 | MOTOR VEHICLE INSPECTION CHARGES | \$180 | \$180,00 |
| 4 | REPLACED LEAKING OIL PAN ASSEMBLY WITH NEW GASKET. | S110 | \$440.00 |
| 1 | REPLACED 1ST DIFFERENTIAL SUSPENSION TORQUE ARM. | \$110 | \$110.00 |
| .5 | REPLACED FAULTY UTILITY LIGHT AT LEFT SIDE AFTER CHECK POWER AND GROUND ISSUE. | S110 | \$55.00 |
| 1 | REPLACED 2ND DIFFERENTIAL SUSPENSION TORQUE ARM. | S110 | \$110.00 |
| 2.5 | REPLACED AXLE#1 RIGHT SIDE WHEEL SEAL >REMOVED WHEEL, DRUM. >BEFORE REMOVING BRAKE FOUND CRACK ON THEM INFORMED CUSTOMER OVER THE PHONE AND ADVISED TO CHANGE B'S SAME TIME DUE TO IN MOST CASE VIBRATION ISSUE DUE TO PAD THICKNESS FRICATION. BUT FINAL CALL CUSTOMER, GOT AUTHORIZATION AND INSTALLED NEW BRAKE PAD AND DRUM. >INSPECTED BEARING AND CUP CONE. >INSTALLED NEW WHEEL SEAL. >INSTALLED BRAKE SHOES. >INSTALLED NEW GASKET ON HUB CAP AND FILLED HUB OIL. >ADJUSTED BRAKES. | S110 | \$275.00 |
| | REPLACED AXLE#1 LEFT SIDE BRAKE SHOES. >REPLACED BRAKE DRUMS. >REPLACED BRAKE SHOES . >REPLACED BRAKE HARDWARE KIT. >ADJUSTED BRAKES. | \$110 | S110.00 |
| | REPLACED STEADY BEARING ON DRIVE SHAFT. >ALL BEARING BALLS BAD AND RUBBER BAD. >RING BADLY STUCK ON SHAFT TO REMOVE WITH HEAT WITH VERY CAUTION. >INSTALLED NEW CENTER BEARING. >INSTALLED SHAFT TO TRUCK. | \$110 | \$275.00 |

parament due on re-eign unless otherwise specified. Increst at 2-spec month (22-spec announced), be charged on the oredise account. Promise to pay to the order of TORQUE TECH TRUCK & TRAILER REPAIR LTD, the outstanding sum. All estimate is for labour only. Materials will be charged enter. This company, loss not assume only responsibility whatever for units left for regules, storage or other purposes, or for articles left in units, during coursed by fire, theft, testing erray, other value beyond the control of TORQUE TECH TRUCK & TRAILER REPAIR LTD. Thereby undontee TITTRL to register a PPSA collateral or any and all assets to cover the total debt outstanding. Unit, payment is tall of the within account. Thereby acknowledge the existence of a mechanic's lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work or der too the value account of a mechanic lien in a labour or the value of the within a count of the vehicle is in no possession or possession of the dealer, and the extensive specific or the vehicle is in no possession or possession of the dealer, and the extensive specific or the vehicle is in no possession or possession of the dealer, and the extensive specific or the vehicle is in no possession or possession or the dealer, and the extensive specific or the vehicle is in no possession or possession or the dealer, and the extensive specific or the vehicle of the vehicle is in no possession or possession or the dealer.

| Customer | Signature: | | |
|----------|------------|------|------|
| | 5.00 | | |

TORQUE TECH TRUCK & TRAILER REPAIR LTD.

7583 UANTAGE PLACE DELTA BC V4G 1.45 Telephone (694) 498-1462 FAX (604) 498-1692 torquetechrepair@gmail.com/torquetechrepair.ca



Invoice #: 10402

Invoice Date: Sep 29, 2023

Due Date: Sep 29, 2023

GST #: 741019483RT0001

| | LABOUR DETAIL | | |
|-----|---|--------------|----------|
| | DESCRIPTION | PER HOUR | AMOUNT |
| 2.5 | REPLACED TRANSMISSION OUTPUT SEAL FOR OIL LEAK. | \$110 | \$275.00 |
| | RE-SEALED PLATE WITH NEW GASKET . | | |
| .75 | REPAIRED AIR LEAK UNDER CAB RIGHT SIDE NEAR FIRE WALL WITH REQUIRED FITTING AFTER CHECK AIR LEAK. | \$110 | \$82.50 |
| | **NO CHARGE*** CLUTCH BRAKE IS GOOD .BUT FILLED WITH GREASE AND OIL. | s | \$0.00 |
| | PARTS DET AIL | _ | |
| QTY | DESCRIPTION | ЕЛСН | AMOUNT |
| 1 | OIL PAN.CUMMINS,AFTER MARKET | \$750.00 | \$750.00 |
| 2 | TORQUE ROD KENWORTH PETERBILT | \$165.00 | \$330.00 |
| 2 | BRAKE SHOES,STEER .RSD | \$136.49 | \$272.98 |
| 1 | BRAKE DRUM,STEER .USA .ALLIANCE | \$210.02 | \$210.02 |
| 1 | GASKET.HUB CUP | \$3.50 | \$3.50 |
| 1 | HUB OIL | \$7.40 | \$7.40 |
| 1 | STEADY BEARING | \$130.80 | \$130.80 |
| 1 | SEAL KIT, TRANSMISSION .REAR | \$83.21 | \$83.21 |
| 1 | WHEEL SEAL STEER | \$60.74 | \$60.74 |
| 1 | ENGINE OIL 15 W 40 DELO .CHEVRON.400 SDE. | \$270.00 | \$270.00 |
| 1 | OIL FILTER | \$60.90 | \$60.90 |
| 2 | ELECTRIC CONNECTOR - \$HRINK TUBE | \$2.00 | \$4.00 |
| 1 | LOAD/UTILITY LED SQUARE WORK 1300 | \$34.00 | \$34.00 |
| 1 | 90ELB DOT 1:4T X 3/8 MPT SW | \$9.30 | \$9.30 |

payment due on receipt unless otherwise specified. Interest at 2% open monto (2% open monto in the sungest on all receiption and receipt unless otherwise specified. Interest at 2% open monto (2% open monto in the sungest on all receiption on the ordinal receiption and the ordinal sum. All estimate is for labour only. Materials was be charged even Tots common dees not assort an intermed at the repair, though no other graphs, so for articles left in units, domage caused by fire, theft, to string or any other cause by and the common of TORQUE TECH IRCCR & TRAILER REPAIR LTD. I hereby authorize TTTIRL to register a PPSL ordinared on any and all assets to cover the total debt outstending. Unit payment in tall of the within all common closests of the existence of a mechanic's line in lavor of the vehicle described herein in respect of the material supplied and services readered under the work or the tall amount charged the center of nature acknowledge that the said line shall common in the dealer to the vehicle to in my passession or passession of the dealer to the account is paid to the **Total Common C

| Customer Signature: | |
|---------------------|--|
|---------------------|--|

TORQUE TECH TRUCK & TRAILER REPAIR

7583 VANTAGE PLACE DELTA BC V4G 1A5 Telephone (604) 498-1462 F4X (604) 498-1692 torquetechrepair@gmail.com/torquetechrepair.ca



Invoice #: 10402

Invoice Date: Sep 29, 2023

Due Date: Sep 29, 2023

GST #: 741019483RT0001

| | Total Labour: | \$1.912.50 |
|--------------------------|----------------------------|------------|
| | Total Parts: | \$2,226.85 |
| All items subject to GST | Shop Supplies: | \$103.48 |
| | Environment Handling Levy: | \$0.09 |
| | Sub-Total: | \$4,242.92 |
| Invoiced by: | ENVIRONMENT: | \$0.05 |
| | GST: | \$212.15 |
| | Invoice Total: | \$4.455.12 |
| | Balance: | \$0.00 |

parment due on re-cipt unless otherwise specified interest at 2° specimon will be surged on all overvitie occumits. Promise to pay to the order of TORQUE TECH TRUCK & TRAILER REPAIR LTD. The outstanding sum, All estimate is for labour only. Materials will be charged extra. This company does not assume air responsibility whatever for units left for replaces, storage or other proposes, or for articles left in units. I damage extised by the cherical sum of the control of TORQUE TECH TRUCK & TRAILER REPAIR LTD. Thereby authorize TITTR: to register a PDS Collaboration any and all assess to cover the total debic outstaining. Until parment in all or the will in account They be achieved by the extrained which shows then in favor of the within dealer on the will all secretical herein in respect of the material supplied and secretical evidence of the material supplied and secretical evidence in the fall annual charged therein. I mathe acknowledge that the wall lien shall, outsine in force at all and the evidence in the proposession of the dealer of the material supplied and secretical evidence of the material evidence of the evidence of the material evidence of the material evidence of the evidence of the

| Customer Signature: | |
|---------------------|--|
| | |

TORQUE TECH TRUCK & TRAILER REPAIR LTD.

7583 UANTAGE PLACE DELTA BC V4G 1.45 Telephone (604) 498-1462 FAX (604) 498-1692 torquetechrepair@gmail.com_torquetechrepair.ca



Invoice #: 10559

Invoice Date: Oct 28, 2023

Due Date: Oct 28, 2023

GST #: 741019483RT0001

| CUSTOMER INFORMATION | | VEHICLE INFOR | RMATION | |
|----------------------|----------------|-------------------|-------------|-------------|
| | Plate No.: | 7689-8P | Mileage: | 703.864KM |
| | Make: | KENWORTH | Unit #: | 1309 |
| | Vehicle ID: | 1XKYD49X2GJ981309 | Year: | 2016 |
| | Reg. No.: | | P.O #: | |
| | Model: | | Hours: | |
| Te | MVI Decal: | | MVI Expiry: | Mar 31,2024 |
| \t | Eng. Serial #: | | PST: | 2048 |

| | LABOUR DETAIL | | |
|-------|--|----------|------------|
| HOURS | DESCRIPTION | PER HOUR | AMOUNT |
| 2 | TROUBLE SHOOT FOR TRANSMISSION SHIFTING ISSUE, TEST DROVE FOUND 3.4.5 7.8 HIGH LOW GEARS CICK BACK. INSPECTED TRANSMISSION ,UNDER ENGINE, FOUND TRANSMISSION LEANING TO RIGHT SIDE DUE TO BROKEN ENGINE MOUNT. | \$110 | \$220,00 |
| 12 | REPLACED ENGINE MOUNT. >REMOVED RIGHT SIDE STEP FENDER. >REMOVED EXHAUST OUTLET PIPING AFTER TURBO TO GET ACCESS. >REMOVED RIGHT SIDE MUDGUARD. >START REMOVING ENGINE MOUNT. >HOLD TRANSMISSION ON JACK. >HOLD CAB RIGHT SIDE ON POWER PORTER JACK. > FOUND ENGINE MOUNT BOLTS (4) TWO OF THEM UNDER CAB HOLDING MOUNT. >MANUALLY OPEN CAB MOUNT BOLTS. BADLY SEIZED. | \$110 | \$1.320.00 |
| -2 | ***DISCOUNT TO CUSTOMER ON RIGHT SIDE ENGINE JOB##M8# | S | \$0.00 |
| | PARTS DETAIL | | |
| QTY | DESCRIPTION | EACH | AMOUNT |
| 4 | BOLT.FLANGE M 16X2X70 10.9 | \$6.17 | 524.68 |
| 1 | ENGINE MOUNT, RIGHT SIDE.OEM | \$942.00 | \$942.00 |
| 1 | HYDRAULIC LINE.CLUTCH | \$228.34 | \$228.34 |
| 2 | BOLT KIT 3 4" | \$6.50 | \$13.00 |

| Customer Signature: | |
|---------------------|--|
| | |

TORQUE TECH TRUCK & TRAILER REPAIR

7583 UANTAGE PLACE DELTA BC 14G 1.15 Telephone (604) 49x-1462 FAX (604) 49x-1692 torquetechrepair@gmail.com_torquetechrepair.ca



Invoice #: 10598

Invoice Date: Nov 04, 2023

Due Date: Nov 04, 2023

GST #: 741019483RT6001

| CUSTOMER INFORMATION | VEHICLE INFORMATION | | |
|----------------------|--------------------------|------------------------|--|
| | Plate No.: 7689-8P | Mileage: 706,497M | |
| | Make: KENWORTH | Unit #: 1309 | |
| | Vehicle ID: 1XKYD49X2GJ9 | 981309 Year: 2016 | |
| | Reg. No.: | P.O #: | |
| | Model: | Hours: | |
| | MVI Decal: | MVI Expiry: Mar 31,202 | |
| | Eng. Serial #: | PST: 2048 | |

| | EABOUR DE TAIL | | | | | |
|-------|---|------------|------------|--|--|--|
| HOURS | DESCRIPTION | PER HOUR | AMOUNT | | | |
| 12 | RE AND RE TRANSMISSION CLUTCH | \$110 | \$1,320,00 | | | |
| 2 | REPLACED TRANSMISSION INPUT SHAFT KIT | \$110 | \$220.00 | | | |
| 1 | TRANSMISSION INSPECTION TOP LID REMOVAL AND RE-SEAL | SILO | \$110.00 | | | |
| 4 | CHANGED LEFT SIDE ENGINE MOUNT(REAR ENGINE SIDE) | \$110 | \$440.00 | | | |
| .5 | REPLACED ENGINE REAR MAIN SEAL | \$110 | \$55.00 | | | |
| | PARTS DETAIL | <u>'</u> | | | | |
| QTY | DESCRIPTION | EACH | AMOUNT | | | |
| 1 | CLUTCH | \$1,337.94 | \$1,337.94 | | | |
| 1 | KIT-CLUTCH INSTALLATIO | \$624.72 | \$624.72 | | | |
| 1 | FLYWHEEL | \$110.00 | \$110.00 | | | |
| ı | TRANSMISSION OIL .SYNTHETIC . 75 W 90 .PAIL | \$285.00 | \$285.00 | | | |
| 1 | SEAL-CRANKSHAFT REAR | \$176.30 | \$176.30 | | | |
| 1 | TRANSMISSION TOP PLATE GASKET | \$7.68 | \$7.68 | | | |
| 2 | BOLT-TOP LID | \$5.50 | \$11.00 | | | |
| 1 | ENGINE MOUNT.RIGHT SIDE.OEM | \$942.00 | 5942.00 | | | |
| 4 | BOLT,FLANGE M 16X2X70 10.9 | \$6.17 | \$24.68 | | | |
| 15 | TIE STRAP 14"/BLACK HEAVY DUTY | \$1.00 | \$15.00 | | | |
| 10 | BOLTS AND LOCK WASHERS | \$3.98 | \$39.80 | | | |
| 1 | BRAKE CLEAN | \$20.00 | \$20.00 | | | |
| 4 | BOLT KIT 3/8 | \$2.60 | \$10.40 | | | |

payment due on receipt unless atherwise specified. Interest at 2 open norm 22 open norm 86, onego of a contract of one to prove the order of TORQUE TECHTRUCK & TRAILER REPAIR LTD, the materialism of the storage of normal substantiang sign. All estimate is not laborated. Make no one open a contract of the storage of normal substantiang sign. All estimates of the storage of normal substantiang sign. All estimates of the storage of normal substantiang sign. All estimates of the storage of normal substantiang sign. All estimates of the storage of the storage

| Customer Signature: | |
|---------------------|--|
| | |

TORQUE TECH TRUCK & TRAILER REPAIR I TD

7583 VANTAGE PLACE DELTA BC V4G IAS Telephone 1614) 498-1462 FAX 1604) 498-1692 torquetechrepair@gmail.com_torquetechrepair.ca



Invoice #: 10598

Invoice Date: Nov 04, 2023 Due Date: Nov 04, 2023

GST #: 741019483RT0001

| All items subject to GST | |
|--------------------------|--|
| | |
| Invoiced by: | |

| Total Labour: | \$2.145.00 |
|----------------|------------|
| Total Parts: | \$3,604.52 |
| Shop Supplies: | \$143.74 |
| Sub-Total: | \$5,893.26 |
| GST: | \$294.67 |
| Invoice Total: | \$6,187.93 |
| Balance: | \$6,187.93 |

Enough due on receipt unless otherwise specified. Interest at 2% per month (24% per month in larger et al. 1% contact of month. Provide to pay to the order of TORQUE TECH TRUCK & TRAILER REPAIR LTD., the outstanding sum, All estimate is for latiour only. Materials such the charged extra. The congram does not assume any responsibility whitever for units demand caused by fire, their, testing or any other caused by a month of the contact of the purposes of any entries left in units. Admage caused by fire, their, testing or any other caused by a month of the contact of the purpose of any other lating or any other caused on any and all assets to cover the total deby outstanding. Until parameter in tall of the value according to the extreme of a mechanical supplied and services remained in the value according to the extreme of a mechanical supplied and services remained in the value of the value according to the extreme of a mechanical supplied and services remained in the value of the value of the extreme of a mechanical supplied and services remained in the value of the v

| rlease make payment by E-transfe | r Or by debit card/account transfer/certified shows to such as |
|----------------------------------|--|
| credit cards. | r or by debit card/account transfer/certified cheque to avoid 2% surcharge which is only being charge on |
| | - |

| Customer Signature: | |
|---------------------|--|
|---------------------|--|


Tire King Truck Repair Ltd



12876 85th Ave Surrey BC V3W 0K8

Phone #604-957-5200 Fax # 604-957-3377 E-mail tirekingrepair @gmail

| | IIIV |
|----------|-----------|
| Date | Invoice # |
| 4/5/2022 | 46680 |
| | |



040Forized Dealers:-

ifinental

GST/HST No. 835471269

NOTE: Nut Retorque after 100 to 150 Km.

| Unit# | Vin# | T | Tique after 100 | to 150 Km. | | | _ | |
|------------------|--------|------------|-----------------|------------|---------------|-------------|----------|-------|
| 19-73 777RT | | Year | Make | | | | TIRE C | F |
| L | 981309 | 2016 | VIII - | Milage | Licence Plate | Rep | | |
| Item | | | KW / TRAILER | | 63473P/921 | | P.O. No. | Terms |
| R516 | Qty | | Dosavi | | 3.7721 | | | |
| levy Stan 6 1 | 4 | 11R22.5 Rc | Description | | Rate | $\neg \neg$ | Amount | |

| Item Qty Description Rate Amount | | |
|--|--|-------|
| R516 | Item | Terms |
| m 65.99 65.99 6 | R516 levy Stem &Valve Tire-RE Rotation Seam | Tax |
| our- Re & Re S-cam -1st axle L/S. Re & Re s 1 tube. Re & Re Slack. Re & Re Brake, Re & 12.00 | Tire King Tro 12876 85TH SURREY, BC | 99 |

| " Work order | 400,0 |
|--|---------------------------|
| th per annum compu | ted from the date of this |
| received, a lien under in respect of the mat this work order for the | the Repair and Storage |
| nd resume possession | |

nd resume possession at any time if the Jue date and realize the amount of such sbursements of the resuming possession. 355

| Sales Tax Summary | |
|-------------------|--------------------|
| | GST@5.0% |
| | 98.70 |
| | Total Tax 98.70 |
| | |
| | |
| Total | \$2.072.69 |
| Total Payment | \$2.072.69 |

ignment and Truck Repairs Ltd.

Ave ,. □C v3W 0K8

..une # 604-628-9500 Fax # 604-628-7453

E-mail: tirekingrepair@gmail.com



Invoice

| 71140166 | | |
|------------|-----------|--|
| Date | Invoice # | |
| 2022-07-27 | 25361 | |

| Invoice To | | |
|------------|--|--|
| | | |
| | | |
| | | |

NOTE: Retorque U-Bolt after 7 days.

| | Unit # | Year# | Vin # | LICENCE | Make | P.O. No. | Milage | Rep |
|---|--------|-------|-------|---------|------|----------|-------------|------|
| | 1973 | | | 63473P | | | | Кер |
| - | | | | | | | 658513miles | Deep |

GST Number

826184400

| Item | Qty | Description | Rate | Amount | Tax |
|--|-----|--|-----------------------------------|-----------------------------------|-------------|
| Oil Change Levy K37-1029 Labour | 1 | Oil Change Levy on Oil FILTER Labour- Reℜ Oil Pan Gasket (Customer) | 350.00 1.25 55.00 100.00 | 350.00 6.25 55.00 400.00 | S G G |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Customer Bus. No.

The undersigned hereby acknowledge: That the understand is indebted the above named company in the amount set out on this work order together with interest of 20% per month, 24th per annum computed from the date of this work order.

That until payment in full for this work order is received, a lien under the Repair and Storage Lien Act of BC on vehicle described herein in respect of the material supplied, all disbursement and service rendered under this work order for the full amount charged therfore and furthe rthat the said lien shall continue in force at all times whether the vehicle is in my possession of the debtor.

That we, or our balliff or agent may seize and resume possession at anytime if the amount of the indebtedness is not paid on due date and relize the amount of such indebtedness together with all costs and disbursements of the resuming possesion

NOTE: Nut Retorque after 100 to 150 KM.

Thank you for you business

Customer Signature:

| | Subtotal | \$811.25 |
|---|-------------------|--|
| ι | Sales Tax Summary | GST@5.0% 40.56 PST (BC)@7.0% 24.50 Total Tax |
| | Total | \$876.31 |
| | Payment | -\$876.31 |
| | Balance Due | \$0.00 |

lignment and Truck Repairs Ltd.

35 Ave Surrey. BC V3W 0K8

Phone # 604-628-9500 Fax # 604-628-7452

E-n.ail: tirekingrepair@gmail.com



Invoice

| Date | Invoice # |
|------------|-----------|
| 2022-06-13 | 24942 |

| NOTE: | Retorque | U-Bolt | after | 7 | davs. |
|-------|----------|--------|-------|---|-------|
| | | U 2016 | 41101 | • | uu;s. |

| Omt # | rear# | Vin # | LICENCE | Make | P.O. No. | Milage | Rep |
|-------|-------|-------|---------|------|----------|-------------|------|
| 1973 | | | 63473P | | | 654796miles | Deep |

GST Number

Invoice To

826184400

| Item | Qty | Description | Rate | Amount | Tax |
|------------------|-----|--|------------------|------------------|--------|
| 5-676X Labora | 1 2 | 1810 U JOINT - 1st Diff Input U-Joint Labour- REℜ 1st Diff Input U-joint. | 145.00 100.00 | 145.00 200.00 | G G |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| Customer Bus. No. | Subtotal | \$345.00 |
|--|-------------------|--|
| The amount set out on this work order together with interest of 20% per month, 24th per annum ton puted from the date of this work order. That until payment in full for this work order is received, a lien under the Repair and Storage Lien Act of EC on vehicle described herein in respect of the material supplied, all disbursement and service for dered under this work order for the full amount charged therfore and furthe rithat the said lien shall continue in force at all times whether the vehicle is in my possession of the debtor. | Sales Tax Summary | GST @5.0% 17.25 Total Tax 17.25 |
| That we, or our balliff or agent may seize and resume possession at anytime if the amount of the indebtedness is not paid on due date and relize the amount of such indebtedness together with all losts and disbursements of the resuming possesion | Total | \$362.25 |
| POTE: Nut Retorque after 100 to 150 KM. Trank you for you business Assomer Signature: | Payment | -\$362.25 |
| | Balance Due | \$0.00 |

Ag Alignment and Truck Repairs Ltd.

12876 85 Ave Surrey. BC V3W OK8


ne # 604-628-9500 Fax # 604-628-745

.-mail: tirekingrepair@gmail.com



Invoice

| Date | Invoice # |
|------------|-----------|
| 2022-03-11 | 24086 |





| Unit # | Year# | Vin # | LICENCE | Make | P.O. No. | Milage | Rep |
|--------|-------|--------|---------|----------|----------|-------------|------|
| 1973 | 2016 | 981309 | 63473P | KENWORTH | | 637880miles | Deep |

GST Number

826184400

| Item | Qty | Description | Rate | Amount | Tax |
|---|--------------------------------------|---|--|--|---------------------|
| MVI 440161MfL NT3030ULS-KIT Part Part Part Part Part Part new tire levy on tire Stem&Valve Labour | 2 2 4 4 1 2 2 2 | MVI Ministry OF Transportation Fire Extinguisher Bendix Maxie Torque Rod Bushing U-Bolt Nuts and Bolts Windshield FS591 Steering Tire LEVY ON TIRE Stem& Valve Labour- Reℜ Fire Extinguisher. Reℜ Spring Bushings- 3rd axle B.S. Reℜ Torque Rod 3rd &2nd axle. Reℜ Maxie B/S. Fixed DEF 90 Bend loose. Fixed Coolant Leakage and Fixed Turbo clamp loose. | 200.00 45.00 85.00 102.55 56.55 40.00 5.50 375.00 550.00 14.00 10.00 | 200.00 45.00 170.00 205.10 113.10 160.00 22.00 375.00 1,100.00 28.00 20.00 900.00 | G G G G G G G G G G |

| Customer Bus. No. | | Subtotal | \$3.338.20 |
|---|--|-------------|---|
| the amount set out on this work order together we computed from the date of this work order. That until payment in full for this work order is read of BC on vehicle described herein in respect of the full amount of BC on the full amount of BC on the full amount of BC or the full of BC or the full amount of BC or the full of BC or | ceived, a lien under the Repair and Storage Lien Ac material supplied, all disbursement and service t charged therfore and furthe rthat the said lien sh | et | GST @ 5.0% 166.91 Total Tax 166.91 |
| continue in force at all times whether the venicular tractive, or our balliff or agent may seize and relightedness is not paid on due date and relize t | ume possession at anytime if the amount of the e amount of such indebtedness together with all | Total | \$3,505.11 |
| costs and disbursements of the resuming possesion MCTE: Nut Retorque after 100 to 150 KM. Thank you for you business | | Payment | -\$3.505.11 |
| Cuttomer Signature: | | Balance Due | \$0.00 |

g Alignment and Truck Repairs Ltd.

12876 85 Ave Surrey. BC V3W 0K8

ne #604-628-9500 Fax # 604-628-745

--mail: tirekingrepair@gmail.com



Invoice

| Date | Invoice # |
|------------|-----------|
| 2022-03-11 | 24087 |

| NOTE: Retorqu | ue U-Bolt | after 7 | days. |
|---------------|-----------|---------|-------|
|---------------|-----------|---------|-------|

| Unit # | Year# | Vin # | LICENCE | Make | P.O. No. | Milage | Rep |
|--------|-------|-------|---------|------|----------|--------|------|
| | | | 9216-9J | | | | Deep |

GST Number

Invoice To

826184400

| Item | Qty | Description | Rate | Amount | Tax |
|---|-----|---|---|--|------------|
| NIVI 572-7097 KE5503-71 3HK051 Drum 5-24088 Solt Part Part Part Self tire Tire Re J. 101040-4AP Jabour | | MVI Ministry OF Transportation Trailer Wheel Seal- 2nd axle LS. EXBSHD7100 ROCK HARD KIT Drum SHOCK ABSORBER 3.4 X 6 3.4 x 4 Nut Washer Used Tire Tire Repalce LED 1" X 4" MARKER LAMP Labour- Reℜ Wheel Seal- 2nd axle L S. Reℜ Brakes- 2nd axle L S. rE&rE sHOCK- 2ND AXLE b/s. Fixed Light | 180.00 70.00 70.00 10.00 140.00 70.00 4.00 5.50 2.50 150.00 30.00 7.50 100.00 | 180.00 70.00 70.00 10.00 140.00 8.00 11.00 10.00 150.00 30.00 7.50 500.00 | 6666666666 |

Customer Bus. No.

The undersigned hereby acknowledge: That the understand is indebted the above named company in the amount set out on this work order together with interest of 20% per month, 24th per annum computed from the date of this work order.

That untile payment in full for this work order is received, a lien under the Repair and Storage Lien Act of BC on vehicle described herein in respect of the material supplied, all disbursement and service rencered under this work order for the full amount charged therfore and furthe rthat the said lien shall continue in force at all times whether the vehicle is in my possession of the debtor.

That we, or our balliff or agent may seize and resume possession at anytime if the amount of the indebtedness is not paid on due date and relize the amount of such indebtedness together with all costs and disbursements of the resuming possesion

NOTE: Nut Retorque after 100 to 150 KM.

Thank you for you business

Customer Signature:

| Subtotal | \$1.326.50 |
|-------------------|--|
| Sales Tax Summary | GST @5.0% 66.33 Total Tax 66.33 |
| Total | \$1.392.83 |
| Payment | -\$1.392.83 |
| Balance Due | \$0.00 |

ent and Truck Repairs Ltd.

12876 85 Ave Surrey. BC V3W 0K8


Phone # 604-628-9500 Fax # 604-628-745

E-mail: tirekingrepair@gmail.com



Invoice

| Date | Invoice # |
|------------|-----------|
| 2022-02-28 | 23970 |



NOTE: Retorque U-Bolt after 7 days.

| Unit # | Year # | Vin # | LICENCE | Make | P.O. No. | Milage | Rep |
|--------|--------|--------|---------|----------|----------|----------------|------|
| 1973 | 2016 | 981309 | 63473P | KENWORTH | | 634942.7 MILES | Deep |

GST Number

826184400

| Item | Qty | Description | Rate | Amount | Tax |
|------------|-----|-------------|--------|--------|--------|
| Oil Change | 1 | Oil Change | 380.00 | 380.00 | S |
| Levy | 5 | Levy on Oil | 1.25 | 6.25 | S G |
| K3^-1029 | ı | FILTER | 55.00 | 55.00 | G |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | i | | |
| | | | | | |
| | | | | | |
| | | | | | } |
| | | | | | |
| | | | | | |
| | | | | | |
| } | | | | | |
| | | | | | |
| İ | | | | | |

Customer Bus. No.

The undersigned hereby acknowledge: That the understand is indebted the above named company in the amount set out on this work order together with interest of 20% per month, 24th per annum computed from the date of this work order.

That until payment in full for this work order is received, a lien under the Repair and Storage Lien Act of BC on vehicle described herein in respect of the material supplied, all disbursement and service rendered under this work order for the full amount charged therfore and furthe rthat the said lien shall continue in force at all times whether the vehicle is in my possession of the debtor.

That we, or our balliff or agent may seize and resume possession at anytime if the amount of the indebtedness is not paid on due date and relize the amount of such indebtedness together with all costs and disbursements of the resuming possesion

NOTE: Nut Retorque after 100 to 150 KM.

Thank you for you business

Customer Signature:_____

\$441.25

| Sales Tax Summary | GST@5.0% 22.06 PST (BC)@7.0% 27.04 |
|-------------------|---|
| | 27.04 Total Tax |

| Total | \$490.35 |
|-------|----------|
|-------|----------|

| Payment | -\$490.35 |
|---------|-----------|
|---------|-----------|

Balance Due

\$0.00