

Sept. 19, 2025 16443 HL @ Summit
A/C pump clutch snaked. Pump seized.
Install new Evaporator dryer.
Replace Evaporator valve, ~~Evaporator~~ evaporator
shock shaft.

May, 17, 2024 15 014 Hr @ Andrus.

250 Hr service + F/F. Fuel
bleed. only on day tank (only tank
used recently) injectors leaking.

Aug, 6, 2024 15, 222 Hr @ Shop
oil in fuel Replaced oil & injectors

Aug, 22, 2024 15 271 Hr @ Shop.
250 Hr Service no F/F

~~Aug 23~~, Oct, 16, 2024 15451 Hr @ S Fife
700 Hr service check swing ole

Dec 13, 2024 15624 hrs @ Fife
Installed new sprockets, added links to right side
tracks, 250 hr service w/ F/F

Feb, 20, 2025 15 963 Hr @ Carbon
250 Hr service NA F/F.

April 28, 2025 hrs @ ~~Andrus~~ Barnes
replaced starter, filled reversing fan hub w/ grease
grapple tong repair

July 10/2025 16304 Hr @ 27 km on the Fostals
250 service + F/F

TEO KALMO + EIE
Q1/A 10/5072 1730H HU @ 51Rw 02 HPC 10240

Design point 10240
TEO KALMO + EIE

TEO KALMO + EIE
TEO KALMO + EIE

TEO KALMO + EIE
TEO KALMO + EIE

TEO KALMO + EIE
TEO KALMO + EIE

TEO KALMO + EIE
TEO KALMO + EIE

TEO KALMO + EIE
TEO KALMO + EIE

TEO KALMO + EIE
TEO KALMO + EIE

Oct, 27, 2023 13 992 HR @ Shop

Replace thumb open port relief - set to
4100 PSI cold oil. Thumb now holds

Replace missing track pad bolts + Hydrate
tracks.

OCT 30, 23 14007 HRS @ EDDY

REPLACE BOOT FROM INTERCOOLER TO
INTAKE

Dec 6, 23 14084 HRS @ whatchan.

250 HR Service no F/F

Replaced 3 tongue grapple cylinder.

Jan 22, 2024 14328 HRS @ watshan. (4430 HR
Hrd oil)

250 HR Service no F/F, 1000 HR Service

no Swing, changed fan Belt, Replace

Broken section on ether line. Tighten

lower Rad hose topped up coolant 8L

Mar, 27, 2024 14,690 HR @ Andres.

250 HR service NO F/F. (computer said it was done)

May, 1, 2024

HR @ Andres.

Gouge + weld cracks bottom of stick

corner end 5" a side.

total cost = 2000 + 1000 = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

total cost = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

total cost = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

total cost = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

total cost = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

total cost = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

INTAKE

total cost = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

total cost = 3000
cost of material = 2000
cost of labor = 1000
total cost = 3000

Apr, 4, 2023 13,320 HR @ Hunt
250 HR service + F/F. Grease +
weld cracks in corners of long palms
both sides. ⊗ Lt side final 2L overflow.

JUN 6, 23 13,578 HRS @ EAST BARNES
250 HR SERVICE NO FF CHECK FINALS OK

June 22/23 HRS @ EAST BARNES
Replace special cross over H40 hose two pump flow.
Fenny Bends CAT MADE HOSE on liner group front
Value Bank LT side End #16 RT side #12 core 6/162 P/rom
orings PN 168-9762 HOSE

July, 31, 2023 13,733 HR @ E. Barnes.
Replace front windshield.

Aug, 21, 2023 13,833 HR @ E Barnes
250 HR service + F/F. Swivell leaky has
slowed down, cleaned grease + oil from car
body will monitor.

Sept, 13, 2023 13,913 hrs @ Shop.
Remove + re-seal swivell. Tap Land
on center piece of swivell worn from
O-ring/debris movement. Minor enough re-use
hardware to replace w/ 3500% +.

- replaced both sprockets w/ new sprockets, reused hardware
- straightened + aligned bent hydraulic compartment + cooler/rad compartment doors + straightened bent hydraulic hardlines to barrel end of both boom cylinders
- greased (after cleaning) rotor gear compartment w/ CAT utility grease (1 case)

Oct, 5, 2023 13,945 HR @ Wodel

Operator ran rock up on track punched
panel below H40 tank elbow from tank
to hose cracked. (GV welder tipped seem)
to be holding (Aluminum) Replace H40 oil 10 pails AW32

AUG, 22, 2022 12,239 HR @ E BARNES
Replace both remote eng oil filter
lines. Blow out coolers.

SEPT 2, 22 12282 HRS @ E BARNES
250 HR SERVICE W F F

Sept, 8, 2022 12,282 HR @ E Barnes.
Re-install repaired + Lim based H Bar.
New bushings on bucket cyl ears re-use
rod end cyl bushing.

Oct, 24, 2022 12,526 HR @ Limekiln
250 HR service NO FIF. Check
swing OK. both finals over full, drained
approx 2L from Lt + 3L from Rt.

Nov, 29, 2022 12,746 HR @ Limekiln
Grage + weld crack in boom Lt side
between boom foot + rod end pin 1/2
way, cracked middle of fish plate all the
way through

Dec, 6, 2022 12,761 HR @ Limekiln
250 HR service + FIF check swing + finals

Feb 3/23 13056 HRS @ Shelterbay
Service 250 HRS NO FIF Done BY FINNIAH BOB

FEB 8/23 13077 HRS @ SHELTER BAY.
WELD UP CRACKED GRAPPLE LUGGING. LT SIDE WEDGE
MOUNT

FEB 16/23 13090 HRS @ HUNT
CHANGE LT SIDE TRACK IDLER + TRACK ADJUSTER.

MAR 24/23 13265 HRS @ HUNT (3367 on HUNT oil SES table)
1000 HR SERVICE W SWING, FINALS RT SIDE 4 LITERS OVER
2 CASE DRAINS, RETURN PILOT, INNER AIR, 2 WATER SEPARATORS
GREASE PIT 2 INCHES DEEP

STRENGTHENING THE FOUNDATION OF THE
COUNTRY THROUGH THE DEVELOPMENT OF THE
RURAL SECTOR AND THE PROMOTION OF
AGRICULTURE AND LIVELIHOODS

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

WORKING
TOWARDS THE DEVELOPMENT OF THE RURAL
SECTOR THROUGH THE PROMOTION OF
AGRICULTURE AND LIVELIHOODS

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

CONCENTRATION ON THE RURAL SIDE OF THE
COUNTRY THROUGH THE DEVELOPMENT OF
RURAL INDUSTRIES

FEB 23/22 11473 @ KILLEEN

250 HR SERVICE W/FF. REMOVE BROKEN BOLT FROM
VALVE BANK

Apr. 22, 2022 11,696 HR @ Shop

Replace #1 initiator started to ground internally.
Also, change valve cover harness wires rubbed/
brittle in spot.

Swing Drive DRY. No oil in it. Gears worn & took out
Ancian seals & metal through
Bearing - GOT Rebuilt & Resealed from

Finnick USED PARTS in Regina. Jim INSTALLED, Clean grease
TUB & INSTALL new Grease. CAT Blue/Green Petrol Bearing Grease

RT Side Final Duo-core leaked sent to Finnick Prince George
Finnick Duo Core Pump use JB weld new main bearing new BRAKE DISC KIT & Seal.
See Invoice # invoice # 0062254879.

MAY 11/22 11720 HRS @ Bussan.

250 HR SERVICE NOFF JIM DID.

JUNE 23/22 11966 HRS @ CARIBOO

250 HR SERVICE W/FF. REPLACE DOWEL IN SWING-DRIVE
TORQUE UP BOLTS. CAME LOOSE??

JULY 5/22 12034 HRS @ CARIBOO

Replace HYD hose cross over special PN 168-9761 with 2607912
control valve stick failure on one clamp end.

1000 HR service change final oil. Replace
all hydraulic filters 2x Water separator inner air.
2136 HRS on HYD oil

JULY 27/22 12200 HRS @ WODEN

250 HR SERVICE NOFF

AUG 18, 22 122²⁸ HRS @ BARNES

CHANGE GRAPPLE CLOSE PORT RELIEF. SET TO
4000 PSI. CLOSE WAS NOT HOLDING PN 250 2508

NOOR BZIF STORE MUB WOL HODU INC W 320 8738
CHANGE CHANGE STORE BOST BELIEF ZEN 10
VINO IS 55 1553 H62 @ BUBWELZ

520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN

520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN
520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN

LOKORNE 6 BELIZ 2 H6 1800 :
520 H6 ZEBORCE WOLE BELIEVE DOMEST 2 H6 1800
520 H6 ZEBORCE WOLE BELIEVE DOMEST 2 H6 1800

520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN
520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN

[REDACTED]

520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN
520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN

520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN
520 H6 ZEBORCE WOLE
DATA 5 155 15500 H62 @ MOVEN

Aug 18 2021 @ Shop. 10550 HR
ReBuild Grapple all tips + tines
Re sealed Swivel, Rebuild Both cylinders @ Nagy's.

Build up Grapple stop. Repaired Swivel stops brake twisted all hoses
Aug 31, 2021 10598 HR @ BR 1500 Renata
Replace thumb open port relief + set
to 4050 PSI C op. temp.

SEPT 10, 21 10656 HRS @ RENATA
250 HRS SERVICE W FF

OCT 19/21 10852 HRS @ Renata
Finnish Bob Replaced all 6 injectors leaking ~~into~~ oil
into Fuel SYSTEM. Replaced injector cups & seals. Resealed
Hwei galley-plug o-rings. DID a Valve Set as well
changed BOTH Fuel Filters Final & W/S.

Nov 3, 2021 10,934 HR @ Worthington
250 HR service + FIT. Repair ether in.
line + test OK. Replace both water separators
still has oil in fuel oil still in tank?

Nov 9/21 10956. HRS @ SEP
James from Finninc-DID 1000 HR service no swing.
Change Final at Pressure SW, Return HYD, Pilot, 2 Cade. Fuel filter
Done to HRS Also for previous repair [REDACTED]
Don't know what BSE Darryl did never saw him again?
LAST SOS with silica related to injectors & cups Replaced Oct 19/21

NOV 23/21 HRS @ Killeen
COOY from Finninc called overheating, its been low on
Coolant & look @ TOP. Darryl obviously not sure what low
TOP up. Sensor ok. Thermostat ok. coolant was only -20°C ???

Jan 6, 2022 11,206 HRS @ Killeen
250 HR service No FIR.

Jan 28, 2022 HRS @ Killeen
Remove + repair mounting plates on ball board.
could not remove 2 bolts welded RT side
mount.

1979 - 1980
1981 - 1982
1983 - 1984

1985 - 1986
1987 - 1988

1989 - 1990
1991 - 1992

1993 - 1994
1995 - 1996
1997 - 1998
1999 - 2000

2001 - 2002
2003 - 2004
2005 - 2006

2007 - 2008
2009 - 2010
2011 - 2012

2013 - 2014
2015 - 2016

2017 - 2018
2019 - 2020
2021 - 2022
2023 - 2024

FEB 22/21 9607 HRS @ WEST WHATSHAN
250 HR SERVICE WFF. WELD UP BROKEN ADAPTER ON
GRAPPLE.

Mar, 10, 2021 9705 HR @ W Whatshan
Weld in missing grapple tang stop. build up
3 others.

APR 8/21 9898 HRS @ BR4000 WEST WHATSHAN
250 HR SERVICE NO FF. 1000 HR SERVICE. FINALS, SWING
INNER AIR/WATER SEPARATORS, 2 CASE DRAIN, PILOT, RETURN
FILTERS. CLEAN TANK FILTER. RS FINAL 2 LITERS OVER
FULL. CHANGE HYD OIL. CHANGE ANTIFREEZE. 5000 HRS.
on BOTH. oil & coolant.

MAY 18/21 10156 HRS @ WEST WHATSHAN.
FINNING ROB. Resealed swivel joint on machine leaking
into ROTAX gear & bearing. cleaned. ROTAX gear AND
ADD some Grease. Dang! DIDNT pick up grease I set off for
him & need new outside DUST Seal. *

MAY 20/21 10154 HRS @ WEST WHATSHAN
Service 250 HRS INCLUDE FF.

May, 28, 2021 10,173 HR @ Bowman 19k.
Replace water / debris seal around top of swivel.

JUN 29, 21 10333 HRS @ BIRCH
CHANGE THERMOSTAT + GASKET. DO BYPASS TEST
ON GRAPPLE CYLINDERS GOOD. DO BYPASS TEST
ON GRAPPLE SWIVEL IT IS BYPASSING.

Jul, 26, 2021 10403 HR @ 2K Worthington
250 HR service NO FF. Bypass test
cyls on grapple 1 leaking. Swivel also
leaking. Going to sweep out & bring to shop
says my waiting...

... ..
... ..
... ..
... ..
... ..

ON 664666E 27 DEF II IS B6B221MG
ON 664666E 67IMDEB2 GOOD DO B1B221E2L
CHANGE THE WORDS IN + C A K E L DO B6B221E2L
27055' S. FD 323 ABC @ B1BCH

... ..
... ..

... ..
... ..

... ..
... ..
... ..
... ..

... ..
... ..
... ..
... ..
... ..

... ..
... ..

664666E
220 ABC 2E60KE 01E - 01E D 06 B60KED 4006LEB CH
EEN 55151 1902 HK2 @ 17E2L 01402144

Mar, 16, 2020 7895 HR @ Cowtral
Replace remote oil filter lines

* APRIL 17, 2020 8022 HRS @ SHOP *All Berco From Inland.*
~~INSTALL NEW UNDERCARRIAGE, ALL NEW EJECT. IDLERS (FROM BURNT MACHINE~~
~~OR EX-113?) 330C) IDLERS were from EX 113. UNDERCARRIAGE IS Berco / TIBERCAT~~
WELD CRACK ON CAB SIDE OF BOOM, WELDED FISH PLATES ON BOTH *PLATES*
SIDES OF BOOM

MAY 6/20 8043 HRS @ WHATSAN SETTLEMENT RD
SWING DRIVE MILKY, CHANGE OIL. PRODUCE ~~30~~

July, 13, 2020 8390 HRS @ Spectrum
250 HR service No F/F, operator following
computer set @ 500 interval fill out
sticker will change setting @ later date.

Aug, 5, 2020 8507 HR @ Spectrum
Install Rebit RH Boom Cyl, Blow out
Eng + Hyd. coolers.

Sept, 7, 2020 8656 HR @ Spectrum
250 HR service No F/F. Repair HYD COMPARTMENT
DOOR CAME OPEN on Danny & He SEALED IT.

SEPT 14, 2020 @ SHOP
REBUILD TINES ON GRAPPLE - 4 NEW CORNER
TIPS, EXTEND 3 CENTER TINES. REBUILD SWIVEL
Rebuild swivel joint

OCT 13/20 8861 HRS @ Spectrum
Kenny Brake GRAPPLE CYL Brake not off and
Pinning BOB Reversed & Set to *WABCO* for Repair

NOV 20/20 9085 HRS @ COWTRAL
250 HR SERVICE W FF

Jan, 14, 2021 9368 HR @ Bodman
250 HR service No F/F.

520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000
520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000
520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000
520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000
520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000
520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000
520 HK 20000 HK 10000
10000 HK 20000 HK 10000

520 HK 20000 HK 10000
10000 HK 20000 HK 10000
520 HK 20000 HK 10000
10000 HK 20000 HK 10000

Apr, 18, 2019 6084 HRS @ Hardman
250 HR service with FIF

June, 6, 2019 6336 HRS @ Andres Rd
250 HR service NO FIF 1000 HR service
Air filters No swing check level OK.

JUNE 21, 2019 UNKNOWN HRS @ SHOP
(GRAPPLE)

→ SERIAL # E63513 MODEL # HX50

GRAPPLE WORK: - DON HILL LINE BORED MAIN PIN BOSSES, W NEW
IMAC PINS⁽²⁾, LINE BORED 9 - CYL HOLES, W NEW IMAC PINS (4)
- BOTH CYL REBUIL (NAGGYS)
- WELDED CRACKS & INSTALL Z-TIPS + REPAIR COVERS

24-July-19 6596 HRS @ THOR.
- 250 HR service w/fuel filter.

Sept, 30, 2019 6942 HRS @ Killeen
250 HR service No F/F

Nov, 20, 2019 7242 HRS @ Andre's
250 HR service with FIF.

Nov, 29, 2019 7283 HRS @ Andres
Gauge + weld boom crack Lt side boom
foot + rod end cyl. pin boss.

JAN 22, 2020 7550 HRS @ RENATA
250 SERVICE NOFF, CHANGE RT SIDE TRACK ADJUSTER

Feb, 21, 2020 7679 HR @ Cowtrail
straighten + weld broken line 3 ton side.

Mar, 12, 2020 7878 HRS @ Cowtrail
250 HR with F/F, 1000 HR service
all filts + swing (swing was milky no entry
paint for water notice will monitor
* Alred Coolant NITRITE INHIBITOR *

SEPT 13/18 4861 HRS @ Mica

Service 250 HRS. No FF's Done BY WDM
Replaced coolant temp sensor rotational sensor
Over heating
Water Separator Fuel of water won't run ??
Repair BOTH X2

Oct, 26, 2018 5087 HRS @ 27 KM Trout Lake

Replaced RT SIDE Boom. CYL with GOOD USED
OFF A LOG-LOADER FROM OVERSIZED EQUIPMENT.
SAME PART # PIPELINE IS DIFFERENT.
Replaced BOOM CYL ROD END Grease Line

6-NOV-18 5156 HRS. @ Trout.

- 250 HR Service w/ ~~Fuel~~ Fuel.
- Replace RH Boom Grease line.

Nov, 15, 2018 5220 HRS @ Trout
Ice log every 4th pad.

Nov, 30, 2018 5282 HRS @ Trout

1000 HR service every hyd filter + inner oil,
2x w/s, change final oil check swing oil.

Dec, 5, 2018 5310 HRS @ Trout

Weld tong face + grapple tip back on (3 tong)

Jan, 7, 2019 5448 HRS @ Trout

250 HR service No FIF

13-Feb-19 5702 HRS @ Trout Lake GOOD

- 250 HR Service No FF

14-MARCH-19

JAN, 31, 2018 3550 HRS @ Hill Cr.
250 HR service ^{with} F/F
Replace 3 ton GRAPPLE CYC

Feb, 15, 2018 3638 HRS @ Hill Cr.
Replace serpentine belt in hopes belt squeal when fan reverses goes away, belt taken off was smaller in dia. by 1/2", tensioner was marked out.

MAR 5/18 3716 HRS @ HILL CR
CHANGE GRAPPLE CLOSE RELIEF VALVE + ADJUST PRESSURE TO 4000. GRAPPLE OPEN CHECKED 2800 PSI. PV. 250-2508 Live Relief

MAR 20/18 3802 HRS @ HILL CR
250 HR SERVICE NO FF

10-may-18 4083 HRS @ EAST BARNES
- 250 HR SERVICE W/F/F

MAY 31/18 4200 HRS @ SOUTH FIVE
1000 HR SERVICE. INNER AIR 2 FUEL SEPARATORS CASE DRAIN. PILOT FILTER. BOTH FINALS PRODURO 50. SWING MOTOR ~~30~~ PRODURO 30.

21-~~May~~ June-2018 4325 HRS @ MariokA.
- 250 HR SERVICE NO FF.
- Replace 2 pad bolts & check pads.
- gouge and weld all cracks. weld in new tips x 2
* Fish plate and reinforce

AUG 7/18 4567 HRS @ MICA
250 HR SERVICE INCLUDE FF Done BY WAYNE.
INSTALL new 2 WAY STOP Valves either SIDE OF SPICH TO THUMB STIC NOT HOLDING.

AUG 21/18 4600 HRS @ MICA.
BOB FROM FINNINE check THUMB CYC BYPASS. ITS BYPASSING

MAY 1/17 2010 HRS @ Summit

Service 250 HRS no FF Swing & Finals OK.

Cut ice w/OS OFF check Rollers & Service

MAY 12/17 2110 HRS @ WINLAW

1000 SERVICE CHANGE & SWING PRODUO 30, FINALS
PRODUO 50, WATER SEPARATORS, INNER AIR FILTER, CASE DRAIN,
GRAPPLE DRAIN, PILOT FILTER, MAIN HYD FILTER.

16-June-17 2268 HRS @ Koch.

-250 HR Service. w/fuel filter.

- Remove Recoil assy Inspect for damage Reinstall
split track Re Install on unit.

25-July-17 2509 HRS @ Koch.

-250 HR Service ~~w/ fuel filter~~ w/ fuel filter

20-Sept-17 2773 HRS @ Koch.

250 HR Service NO FF.

22-Sept-17 2798 HRS @ Shop.

- Remove grapple Swivel and Reseal
- Weld on grapple tip and Reinforce.

OCT 31/17 3017 HRS @ BIGGER

Service 250 HRS. INCLUDE FF. Reset computer

Service 1000 HRS. 1-RETURN, Pilot, 2-case, inner AF.

AND CHANGE Final oil SOW PRODUO. 2-TANK FILTERS.

Swing OK. Replace Air cleaner Pre cleaner ASSEMBLY.

NOV 9/17 3083 HRS @ BIGGER

WELD ON CORKS

DEC 8/17 3300 HRS @ BIGGER

250 SERVICE NO FF

324 216 100 100
DLE 211 331 HK2 @ BICCEB

.. MLEO OV 2062
WVW 211 2023 102 @ BICCEB

20110 OK 21100 100 20000 20 1000 20000
20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000

20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000

20110 20000 20000 20000 20000 20000

20110 20000 20000 20000 20000 20000

20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000

20110 20000 20000 20000 20000 20000

20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000

20110 20000 20000 20000 20000 20000
20110 20000 20000 20000 20000 20000

OCT 3/16 626 HRS @ SHOP

- EXTEND THUMB ENDS TO FIT LARGER BUCKET
- REPLACE BROKEN CAB LIGHT
- REWELD NUT IN ON RS TRAVEL MOTOR COVER

25-OCT-16 760 HRS @ Slewiskin.

- 250 HR Service w/fuel filter
- check and adjust swing pressures to 4800psi.

NOV, 30, 2016 1010 HRS @ Slewiskin

- 250 HR service NO F/F
- 1000 HR service, Change both finals (Proforma 50w)
check swing OK, Change inner A/F, pilot filt, Case drain & Hyd. return, Install ether cannister

JAN 12/17 1265 HRS @ SLEWISKIN

- 250 HR SERVICE W/F/F
- CHANGE HYDRAULIC DIRECTION VALVE ON L/S OF STICK

JAN 23/17. 1300. HRS @ SHOP.

INSTALL OLD HX50 GRAPPLE FROM EX114 ONTO EX-1257
PLUMB HYD Valve. on machine Pull Valve out of GRAPPLE
Change from plumbing for GRAPPLE Build SPARE dump hoses.

Feb 14/17 1475 HRS @ Summit

FAB & weld RT SIDE HYD Block BACK ON. RETATE GRAPPLE
Hoses. Remove plumbing. INSTALL LOCK PLATES. MISSING TWO.

Feb 17/17 1508 HRS @ Summit.

- 250 HR Service NO FF.

March 21/17 1760 HRS @ Summit

250 HR service w/FF
Cylinder replace on grapple for
long side.

JUNE 20/16 6 HRS @ SHOP

BOB FROM FINNING INSTALLED GRAPPLE PLUMBING
VALVE on machine.

REMOVE HANDLES, ROTARIES, WIRES & ARMS. INSTALL CAB DOOR
HANDLE & BOOM LIGHT BOXES & LED LIGHTS.

JULY 4/16

HRS @ HADLOW

BOB INSTALLED GRAPPLE & SET UP. EVERYTHING WORKS GOOD
CHECK ALL OK, CHECKED AIR FLOW GOOD

GRIND BUCKET EAR LUGGING TO FIT 1/4" TOPPER @ THUMB.
WELD IN ~~GR~~ THUMB TIP EXTENSION KEVIN 4"

JULY 27/16

250 HRS @ HADLOW

250 HR SERVICE NO FF

AUG 3/16 290 HRS @ HADLOW.

BOOM DROPS. SLIGHT JOLT/STICK MOVEMENT RIOT PSF

PUMP STROKING PUMP #1 PRESSURE 12662 KPA

PUMP #2 PRESSURE 4000 KPA

POWERSHIFT PRESSURE 3550 KPA.

THEN BOOM SUDDENLY DROPS FINNING BOB B HADLOW HAVE.

VIDEOS, NEED TO CHECK GRAPPLE ROTATE STICKY, BOOM NOT

POSSIBLE DRIFT/LEAK NO POWER. STOP VALVE NOT HOLDING

THUMB ON LTSIDE PN 320165774.

AUG 11/16. 335 HRS @ HADLOW.

ROB HADFORD FROM FINNING DIAGNOSE BOOM DROPS.

THEY INSTALLED BOOM DRIFT VALVE ASSEMBLY. NOT

THE PROBLEM. INSTALL NEW VALVES ON THUMB STOP WORK

GOOD NOW. PN 320005870 2 WAY STOP VALVE POSITIVE

NO LEAKAGE.

SEPT 8/16 490 HRS @ HADLOW

250 SERVICE WITH FF

77 H110 E 0101 202

PROGRAM @ 211 011 112 932

no record

SEARCHED BY: [unclear] DATE: [unclear]
INDEXED BY: [unclear] DATE: [unclear]
SERIALIZED BY: [unclear] DATE: [unclear]

112 932 211 011 112 932

SEARCHED BY: [unclear] DATE: [unclear]

INDEXED BY: [unclear] DATE: [unclear]
SERIALIZED BY: [unclear] DATE: [unclear]

112 932 211 011 112 932

SEARCHED BY: [unclear] DATE: [unclear]

INDEXED BY: [unclear] DATE: [unclear]

SERIALIZED BY: [unclear] DATE: [unclear]

112 932 211 011 112 932

77 H110 E 0101 202

PROGRAM @ 211 011 112 932

SEARCHED BY: [unclear] DATE: [unclear]
INDEXED BY: [unclear] DATE: [unclear]
SERIALIZED BY: [unclear] DATE: [unclear]

112 932 211 011 112 932

SEARCHED BY: [unclear] DATE: [unclear]

INDEXED BY: [unclear] DATE: [unclear]
SERIALIZED BY: [unclear] DATE: [unclear]

112 932 211 011 112 932