

2F15-2



CPS MECHANICAL Inc.

P.O. Box 135
620 1st Avenue East
Brooks AB
T1R 1B2

(P) 403.362.0211
(F) 403.362.0219
GST#: 817259757RT0001

Invoice # SC20447

Hollow River Transport

2019 Peterbilt 389 Base

VIN: 1XPXDP9XXKD261318
Engine: 612.9L, 787cid, DIESEL
Trans:

License #
ODO In: 1138617
Color:
Mfg. Date:

Inv Date: 2/24/2024 @ 10:48am

Service Writer: Mikayla Brown
Status: Posted

Driver:
PO # 23691

Unit # 155

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Customer states that: water pump nr- check and advise on repair						2,379.71
Labor Service - R+R waterpump, refill coolant CS, GK			1.29		160.00	206.40
Part RCC16324	50/50 Red (Sold/4L Jug)(no Env)			1.00	12.79	12.79
New 2267065PE	coolant pump/speed sensors			1.00	1,916.20	1,916.20
New 2130588	O-Ring			1.00	16.83	16.83
Sublet FREIGHT	FREIGHT - 32515640			1.00	66.94	66.94
Labor Service - check for faults humidity sensor and bvp sensor no power , diagnose			1.00		160.00	160.00
fuse blown in pdm replace fuse ad clear codes. ok CS, GK						
New 731.015	Ato Fuse 15 Amp			1.00	0.55	0.55
Customer states that: Manual Regen Needed						320.00
Labor Service - perform regen, preformed def and egr derate disable run reenclear			2.00		160.00	320.00
codes release truck to customer CS, GK						

Add On Charges Breakdown
Enviro Fee

0.35

pd me 4762
Bn

Warranty

EFFECTIVE OCT 1, 2018

All VG turbochargers and electronically operated actuators must be diagnosed on-engine by authorized or certified Cummins Service Provider to be considered for warranty. Cummins will no longer offer the over the counter warranty exchange

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. CPS Mechanical employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. A Garage Keeper's Lien will be filed on said vehicle to secure the amount of repairs thereto. CPS Mechanical will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event that default is made in any payment due. Vehicles returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read & understand the above & acknowledge receipt of an estimate

Credit Cards are accepted at point of sale only. Credit card usage after point of sale will be subject to a 2%

Posted 2/24/24 10:21AM

A/R Charge 2,890.36

Invoice Summary

Parts	1,946.37
Labor	686.40
Sublet	66.94
Shop Supplies	52.66
Add On Charges	0.35

Overdue accounts are charged 2% interest with a minimum finance charge of \$1.00

X

Vehicles left after repair is completed may be subject to a storage fee. If wheels are removed for any reason, it is the customer's responsibility to have them re-torqued after 100kms

X

Terms: CASH unless prior arrangements have been made. Service charges: 2% per month or 24% per annum on overdue accounts. Customer acknowledges receipt of merchandise and services

Sub Total	2,752.72
Sales Tax (AB)	137.64