



Agri-Trans Services Inc.
PO Box 188
Armstrong BC V0E 1B0
Work: 250-546-8898 Fax: 250-546-8894

CL20-6

Equipment: 1004

Work Order #: 81057

Date: 02/13/24

Completed Date: 02/13/24

Year: 2016

Make: Peterbilt

Model: 389

Odometer: 932,246

Serial Number: 1XPXD49X7GD287431

Entered By: cassios

Taxes: None

Engine Type: 79824920 ISX

Labor

Description	Amount
PULL DRIVESHAFT AND REPLACE #1 DIFFERENTIAL INPUT SEAL	289.40
REINSTALL DRIVESHAFT FOR PRELOAD	347.28
REPLACE #1 UJOINT AND REFILL DIFFERENTIAL	115.76
REMOVE AND REPLACE #1 DIFFERENTIAL	694.56
REPLACE #2 AXLE BUSHING/PIN SPRING LEFT SIDE	57.88

Parts

Part #	Part Description	Quantity/Hours	Price/Rate	Taxes	Amount
59703	COPPER SILICONE	1.00	12.33	None	12.33
SPL250-3X	U JOINT	1.00	248.68	None	248.68
250-70-18X	SPICER LIFE U JOINT STRAP KIT	1.00	32.15	None	32.15
1205E473	PLUG WITH MAGNET	1.00	.00	None	.00
75W90SYN	OIL GEAR SYNTHETIC	3.00	13.75	None	41.25
MW1403BK	HUBCAP DRIVE POINTED	1.00	9.47	None	9.47
512896ETN	KIT CARRIER	1.00	176.89	None	176.89
DD46170P373CGL	CARRIER-REMAN, DD461,3.73	1.00	5,487.49	None	5,487.49
HWC09180	BOLT SUSPENSION BUSHING	2.00	32.43	None	64.86
29216-01	M20 LOCK NUT	2.00	7.07	None	14.14
6600-004	LAMP ASSEMBLY OUTER	1.00	60.07	None	60.07

Total Labor	1,504.88
Total Parts	6,147.33
Total Returns	.00
Total Sublet	.00
Shop Supplies	225.73
Invoice Total	7,877.94



Agri-Trans Services Inc.
PO Box 188
Armstrong BC V0E 1B0
Work: 250-546-8898 Fax: 250-546-8894

Equipment: 1004

Work Order #: 79327
Date: 10/23/23

Completed Date: 10/23/23

Year: 2016
Make: Peterbilt
Model: 389
Odometer: 897,675

Serial Number: 1XPXD49X7GD287431
Entered By: cassios
Taxes: None

Engine Type: 79824920 ISX

Labor

Description	Amount
PERFORM CVI TRUCK INSPECTION DECAL #FW04638	276.90
REPLACE AIRBAG LEFT REAR	110.76
REPLACE AIR DRYER ASSEMBLY	168.14
REMOVE AND REPLACE TURBO	886.08

Parts

Part #	Part Description	Quantity/Hours	Price/Rate	Taxes	Amount
101113	GLAD HAND SEAL	4.00	.65	None	2.60
LED0700CP	LED 3/4 CLEAR WHITE LIGHT	1.00	6.57	None	6.57
AS70360	SPRING AIR BAG	1.00	55.35	None	55.35
PI220808S	1/4X1/4 90 ELBOW MXF	1.00	6.14	None	6.14
3900630CUM	SCREW HEX FLANGE	1.00	2.95	None	2.95
298900	HOLDER - MEGA FUSE	1.00	25.21	None	25.21
MEG150	MEGA FUSE	2.00	12.14	None	24.28
5010696BXW	DRYER ADIS REMAN	1.00	601.87	None	601.87
11014	MOOVIT LUBE	1.00	13.87	None	13.87
M705C	BRAKE CLEAN	1.00	5.30	None	5.30
DECAL	DECAL	1.00	11.00	None	11.00
FLTW18	WIPER WINTER	2.00	13.06	None	26.12
ELC4	50/50 ANTIFREEZE	4.00	12.28	None	49.12
5458260RXCUM	TURBO KIT	1.00	9,769.44	None	9,769.44
5264570CUM	GASKET, TURBO DRAIN ISX CM2250	1.00	5.19	None	5.19
4298975CUM	NUT TURBO - CM2250	4.00	13.27	None	53.08
4298242CUM	STUD TURBO - CM2250	4.00	23.86	None	95.44

Total Labor	1,439.88
Total Parts	10,753.53
Total Returns	.00
Total Sublet	.00
Shop Supplies	259.18
Invoice Total	12,452.59



Agri-Trans Services Inc.
PO Box 188
Armstrong BC V0E 1B0
Work: 250-546-8898 Fax: 250-546-8894

Equipment: 1004

Work Order #: 76160
Date: 04/18/23

Completed Date: 04/18/23

Year: 2016
Make: Peterbilt
Model: 389
Odometer: 880,747

Serial Number: 1XPXD49X7GD287431
Entered By: cassios
Taxes: None

Engine Type: 79824920 ISX

Labor

Description	Amount
DIAGNOSE KNOCKING IN GEAR AND CONFIRM COUNTER SHAFT TOOTH DAMAGED	94.76
REMOVE AND REPLACE #3 AXLE SPRING BRAKEPOT LEFT SIDE	94.76
REMOVE TRANSMISSION	568.56
REMOVE AND REPLACE CLUTCH	1,137.12
REMOVE AND REPLACE TRANSMISSION	758.08

Parts

Part #	Part Description	Quantity/Hours	Price/Rate	Taxes	Amount
NT3030ELS80	BRAKE POT COMBO LONG STROKE	1.00	90.28	None	90.28
C1001	CLEVIS 5/8X1/2 PIN	1.00	2.44	None	2.44
PC1469-5/32A	FITTING PUSH TO CONNECT 90D MPIPE	3.00	7.88	None	23.64
06-01093	SHAFT CLUTCH LONG	1.00	123.07	None	123.07
106C1498	CLUTCH SHAFT SHORT	1.00	22.94	None	22.94
CF105C137	TRANSMISSION FORK	1.00	36.04	None	36.04
K4148	KIT SPEED SENSOR	1.00	50.84	None	50.84
CB313SP	BRAKE CLUTCH	1.00	49.70	None	49.70
6306	BEARING	1.00	19.72	None	19.72
1468-6A	3/8 X 1/8 CONNECTOR BR DOT A/B-M	1.00	2.50	None	2.50
1468-4A	1/4 X 1/8 STRAIGHT	1.00	1.64	None	1.64
21-635P	SWITCH BACK UP	1.00	13.44	None	13.44
2866337CUM	GASKET CIRCULAR 5"	2.00	20.35	None	40.70
RESURFACE	RESURFACED FLYWHEEL	1.00	119.24	None	119.24
308925-25	CLUTCH ASSY	1.00	1,358.49	None	1,358.49
K3762	CLUTCH INSTALL KIT	1.00	459.87	None	459.87
EC50PLS	EXHAUST CLAMP	2.00	13.81	None	27.62
RTL020918B-PCAN	TRANSMISSION REMAN	1.00	5,930.95	None	5,930.95

Total Labor	2,653.28
Total Parts	8,373.12
Total Returns	.00
Total Sublet	.00
Shop Supplies	265.33
Invoice Total	11,291.73



Peterbilt Pacific Inc.

PETERBILT PACIFIC INC.
1955 W. Trans Canada Hwy.
Kamloops BC, V1S 1J6
Phone: (250) 374-3181

Customer: AGRI-TRANS SERVICES INC.

Account #
Phone #
Invoice Date: 07-08-19

Repair Order No:
KA124208
CUSTOMER INVOICE

Tax ID: PST 1004-9671

Tax ID Date: 12-22-16

Page 1 of 3

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2016	Peterbilt / 389	1XPXD49X7GD287431	40788P	638279	1004	
Open Date / Time		Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio
06-25-19 / 10:23AM		08-04-15	4071	10921.0		3.73
Engine Model / Serial #		Transmission Model/Serial #		Rear Axle Model/Serial #		
ISX15 / 79824920		FULLER RTLO20918B 18 SPEED / S1135702		D40-170 HN04729122 PACCAR HN04729123		
CPL ARR		Complete	P.O. Number		Authorization	Service Writer
		07-02-19	014512		734689	GP*GP
Memo	PAT @ ATS (778) 442-4011					

- 1 CHECK COMPLAINT OF BLOWN HEAD GASKET.
CHECKED FOR COMBUSTION GAS IN COOLANT - CONFIRMED. INSPECTED EGR COOLER - GOOD. REMOVED HEAD AND FOUND #5 BLOWN AT THE FRONT SECTION ON FIRE RING. MEASURED LINER PROTRUSION - 0.006 AT RH SIDE OF #5 LINER. INSPECTED BREAK AWAY TORQUE ON HEAD BOLTS AS PER CUMMINS. REMOVED LINERS AND PISTONS - FOUND COUNTER BORES ERRODED. CUT ALL 6 COUNTER BORES TO .017". REUSED PISTONS. REASSEMBLED WITH NEW RINGS, LINERS, ROD BEARINGS. REUSED HEAD. ALL LINER PROTRUSIONS ARE 0.0135 TO 0.014. ROAD TESTED - GOOD. REGENNED - GOOD.

TOTAL LABOR	6,705.00
TOTAL PARTS	6,491.16
TOTAL GAS/OIL	200.57
TOTAL B.C. ENVIR LEVY	3.53
TOTAL EHC-OIL	2.40
TOTAL COUPON DISCOUNT	-2.00

Qty	Part Number	Desc	List	Unit	Extended
1	4376104CUM	GSKT KIT	1,996.79	1,504.31	1,504.31
6	5472970CUM	KIT, LINER	1,736.04	289.34	1,736.04
6	4376565CUM	SET-PISTO	1,425.24	237.54	1,425.24
6	2882087CUM	SET-ROD B	629.94	104.99	629.94
6	5298564CUM	SHIM	350.10	58.35	350.10
12	3064305CUM	RING, RETA	69.36	5.78	69.36
1	4026684CUM	GASKET-OI	331.97	250.14	250.14
1	3678756CUM	SEAL-O RI	12.77	9.78	9.78
10	3678506CUM	SCREW, HEX	239.90	23.99	239.90
1	3688976CUM	CONNECTIO	57.10	43.16	43.16
1	3686839CUM	CLAMP-T B	34.86	26.36	26.36
1	3683940CUM	SEAL-INTE	70.30	52.99	52.99
1	3683144CUM	CLAMP-V B	77.29	58.35	58.35
3	3896408CUM	SCREW, HEX	23.34	7.78	23.34
1	LF9070FLG	FILTER	106.00	51.99	51.99
4	3264512	MOUNT-FIR	6.36	1.59	6.36
12	CT05512	TIE-CABLE	4.32	0.36	4.32
12	CT05317	CABLE TIE	2.28	0.19	2.28
20	CT05512	TIE-CABLE	7.20	0.36	7.20
1	105FBC	GREASE-MO	10.28	7.95	7.95
48	257000-990C	10W30BULK	172.32	3.59	172.32
1	16-834	A/FREEZE	13.78	10.15	10.15
1	16-834	A/FREEZE	13.78	10.15	10.15
1	LF9070FLG&	ECO-FEE	1.25	1.25	1.25
1	16-834&	ECO-FEE	1.14	1.14	1.14

Repair Order No:

KA124208

Page 2 of 3

Invoice Date: 07-08-19

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2016	Peterbilt / 389	1XPXD49X7GD287431	40788P	638279	1004	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
06-25-19 / 10:23AM	08-04-15	4071	10921.0		3.73	
Engine Model / Serial #		Transmission Model / Serial #		Rear Axle Model / Serial #		
ISX15 / 79824920		FULLER RTLO209188 18 SPEED / S1135702		D40-170 HN04729122 PACCAR HN04729123		
CPL/ARRG	Complete	P.O. Number		Authorization	Service Writer	
	07-02-19	014512		734689	GP*GP	
Memo	PAT @ ATS (778) 442-4011					

1	16-834&	ECO-FEE	1.14	1.14	1.14
48	257000-990C&	EHC-OIL	2.40	0.05	2.40
-1	COUPON DISCOUNT	Y1956	2.00	2.00	-2.00

2. REPLACE ERRODED EXHAUST MANIFOLD
 REPLACED FRONT SECTION OF MANIFOLD AND EGR INLET COLLAR.
 TOTAL PARTS

375.54

Qty	Part Number	Desc	List	Unit	Extended
1	3688488CUM	MANIFOLD-	498.34	375.54	375.54

3. REPLACE FRONT STRUCTURE
 REPLACED FRONT HOUSING, ADJUSTABLE IDLER BOLTS AND FUEL PUMP IDLER
 SHAFT AND BOLTS.

TOTAL LABOR	1,580.00
TOTAL PARTS	1,108.80

Qty	Part Number	Desc	List	Unit	Extended
1	4393089CUM	GASKET, G	103.90	78.35	78.35
1	3685556CUM	GASKET-AD	17.41	13.17	13.17
1	3685173CUM	SEAL-OIL	94.57	71.35	71.35
1	3685614CUM	GASKET-AC	21.73	16.37	16.37
1	5484100CUM	SHAFT	126.12	95.15	95.15
1	5414049CUM	GASKET	36.54	27.56	27.56
1	5468170CUM	HOUSING, G	992.21	747.53	747.53
3	4374074	SCREW, TWE	7.77	2.59	7.77
1	D84-1000-6061620	BELT-POLY	69.56	51.55	51.55

SUPPLIES/TECHNOLOGY	695.00
---------------------	--------

G.S.T. - REG. NO. 888250784RT0001	5 % OF 17,160.00 =	858.00
-----------------------------------	--------------------	--------

SALES-PARTS-SERVICE	4070302	7,975.50
SALES-OIL & GREASE	4130302	200.57
SALES-LABOUR	4300303	8,285.00
SUPPLIES/TECHNOLOGY	6620303	695.00
WASTE DISPOSAL	6660303	5.93
DISCOUNT ON SALES	6700302	-2.00
G.S.T. 888250784RT00012180101		858.00
PLEASE PAY THIS TOTAL	1110100	18,018.00

Repair Order No:

KA124208

Page 3 of 3

Invoice Date: 07-08-19

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2016	Peterbilt / 389	1XPXD49X7GD287431	40788P	638279	1004	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
06-25-19 / 10:23AM	08-04-15	4071	10921.0		3.73	
Engine Model / Serial #		Transmission Model/Serial #		Rear Axle Model/Serial #		
ISX15 / 79824920		FULLER RTLO209188 18 SPEED / S1135702		D40-170 HN04729122 PACCAR HN04729123		
CPL ARRG	Complete	P.O. Number		Authorization	Service Writer	
	07-02-19	014512		734689	GP*GP	
Memo	PAT @ ATS (778) 442-4011					

I, THE UNDERSIGNED, OWNER OR DULY AUTHORIZED REPRESENTATIVE, HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE TOTAL AMOUNT SHOWN ABOVE. I HAVE READ AND UNDERSTOOD THE TERMS AND CONDITIONS LISTED BELOW.

Customer: X

Date:

1. **PAYMENT TERMS:** Due and payable new 15th following. It is understood and I agree to pay carrying charges of 2.25% per month (30.6% per annum) on any balance unpaid after the 15th of the following month of the date of purchase.

2. **WARRANTY CONSIDERATIONS:** Any portion of this repair order that is designated for warranty considerations will be submitted as a warranty claim to the manufacturer. If for any reason the manufacturer rejects the claim or a portion of the claim, it will become the immediate responsibility of the owner to pay that portion which is rejected.

3. **WARRANTY LIMITATION:** All service repairs carry a maximum of 30 days warranty from day of completion. Any claims must be made within 5 days of the failure date. Certain parts, products, accessories, and other items used in completing the repair and service work covered in this repair order are manufactured and supplied by others, the quality and workmanship of which are entirely outside the control of Peterbilt Pacific, Inc. With regard to such parts, products, and accessories, ect. PETERBILT PACIFIC INC. MAKES NO WARRANTIES, WHETHER EXPRESSED, IMPLIED, STATUTORY, OR OTHERWISE, INCLUDING ANY WARRANTY OF MERCHANTABILITY OR OF FITNESS FOR A PARTICULAR PURPOSE.

4. **RESPONSIBILITY OF EQUIPMENT:** Peterbilt Pacific Inc. will not be held responsible for the loss or damage to vehicles, or articles left in vehicles, in case of fire, theft, accident, or any other cause beyond their control.

5. **ALL OLD PARTS** removed will be disposed of, unless otherwise specified before repairs started.

6. **THE SIGNATURE** of the owner or duly authorized representative on the original work order request, authorized the repair and service work listed on this repair order, along with the necessary material.

7. **PRIVACY:** Personal information is collected in accordance with applicable privacy legislation and is governed by Peterbilt Pacific Inc. Privacy Policy.