

DT22-1

MORIN REPAIRS

11204C 100 St, Morinville, AB T8R 1R4
 Ph: 780-939-7999 Email: service@morinrepairs.com
 morinrepairs.com

**AUTOPRO****LOCAL TIRE
& AUTO****Invoice**

Bill To Grant Greaves

Invoice # 3463
 Work Order # 4493
 Invoice Date 5/5/2025 4:31 PM
 Service Advisor S.D
 Technician J.B

Mobile
 Email

Plate AB CLK8851
 VIN 1G1AY0788E5104490

Description Brown 1984 Chevrolet Corvette Base V8 5.7L
 350CID VIN 8
 Odometer 72,029 In / 72,036 Out

Inspection**Write-up Walk Around Inspection**

Visual walk around during service RO write-up.
 Inspection

Sub \$0.00

-- Inspection Results from AutoVitals SmartFlow --
 Walk Around Inspection (internal only), rev. 1
<https://avlink.io/l/44gvD4t>

Complimentary Interior Tidy-Up

Complimentary interior tidy-up. Pick up garbage and wipe down dash.
 Clean

Sub \$0.00

Comprehensive Inspection

Perform Comprehensive Inspection
 Inspection

Sub \$159.95

-- Inspection Results from AutoVitals SmartFlow --
 Comprehensive Inspection, rev. 1
<https://avlink.io/l/44hfdxa>

Digital Inspection Result(s)

Inspection results from SmartFlow Digital Vehicle Inspections

-- Added by SmartFlow on 5/5/2025 --
 Comprehensive Inspection, rev. 1
<https://avlink.io/l/44hfdxa>

Sub \$0.00

Service**Diagnose Fluid Leak Concern - Diagnosed during comprehensive inspection**

Customer concern: large oil leak somewhere near the engine. All over garage floor.
 Diagnosis Time

Sub \$0.00

PLEASE NOTE: 1 Hour of diagnosis time is included. If less time is needed a minimum of 1/2 hour will be billed. If more time is needed, client will be contacted and initial findings discussed before any more time is billed.

-- Technician Notes from AutoVitals SmartFlow --
 Power steering pressure line is leaking

Power Steering Hose Pressure Line

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Remove & Replace Power Steering Hose
Power Steering Pressure Hose
Freight

Sub \$377.75

-- Technician Notes from AutoVitals SmartFlow --
Remove and replace power steering pressure line flush and fill power steering system

Power Steering Pump

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Remove & Replace Power Steering Pump
Reman Power Steering Pump
Power Steering Fluid
GM1050017
Freight

Sub \$658.07

-- Technician Notes from AutoVitals SmartFlow --
Remove and replace power steering pump clean and fill power steering system

Wheel Studs & Lug Nuts

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Please Note: Keeping your tires properly inflated and rotated will assist in maximizing tire wear life and vehicle handling.

*Wheels require lug nut re-torque. Ask your Service Consultant for details.

Replace Broken Wheel Stud & Nut
Wheel Stud
Wheel Lug Nut Chrome Single
Lug Nut
Covered under warranty

Sub \$85.91

-- Technician Notes from AutoVitals SmartFlow --
Remove old wheel stud on right rear and replace with a new wheel stud and a nut

Total Parts		\$433.46
Total Labor		\$745.52
Total Sublet		\$102.70
Total Before Taxes & Miscellaneous Charges		<u>\$1,281.68</u>
(*) Materials & Environmental Handling Fee		\$89.46 G
(G) Canadian Goods and Services Tax (GST)	5 %	<u>\$68.56</u>
Grand Total		<u>\$1,439.70</u>

Payment can be made:
in person by Credit Card, Interac, or Cash or Online through E-Transfer to service@morinrepairs.com

GST#738988344

Greaves, Grant paid \$1,439.70 by Mastercard

YOU'RE COVERED BY OUR 24 MONTH / 40,000KM LIMITED WARRANTY!
We stand behind our parts and our workmanship! For eligible warranty service, you must have a copy of your original service invoice. If



OK Tire Morinville
2 Heritage Drive
Morinville AB T8R 1S1
Phone: 780-939-5620 Fax:
e-mail: morinville@oktire.com

It's going to be OK.

PAGE: 1
DATE: 24 Oct 16
GST REG#: 767954068 RT0001
PST REG#:
INVOICE
IN010850
(Copy)

SOLD TO:

GRANT GREAVES

CONTACT

MOBILE : HOME:
BUSINESS: FAX :
EMAIL : reg@hallsautoparts.com

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
GOLD	1984 Chevrolet Corvette 5.7 L 350 CID V8				72007
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1G1AY0788ES104490				KT	72007
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
8:15 AM		Cash			72007
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
1	moil	OIL CHANGE LABOR EB 24 Oct 16 PERFORMED OIL CHANGE FREE WASHER FLUID TOPUP			19.99
1	NGF 1069	Oil Filter - NAPA Gold		14.80	14.80
1	ENVFIL	ENVIRONMENTAL FEE - OIL FILTER		.55	.55
4.7	0001605	5W-30 GTX Ultraclean		8.90	41.83
4.7	ENVOIL	ENVIRONMENTAL FEE - OIL		.50	2.35
	CSER	THERMOSTAT Remove & Replace EB 24 Oct 16 (Actual 1hr) REPLACED THERMOSTAT AND FLUSHED COOLING SYSTEM.			98.00
1	THM 170	THERMOSTAT		21.00	21.00
1	THM 1038ST	GASKET		1.30	1.30
1	KFL 708	10 MIN RAD FLUSH		14.60	14.60
1	UNI FS111	Coolant Fan Switch		67.70	67.70
2	RCO 49604OGM	Antifreeze 50/50 GM ORANGE		26.65	53.30
	lab	SERVICE/MECHANICAL LABOR SB 24 Oct 16 replace door handle REPLACED DOOR HANDLE			140.00
	ENSE	ENGINE SERVICE EB 24 Oct 16 REPLACED HEAD GASKETS FOR OVER HEATING AND BLOWING COOLANT OUT.			1680.00
2	5577733 PT-2	HEAD GASKET		50.60	101.20
2	55770950	EGR GASKET SET		6.05	12.10
1	557MS 91440	IN GASKET SET		121.75	121.75
1	5575152	WATER PUMP GASKET		5.55	5.55
2	55760535	AIR CLEANER MOUNTING GASKET		10.70	21.40
1	557MS 94054	EXHAUST MANIFOLD GASKET		34.55	34.55
1	SKF17286	SEAL		28.90	28.90
1	GAT33624	THERMOSTAT GASKET		1.20	1.20
1	FPG VS50265C	Valve Cover Gasket Set		51.80	51.80
1	557 1204	Engine Intake Manifold Gasket		62.00	62.00
1	SS	SHOP SUPPLIES THANK YOU for shopping local and please don't forget to leave us a positive REVIEW on GOOGLE and FACEBOOK !!!		155.04	155.04

INVOICE TO:

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions. I promise to pay the amount due upon completions of the work. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

THANK YOU FOR YOUR PATRONAGE!! Signature: _____

WHEELS SHOULD BE RETORQUED IN 100KM

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	
GST:	
PST:	
TOTAL:	Cont'd





It's going to be OK.

OK Tire Morinville
2 Heritage Drive
Morinville AB T8R 1S1
Phone: 780-939-5620 Fax:
e-mail: morinville@oktire.com

PAGE: 2
DATE: 24 Oct 16
GST REG#: 767954068 RT0001
PST REG#:

INVOICE

IN010850

(Copy)

SOLD TO:

GRANT GREAVES

CONTACT

MOBILE : HOME:
BUSINESS: FAX :
EMAIL : reg@hallsautoparts.com

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
GOLD	1984 Chevrolet Corvette 5.7 L 350 CID V8				72007
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1G1AY0788ES104490				KT	72007
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
8:15 AM		Cash			72007

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
		Payment Method: DebitCard=1000.00 DebitCard=1000.00 Mastercard =888.49 Thank you for your business.			

INVOICE TO:

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions. I promise to pay the amount due upon completions of the work. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

THANK YOU FOR YOUR PATRONAGE!! Signature: _____

WHEELS SHOULD BE RETORQUED IN 100KM

PARTS:	654.98
LABOUR:	1937.99
OTHER:	157.94
SUB-TOTAL:	2750.91
GST:	137.58
PST:	N/C
TOTAL:	2888.49





It's going to be OK.

OK Tire Morinville
2 Heritage Drive
Morinville AB T8R 1S1
Phone: 780-939-5620 Fax:
e-mail: morinville@oktire.com

PAGE: 1
DATE: 24 Aug 28
GST REG#: 767954068 RT0001
PST REG#:
INVOICE
IN010438 (Copy)

SOLD TO:

GRANT GREAVES

CONTACT

MOBILE : HOME:
BUSINESS: FAX :
EMAIL : reg@hallsautoparts.com

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
GOLD	1984 Chevrolet Corvette 5.7 L 350 CID V8				71917
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1G1AY0788ES104490				KT	71917
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
9:30 AM		Cash			71917
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
		Tech DW: found fan not turning on while vehcile is hot. found the relay unplugged. tested the relay. relay ok. jumped power to the fan to test fan. fan is good. retested found the fan still did not turn on. found the coolant temp sensor. found pin fit not good on the connector. applied ground to the connector and fan turn on. tested the sensor to see if it works found when adding heat the sensor comes on. replaced the connector. found the fan comes on around 235. and goes off at 215. drained the coolant when sensor was out. refilled with new coolant. found door lock come apart inside the door. replaced spring in the door lock reinstalled the door lock. window down on passenger side of the vehcile jumped the wires motor moves. removed the center consol and found the wires broken of the connector. replaced with new connector. window goes up and down. tested the washer pump. found good power and ground at the washer pump. reconnected to washer pump found pump work. have to push down on the swtich for washer to work. ajusted the hood linkage			
1	ELSE S1644	WINDOW SWITCH Remove & Replace - Front,Each DW 24 Aug 28 POWER WINDOW SWITCH CONNECTOR		89.75	84.00 89.75
1	CSEER	COOLANT TEMPERATURE SENDER OR SENSOR Remove & Replace DW 24 Aug 28			140.00
1	UNI TS4032	Coolant Temperature Sensor		35.05	35.05
2	RCO 496040GM	Antifreeze 50/50 GM ORANGE		26.65	53.30
1	UNI FSC10	Tailgate Harness Connector		31.55	31.55
1	SS	SHOP SUPPLIES		15.68	15.68

INVOICE TO:

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions. I promise to pay the amount due upon completions of the work. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

THANK YOU FOR YOUR PATRONAGE!! Signature: _____

WHEELS SHOULD BE RETORQUED IN 100KM

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	
GST:	
PST:	
TOTAL:	Cont'd





OK Tire Morinville
2 Heritage Drive
Morinville AB T8R 1S1
Phone: 780-939-5620 Fax:
e-mail: morinville@oktire.com

It's going to be OK.

PAGE: 2
DATE: 24 Aug 28
GST REG#: 767954068 RT0001
PST REG#:
INVOICE
IN010438 (Copy)

SOLD TO:

GRANT GREAVES

CONTACT

MOBILE : HOME:
BUSINESS: FAX :
EMAIL : reg@hallsautoparts.com

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
GOLD	1984 Chevrolet Corvette 5.7 L 350 CID V8				71917
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1G1AY0788ES104490				KT	71917
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
9:30 AM		Cash			71917

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
		THANK YOU for shopping local and please don't forget to leave us a positive REVIEW on GOOGLE and FACEBOOK !!! Payment Method: DebitCard=471.80 Thank you for your business.			

INVOICE TO:

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions. I promise to pay the amount due upon completions of the work. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

THANK YOU FOR YOUR PATRONAGE!! Signature: _____

WHEELS SHOULD BE RETORQUED IN 100KM

PARTS:	209.65
LABOUR:	224.00
OTHER:	15.68
SUB-TOTAL:	449.33
GST:	22.47
PST:	N/C
TOTAL:	471.80





It's going to be OK.

OK Tire Morinville
2 Heritage Drive
Morinville AB T8R 1S1
Phone: 780-939-5620 Fax:
e-mail: morinville@oktire.com

PAGE: 1
DATE: 24 Jul 29
GST REG#: 767954068 RT0001
PST REG#:
INVOICE
IN009569 (Copy)

SOLD TO:

GRANT GREAVES

CONTACT

MOBILE : HOME:
BUSINESS: FAX :
EMAIL : reg@hallsautoparts.com

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
GOLD	1984 Chevrolet Corvette 5.7 L 350 CID V8				71917
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1G1AY0788ES104490				KT	71917
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
8:00 AM		Cash			71917
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
1	INSU	INSURANCE INSPECTION AL 24 Jun 04 PERFORMED INSURANCE INSPECTION. windshield washer tank craked leaking, drivers door cable loose not opening, passenger door key won;t work, both doors lock switches not working feels loose, thin tube under engine oil dip stick is broken/ disconnected, no cruise control HORN DOES NOT WORK (DONE) COULD USE NEW WIPER BLADES CLUNK IS I SHAFT FRONT WHEELS ON WRONG SIDES (TIRES ARE DIRECTIONAL) (DONE) ELECTRIC LOCKING DOES NOT FUNCTION HATCH DOES NOT RELEASE (DONE) RADIO IS ONLY STATIC HEADLIGHTS STUCK IN ON POSITION/ DONE ELEC MIRRORS NOT WORKING/ DONE			119.99
	DISE	DIAGNOSTICS SERVICE EB 24 Jul 29 REMOVE EXCESS END OFF BOLT THAT IS HITTING EXHAUST.			70.00
	LAB	SERVICE/MECHANICAL LABOR SB 24 Jul 29 replace door lock tumblers remove intierior door panels and door handles try multipel door tumblers did not fit, found the right ones and installed reinstall door panels			280.00
1	s	door locks tumblers		150.00	150.00
1	OES 7355017	Door Lock Rod Clips		5.70	5.70
	LAB	SERVICE/MECHANICAL LABOR EB 24 Jul 29 REPLACE BRAKE BOOSTER POWER BRAKE BOOSTER			280.00
1	540-00854			375.99	375.99

INVOICE TO:

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions. I promise to pay the amount due upon completions of the work. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

THANK YOU FOR YOUR PATRONAGE!! Signature: _____

WHEELS SHOULD BE RETORQUED IN 100KM

PARTS:
LABOUR:
OTHER:
SUB-TOTAL:
GST:
PST:
TOTAL: Cont'd





It's going to be OK.

OK Tire Morinville
2 Heritage Drive
Morinville AB T8R 1S1
Phone: 780-939-5620 Fax:
e-mail: morinville@oktire.com

PAGE: 2
DATE: 24 Jul 29
GST REG#: 767954068 RT0001
PST REG#:
INVOICE
IN009569 (Copy)

SOLD TO:
9100011
GRANT GREAVES

CONTACT

MOBILE : HOME:
BUSINESS: FAX :
EMAIL : reg@hallsautoparts.com

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
GOLD	1984 Chevrolet Corvette 5.7 L 350 CID V8				71917
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1G1AY0788ES104490				KT	71917
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
8:00 AM		Cash			71917
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
1	lab DS-265	SERVICE/MECHANICAL LABOR EB 24 Jul 29 diag and replace head light switch HEADLIGHT SWITCH CORVETTE		203.50	140.00 203.50
1	LAB 172623	WINDSHIELD WASHER PUMP Remove & Replace EB 24 Jul 29 WINDSHIELD WASHER PUMP		42.50	154.00 42.50
	lab	SERVICE/MECHANICAL LABOR SB 24 Jul 29 remove door panels and parts of dash to trace wiring for power door locks, power mirrors reassemble and tigh up wiring, customer said to stop chasing wiring.			420.00
	lab	SERVICE/MECHANICAL LABOR EB 24 Jul 29 diag and repair rear hatch not opening found faulty relay check connection repaired and retest ok			70.00
1	SS	SHOP SUPPLIES THANK YOU for shopping local and please don't forget to leave us a positive REVIEW on GOOGLE and FACEBOOK !!! A/C WIRING AND HOSE (DONE) , BREATHER TOO INTAKE, WARM AIR PIPING , HORN. WIRING AT LEFT SIDE HEADLIGHT WELL. WIRING HANGING IN FOOT WELL. Payment Method: Mastercard =1000.00 DebitCard=1540.03 Thank you for your business.		107.38	107.38

INVOICE TO:

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions. I promise to pay the amount due upon completions of the work. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

THANK YOU FOR YOUR PATRONAGE!! Signature: _____

WHEELS SHOULD BE RETORQUED IN 100KM

PARTS:	627.69
LABOUR:	1533.99
OTHER:	257.38
SUB-TOTAL:	2419.06
GST:	120.97
PST:	N/C
TOTAL:	2540.03



Invoice Number: 23668

Western Corvette Service & Performance
3605 Manchester Rd Se
Calgary, Alberta, T2G 3Z7
Phone: (403) 255-2111 Fax: (403) 252-9409

Status Completed
Inv. Date October 19, 2023
Date Rec'd September 22, 2023
PO Number 1

Entered By Block, Jason

Contact

Year 1984 Chevrolet
Model Corvette Style: Brown Cou
Mileage 71917
Serial Number 1g1ay0788e5104490

Home Phone:

Description

Cell Phone:

Work Phone:

Fax Number:

Part Number	Part Description	Quantity	Unit	List Price	Unit Price	Subtotal
564238	STEERING RACK PINION SERVICE - REBUILD STANDARD CODE WL	1	Eac	\$618.40	\$618.40	\$618.40
KF586	Power Steering Fluid	2		\$12.50	\$12.50	\$25.00

Parts Total \$643.40

Technician	Comments	Hours	Rate	Subtotal
Morgan, Cole	R&R rack and pinion	4.5	\$165.00	\$742.50
Morgan, Cole	"pulls" from 1st to 2nd gear? Trans issue? Take it for a drive and see how it feels. Check trans fluid level - fluid level looks good. Customer chose to leave for now - no charge	0.25	\$0.00	\$0.00

Labour Total \$742.50

Invoice Number: 23668

Western Corvette Service & Performance

3605 Manchester Rd Se

Calgary, Alberta, T2G 3Z7

Phone: (403) 255-2111 Fax: (403) 252-9409

Entered By Block, Jason

Status Completed

Inv. Date October 19, 2023

Date Rec'd September 22, 2023

PO Number 1

Contact

Year 1984 Chevrolet

Model Corvette

Style: Brown Cou

Mileage 71917

Serial Number 1g1ay0788e5104490

Home Phone :

Cell Phone:

Work Phone:

Fax Number:

Description

ELECTRICAL PARTS NOT RETURNABLE

Shop Supplies \$55.69

Shipping \$0.00

Subtotal \$1,441.59

G.S.T \$72.08

Total \$1,513.67

G.S.T. Reg# 10073 2510 RT0001

Total Payment

Amount Due \$1,513.67

We appreciate your business - Thank You!

I hereby authorize the repair work set out above to be conducted with the supply of parts and materials required, together with any additional work, parts and materials subsequently agreed to. You shall only be responsible for loss or damage to the vehicle caused directly by your own gross negligence or misconduct and for no other loss or damage. I acknowledge that the vehicle may be located outside of a building while on your premises. I acknowledge my obligation to maintain insurance on my vehicle while on your premises or otherwise in your possession. I hereby grant you and your employees permission to operate the vehicle on streets, highways or elsewhere for the purpose of testing and/or inspection. Payment is due on completion of repair work, subject to earlier progress payments agreed to. I acknowledge until payment in full the existence of a garageman's/mechanic's lien on the vehicle your favor in respect of the material supplied and services rendered for the full amount charged therefor. If the vehicle is not picked up within two weeks of me being notified of the completion of the work, I agree to pay to you a storage fee of \$25.00 per day (commencing on the end of such two week period) until the vehicle is removed from your premises.

Invoice Number: 23463

Western Corvette Service & Performance
3605 Manchester Rd Se
Calgary, Alberta, T2G 3Z7
Phone: (403) 255-2111 Fax: (403) 252-9409

Status Completed
Inv. Date August 23, 2023
Date Rec'd August 10, 2023
PO Number 1

Entered By Block, Jason

Contact
Year 1984 Chevrolet
Model Corvette **Style:** brown coup
Mileage 71917
Serial Number 1g1ay0788e5104490

Home Phone: **Description**
Cell Phone:
Work Phone:
Fax Number:

Part Number	Part Description	Quantity	Unit	List Price	Unit Price	Subtotal
584150	SPINDLE CONTROL ROD SET - UPR AND LWR FACTORY RUBBER BUSHINGS 4 PC	1	Eac	\$498.85	\$200.00	\$200.00
51069	Oil Filter	1	1	\$15.50	\$15.50	\$15.50

Parts Total \$215.50

Technician	Comments	Hours	Rate	Subtotal
TS, Technician	OLF (customer supplied oil) and diagnose oil leaks - Numerous leaks noticed but main leaks are coming from power steering rack and water pump. Customer chose not to repair leaks. Oil change	0.5	\$165.00	\$82.50
TS, Technician	Horn button dangling from steering column - button has broken tabs on the back of it. It is currently in place but if customer would like it better we would have to order him a new horn button - no charge	0.25	\$0.00	\$0.00
TS, Technician	Squeek in rear end when going over bumps - Number of worn items in rear suspension. Worst ones appear to be upper and lower control arms. No new bushings available locally so replaced entire arms with known good used units.	2	\$165.00	\$330.00

Labour Total \$412.50

Invoice Number: 23463

Western Corvette Service & Performance

3605 Manchester Rd Se

Calgary, Alberta, T2G 3Z7

Phone: (403) 255-2111 Fax: (403) 252-9409

Entered By Block, Jason

Status Completed

Inv. Date August 23, 2023

Date Rec'd August 10, 2023

PO Number 1

Contact

Year 1984 Chevrolet

Model Corvette

Style: brown coup

Mileage 71917

Serial Number 1g1ay0788e5104490

Home Phone :

Description

Cell Phone:

Work Phone:

Fax Number:

ELECTRICAL PARTS NOT RETURNABLE

G.S.T. Reg# 10073 2510 RT0001

Shop Supplies \$30.94

Shipping \$0.00

Subtotal \$658.94

G.S.T \$32.95

Total \$691.89

Total Payment \$691.89

Amount Due \$0.00

We appreciate your business - Thank You!

I hereby authorize the repair work set out above to be conducted with the supply of parts and materials required, together with any additional work, parts and materials subsequently agreed to. You shall only be responsible for loss or damage to the vehicle caused directly by your own gross negligence or misconduct and for no other loss or damage. I acknowledge that the vehicle may be located outside of a building while on your premises. I acknowledge my obligation to maintain insurance on my vehicle while on your premises or otherwise in your possession. I hereby grant you and your employees permission to operate the vehicle on streets, highways or elsewhere for the purpose of testing and/or inspection. Payment is due on completion of repair work, subject to earlier progress payments agreed to. I acknowledge until payment in full the existence of a garageman's/mechanic's lien on the vehicle your favor in respect of the material supplied and services rendered for the full amount charged therefor. If the vehicle is not picked up within two weeks of me being notified of the completion of the work, I agree to pay to you a storage fee of \$25.00 per day (commencing on the end of such two week period) until the vehicle is removed from your premises.



Randy Robbins <randyryanrobbins@gmail.com>

Invoice - INV015391 (PAID)

1 message

Good Tire <donotreply@app.helcim.com>

To: randyryanrobbins <randyryanrobbins@gmail.com>

Fri, Aug 4, 2023 at 4:48 PM

GOODTIRE

Invoice

INVOICE # INV015391

Paid

Details

Issued on: Aug 3, 2023

Paid on: Aug 3, 2023

Payment Terms: 0 days

Created By: AJ Ghandour

Customer

Billing to

Alberta, Canada

Shipping to

Alberta, Canada

Item	Qty	Price	Total
245/50R16 Falken	4	\$ 255.76	\$ 1,023.04
Mount and balance	4	\$ 25.00	\$ 100.00
Tire recycling fee	4	\$ 4.00	\$ 16.00
Comments Please have your vehicle re-torqued. Maintain alignment to ensure warranty is not void.	Subtotal		\$ 1,139.04
	Tax		
	(1) GST 5.0000%		\$ 51.15
	(2) GST 5.0000%		\$ 5.00
	(3) GST 5.0000%		\$ 0.80
	Total		\$ 1,195.99
	Amount Paid		\$ 1,196.00
	Amount Due		\$ 0.00

Transactions

ID	DATE	TYPE	CODE	CARD #	AMOUNT
#37953096	08/03/23 13:29	CARD Purchase			\$ 1,196.00

Thank you for your business!

Good Tire 130-1830 52 Street Southeast, Calgary, AB, T2B 1N1, CAN
Phone: 403-453-2008 Info@goodtire.ca https://goodtire.ca

Invoice Number: 23157

Western Corvette Service & Performance

3605 Manchester Rd Se

Calgary, Alberta, T2G 3Z7

Phone: (403) 255-2111 Fax: (403) 252-9409

Entered By Block, Jason

Contact

Year 1984 Chevrolet

Model Corvette

Style: brown coup

Mileage 71917

Serial Number 1g1ay0788e5104490

Home Phone:

Cell Phone:

Work Phone:

Fax Number:

Description Technician notes* brake booster leaking, steering coupler sometimes binds on itself, tires are marginal and should be replaced*

Parts:

Part Number	Part Description	Quantity	Unit	List Price	Unit Price	Subtotal
rfl	Request for Inspection	1	ea	\$11.00	\$11.00	\$11.00
crtsts-1	Fuel Strainer	1	ea	\$12.75	\$12.75	\$12.75
acpr45ts	Spark Plug	8	ea	\$9.30	\$9.30	\$74.40
oem7024	Ignitor - Ignition Module	1	ea	\$105.97	\$105.97	\$105.97
acdd336x	Distributor Cap - Delco	1	ea	\$68.78	\$68.78	\$68.78
dlpfe0115	Fuel Pump	1	ea	\$158.84	\$158.84	\$158.84
oem8672	Brake light switch	1	ea	\$21.43	\$21.43	\$21.43
584116	SPRING CENTER MOUNT INSULATOR - REAR ON SPACER 2 REQUIRED	1	Eac	\$20.00	\$20.00	\$20.00
26693	Steering Column Hub	1		\$66.00	\$66.00	\$66.00
37736	Lower Horn Contact w/ Spring	1	ea	\$41.25	\$41.25	\$41.25
tiltpins	Steering Column Tilt Pins	2	EA	\$35.00	\$35.00	\$70.00
58625	Steering Column Lower Bearing	1	kit	\$68.00	\$68.00	\$68.00
40918	PCV Valve.	1	EA	\$15.30	\$15.30	\$15.30
38190	Door Window Regulator. RH	1	EA	\$448.04	\$175.00	\$175.00
GE1157	BULB	2		\$3.50	\$3.50	\$7.00
39235	Hazard Flasher.	1	EA	\$8.69	\$8.69	\$8.69
GAS	GAS SUPPLIED BY WESTERN CORVETTE	1	EA	\$35.00	\$35.00	\$35.00

Parts Total

\$959.41

Labour:

Technician	Comments	Hours	Rate	Subtotal
Block, Lawrence	OOP - found numerous light issues (markers signals etc, rh window non-op, rear spring loose, loose column tilt pins, blower motor doesn't work, no battery hold down, horn non-op,	1	\$247.50	\$247.50
Morgan, Cole	R&R RF marker light housing	0.75	\$165.00	\$123.75

July 14, 2023

Page 1 of 3

Invoice Number 23157

Invoice Number: 23157

Western Corvette Service & Performance
3605 Manchester Rd Se
Calgary, Alberta, T2G 3Z7
Phone: (403) 255-2111 Fax: (403) 252-9409

Status Completed
Inv. Date July 14, 2023
Date Rec'd June 8, 2023
PO Number 1

Entered By Block, Jason

Contact **Year** 1984 Chevrolet
Model Corvette **Style:** brown coup
Mileage 71917
Serial Number 1g1ay0788e5104490

Home Phone :
Cell Phone:
Work Phone:
Fax Number:

Description

Morgan, Cole	R&R signal switch - also found very worn column tilt pins, broken tilt hub, broken horn contact spring and bad connection at column plug. Remove & Rebuild steering column	3.25	\$165.00	\$536.25
Morgan, Cole	Diagnose and repair poor running - poor fuel pump performance, R&R pump and strainer. Car quit again while in shop. Diagnose as Faulty ignition module - R&R ignition module, distributor cap & spark plugs.	5	\$165.00	\$825.00
Morgan, Cole	Horn doesn't work - Diagnose as somebody wiring power for hood light direct to ground. This causes horn/courtesy/clock fuse to blow. Repair wiring and replace fuse. Horn now works	1.75	\$165.00	\$288.75
Morgan, Cole	Rear spring loose in vehicle and sitting very low in back. Rear spring spacer plate missing. Remove spring, install spacer plate and re-assemble	0.75	\$165.00	\$123.75
Morgan, Cole	RH window worked at first then wouldnt go up or down - Diagnose as faulty window regulator. R&R window regulator	1.5	\$165.00	\$247.50

Labour Total

\$2,392.50

Invoice Number: 23157

Western Corvette Service & Performance

3605 Manchester Rd Se

Calgary, Alberta, T2G 3Z7

Phone: (403) 255-2111 Fax: (403) 252-9409

Entered By Block, Jason

Status Completed

Inv. Date July 14, 2023

Date Rec'd June 8, 2023

PO Number 1

Contact

Year 1984 **Chevrolet**

Model Corvette **Style:** brown coup

Mileage 71917

Serial Number 1g1ay0788e5104490

Home Phone :

Cell Phone:

Work Phone:

Fax Number:

Description

Work Order Total

ELECTRICAL PARTS NOT RETURNABLE

Shop Supplies	\$179.44
Shipping	\$0.00
Subtotal	\$3,531.35
G.S.T	\$176.57
Total	\$3,707.91
Total Payment	
Amount Due	\$3,707.91

G.S.T. Reg# 10073 2510 RT0001

PAID 

We appreciate your business - Thank You!

I hereby authorize the repair work set out above to be conducted with the supply of parts and materials required, together with any additional work, parts and materials subsequently agreed to. You shall only be responsible for loss or damage to the vehicle caused directly by your own gross negligence or misconduct and for no other loss or damage. I acknowledge that the vehicle may be located outside of a building while on your premises. I acknowledge my obligation to maintain insurance on my vehicle while on your premises or otherwise in your possession. I hereby grant you and your employees permission to operate the vehicle on streets, highways or elsewhere for the purpose of testing and/or inspection. Payment is due on completion of repair work, subject to earlier progress payments agreed to. I acknowledge until payment in full the existence of a garageman's/mechanic's lien on the vehicle your favor in respect of the material supplied and services rendered for the full amount charged therefor. If the vehicle is not picked up within two weeks of me being notified of the completion of the work, I agree to pay to you a storage fee of \$25.00 per day (commencing on the end of such two week period) until the vehicle is removed from your premises.