

ES16-60

# TOP DOG MECHANICAL LTD.

## INVOICE

Box 1891  
Beaverlodge, Alberta T0H 0C0  
Canada  
topdogmech1@gmail.com



Sold to: Canadian Fiber Optics

Invoice No.: 2008871  
Date: 06/19/2024  
Page: 1

repairs - ball cage, float gauge, filter, air fitting on brake valve

Business No.:

Quantity	Description	Tax	Unit Price	Amount
1.0	Unit 129. Grease and check over truck	G	140.00	140.00
6.0	Cut off old ball cage. Send out to have two cages fabricated. Drill out new cage and install with the balls	G	140.00	840.00
2.0	Replace float gauge in tank	G	140.00	280.00
2.5	Could not get same vac filter so modified house to fit more common filters. Install new filter.	G	140.00	350.00
1.0	Replace air fitting on brake valve leaks badly.	G	140.00	140.00
1,750.0	Shop Supplies	G	0.08	140.00
1.0	Fabricated Ball Cages	G	1,518.92	1,518.92
	Subtotal:			3,408.92
	G - GST 5%			
	GST/HST			170.45
Shipped By: Tracking Number:				Total Amount 3,579.37
Comment: Payment due upon receipt of invoice. Thank you for your business!				Amount Paid 0.00
Sold By:				Amount Owning 3,579.37

**TOP DOG MECHANICAL LTD.****INVOICE**

**Box 1891**  
**Beaverlodge, Alberta T0H 0C0**  
**Canada**  
**topdogmech1@gmail.com**



Sold to: Canadian Fiber Optics

Invoice No.: 200461  
 Date: 01/23/2024  
 Page: 1

repairs - coolant leak, pto and pump, line injector

Business No.:

Quantity	Description	Tax	Unit Price	Amount
	Unit 129. 2013 Western Star. 6486hrs. 509.8Miles. SER#5KKPALD19EPFV4766			
8.00	Check for coolant leak. Pressure test and found going into tank on back of truck through piping and found coolant pipe inside of water pipe to have failed. Repaired for heater fan in back not working. Found wire issue in control panel. Loose connection not making good contact. Repaired and tested. Good	G	140.000	1,120.00
6.00	Remove rotation from boom. Measure up hose on boom. Seperate pto and pump.	G	140.000	840.00
6.50	R&R injector Line pass through seals. Remove pto, remove water lines wiht coolant heaters to be repaired.	G	140.000	910.00
6.00	Disassemble pto and prep for new parts. Remove big suction hose, remove driveline and disassemble drop box for new seal. Changed turbo drain gasket and oring into block. Changed fitting to oil spinner for leaking.	G	140.000	840.00
4.00	Install seal and reassemble drop box. Reseal Pto and install. Fill with oil. Clear codes.	G	140.000	560.00
2.00	Remove vac hose and install new dust shield.	G	140.000	280.00
6.00	Changed drop box oil. Reinstall driveline. Install piping and coolant lines.	G	140.000	840.00
8.00	Installed new vac hose. Install hose couplers on 8" hose. Install rotary manifold.	G	140.000	1,120.00
6,510.00	Shop Supplies	G	0.080	520.80
1.00	Tear down and Reseal valve. All bearings and seals replaced	G	691.600	691.60
6.00	Metal Seal. Pass Thru Seal	G	20.920	125.52
1.00	Fitting	G	23.360	23.36
1.00	Oil Return Line Gasket	G	16.380	16.38
1.00	Oring	G	10.100	10.10
12.00	Hex Flange Head Cap Screw	G	9.280	111.36
1.00	Grooved Bolt Clamp T Gasket	G	94.000	94.00
2.00	FM JIC STR	G	17.330	34.66
59.00	1/2" 2 Wire Hyd. Hose	G	0.490	28.91
1.00	M NPT TO M JIC	G	2.770	2.77
1.00	Input/Output seal	G	158.570	158.57
2.00	Shaft Seal	G	30.810	61.62
4.00	Gasket	G	9.480	37.92
1.00	Freight	G	35.000	35.00
1.00	Flex Seal Clamp HD.4.06-4.37	G	15.002	15.00
1.00	Dust Shield	G	168.710	168.71
8.00	75/90 Mobile Syn Gear Oil Bulk	G	14.400	115.20
20.00	50W Syn Trans Mobil 18.4L	G	18.330	366.60
2.75	Case 50/50 Diesel Antifreeze.	G	55.900	153.73
	Subtotal:			9,281.81
	G - GST 5%			

**Comment:** Payment due upon reciept of invoice. Thank you for your business!

**Continue...**