

29 May 2025



BILL TO

VICARY RESOURCES INC.

FROM

Derrick Wilson

Business Number: 777077140

Box 373

Naicam S0K2Z0

buckshotltd74@gmail.com

+13068748490

INVOICE ITEMS

AMOUNT

\$1,550.00

MAY 20/25 UNITS# RT-01, RT-02, RT-03, TRAVEL TO SITE, SET PARK BRAKES ON ALL UNITS, CHECKED ALL FLUID LEVELS, AND SUSPENSION COMPONENTS, CHECK OVER ALL ENGINES AND CYLINDERS, FILLED TIRES AS REQUIRED, REMOVE STARTER FROM RT-01 TO BE REBUILT,

10 hrs x \$155.00/hr

ADJUSTED HOOD ON RT-02, WENT BACK TO SHOP, BACK TO SITE, INSTALL STARTER ON RT-01, INSTALL NEW OIL SUPPLY LINE ON WATER TRUCK

\$0.00

Subtotal (excl. GST) \$1,550.00 5% GST \$77.50

\$1,627.50

PAYMENT DUE

MESSAGE

Thanks for your business.

6 Blackfoot Court West Lethbridge AB T1K 7P5 Truscottm7@gmail.com

GST/HST Registration No.: 852833474

Bict 0 Vicary Resources I	inc			INVOICE DATE TERMS DUE DATE	2319 RT02 01/07/2025 Net 30 31/07/2025	į
DATE	ACTIVITY	DESCRIPTION		QTY	RATE	AMOUNT
04/06/2025	Services	RT02: Sand dr	iver door.	1.50	105.00	157.50
10/06/2025	Services	RT02: Sand ar	nd paint cab.	0.50	105.00	52.50
11/06/2025	Services	RT02; Paint ca install decal.	b black to match RT03,	1.75	105.00	183.75
•			SUBTOTAL			393.75
			GST/HST @ 5%			19.70
			TOTAL			413.45
TAX SUMMARY			BALANCE DUE			\$413.45
TON OURINANT		RATE		TAX		NET
		GST/HST @ 5%		19.70		393.75

L Broz

Box 73 Hillcrest Alberta T0K1C0 brett.d.linderman@gmail.com GST/HST Registration No.: 781961750

INVOICE

Vicary Resources

TAX SUMMARY



16/03/2025 Due on receipt 16/03/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
labour	RT02- go over and check new wiring harness install	GST	5	120.00	600.00

19516hrs

600.00

630.00

30.00

RATE

TAX

30.00

\$630.00 NE 600.00

GST @ 5%

45213.25

Mar. 19/25

6 Blackfoot Court West Lethbridge AB T1K 7P5 Truscottm7@gmail.com

GST/HST Registration No.: 852833474

Vicary Resources In	nc		1 (1) 1 (1) 1 (1) 1 (1) 1 (1)	01/03/20 Net 30	
DAFE	ACTIVITY	DESCRIPTION	от	Y RATE	AMOUNT
06/01/2025	Services	RT02: Replace engine	e wiring harness. 5.5	0 105.00	577.50
14/01/2025	Services	RT02: Check over equal to the control.		5 105.00	131.25
		214 1	e 1.00A		708.75
		68	Page por		35.44
		(Q)	T.V.		744.19
TAX SUMMARY		řík.	r Afg. (CTR)(\$744.19
IAA QUIBIPAA I		RATE	TAX		NET
		GST/HST @ 5%	35.44		708.75

6 Blackfoot Court West Lethbridge AB T1K 7P5 Truscottm7@gmail.com

GST/HST Registration No.: 852833474

Vicary Resources I	nc		e e E	era Maria	2257 01/03/2025 Net 30 31/03/2025	
DATE	ACTIVITY	DESCRIPTION		QTY	RATE	AMOUNT
07/01/2025	Services	RT02: Change 6 injectors test.	s and road	7.25	105.00	761.25
15/01/2025	Services	RT02: Install 2 way radio.		1.75	105.00	183.75
		\$1,473,	≯* * <u>.</u>			945.00
			No section			47.25
		T.Y.O.				992.25
TAX SUMMARY		fakt ed	我"先《二·书"			\$992.25
		RATE	· TAX			NET
		GST/HST @ 5%	47.25			945.00

6 Blackfoot Court West Lethbridge AB T1K 7P5 Truscottm7@gmail.com

GST/HST Registration No.: 852833474

BILL 10 Vicary Resources In	c		INVOICE DATE TERMS DUH DATE	2242 01/02/2025 Net 30 03/03/2025	
DATE	ACTIVITY	DESCRIPTION	OTY	RAIE	AMOODIT
04/12/2024	Services	RT02: Remove radio from RT03 and put into RT02, some cut power wire and removed antenna, put radio back in RT03.	0.50	105.00	52.50
10/12/2024	Services	RT02: Check engine wiring harness for shorts.	4	105.00	420.00
11/12/2024	Services	RT02: Repair wiring harness and order a new engine wiring hamess.	4.25	105.00	446.25
		SUBTOTAL			918.75
		GST/HST @ 5%			45.94
		TOTAL			964.69
TAX SUMMARY		BALANCE DUE			\$964.69
TAM OUMSTALL		RATE	TAX		NET
		GST/HST @ 5%	45.94		918.75

Invoice

6 Blackfoot Court West Lethbridge, Alberta T1K 7P5

Date	Invoice #
2024-12-01	2220

Invoice To	
Vicary Resources Inc	



Due Date 2024-12-31

Date	Description	Hours/Qty	Rate	Amount
2024-11-05	RT02: Install wiring harnesses.	1.25	105.00	131.25
2024-11-06	RT02: Assemble dash wiring harness, order parts, check electrical switches.	6.5	105.00	682.50
2024-11-07	RT02: Install oil pan and gasket, remove park brake switch, check electrical circuit for	6.25	105.00	656.25
*	shorts, replace 6 pin harness plug at hitch, remove broken bolt from park brake actuator and fill with engine oil.			
2024-11-13	RT02: Locate wiring shorts.	9.75	105.00	1,023.75
	RT02: Trace electrical short in light wiring, trace problem with park brake circuit.	5.5	105.00	577.50
	RT02: Diagnose electrical problems with park brake and transmission.	6.75	105.00	708.75
	RT02: Sand, repair, bondo and paint R/H cab side cover.	4.5	105.00	472.50
	42458A Decal CAT logo for Rock truck	1	99.99	99.99
2024-11-20	RT02: Hook up laptop and check diagnostic codes and install side cab cover.	1.25	105.00	131.25
2024-11-26	RT02: Road test, check for active codes.	0.5	105.00	52.50
	GST On Sales		5.00%	226.81

I agree to pay on completion of services of machine or on terms satisfactory with you and until paid in full, an express mechanics lien is acknowledged on above machine to secure the amount of parts and repairs thereto. It is understood that Truscott Heavy Equipment Repairs assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, repairs or while field testing.

Received By:

Phone # 1-403-330-7751 truscot@telusplanet.net

GST/HST No.

852833474

Subtotal	\$4,536.24
GST	\$226.81
Total	\$4,763.05

Invoice

6 Blackfoot Court West Lethbridge, Alberta T1K 7P5

Date	Invoice #	-
2024-11-01	2210	

Invoice To		
Vicary Resources Inc	 	



Due Date 2024-11-30

Date	Description	Hours/Qty	Rate	Amount
2024-10-22	RT02: Check for damage wiring harness and repair wires.	9	105.00	945.00
	RT02: Drain hydraulic tank and replace sight glass.	2	105.00	210.00
	RT02: Install wiring harness.	5.75		603.75
2024-10-29	RT02: Patch hole in heater box.	1	105.00	105.00
	GST On Sales		5.00%	93.19
1				
		1		
1				

I agree to pay on completion of services of machine or on terms satisfactory with you and until paid in full, an express mechanics lien is acknowledged on above machine to secure the amount of parts and repairs thereto. It is understood that Truscott Heavy Equipment Repairs assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, repairs or while field testing.

Received By:

Phone #	
1-403-330-7751	

truscot@telusplanet.net

GST/HST No. 852833474

Subtotal	\$1,863.75		
GST	\$93.19		
Total	\$1,956.94		

Invoice

6 Blackfoot Court West Lethbridge, Alberta T1K 7P5

Date	Invoice #
2024-09-01	2190

Invoice To	
Vicary Resources Inc	an an air an tagair ann an an tagair ann ann ann an an an an an an an an an



Due Date

2024-09-30

ENTERED

Date	Description	Hours/Qty	Rate	Amount
	RT02: Transmission shifter not working.	0.5	105.00	52.50
	RT02: Replace spring in transmission shifter.	0.25	105.00	26.25
2024-08-19	RT02: Replace driver seat shocks, remove hydraulic brake pump and silicone gasket.	2.75	105.00	288.75
	GST On Sales		5.00%	18.38
	RT02			
	11102			
	1		,	
	,			

I agree to pay on completion of services of machine or on terms satisfactory with you and until paid in full, an express mechanics lien is acknowledged on above machine to secure the amount of parts and repairs thereto. It is understood that Truscott Heavy Equipment Repairs assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, repairs or while field testing.

Received By:

Phone #	
1-403-330-7751	

truscot@telusplanet.net

GST/HST No. 852833474


Subtotal	\$367.50		
GST	\$18.38		
Total	\$385.88		

Invoice

6 Blackfoot Court West Lethbridge, Alberta T1K 7P5

Date	Invoice #
2024-08-01	2175

Invoice To	
Vicary Resources Inc	CONTRACTOR OF AMERICAN CONTRACTOR OF THE CONTRAC



Due Date 2024-08-31

Date	Description	Hours/Qty	Rate	Amount
2024-07-08 2024-07-12 2024-07-30	RT02: Repair grease line. RT02: Remove cab decals. RT02: Change engine air filters, fuel filters and oil filter, use 40 L of 15W40. Remove starter, change o-ring and gasket.	0.5 1.75 3.75	105.00 105.00 105.00	52.50 183.75 393.75
2024-07-30	RT02: Remove decals. GST On Sales	0.5	105.00 5.00%	52.50 34.13
				Seller me

I agree to pay on completion of services of machine or on terms satisfactory with you and until paid in full, an express mechanics lien is acknowledged on above machine to secure the amount of parts and repairs thereto. It is understood that Truscott Heavy Equipment Repairs assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, repairs or while field testing.

Received By:

Phone # 1-403-330-7751 truscot@telusplanet.net

852833474


GST/HST No.

Subtotal	\$682.50		
GST	\$34.13		
Total	\$716.63		

6 Blackfoot Court West Lethbridge, Alberta T1K 7P5

Invoice

Date	Invoice #
2024-07-01	2156



Due Date

2024-07-31



Date	Description	Hours/Qty	Rate	Amount
2024-06-05 2024-06-06 2024-06-13	RT02: Repair RR tail light. RT02: Fill engine oil. RT02: Recharge A/C. R134a Freon /lb, DUP-SUVA134A per oz. 40914 Hose engine oil filter U/O rock truck 40976A Hydraulic hose U/O rock truck 2406746A Freight charges on Item 2406746 motor from PTI GST On Sales	0.25 0.25 1.5 70.5 1	105.00 105.00	26.25 26.25 157.50 141.00 168.36 127.64 94.50 37.08

I agree to pay on completion of services of machine or on terms satisfactory with you and until paid in full, an express mechanics lien is acknowledged on above machine to secure the amount of parts and repairs thereto. It is understood that Truscott Heavy Equipment Repairs assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, repairs or while field testing.

Received By:

Phone # 1-403-330-7751 truscot@telusplanet.net

GST/HST No.

852833474

Subtotal	\$741.50
GST	\$37.08
Total	\$778.58