

# KJ's Repair Service Ltd.

35 Years of Service  
RR #1 Ponoka, AB T4J 1R1

Phone 403-783-4729 Fax 403-783-3983

Toll Free 1-877-557-3797

## Invoice

Date	Invoice #
2023-04-14	13613

ED23-1

Invoice To		Toll Free 1-877-557-3797				FD25-1	
Larry's Hot Oil Service		Vehicle		Mileage/Hours		Serial #	
		2005 GMC Top Kick		572074 Km		5F520450	
Parts and Labor				Qty	U/M	Rate	Amount
UNIT # 6							
RS4859 Air Filter				1		65.28	65.28
MA274 Mass Air Flow Sensor				1		261.60	261.60
Freight				1		25.00	25.00
848212-9001S Turbo				1		2,095.50	2,095.50
AP0162 Turbo Install Kit				1		115.16	115.16
Freight for turbo to Edmonton & return				2		34.50	69.00
97303635 Turbo Pipe				1		194.64	194.64
97331137 Gasket				2		6.47	12.94
771864-0001 Harness				1		100.01	100.01
Shop Supplies				1		10.04	10.04
Commercial Vehicle Inspection # CV7749230, Inspect truck for CVIP				2.5		145.00	362.50
Check low power, Check fault codes, Check fuel pressure, Check turbo boost, Disassemble & inspect turbocharger, Remove turbo & send out for repair, Install new turbo, Reassemble engine, Reinstall doghouse, Test drive truck.				19		145.00	2,755.00
GST On Sales						5.00%	303.33
				Subtotal		\$6,066.67	
				Sales Tax		\$303.33	
				Total		\$6,370.00	

GST # 860813278

E-mail kjsrepair@gmail.com



1 4527 48th Avenue  
Lacombe, AB T4L 2C1  
403.782.5405/1.866.780.5405

# Invoice

Job #	Date	Invoice #
4269	2022-12-08	4881

Invoice To	P.O. Number			
Larry's Hot Oil Service	Unit Number	6		
	Year/Make/Model/Plate#	2005/GMC/5500		
	Terms	Due on receipt		
	V.I.N.	1GDE5C3225F520450		
GST/HST No. 821176070	Mileage	561698		
Description	Qty	Rate	Amount	
Road test for loss of power, has codes for FRP low during power enrichment. Found that on test drive cold, truck makes good rail pressure however fall off hotter truck gets, the fuel rail pressure falls off down to about 80 mpa. Balance rates open injectors are all within spec, check return rates on individual banks, 12 ml return on each side. Suspect ump issue. Replace injection pump an drive, truck failed within 10 km. Perform diag again, leads back to pump issue. Swap in know good pressure regulator, no change. Remove discharge pipe from pump, no fuel coming out. Install warranty pump, truck still does not fire, however makes better rail pressure cranking. Perform return test again, now 20 ml per side. Drain fuel tank, fuel smells and looks bad flush system and add new fuel, replace all eight injectors and fuel filter, truck starts and ruins well. Rail pressure and balance rates all good.	43	129.95	5,587.85	
Injection Pump	1	1,434.00	1,434.00	
Gasket	1	35.99	35.99	
Seal	1	7.79	7.79	
Gasket	2	7.75	15.50	
Seal	1	4.29	4.29	
ACD TP3018F - AC Delco Fuel Filter - 6.6L GM	1	102.96	102.96	
Seal	2	7.625	15.25	
LLY Fuel Injector	8	531.375	4,251.00	
Clean Fuel	1	100.00	100.00	
Subtotal			11,554.63	

Please Note: Modifications to your vehicle, in any way, may affect your manufactures factory warranty. Maximum Performance Limited/ MPL Motorsports is not responsible for any warranty conflicts, or damage to original equipment caused by the products which we sell and install. Performance modifications carry no warranty other than what is offered by the manufacturer of the product, and is solely up to them. We will not be involved in any disputes between our customers and their servicing dealers. We are not responsible for any lost of stolen items while your vehicle is in our control. You give us permission to drive your vehicle in a desirable manner for testing and verification of the services which we provide. You grant permission to Maximum Performance Limited/MPL Motorsports to use any pictures they may take of your vehicle to be used for company promotion (i.e. website/posters. In signing this disclaimer you have read and agree to the terms and conditions outlined therein.

**Total**

**Payments/Credits**

**Balance Due**

Signature: \_\_\_\_\_

Phone #

Fax #

E-mail

Web Site

(403)782-5405

(403)782-5430

mplteddy@gmail.com

@mplmotorsports



1 4527 48th Avenue  
Lacombe, AB T4L 2C1  
403.782.5405/1.866.780.5405

# Invoice

Job #	Date	Invoice #
4269	2022-12-08	4881

Invoice To		P.O. Number				
Larry's Hot Oil Service     GST/HST No. 821176070		Unit Number				
		Year/Make/Model/Plate#		2005/GMC/5500		
		Terms		Due on receipt		
		V.I.N.		1GDE5C3225F520450		
		Mileage		561698		
Description				Qty	Rate	Amount
Miscellaneous Supplies And Waste Disposal GST on sales					4.99999%	577.73
					5.00%	606.62

Please Note: Modifications to your vehicle, in any way, may affect your manufactures factory warranty. Maximum Performance Limited/ MPL Motorsports is not responsible for any warranty conflicts, or damage to original equipment caused by the products which we sell and install. Performance modifications carry no warranty other than what is offered by the manufacturer of the product, and is solely up to them. We will not be involved in any disputes between our customers and their servicing dealers. We are not responsible for any lost of stolen items while your vehicle is in our control. You give us permission to drive your vehicle in a desirable manner for testing and verification of the services which we provide. You grant permission to Maximum Performance Limited/MPL Motorsports to use any pictures they may take of your vehicle to be used for company promotion (i.e. website/posters. In signing this disclaimer you have read and agree to the terms and conditions outlined therein.

**Total** \$12,738.98

**Payments/Credits** -\$6,000.00

**Balance Due** \$6,738.98

Signature: \_\_\_\_\_

Phone #

Fax #

E-mail

Web Site

(403)782-5405

(403)782-5430

mplteddy@gmail.com

@mplmotorsports