EJ46-2

Ethos Mechanical Inc.

Site 645 Comp 18 RR 2 Lac La Biche, AB T0A 2C2, CA

ap@ethosmechanical.ca

(780) 798-2691

Bill To

ETHOS MECHANICAL

P:

Invoice:

25895

Date:

7/2/2025

Remit Payment To Site 645 Comp 18 RR 2 Site 645 Comp 18 RR 2 Lac La Biche, AB T0A 2C2, CA

Service Order		Terms Due Date		Authorizer	Customer P	Customer PO	
	7888	COD	7/2/2025	THE CONTRACTOR OF THE CONTRACTOR OF		na naga samban a a a a a a a a a a a a a a a a a a	Jeep
Item	Description				Quantity	Rate	Amount
Complair	nt: CVIP Repair as req	uired.	and the second of the second o	entro y de la companione	a na	enterente especialista de la companio del companio del companio de la companio del la companio de la companio della companio de la companio de la companio della companio de la companio de la companio de la companio della companio d	The second secon
Cause: C	ustomer request						
Labor	REPLACED AXLE	E 1 RH S-CAM AND E 1 LH LIMITING CH E 1 AND 2 RH WHE E 1 RH, AXLE 2 RH E 2 LH HUBCAP, E 2 RH SHOES, E 1 LH DRUM, E 1 AND 2 SHOCKS E 1 RH INNER VALVE E 2 LH DUST COVE	HAIN CLEVIS, EL SEALS, HUBCAP GASKETS, (C)		12.00000	\$145.00	\$1,740.00
Parts	WHEEL SEAL TR	AILER 2110			2.00000	\$75.82977	\$151.66
Parts	HUB CAP GASKE	T .			2.00000	\$1.15992	\$2.32
Parts	2" AMBER LED M	ARKER LIGHT			1.00000	\$5.71261	\$5.71
Parts	2" RED LED MAR	KER LIGHT			2.00000	\$4.71218	\$9.42
Parts	6"-10SPL X 6" AU	TO SLACK ADJUST	TER MERITOR 5/8" CLE	VIS .	2.00000	\$85.00	\$170.00
Parts	4707 BRAKE SHO	DE Q+ 16.5"" X 7""			2.00000	\$94.2435	\$188.49
Parts	BRAKE DRUM CA	AST 16.5 X 7			1.00000	\$130.491	\$130.49
Parts	75W90 GEAR OIL	.W/LS BULK			2.00000	\$12.47929	\$24.96
Parts	S CAM TUBE 1-1/	2"" X 21" SOLID			1.00000	\$43.88847	\$43.89
Parts	1-1/2" ID x 6" OD x	x 1/16" D WASHER	EATON		1.00000	\$4.46569	\$4.47
Parts	1-1/2" ID X 1/4" TH	HICK S CAM SEAL			1.00000	\$3.30577	\$3.31
Parts	1-1/2" ID X 1/16" T	HICK SNAP RING			1.00000	\$0.86994	\$0.87
Parts	1-1/2" ID X 2-1/4"	X 1/16" THICK SHIM	M		5.00000	\$1.15992	\$5.80
Parts	3-3/4" VALVE STE	M STEEL RIM			1.00000	\$2.53733	\$2.54
Parts	MARATHON SHO	CK COMP: 13-1/16	"" EXT: 20-29/64""		2.00000	\$71.37858	\$142.76
Parts	LARGE STEER/TF	RAILER HUBCAP			1.00000	\$6.99	\$6.99

8/22/25, 10:51 AM Invoices

tem				
	Description	Quantity F	Rate	Amoun
Parts	5" DUST SHEILD CLAMP	1.00000 \$16.38	387	\$16.3
Parts	7/16" DOUBLE LINK CLEVIS	1.00000 \$12.13	566	\$12.1
Parts	1/2" AIR TO 3/8" MALE PIPE BRASS CONNECTOR	1.00000 \$4.03	217	\$4.0
arts	MARATHON SHOCK COMP: 13-1/16"" EXT: 20-29/64""	2.00000 \$71.37	858	\$142.7
Parts	1/2" EMERGENCY GLADHAND RED	1.00000 \$5.06	015	\$5.0
Parts	5X1/4X7/8 PWR PLUS DC WHEEL	1.00000 \$4.62	518	\$4.6
Parts	1/4"" X 3/4"" HEX HEAD BOLT GRADE 8 NC ZINC	2.00000 \$0.10	686	\$0.2
arts 5/16X1-1/2 HEX HEAD BOLT GRADE 8 NC ZINC		2.00000 \$0.33	136	\$0.6
Parts	5/16"" LOCK NUT	2.00000 \$0.13	049	\$0.2
Parts	1/4" LOCK NUT	2.00000 \$0.09	832	\$0.2
Parts	TOP PLATE 5TH WHEEL 351	1.00000 \$1,94	7.00	\$1,947.0
		Subt	otal	\$4,767.0
omplain	nt: CVIP 2 AXLE	Antonina (C. antonina). The control in appearance of the State Control in the Control of the Co	etina letera i indes	established to the second of the second
ause: C	ustomer request			
abor	Correction:	1.72000 \$14	5.00	\$249.4
	Chassis / Chassis / INSPECT UNIT - Completed: 6/12/2025	Subt		\$249.4
T-Weiter also graphy and the second		Subt	Otal	Ψ 2 43.4
	+ DEDLACE MELD IN MINO DIN			
omplain	t: REPLACE WELD IN KING PIN			
	ustomer request			
ause: Ci	ustomer request			
ause: Ci	ustomer request n) Correction:	8.00000 \$145	5.00	\$1,160.00
ause: Ci	ustomer request n) Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN	8.00000 \$145	5.00	\$1,160.00
ause: Ci	ustomer request n) Correction:	8.00000 \$145	5.00	\$1,160.0
	ustomer request n) Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN	8.00000 \$145	5.00	\$1,160.00
ause: Ci	ustomer request n) Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA	8.00000 \$145	5.00	\$1,160.00
ause: Ci	ustomer request n) Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING	8.00000 \$145	5.00	\$1,160.00
ause: Co	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025			\$1,160.00
ause: Ci	ustomer request n) Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING	8.00000 \$145 1.00000 \$114.62		
ause: Conspection	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025		909	\$114.63
ause: Conspection	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025 5TH WHEEL KING PIN HITCH 3/8" PLATE	1.00000 \$114.62 Subte	909 otal	\$114.63 \$1,274.63
ause: Conspection abor arts nit: Jeep 004 Peer	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025 5TH WHEEL KING PIN HITCH 3/8" PLATE	1.00000 \$114.62 Subte	909 otal	\$114.63 \$1,274.63 \$3,149.40
ause: Conspection abor arts nit: Jeep 004 Peer	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025 5TH WHEEL KING PIN HITCH 3/8" PLATE	1.00000 \$114.62 Subto	909 otal bor arts	\$114.63 \$1,274.63 \$3,149.40 \$3,141.64
ause: Conspection abor arts nit: Jeep 004 Peer	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025 5TH WHEEL KING PIN HITCH 3/8" PLATE	1.00000 \$114.62 Subte	909 otal bor arts lies	\$114.63 \$1,274.63 \$3,149.40 \$3,141.64 \$314.94
ause: Conspection abor arts nit: Jeep 004 Peer	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025 5TH WHEEL KING PIN HITCH 3/8" PLATE	1.00000 \$114.62 Subte La Pa Shop Suppl Pre-Charge Subte	909 otal bor arts lies otal	\$114.63 \$1,274.63 \$3,149.40 \$3,141.64 \$314.94 \$6,605.98
ause: Conspection abor arts nit: Jeep 004 Peer	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025 5TH WHEEL KING PIN HITCH 3/8" PLATE	1.00000 \$114.62 Subte La Pa Shop Suppl Pre-Charge Subte G (5% of \$6,605.	909 otal bor arts lies otal SST 98)	\$114.63 \$1,274.63 \$3,149.40 \$3,141.64 \$314.94 \$6,605.98 \$330.30
ause: Conspection abor arts nit: Jeep 004 Peer	Correction: Chassis / Frame / - CUT GUSSET WELDED TO KINGPIN - GOUGED OUT KINGPIN - GRIND / PREP AREA - WELD IN NEW KINGPIN - RE WELD IN GUSSET - RE INSTALL AIR LINES - REPLACE AIR LINE FITTING - WELD IN BOLT TO BOLT DOWN FUSE BOX - Completed: 6/18/2025 5TH WHEEL KING PIN HITCH 3/8" PLATE	1.00000 \$114.62 Subte La Pa Shop Suppl Pre-Charge Subte G (5% of \$6,605.	909 otal bor arts lies otal 98)	\$1,160.00 \$1,160.00 \$1,14.63 \$1,274.63 \$3,149.40 \$3,141.64 \$314.94 \$6,605.98 \$330.30 \$6,936.28 \$0.00

8/22/25, 10:51 AM Invoices

GST 828137562RT0001

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature:		
Printed Name:	Date:	