

# EQUIPMENT MAINTENANCE & SUPPLY CO.

PHYSICAL: MAILING:

 1810 Industrial Drive
 1810 Industrial Drive

 RM of Sherwood, SK S4K 0A6
 RM of Sherwood, SK S4K 0A6

 306-550-3599 - Office
 306-522-4033 - Fax

PLEASE REMIT PAYMENT TO: EMSCO Holdings LP 1810 Industrial Drive RM of Sherwood, SK S4K 0A6

> Salesperson 94

www.emsco.ca

Ship To: IN STORE PICKUP

Branch				
REGINA				
Date	Time			Page
09/26/23	15:55	5:36 (O)		01
Account No	Phone No		Inv No	
			WO	5241
Ship Via		urchase Orde	r	
		PT1435		
PST No	G	ST/HST No		

GST/HST Registration: 830341129

Sold To: POTZUS PAVING & MAINTENANCE LTD.

## SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

PT-1435

Truck T800 854417 1XKD040X0EJ967935

2441/ INVDOGONOFO30/322

SEGMENT# 1 5 CUST N/A

04/03/23 04/03/23

MANUEVER TRUCK INTO SHOP

**CORRECTION:** 

Pushed dead truck into shop bay. Removed from shop while waiting for replacement engine. Brought back into shop when engine arrived.

LABOR

1176.00

12000000

SEGMENT TOTAL ==>

1176.00

SEGMENT# 2 5 CUST NA

04/03/23 04/03/23

R&I HOOD

CORRECTION:

Unplugged and marked wiring. Removed hood cables and hood mount hardware. Removed hood with use of forklift crane. For reinstall, used forklift to lift the truck hood then slide the hood towards truck and tilt to line up the mount bolts. Attached hood cables and closed hood to ensure it is lined up correctly. Tightened and torqued hood mount bolts to 100 ft./lbs. Hooked up lights.

LABOR

840.00

12000000

SEGMENT TOTAL ==>

840.00

SEGMENT# 3 5 CUST NA

04/03/23 04/03/23

R&I ENGINE

CORRECTION:

Drained coolant from rad. Removed rad hoses from top and bottom and removed pipes. Removed rad/intercooler as a pack and set aside. Unplugged all harnesses and marked with ties. Removed fuel lines. Removed air lines and set aside.

CONTINUED ON PAGE 02

Thank You For Your Business!

HEAVY EQUIPMENT
RENTAL - SALES - PARTS - SERVICE

Saskatoon, SK

Grande Prairie, AB

Regina, SK



#### EQUIPMENT MAINTENANCE & SUPPLY CO. MAILING:

PHYSICAL: 1810 Industrial Drive

306-550-3599 - Office

1810 Industrial Drive RM of Sherwood, SK S4K 0A6 RM of Sherwood, SK S4K 0A6

306-522-4033 - Fax

PLEASE REMIT PAYMENT TO: **EMSCO Holdings LP** 1810 Industrial Drive RM of Sherwood, SK S4K 0A6

www.emsco.ca

Ship To: IN STORE PICKUP

Sold To: POTZUS PAVING & MAINTENANCE LTD.

<sup>Fax</sup> Gs	T/HST Regist	tration: 830	34112	9
Branch				
REGINA				
Date	Time			Page
09/26/23	15:	55:36	(0)	02
Account No	Phone No			Inv No
				W05241
Ship Via		Purchase	Order	
		PT143	5	
PST No		GST/HST	No	
		L	Sale	sperson
				94

#### **SERVICE INVOICE**

STK#/FLEET#

HRS PIN/EIN WARRANTY DATE

HRS

PT-1435

Truck T800

1XKD040X0EJ967935 854417

Removed A/C lines. Installed brackets and hooked up hoist. Used a 2 inch strap and jack to support transmission. Opened up inspection hole on transmission. Removed clutch linkage. Removed transmission mount bolts. Turned clutch arm to free engine from transmission. Removed from mount hanger. Lifted engine and slowly moved forward and out. Set engine on stands for disassembly. Used pressure washer to wash truck frame and wires prior to reinstalling the engine. Attached crane to engine by using spreader bar and lifting links to lift and tilt engine. Transmission was tilted and made it difficult to line up with engine. Used a transmission jack with a bottle jack to lift and tilt the transmission, took some time but ws able to get engine to seal perfectly with transmission. Applied Loctite and torqued bolts. Installed engine mounting bolts and torqued. Installed fan clutch and radiator pack. Installed all engine accessories and wiring. Ensured everything was correctly torqued. Filled engine with 42L 5W40. Installed A/C hose and charged system. Installed coolant fittings and filled coolant system. Hooked up JPRO to ECM and started truck. There were no codes. Engine oil pressure was recorded at 40 PSI. Took truck for test drive, no faults found.

11.14 ADAPTER 1 N 11.14 AP3549 149.85 49.95 P/S HOSE 3 N FC35016 69.00 17.25 FREIGHT FRT 3.28 2 1.64 06 ORFS CAP FS0304-C-06 6.70 3/4- 1 1/16 HC 2 3.35 PET10 6.64 2 3.32 PET8 HOSE CLAMP 2.52 5.04 2 N PHS16 1-1/2 OD CLAMP CONTINUED ON PAGE 03

Thank You For Your Business!

**HEAVY EQUIPMENT** RENTAL - SALES - PARTS - SERVICE

Saskatoon, SK

Grande Prairie, AB



## EQUIPMENT MAINTENANCE & SUPPLY CO.

PHYSICAL:

**MAILING:** 

1810 Industrial Drive 1810 Industrial Drive RM of Sherwood, SK S4K 0A6 RM of Sherwood, SK S4K 0A6 306-550-3599 - Office

PLEASE REMIT PAYMENT TO: **EMSCO Holdings LP** 1810 Industrial Drive RM of Sherwood, SK S4K 0A6

www.emsco.ca

Ship To: IN STORE PICKUP

306-522-4033 - Fax

GST/HST Registration: 830341129

Branch		
REGINA		
Date	Time	Page
09/26/23	15:55:36 (0	) 03
Account No	Phone No	Inv No
		W05241
Ship Via	Purchase Ord	er
	PT1435	
PST No	GST/HST No	
	S	alesperson
		94

Sold To: POTZUS PAVING & MAINTENANCE LTD.

SERVICE INVOICE					
STK#/FLEET#	HRS PIN/EIN	WARRANTY DATE HI	RS		
PT-1435 Truck	854417 1XKD040X0EJ	967935			
T800					
V38-1090	FITTING-3/4	4 N 114.75	459.00		
0304-C-04	04 JIC CAP NUT	1 .82	. 82		
117197HB	HOSE BUILD	1 N 137.05	137.05		
117371НВ	HOSE BUILD	1 N 139.60	139.60		
14684A	4×18NPT COMP	1 N 6.06	6.06		
209436	5W40 1L SYN	42 9.21	386.82		
227819-960	PRMX 50/50 1L	56 5.39	301.84		
3600008	HEATER CORD	1 N 52.51	52.51		
4988280	GASKET	1 N 7.50	7.50		
509827	AC LINE HB	1 188.60	188.60		
5526-075	3/4 heater hose	3 9.75	29.25		
		PARTS	1960.70		
		LABOR	7812.00		
12000000		SEGMENT TOTAL ==>	9772.70		
SEGMENT# 4 5 CUST NA	04/03/23 04/05/23				
SUPPLY EXCHANGE ENGINE					
CORRECTION:					
Supplied new exchange, pre					
FRT	FREIGHT	2 970.00	1940.00		
TTD2350	ENGINE ASSY.	1 N 56250.00	56250.00		
		PARTS	58190.00		
12000000		SEGMENT TOTAL ==>	58190.00		

SEGMENT# 5 5 CUST NA

04/03/23 04/06/23

DISASSEMBLE & DIAGNOSE ENGINE FAILURE

CORRECTION:

Removed valve cover, fuel lines and hoses. Removed front

components from engine including alternator, a/c

compressor, pulleys, fan clutch and fan. Removed front

CONTINUED ON PAGE 04

Thank You For Your Business!

**HEAVY EQUIPMENT** RENTAL - SALES - PARTS - SERVICE

#### EQUIPMENT MAINTENANCE & SUPPLY CO. **MAILING:**

PHYSICAL: 1810 Industrial Drive

306-550-3599 - Office

1810 Industrial Drive RM of Sherwood, SK S4K 0A6 RM of Sherwood, SK S4K 0A6 PLEASE REMIT PAYMENT TO: **EMSCO Holdings LP** 1810 Industrial Drive RM of Sherwood, SK S4K 0A6

www.emsco.ca

Ship To: IN STORE PICKUP

306-522-4033 - Fax GST/HST Registration: 830341129

Time	Page		
15:55:36 (	0) 04		
Phone No	Inv No		
	W05241		
Purchase C	rder		
PT1435			
GST/HST N	GST/HST No		
	Salesperson		
	94		
	15:55:36 ( Phone No  Purchase O PT1435		

Sold To: POTZUS PAVING & MAINTENANCE LTD.

#### SERVICE INVOICE

STK#/FLEET#

PT-1435

Truck

PIN/EIN HRS

WARRANTY DATE

HRS

1XKD040X0EJ967935 854417

T800

cover to access cam for head removal. Built a tool to remove the cam gear. Removed bolts and lifted out rocker shaft assemblies. Marked and set aside. Removed jakes. Slid camshaft out of head. Removed brackets from head/front housing. Removed all head bolts and lifted off cylinder head. Inspected head. Looked inside cylinders to observe damage. Set head aside on table. Removed 3 crank mains to inspect damage. Removed all rod caps. Removed all piston/rod assemblies for inspection. Removed #4 sleeve. \*\*\*\*this engine had been taken apart prior to arriving at EMSCO, lots of rod bolts loose as well as mains. Engine oil pan was removed prior to arrival. \*\*\*\* All parts removed were set on bench for further inspection and failure analysis. Observed all failed parts on bench. Went through oil gallery routing and oil passages. Inspected damage on each rod bearing as well as main bearings. Inspected damaged sleeve and piston. From what was observed, believe a wrist pin snap ring was installed incorrectly and the pin slowly worked its way out causing catastrophic damage. Insurance company's theory was when 2nd oil change was performed dirt was introduced into the new engine oil filter on the clean oil side causing damage leading to wrist pin seizure. Inspected turbo and it is fine, if dirt was introduced it would have caused the turbo to fail or be damaged.

LABOR

2940.00 2940.00

12000000

SEGMENT# 6 5 CUST NA REPAIR EXHAUST SYSTEM SEGMENT TOTAL ==>

04/03/23 09/26/23

CONTINUED ON PAGE 05

Thank You For Your Business!

**HEAVY EQUIPMENT** RENTAL - SALES - PARTS - SERVICE

Saskatoon, SK

Grande Prairie, AB



## EQUIPMENT MAINTENANCE & SUPPLY CO.

PHYSICAL:

**MAILING:** 

1810 Industrial Drive 1810 Industrial Drive RM of Sherwood, SK S4K 0A6 RM of Sherwood, SK S4K 0A6 306-550-3599 - Office

PLEASE REMIT PAYMENT TO: **EMSCO Holdings LP** 1810 Industrial Drive RM of Sherwood, SK S4K 0A6

> Salesperson 94

www.emsco.ca

306-522-4033 - Fax

GST/HST Registration: 830341129

Branch Ship To: IN STORE PICKUP REGINA Date Time Page 09/26/23 15:55:36 (O) 05 Account No Phone No Inv No W05241 Ship Via Purchase Order Sold To: POTZUS PAVING & MAINTENANCE LTD. PT1435 PST No GST/HST No

**SERVICE INVOICE** 

STK#/FLEET#	:	HRS	PIN/EIN	WAR	RANTY DATE	HRS	
PT-1435	Truck	854417	1XKD040X0E	J967935			
	T800						
CORRECTION	L <u>:</u>						
Exhaust do	wnpipe and	bellows damaged.	Quote repai	rs. Order	ed		
		new exhaust compon					
M66-6647		PIPE-EX	HAUST	1 N	1383.75		1383.75
M66-9393-0	320	PIPE-BE	LLOWS	1 N	843.75		843.75
286637		GASKET		1 N	37.13		37.13
2866636		GASKET		3 N	37.13		111.39
900012		CLAMP-V	BAND	3 N	23.63		70.89
900013		CLAMP-V	BAND	1 N	24.64		24.64
					PARTS		2471.55
					LABOR		336.00
12000000				SEGMEN	T TOTAL==>		2807.55

****	WORK	ORDER	TOTALS *****
PARTS			62622.25
LABOR			13104.00
SHOP SUPPLIES			917.28
SUB TOTAL==>			76643.53
GST# 830341129RT001			3832.17
SK PST @ 6.00%			4598.63
AMOUNT DUE (CAD)			85074.33

Thank You For Your Business!

**HEAVY EQUIPMENT** RENTAL - SALES - PARTS - SERVICE