

Sold to:

Customer Acct # 00-001476

Estate of Don Paulow
 Box 457
 Hafford SK S0J 1A0

Part Number	Description	Quantity	Unit Cost	Total
	2002 International			
Labour	Labour	1.50	190.00	285.00
	Check over made list frame getting thin under 5th wheel not doing the repairs			
Labour	Labour	2.00	190.00	380.00
	Abs light on requested to look into it LH rear wheel sensor gap to large pulled wheels cleaned tone ring pushed sensor in installed wheels torqued wheel nuts, cleaned connection at LH front steer wheel took for test drive light stayed out			

Retorque wheel nuts at 100 km

Thank You!
 We appreciate your business!

Sub Total	\$665.00
Shop Supplies	\$45.00
PST 6%	\$42.60
GST 5%	\$35.50
Total	\$788.10
Paid	\$0.00
Balance	\$788.10