

Print Date: April 09, 2018 2:27 pm

VIN	1FVABTBV61HH66463
Vehicle Make	Freightliner
Model	
Model Year	2001

Vehicle Components				
Component	Description	Serial Number	Software Version	Network
Engine	Cummins 5.9L ISB	46004514	00000000 02028357 0704B6E8 EN	J1587 (Low)
Instrument Cluster	Freightliner ICU3	N/A	U.r.1.1.0	J1587 (Low)
Brakes	WABCO D Basic(12V) 4S/4M	411060	B171	J1587 (Low)

Vehicle Key Data Points			
Parameter Description	Value	Parameter Description	Value
Battery Potential	12.40 volts	Coolant Level	Not Available
Engine Oil Level	Not Available	Odometer	20,140.60 km
Total Avg Fuel Econ	1.90 km/L	Total Engine Hrs	985.50 hrs
Road Speed Limit	145.00 km/hr	Cruise Spd Limit	145.00 km/hr
DPF Soot Level	Not Available	DPF Derate	Not Available
Malfunction Indicator Lamp	Off	Red Stop Lamp	Off
Amber Warning Lamp	On	Protect Lamp	Off
Parking Brake Switch	On	DPF Lamp Command	Not Available
Exhaust System High Temperature	Not Available	ABS Control Status	Not Available
ABS Control Status, Trailer	Not Available	Engine Speed	0 rpm

Vehicle Issues

2 Active Fault(s) Present

Faults					
Status	Component	Description	Lookup Code	FMI	Count
Active	Brakes	Warning Light Open	SID 23	5	N/A
Active	Engine	Supply voltage fell below (+) 6.2 VDC for a fraction of a second, or the electronic control module (ECM) was not allowed to power down correctly (retain battery voltage for 30 seconds after key-off). (Flash Code 434)	SID 251	2	N/A
Inactive	Brakes	SAE - Wheel Sensor ABS Axle 1 Left - Abnormal frequency, pulse width, or period	SID 1	8	N/A



EVERY TRUCK. EVERY TIME.™

DIAGNOSTIC REPORT

Print Date: April 09, 2018 2:27 pm

Status	Component	Description	Lookup Code	FMI	Count
Inactive	Brakes	Right Front Wheel Sensor Speed Drop Out	SID 2	10	2
Inactive	Brakes	Diagonal 1 or 2 Over Voltage	SID 251	3	1
Inactive	Brakes	Excessive Slip / Dynamometer	SID 254	8	N/A
Inactive	Brakes	Left Rear Wheel Sensor Air Gap Too Large	SID 3	1	N/A
Inactive	Brakes	Left Rear Wheel Sensor Speed Drop Out	SID 3	10	N/A