

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

Sold To: CIMMARON VENTURES INC

Ship To: CIMMARON VENTURES INC

SERVICE INVOICE #
Sr169326
DATE
06-10-22

REPRINT CUSTOMER INVOICE

Year	Make / Model	VIN		License	Mileage	Unit/Stock
2015	Peterbilt / 389	1XPXDP9X9F	0253345	K56098	1044570K	614
Delivery Mileage	Delivery Date	Engine Hours	Engine Model / Serial #		Transmission Model/Serial #	
	06-20-14	17601.0	MX-13	3 / Y045218	RTLO18918E	3 / S1064724

	Memo	P.O. Number	Open Date / Time	Complete	Service Writer
	Darcy Chalmers (780) 818-1111	614	04-27-22 / 08:43AM	06-08-22	CLC*AEB
1	Tax ID Date: 01-07-98 COVID Default Variation SA ADVISED DISINFECTEDTECH #	Tax ID: 894	948090RT _TOUCH POINTS HAV	E BEEN	
	TOTAL LABOR		-	0.00	

2 LOYALTY DISCOUNT IF APPLICABLE Default Variation LOYALTY DISCOUNT IF APPLICABLE

TOTAL LOYALTY DISC

-52.00

Qty	Part Number			Description	List	Unit	Extended	
-1	YALTY			Y223235	40.00	40.00	-40.00	
		\$40.00	Off	- EATON CLUTCH	ES			
-1	YALTY			N22JUN3726	12.00	12.00	-12.00	
		\$12.00	Off	- DOT / CVI IN:	SPECTION			

- 3 CUSTOMER CONFIRMED ENGINE IS NOT DELETED AND PROGRAMMING HAS NOT BEEN ALTERED FROM FACTORY SPECIFICATIONS Default Variation
- LEVEL TWO OVERHAUL QUOTE Loadered unit into the engine shop, drained fluids. Removed radiator and mounts, lower rad hose. Evacuate the refrigerant and capped lines. Disconnected starter cables, clutch, and lower bell housing bolts. Disconnected OEM harnesses, block heater cord, coolant hoses. Removed engine from the chassis, drained oil and dismantled the drivers side and passenger side of engine dismantled the top end. Removed the head bolts, lifted cylinder head off and set onto blocks on bench. Removed the head gasket, inspected deck surface. Continued onto dismantling the exhaust side of engine for engine stand prep. Dismantled engine further, bolted it onto engine stand. Removed turbo and actuator complete, kept all lines and hoses connected. Removed oil module complete. Tapped holes for engine stand mount. Mounted and used crane to lift engine into place. Rolled engine over, removed flywheel and hoses, rear engine mounts and rear seal. Started to remove rear structure removed oil pan, broke numerous bolts. Had to pry the lower aluminum plate off, it had cracked before this repair, due to massive amounts of corrosion, removed all pieces. Split the rear structure off the engine, the oil pan fused to it. Removed pistons, measure liners and they were sitting at 0.10mm. Removed liners, used the stone on the deck surface, cut six liner shelfs, dry fit loners, checked protrusion, in spec. Lubed liner orings and installed. Flipped engine



P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780,539,9991 TF: 888,538,5414 F: 780,539,9902

www.stahlpeterbilt.com

Sold To: CIMMARON VENTURES INC

Ship To: CIMMARON VENTURES INC

SERVICE INVOICE #

sr169326

DATE 06-10-22

REPRINT CUSTOMER INVOICE

Year	Make / Model	VIN		License	Mileage	Unit/Stock
2015	Peterbilt / 389	1XPXDP9X9FI	D253345	K56098	1044570K	614
Delivery Mileage	Delivery Date	Engine Hours	Engine M	odel / Serial #	Transmission	Model/Serial #
	06-20-14	17601.0	MX-13	/ Y045218	RTLO18918E	3 / S1064724

Memo	P.O. Number	Open Date / Time	Complete	Service Writer
Darcy Chalmers (780) 818-1111	614	04-27-22 / 08:43AM	06-08-22	CLC*AEB

Tax ID Date: 01-07-98

Tax ID: 894948090RT

and removed front horseshoe housing, cleaned surfaces, installed new main bearings. Reinstalled the rear structure using the updated sealant, reinstalled it and torqued up. Installed new rear seal. Installed machined flywheel and used new pilot bearing. Torqued it up. Reinstalled the front engine structure and torqued hardware, installed a new front crank seal. And installed the damper and pulley, torqued the hardware. Replaced the pistons with the new ones, installed into engine and torqued it up to spec. Removed engine off the stand and replaced the piston cooling nozzles, resealed the oil module and replaced the oil cooler. Unit is completely flushed and clean with engine oil. Resealed the water module with new gaskets, replaced the water pump and installed the new thermostat housing. Installed onto the engine and torqued hardware. Reinstalled engine into unit, bolted up and torqued up the new hardware. Hooked up hoses, tied up lines. Installed cylinder head onto the block with new injectors and lines installed. Used the updated head gasket. Bolted down with the new head bolts and torqued to Paccar specs. Installed the new push rods and top end, torqued down, and set valves. Installed the resealed valve cover. Installed EGR cooler mount bracket and the manifold, changed over turbo the new and resealed every single oring on all lines. Installed the new turbo and bolted up and hooked up. Replaced any electrical connector that needed it. Installed new push rods, set the valves. Hooked up to unit, had battery charger set on medium for a day to charge up batteries. Changed over injector trim codes, had to remove the truck GPS tracker plug to get proper connection. Reinstalled the train horn, vacuumed and charged ac system. Bolted it up, primed the fuel system and filled oil ran unit and topped up fluids, regened unit successfully. DPF had been recently cleaned, temps were proper, soot load was low. Regen finished successfully, road tested unit. Washed the engine compartment off, returned all parts for cores. Double checked fluid levels. Resealed engine unit pumps. Used new orings and new hold down bolts that came in the kit. Used all new fuel lines, all came in the kit. Remove and replace coolant tube to turbo run unit to temp, check for leaks, top off coolant.

TOTAL LABOR 16,915.50 TOTAL PARTS 38,526.20

Qty Pa	art Number	Description	List	Unit	Extended
6 19	982746PE	CYLINDER	2,022.00		
1 22	299991PE	OVERHAUL	12,524.36	7,625.91	7,625.91
1 23	312234PE	GASKET-CY	1,858.23	1,131.45	1,131.45



P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780,715.3627 TF: 866,715,5111 F: 780,715,3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

CIMMARON VENTURES INC Sold To:

CIMMARON VENTURES INC Ship To:

SERVICE INVOICE # sr169326 DATE

06-10-22

REPRINT **CUSTOMER INVOICE**

Year	Make / Model	VIN		License	Mileage	Unit/Stock
2015	Peterbilt / 389	1XPXDP9X9FD	0253345	K56098	1044570K	614
Delivery Mileage	Delivery Date	Engine Hours	Engine Mo	del / Serial #	Transmission	Model/Serial #
	06-20-14	17601.0	MX-13 /	Y045218	RTLO18918E	3 / S1064724

Memo			P.O. Number	Open Date / Tin		nplete	Service Write
Darcy Chalmers (78			614	04-27-22 / 08:43	3AM 06-0	08-22	CLC*AEB
1 21244FFDDV	Tax I	D Date: 01-07-98	Tax ID: 89494		4 002 62		
1 2134455PRX		TURBOCHAR		4,982.62			
2 1930520PE		PIPE-FUEL	427.92	213.96	427.92		
4 2047593PE		PIPE-FUEL	845.92	211.48	845.92		
2 2047594PE		PIPE-FUEL	422.96	211.48	422.96		
2 15ABF4		10W30 OIL	252.52	126.26	252.52		
2 15ABF4&		EHC	3.60	1.80	3.60		
2 15ABF6		10W30 OIL	55.46	27.73	55.46		
2 15ABF6&		EHC	1.00	0.50	1.00		
100 CT03316		TIE-CABLE	17.00				
100 CT05512		TIE-CABLE	87.00				
1 105FBC		GREASE-MO	16.07	9.10	9.10		
18 2135209PE		FLANGE BO	64.80	3.60	64.80		
1 1844253PE		GASKET-EX	29.09	17.84	17.84		
1 1844896PE		GASKET-EX	29.09	17.84	17.84		
1 1886111PE		GASKET-EX	25.25	14.31	14.31		
1 1923003PE		GASKET	24.00	13.60	13.60		
	B/O RELEASE		CONFIRM #				
6 1972591PEX		INJECTOR,	7	1,194.67			
1 1922163PEX		EGR COOLE	5	2,407.78			
1 AP2384		ADAPTER-S	7.29	4.71	4.71		
1 AP2423		ADAPTER-S	6.87	4.44	4.44		
1 1857669PE		SET-GASKE	24.78	15.69	15.69		
4 R134A-1		R134A /LB	99.60	24.90	99.60		
1 0963981PE		FRAME-FIX	1,103.25	601.05	601.05		
1 1781714PE		GASKET-GE	66.36	37.60	37.60		
1 1876189PE		RING-SEAL	233.57	132.35	132.35		
1 1876190PE		SEALRING-	233.57	132.35	132.35		
1 82194		SEALANT	20.70	11.73	11.73		
1 2146959PE		OIL COOLE	1,501.64	818.08	818.08		
1 1936325PE		SCREW CAP	284.36	161.13	161.13		
1 1643075PE		GASKET SE	68.84	39.01	39.01		
15 1313115PE		BOLT-FLAN	25.80	1.72	25.80		
1 VH11600		KIT- O-RI	7.22	4.09	4.09		
1 2144945PE		HARNESS-I	383.39	208.88	208.88		
1 2126981PE		SENSOR-TU	212.94	120.67	120.67		
1 1893478PE		SENSOR-TE	328.62	179.03	179.03		
1 P20-1258-110	041020G	CONNECTOR	90.54	49.50	49.50		
4 1974191PE		O-RING-12	20.08	5.02	20.08		
1 1949630PE		VALVE & S	73.68	45.44	45.44		
1 1857668PE		PUMP-MANU	68.28	42.11	42.11		
1 2003641PE		SENSOR, E	521.72	284.22	284.22		
1 1313117PE		BOLT-FLAN	0.99	0.56	0.56		



P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

CIMMARON VENTURES INC Sold To:

CIMMARON VENTURES INC Ship To:

SERVICE INVOICE #

sr169326 DATE

06-10-22

REPRINT **CUSTOMER INVOICE**

Year	Make / Model	VIN		License	Mileage	Unit/Stock
2015	Peterbilt / 389	1XPXDP9X9FD	253345	K56098	1044570K	614
Delivery Mileage	Delivery Date	Engine Hours	Engine M	lodel / Serial #	Transmission	Model/Serial #
The state of the s	06-20-14	17601.0	MX-13	/Y045218	RTLO18918E	3 / S1064724

		Memo	0		P.O. Number	Open Date / Tir		Complete	Service Writer
A street in		Darcy Chalmers (7	80) 818-1111		614	04-27-22 / 08:4	3AM C	06-08-22	CLC*AEB
a the			Tax	ID Date: 01-07-98	Tax ID: 8949	48090RT			
	1	1313115PE		BOLT-FLAN	3.03	1.72	1.72		
	2	0331328PE		RING-COPP	2.70	1.35	2.70		
	2	2035973PE		GASKET-EX	62.86	31.43	62.86		
	1	1786103PE		GASKET-AI	34.79	19.71	19.71		
	2	1976451PE		V-CLAMP,	109.46	54.73	109.46		
	1	1976452PE		V-CLAMP,	97.41	55.20	55.20		
	1	D16-1006A		CLAMP-VBA	36.08	20.44	20.44		
	52	227811-800		A/F 50/50	183.04	3.52	183.04		
			B/O RELEASE	EPE107333	CONFIRM #	187034			
	1	2190203PEX		CYLINDER	11,239.83	6,601.04	6,601.04		
	1	1982775PE		O-RING, 1	6.75	3.83	3.83		
	3	EC7501		COOLANT-T	29.97	9.99	29.97		
-	25	CT05512		TIE-CABLE	21.75	0.87	21.75		
	1	1974735PE		PIPE-COOL	656.39	357.59	357.59		
	10	CTD6511		TIE-CABLE	48.00	4.80	48.00		
	10	CT6713R		TIE-CABLE	13.00	1.30	13.00		
	1	1959440PE		PIPE-COOL	247.43	131.80	131.80		
	1	1945913PE		PIPE-COOL	254.73	135.69	135.69		
	1	1982773PE		O-RING, 9	6.86	3.88	3.88		
	1	1977943PE		O-RING 9.	9.83	5.57	5.57		
	1	1974190PE		O-RING-10	9.27	5.25	5.25		
	1	1974189PE		O-RING-9.	9.15	5.19	5.19		
	2	1738898PE		BRACKET	81.74	40.87	81.74		

5 REPLACE BLOCK HEATER CORD AND COOLANT HEATER ELEMENT Replaced the block heater cord while the engine is out. Replaced the coolant heater as well.

> TOTAL LABOR TOTAL PARTS

187.95 215.94

Qty	Part Number	Description	List	Unit	Extended
1	351-0474	BLOCK HEA	71.75	10.66	40.66
1	860-8059	Y-CORD-(8 2	92.13	75.28	175.28

6 SPLIT AND WASH RADIATOR

Washed radiator while it was out, installed. Removed air to air and washed the rad core in the truck.

TOTAL LABOR

469.88

REPLACED MEGA FUSE AND HOLDER IN BATTERY BOX AND SERVICE BATTERIES AND



P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

Sold To: CIMMARON VENTURES INC Ship To: CIMMARON VENTURES INC

SERVICE INVOICE #

sr169326

DATE 06-10-22

REPRINT CUSTOMER INVOICE

Year	Make / Model	VIN		License	Mileage	Unit/Stock
2015	Peterbilt / 389	1XPXDP9X9FD	253345	K56098	1044570K	614
Delivery Mileage	Delivery Date	Engine Hours Engin		odel / Serial #	Transmission Model/Serial #	
	06-20-14	17601.0	MX-13	/Y045218	RTLO18918E	3 / S1064724

Memo	P.O. Number	Open Date / Time	Complete	Service Writer
Darcy Chalmers (780) 818-1111	614	04-27-22 / 08:43AM	06-08-22	CLC*AEB

Removed the battery ends, serviced the connections. Replaced the mega fuse and holder to avoid any future issues from happening. Lots of corrosion.

> TOTAL LABOR 281.93 104.90 TOTAL PARTS

Description List Unit Extended Qty Part Number HOLDER-FU 185.12 104.90 104.90 1 P27-6180-100

8 REPLACE ENGINE AIR FILTERS

Remove air filter housing lids, swing mirror out of the way and replace filters, clean debris from bottom of filter housing, re-assemble and put mirrors back as they were.

> TOTAL LABOR TOTAL PARTS

187.95 341.64

Description List Unit Extended Oty Part Number

PACCAR 15 341.64 170.82 2 X011623

9 CVIP INSPECTION SPECIAL

DOES NOT INCLUDE WHEEL PULL

CVIP

Performed safety as requested.

SERVICE SPECIAL

199.99

10 PERFORM WHEEL PULL

Performed wheel pull for brake inspection as required.

TOTAL LABOR

563.85

11 #1 DRIVE AXLE QUICK RELEASE VALVE LEAKS WHEN BRAKES RELEASED Remove and replace valve, test operation, no leaks, all okay.

TOTAL LABOR

187.95

TOTAL PARTS 120.52

Qty Part Number Description List Unit Extended 1 800348BXW VALVE-QUI 212.69 120.52 120.52



P: 780,483,6666 TF: 800,252,7981 F: 780,484,2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

Sold To: CIMMARON VENTURES INC Ship To: CIMMARON VENTURES INC **SERVICE INVOICE #**

sr169326

DATE

06-10-22

REPRINT **CUSTOMER INVOICE**

Year	Make / Model	VIN		License	Mileage	Unit/Stock
2015	Peterbilt / 389	1XPXDP9X9F	0253345	K56098	1044570K	614
Delivery Mileage	Delivery Date	Engine Hours	Engine N	lodel / Serial #	Transmission I	Model/Serial #
	06-20-14	17601.0	MX-13	3 / Y045218	RTLO18918E	3 / S1064724

Memo	P.O. Number	Open Date / Time	Complete	Service Writer
Darcy Chalmers (780) 818-1111	614	04-27-22 / 08:43AM	06-08-22	CLC*AEB

Tax ID Date: 01-07-98 Tax ID: 894948090RT

12 3 MAXI POTS MISSING PLUGS

Replace missing brake chamber plugs.

TOTAL LABOR TOTAL PARTS 56.39

6.90

Qty	Part Number	Description	List	Unit	Extended
3	RTP2M1D	STUD-RELE	6.90	2.30	6.90

13 RIGHT SIDE SIGNAL/MARKER LIGHT IN MOOSE BUMPER OUT Trouble shot issue, found a ground by the frame at the hood hinge broken. Repaired that ground. Also found a power wire to the connector had corrosion. Repaired wire.

TOTAL LABOR

TOTAL PARTS

187.95

3.28

Qty	Part Number	Description	List	Unit	Extended
2	2 1-1962JDSP 2 CT03316 2 CT05512	CONNECTOR TIE-CABLE TIE-CABLE	1.20 0.34 1.74	0.60 0.17 0.87	1.20 0.34 1.74
	ICENSE PLATE LIGHT OUT	345.0			93 98

TOTAL LABOR

93.98

15 SERVICE SIDE GLAD HAND SEAL TORN Replaced seal as required. TOTAL LABOR

TOTAL PARTS

56.39

1.11

Unit Extended Oty Part Number Description List 1.11 1 248579BXW SEAL-GLAD 1.97 1.11

16 NO FIRE EXTINGUISHER / HAZARD KIT

17 #2 DRIVE AXLE RIGHT SIDE OUTER TIRE VALVE STEM LEAKING - LEFT SIDE OUTER TIRE HAS A NAIL IN IT - SUBLET



P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780,715,3627 TF: 866,715,5111 F: 780,715,3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

Ship To:

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

CIMMARON VENTURES INC Sold To:

SERVICE INVOICE# sr169326 DATE 06-10-22

> REPRINT **CUSTOMER INVOICE**

Year	Make / Model	VIN		License	Mileage	Unit/Stock
2015	Peterbilt / 389	1XPXDP9X9FD	0253345	K56098	1044570K	614
Delivery Mileage	Delivery Date	Engine Hours	Engine Mo	odel / Serial #	Transmission	Model/Serial #
	06-20-14	17601.0	MX-13	/ Y045218	RTLO18918E	3 / S1064724

Memo	P.O. Number	Open Date / Time	Complete	Service Writer
Darcy Chalmers (780) 818-1111	614	04-27-22 / 08:43AM	06-08-22	CLC*AEB

Tax ID Date: 01-07-98

Tax ID: 894948090RT

CIMMARON VENTURES INC

18 REPLACE CLUTCH WHILE ENGINE REMOVED, MACHINE FLYWHEEL Replaced clutch, machined flywheel, installed clutch installation kit as required.

TOTAL LABOR

563.85

TOTAL PARTS 1,651.37

Qty	Part Number	Description	List	Unit	Extended	
1	308925-25	CLUT EP 1	2,679.95	1,100.00	1,100.00	
1	K2468	KIT-CLUTC	539.85	317.04	317.04	
1	06-01093	SHAFT-CLU	135.66	76.87	76.87	
1	CS106C1498	SHAFT-CRO	21.72	12.31	12.31	
8	HWC04705	BOLT-HEX	14.24	1.78	14.24	
1	HWC00063	NUT-HEX S	7.44	4.22	4.22	
1	AP3380	ADAPTER-S	4.04	2.61	2.61	
12	W34-1166	BOLT - ST	124.08	10.34	124.08	

G.S.T. - REG. NO. GST# 870331105 RT0005 % OF 60,873.42 = 3,043.67

	CUST MECH LBR-TRK	19,953.56
	P&A-TRK RO-MECH	40,971.86
	Discounts	-52.00
	G.S.T. GST# 870331105	3,043.67
9350	CHARGE	63,917.09

Terms and Conditions:

Repair Acknowledgment: I the undersigned owner or representative, acknowledge the indebtedness related to the regain and service work listed above, along with the purchase and installation of any necessary parts and materials. I confirm I have the authority to bind the owner.

Payment Terms: Payment for repairs are due upon receipt of unit unless charged to customer's account. Payment of

account is due in full by the 15th day of the month following the statement date. Unpaid balances will be charged interest of

2% per month compounded monthly (26.82% per annum.).
Garage Keepers Lien: By signing below you acknowledge and agree that the vehicle described above is subject to a Garage Keepers' Lien in favor of Stahl Peterbilt Inc., for the full dollar amount of repairs, parts, accessories, materials, and services provided by Stahl Peterbilt Inc., as permitted under the Garage Keepers' Lien Act (Alberta), as amended from time to time.

anufacturer for any portion of this repair that Warranty Considerations: Stahl Peterbilt Inc. will submit a warterly gaim to the m is designated for warranty considerations. If the manufacturer rejects the claim or a portion of the claim, the owner shall pay that portion which is rejected in accordance with the Payment Terms set out above.

FINANCE FER

Warranty Limitation: Subject to the requirement below, all repair and services carry a 30 day warranty from the date Stahl

when most advise Stahl Peterbilt Inc. of any warranty from the date Stahl when most advise Stahl Peterbilt Inc. of any warranty claim within 5 days of the failure synterials, and other items used in completing the repair and service work may be such that work warrants in or such items are entirely outside the control of Stahl items are entirely outside the control of Stahl items are such as the control of Peterbilt Inc. completed the work The date. Certain Parts, products cessories quality and workmanship of such items are entirely outside the control of Stahl
warranties, whether expressed, implied, statutory, or otherwise, including any manufactured and supplied Peterbilt Inc. and Stahl Ht.Inc. mak purpose with respect to such items. warranty of merchantab

pilt Inc. is not responsible for loss or damage to the vehicle, or to articles Responsibility for Vel left in vehicles, in case

Print Name:	Authorized Signature:	Date:	
Drivers License:			