

Coppertop Truck Repair

16638 110 ave
Edmonton, AB T5P 1G9, CA
accounts@coppertoptruck.com
780-668-9068

Invoice: **32395**

Date: **10/9**
/2025

Bill To

Ritchie Bros Auctioneer
1500 Sparrow Drive
Nisku, AB T9E 8H6, CA
P: (780) 955-4609

Remit Payment To

Bay #1
16638 110 ave
Edmonton, AB T5P 1G9, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
15930	Net 30	11/8/2025	Sarah Kirtzinger	M0415941	Burchak, Kirk	P05/1

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: no start

Checked and performed some swapnostics on all ignition, starter, transmission controller fuses circuit breakers and relays. Couldn't find anything failed. The transmission controller should be showing an N, as in neutral, see pics. Plugged in computer to scan as it said "transmission controller failed communication to ECM" tested power from fuse to transmission controller, power present. Possibility the transmission controller is faulty, possible wiring harness issues.

Cause: Customer request

Labor	Correction: Chassis / Chassis / Drove to the site. Located unit found batteries stone dead, boost unit and unit starts right up without issue, trans shifter showing neutral on screen, no codes or issues, went to get computer to hook up to and by the time got back to the unit, trans shifter screen cut out to cat eyes and could not get computer to hook up. Locate TCU, removed TCU, and tested power and ground inputs with the headlight; all checks out good. Will need to come back with test TCU and test. Installed test TCU, and the unit is fine; it needs a new TCU. Picked up the new TCU, drove back to the site, and installed the TCU test unit. The unit starts, runs, and drives as it should. No issues now; I've hooked up the computer, and the TCU connects, showing no faults. All good, drove back. - Completed: 10/7/2025	5.00000	\$136.50	\$682.50
Parts	TCU programmed	1.00000	\$2,688.096	\$2,688.10
Subtotal				\$3,370.60

Unit: P05/1 **VIN:** 1HTWPAZT09J169907

2009 International SF537

Chassis: 107,771 Kilometers**Engine:** 0 Kilometers

Labor	\$682.50
Parts	\$2,688.10
Shop Supplies	\$68.25
Pre-Charge Subtotal	\$3,438.85
GST (5% of \$3,438.85)	\$171.94
Total	\$3,610.79
Payments & Credits	\$0.00
Balance Due	\$3,610.79

GST #839565405

eTransfer payments can be made to accounts@coppertoptruck.com

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that Coppertop Truck Repair Ltd is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employee's permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. If wheels have been removed as part of the above repairs than the driver must re-torque all wheels within 150 km. Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that Coppertop Truck Repair Ltd makes no warranties of any kind unless expressed in writing. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Vehicles left for more than 48 hours after completion may be subject to storage fees at a minimum of \$50 per day. Units that have been left for more than 90 days will be considered abandoned. Interest of 2.4% per month will be added to all outstanding invoices over 30 days.