DJ Mechanical

Box 2586

Whitecourt, AB T7S 2A1, CA tiffany@djmechanical.net

(780) 779-1707

Invoice:

Page: 1 of 2

553

Date:

2.00000

4.00000

7/4/2022

Bill To

Stubers Cat Services Ltd.

Remit Payment To

DJ Mechanical

Box 2586

Whitecourt, AB T7S 2A1, CA

P:

| | Service Order | Terms | Due Date | Authorizer | Customer PO | | Unit # | |
|-----|-----------------------|----------------|----------|-------------|-------------|------|--------|--|
| | 1577 | Net 30 | 7/5/2022 | Mike Stuber | | | 90 | |
| Ite | m Description | | | | Quantity | Rate | Amount | |
| Co | mplaint: Troubleshoot | and Repair AWD | | | | | | |

Cause: Customer request

Labor Correction:

> Equipment / Hydraulics / Start machine warm up, run machine to see what issue is, lift front up and L.H wheel goes in revers when going in forward, shift to reverse and wheel goes forward, check hoses and found hoses are on backwards remove cover on front of grader, loosen hoses so they can turn, remove hoses on motor and swap around, reinstall hoses and tighten other ends test grader and everything is working right. -7/4/2022

> > Subtotal \$300.00

\$150.00

\$300.00

\$600.00

\$150.00

Complaint: Troubleshoot and Repair AWD speed sensor codes

Cause: Customer request

(Inspection)

Labor Correction:

> Transmission / Hydrostatic Components / Plug into machine and check codes found R.H. and L.H. speed sensor codes for drive motors, order sensors and harness's, pick up parts, remove both harness and test, the L.H. one has open wires and the R.H. pulled apart upon removal, install new harness's and route plug in and test still no speed. replace both speed sensors and test everything is working right now, reinstall guards and

test machine everything is all good for reading speeds, clear all codes on machine. -

7/4/2022

Subtotal \$600.00