



Brandt Tractor Ltd.
10121 Barlow Trail NE
Calgary, Alberta
T3J 3C6
(403)248-0018

7911
A08-1
Service
Invoice



JOHN DEERE

SOLD TO:

PIDHERNEY'S INC
STK # 04031869

S/N # 1T0750LXPNE420836

INVOICE DATE	BRANCH	INVOICE NO.
13JUN22	04	4031869

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P

T
O

PIDHERNEY'S INC

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	AUTHORIZED BY
		4031869	02	06JUN22		
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER		
JD	750L	1T0750LXPNE420836	750L	CRA	6	

DESCRIPTION	AMOUNT
REPAIR HYDRAULIC LEAK COMPLAINT: UNIT HAS HYDRAULIC OIL LEAK CAUSE: FOUND O-RING PINCHED CORRECTION: REMOVE HYDRAULIC PUMP DISSCHARGE HOSE, REPLACE ORF O-RING AND REATTACH HOSE. TOP UP HYDRAULIC OIL LEVEL. RUN AND VERIFY REPAIR-OK. CLEAN OIL FROM INSIDE FRAME AT HYDRAULIC PUMP. REINSTALL LOWER PANEL AND PANEL AT RIPPER. REMOVE HYDRAULIC PUMP DISSCHARGE HOSE, REPLACE ORF O-RING AND REATTACH HOSE. TOP UP HYDRAULIC OIL LEVEL. RUN AND VERIFY REPAIR-OK. CLEAN OIL FROM INSIDE FRAME AT HYDRAULIC PUMP. REINSTALL LOWER PANEL AND PANEL AT RIPPER. REMOVE HYDRAULIC PUMP DISSCHARGE HOSE, REPLACE ORF O-RING AND REATTACH HOSE. TOP UP HYDRAULIC OIL LEVEL. RUN AND VERIFY REPAIR-OK. CLEAN OIL FROM INSIDE FRAME AT HYDRAULIC PUMP. REINSTALL LOWER PANEL AND PANEL AT	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**



Brandt Tractor Ltd.
P.O. Box 1200
800, 60th Street W
Saskatoon, SK S7K 3N2
(306) 664-4141

Service
Invoice



JOHN DEERE

SOLD TO:

PIDHERNEY'S INC
STK # 01285182

S/N # 1T0750LXPNE420836

INVOICE DATE	BRANCH	INVOICE NO.
18NOV22	02	1285182

PAGE	1
SALE TYPE	
WARRANTY	
CUSTOMER NO.	

S
H
I
P

T
O

PIDHERNEY'S INC

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
		1285182	02	01NOV22	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	750L	1T0750LXPNE420836	7911	372	MARVIN

DESCRIPTION	AMOUNT
REPAIR ECU CODE 654.05 COMPLAINT: COMPLAINT OF UNIT GETTING ENGINE CODE 654.05 CAUSE: FOUND INJECTOR HARNESS WAS NOT PROPERLY SECURED AND CAME LOOSE. RE558155 CORRECTION: CHECK OVER UNIT, FOUND HISTORY CODE 654.05 INJECTOR#4 CIRCUIT HAS HIGH RESISTANCE, PERFORM TERMINAL CHECK ON INJECTOR HARNESS, FOUND INJECTOR HARNESS AT VALVE COVER WAS NOT CLIPPED INTO VALVE COVER HARNESS. FILL OUT STA, REMOVE PLUG, INSPECT AND CLEAN UP TERMINALS AND CLIP HARNESS BACK TOGETHER. ENSURE LOCK TAB WAS SECURED AS WELL. RECHECK UNIT FOR CODES, FIRE UP ENGINE TO CHECK FOR PROPER OPERATION. UNIT IS WORKING PROPERLY AT THIS TIME AND NO CODES PRESENT.MM ** TOTAL LABOR ** CARBON TAX SURCHARGE	

>>--> SEG# 02 PRT

LAB

MSC

TOTAL

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST 4 1220537240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**



Brandt Tractor Ltd.
101 Burnt Park Dr.
Red Deer, AB
T4P 0J7
(403) 343-7557

Service
Invoice



SOLD TO:

PIDHERNEY'S INC
STK # 01560913

S/N # 1T0750LXPNF420836

INVOICE DATE	BRANCH	INVOICE NO.
31DEC22	05	1560913

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P
T
O

PIDHERNEY'S INC

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
7911		1560913	01	20DEC22	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	750L	1T0750LXPNF420836	7911	552	MARVIN

DESCRIPTION	AMOUNT
REPAIR COOLANT LEAK COMPLAINT: COMPLAIN TOF COOLANT LEAK CAUSE: Coolant hose clamp stripped threads. CORRECTION: Spoke with customer. Reviewed STA with tech. Ordered potential parts. Filled out service task assessment. Ran machine to operating temperature and inspected engine compartment for leaks. Found leak coming from coolant supply hose, attempted to tighten hose clamp but clamp was stripped. Removed bottom guard, drained engine coolant. Removed leaking coolant hose, removed stripped clamp and installed new clamp. Installed hose and tightened clamp to spec. Refilled engine with coolant and ran machine to operating temperature and reinspected for leaks, no further leaks found. SGS 1 N AR44217 CLAMP CY ** TOTAL LABOR ** CARBON TAX SURCHARGE	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____
SIGNATURE

DATE

QST # 1226937240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	▶ **CONTINUED**



Brandt Tractor Ltd.
101 Burnt Park Dr.
Red Deer, AB
T4P 0J7
(403) 343-7557

Service
Invoice



SOLD TO:

PIDHERNEY'S INC
STK # 01562041

S/N # 1T0750LXPNF420836

INVOICE DATE	BRANCH	INVOICE NO.
20APR23	05	1562041

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P

T
O

PIDHERNEY'S INC

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
7911		1562041	04	05APR23	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	750L	1T0750LXPNF420836	7911	623	COLIN

DESCRIPTION	AMOUNT
<p>REPAIR CONDENSOR FAN NOT SPINNING</p> <p>COMPLAINT: Repair A/C LH Condenser Fan.</p> <p>CAUSE: Causd by Shorted fan motor</p> <p>CORRECTION: LH rear condenser fan not moving. Check fuse, fuse was blown. Install fuse saver and run A/C system. Fuse saver tripped. Remove side panel on HVAC system. Check for short on power wire. No shorts are indicated. Compare resistance of LH&RH motor. LH motor has high resistance Filled out STA. Remove rear fan motor and condenser hardware, drop down fan and condenser assembly. Remove LH condenser fan, install and secure hardware. Reassemble condenser assembly back into position, secure hardware. Replace fuse and test fan operation. Condenser fan has continued to work. SGS</p> <p>1 AT460606 FANFAN XY ** TOTAL LABOR ** CARBON TAX SURCHARGE</p>	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____
SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	***CONTINUED**



Brandt Tractor Ltd.
101 Burnt Park Dr.
Red Deer, AB
T4P 0J7
(403) 343-7557

Service
Invoice



JOHN DEERE

SOLD TO:

PIDHERNEY'S INC
STK # 01567482

S/N # 1T0750LXPNF420836

INVOICE DATE	BRANCH	INVOICE NO.
28SEP24	05	1567482

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P

T
O

PIDHERNEY'S INC

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
7911		1567482	01	24SEP24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	750L	1T0750LXPNF420836	7911	1432	MARVIN

DESCRIPTION	AMOUNT
REPAIR RH BLADE LIFT CYLINDER LEAKING	
COMPLAINT: Repair RH Blade lift Cylinder	
CAUSE: FOUND o-ring torn	
CORRECTION: Spoke with customer. Reviewed STA with tech. Ordered seal kits and oil. Inspected unit for hydraulic leak and found leaking from outside of gland. Complete service task hazard assessment. Removed 2 lines and rod pin. Removed cylinder. Set in press. Removed snap ring. Drove in guide installed removal tool. Removed rod assembly. Removed piston nut, piston and guide. Resealed cylinder and assembled reverse of procedure. Installed cylinder and barrel pin. Installed 2 lines. Cycled cylinder to remove air. installed rod pin. Ran unit to verify repair.UDUSYN	
1 N AHC21922	HYDRAULI
1 N AHC13362	HYDRAULI
2 N 51M7045	O-RING

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUUM), MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**



Brandt Tractor Ltd.
101 Burnt Park Dr.
Red Deer, AB
T4P 0J7
(403) 343-7557

Service
Invoice



SOLD TO:

PIDHERNEY'S INC
STK # 01569518

S/N # 1T0750LXPNF420836

INVOICE DATE	BRANCH	INVOICE NO.
15MAY25	05	1569518

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P
T
O

PIDHERNEY'S INC

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
7911		1569518	01	08MAY25	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	750L	1T0750LXPNF420836	7911	1629	MARVIN

DESCRIPTION	AMOUNT
-------------	--------

REPAIR BLADE FUNCTIONS RH JOYSTICK

COMPLAINT:

Repair blade side to side function

CAUSE:

broken switch in handle - weak material

CORRECTION:

Started unit and found hydraulic pilot enable not turning off. Centred the blade side to side and pilot enable turned on. Found rocker toggle not centering back to neutral and found blade moving all over the place. No codes present replacing the joystick. Removed right hand side joystick. Dissassembled joystick and replaced. Had to slightly heat the screws to warm loctite to removed (very tight and stripping the small alen key heads). Removed old joystick and installed new one. Secured wiring and installed joystick back into unit. Started and tested operation. All functions working as they should. Verified all buttons in monitor.UDUSYN

1 N AT482788 CONTROL XY
** TOTAL LABOR **
ENVIRONMENTAL FEE

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1220957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**



Brandt Tractor Ltd.
101 Burnt Park Dr.
Red Deer, AB
T4P 0J7
(403) 343-7557

Service
Invoice



JOHN DEERE

SOLD TO:

PIDHERNEY'S INC
STK # 01569809

S/N # 1T0750LXPNE420836

INVOICE DATE	BRANCH	INVOICE NO.
26JUN25	05	1569809

PAGE	1
SALE TYPE	
WARRANTY	
CUSTOMER NO.	

S
H
I
P

T
O

PIDHERNEY'S INC

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
7911		1569809	01	11JUN25	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	750L	1T0750LXPNE420836	7911	1753	MARVIN

DESCRIPTION	AMOUNT
REPAIR 3359.31 TRANSMISSION FILTER RESTRICTED COMPLAINT: Repair Transmission Filter Restriction Code 3359.31 CAUSE: Shorted filter restriction switch. CORRECTION: Work through diagnostics in Service advisor with technician over the phone. Start machine and transmission filter switch warning 3359.31 came on immediately. Customer has just replaced filter. Release tank pressure, remove restriction switch. tested switch - shorted. Install new filter restriction switch, run crawler and inspect repairs. No active warnings for filter restriction. UDUSYN 1 N AT305595 PRESSURE ** TOTAL LABOR ** ENVIRONMENTAL FEE >>--> SEG# 01 PRT LAB MSC TOTAL	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____
SIGNATURE

DATE

QST # 1220937240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	