

# Edwards

Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

INVOICE ORIGINAL

Work Order

#393643

FL17-58

Challand Pipeline Limited

November 29, 2023

Svc.Adv Campeau, Daryl

Cust.Ph. (403) 845-2469

Tag# 3643

Page 1 of 2

01/08/2024 09:00:19

To: Challand Pipeline Limited

Year: 2020 Veh Id: 70698 Unit #: CHAL20-37  
Make: GMC License #:  
Model: 3500 Sierra 4WD Crew Cab D Odo. In: 39,035  
Colour: GAZ Summit White Odo. Out: 39,038  
V.I.N.#: 1GD49TE72LF211650 Next Service: 1/8/2024  
Date In: 11/29/2023 In Service Date: 03/12/2020  
Out: 12/13/2023 Cases: 2  
Ext. War - - ( mo/ ) - D: \$0.00  
Promised Time: 00/00/0000 00:00:00 AM Call When Ready:

Case: 1 Drivers rear hub seal is leaking

Quantity	Description/Correction	Retail	Price	Total
1.00	84757390 - GASKET-R/AXL SHF (Extra Item) - Warranty	\$9.25	\$0.00	\$0.00
1.00	84271030 - SEAL ASM-R/AXL SHF (Extra Item) - Warranty (FP)	\$105.94	\$0.00	\$0.00
2.00	SYN7590W - Synlube 75W90 (Extra Item) - Warranty	\$18.65	\$0.00	\$0.00
			\$0.00	\$0.00
	• Tech Cause: Related to case 2			
	• Tech Comments: Related to case 2 - Warranty			
	• Completed by Technician number: 18		\$0.00	\$0.00
0.00	Labour	\$0.00	Parts	\$0.00
	Prepaid Parts Amt:	\$0.00	Case Total:	\$0.00

Case: 2 Ebrake shoes have come apart.

Quantity	Description/Correction	Retail	Price	Total
1.00	86792660 - Pad kit (Extra Item)	\$466.25	\$309.42	\$309.42
1.00	84582652 - BRAKE ASM-PARK (Extra Item)	\$483.64	\$320.96	\$320.96

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6

Telephone: (403)845-3328 · Fax: (403)845-4661

GST #101584076

INVOICE ORIGINAL

Work Order

#393643

Challand Pipeline Limited

November 29, 2023

Svc. Adv. Campeau, Daryl

Cust. Ph. (403) 845-2469

Tag# 3643

Page 2 of 2

01/08/2024 09:00:20

\$334.00 \$334.00

- Tech Cause: Service park brake message on. Cecked for codes
- C060B - Left Park Assist Brake Actuator Circuit
- C060B 64 - Left Park Brake Actuator Circuit Slip Detected
- C0616 36 - Park Brake Control Circuit Performance
- C116B 55 - Rear Brake Pad Wear Signal Circuit.
- raised vehicle and inspected, found Left rear brake pads are oil soaked, left rear park brake shoes, actuator and backing plate are damaged causing left rear axle seal to leak.
- Tech Comments: Raised vehicle, removed left rear wheel, brake caliper, axle shaft and wheel hub, removed and replaced left rear caliper and park brake bracket with new park brake shoes and actuator. Removed and replaced left rear axle seal, reinstalled left rear wheel hub and rotor, set up left rear wheel bearings, reinstalled left rear axle shaft with new gasket. Reinstalled left rear brake caliper with new brake pads due to old ones were oil contaminated. Reinstalled left rear dual wheels and torque to 140ft-lbs.
- Removed RH rear dual wheels, removed and replaced right rear brake pads, reinstalled RH rear dual wheels and torque to 1404ft-lbs. Reset rear brake pad life.
- Topped up rear diff fluid. Cleared codes. Recalibrated park brake. Tested - park brake operating properly.
- Completed by Technician number: 18
- Miscellaneous

Misc	\$37.41	Labour	\$334.00	Parts	\$630.38	Prepaid Parts Amt:	\$0.00	Case Total:	\$1,001.79
									\$0.00

Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.

Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.

\_\_\_\_ agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime. I would like to unsubscribe from receiving:

\_\_\_\_ All messages from Edwards Garage. \_\_\_\_ All promotional messages from Edwards.

Currency:

Labour: \$334.00

Parts: \$630.38

Misc: \$37.41

Sub Total: \$1,001.79

G/HST: \$50.09

PST: \$0.00

Tax Adjustment: \$0.00

Payment Ref:

Expiry Date:

P/O#:

G/HST Reg # R101584076

12/13/2023

Date

Signature

Payment Type Charge

Total:

\$1,051.88

Payer

Challand Pipeline Limited

Payment Type

Charge

Reference

Date

12/22/2023

\$1,051.88

Balance Owing:

\$0.00