

G93-1


Autogermany

15227 119 Avenue Northwest
Edmonton, AB T5V 1S4
(780) 800-9123
contact@autogermany.ca
https://www.autogermany.ca/

Invoice for RO #13450

Service Advisor: Adrian Cocis
Posted Date: 08/29/25 at 01:02 PM MDT
Client: Doug Johnson
Vehicle: 2013 Volkswagen Touareg TDI Lux

Doug Johnson 73-2304 Township 522 Parkland, T7Y2J7 Phone: (780) 918-7785 Email: alsaskboy@gmail.com	2013 Volkswagen Touareg TDI Lux 3.0L 6Cyl DIESEL CNRB Turbocharged VIN: WVGDP98P6DD011459 License: BFF-8763 Color: Silver Odometer In: 269814 / Out: 269823	RO # 13450 Time In: 08/12/25 at 11:06 AM MDT
--	--	--

1 - REPLACE EGR VALVE + CLEAN EGR VALVE HOUSING

Note: Gained access to EGR valve by removing intake manifold. Cleaned EGR housing and components, replaced EGR valve. Found coolant flange in valley of the engine that was leaking, replaced flange. Re-attached components, filled and bled cooling system.

Labor:	Replace EGR valve and clean housing	
Parts:	EGR Valve	1
	EGR Valve Gasket	1
	EGR Cooler Gasket	1
	Intake Manifold Gasket	6
	Intake Manifold Gasket	6
	EGR Cooler Gasket	1
	EGR Tube Gasket	1
	Coolant G13	3
	O-ring	1
	O-ring	1
	Gasket	1
	Throttle seal	1
	Flange	1
✓ Approved on 08/19/25 at 03:59 PM MDT		Subtotal \$2,524.06 + est. Tax \$126.20 \$2,650.26

RO Fees		
Fee:	Materials and Consumables	\$150.00
	Subtotal	\$150.00

Warranty: From the date of delivery for a period of 36 months or 40,000 kilometers, whichever comes first*, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All warranty repairs to be done at Autogermany only. This does not include towing charges or customer supplied parts. Neglect/abuse of vehicle will immediately void any and all warranties. Warranty is transferable to subsequent vehicle owner(s) as long as the vehicle continues to be serviced, maintained and repaired at Autogermany. Semi-annual inspection must be performed by Autogermany to retain the warranty. *Some limitations apply. This does not include wearable items including but not limited to brakes, belts, tires, hose, etc. Ask advisor for details on the specific part being installed. GST#: 744 546 516

Wheel nuts (bolts) tightness (torque) must be rechecked by AUTOGERMANY after 80 kilometers.

Once vehicle repairs are completed, customers will be notified promptly using the contact information provided at the time of service. Customers are expected to pick up their vehicles within 14 calendar days of this notification. Starting on the 15th day, a storage fee of \$20.00 per day will be applied to the total bill for each day the vehicle remains on the premises.



Autogermanny
15227 119 Avenue Northwest
Edmonton, AB T5V 1S4
(780) 800-9123
contact@autogermanny.ca
https://www.autogermanny.ca/

Invoice for RO #11002
Service Advisor: Adrian Cocis
Date Created: 07/03/24 at 09:29 AM MDT
Client: Doug Johnson
Vehicle: 2013 Volkswagen Touareg TDI Lux

Doug Johnson Phone: (780) 918-7785	2013 Volkswagen Touareg TDI Lux 3.0L 6Cyl DIESEL CNRB Turbocharged VIN: WVGD98P6DD011459 License: BFF-8763 Color: Silver Odometer In: 233617 / Oia: 233625	RO #11002 Time-In: 07/03/24 at 09:29 AM MDT
---------------------------------------	---	--

1 - EMISSION SYSTEMS DELETE - OFF ROAD USE ONLY Note: Removed DPf from vehicle, cut open and gutted. Welded bottom of DPf where it was cut re-attached to the vehicle and programmed vehicle for a delete. Took for a test drive and found no further issues.		
Labor:	Emissions system delete	
Parts:	Exh Man to Pipe Gasket	1
	Exhaust Pipe Gasket	1
	Exhaust Nut	6
✓ Approved on 07/03/24 at 01:43 PM MDT		
Subtotal \$937.57 + est Tax \$46.63		\$979.15

2 - VEHICLE HEALTH CHECK Note: Performed vehicle health check. Please see report for details. https://autogermanny.autotext.me/Admin/microsite/index.php?id=cWZ3R285ZVRfbFJuSVJNNGZxU2JpZDRNMGJ5dG1Q9l5c091bmFwcC:GMDC&so=1		
Labor:	Vehicle health check	
Discount:	Discount	-\$82.50
✓ Approved on 07/03/24 at 01:43 PM MDT		0

3 - DIAGNOSE FRONT END HUMMING NOISE WHILE DRIVING Note: Found humming noise during test drive. Lifted vehicle up and performed dyno test to check for noise, found front diff making major noise also both front wheel bearings, output transfer case bearing has minor noise as well. Check condition of front diff fluid found there is metal inside which indicate that front diff bearing worn out/damaged. Vehicle will require front diff assembly and further checking.		
Labor:	Diagnosis	
✓ Approved on 07/11/24 at 10:32 AM MDT		
Subtotal \$180.00 + est Tax \$9.00		\$189.00

4 - ECU PROGRAMMING - Special coding		
Sublet:	ECU programming	\$1,100.00
✓ Authorized on 07/03/24 at 01:43 PM MDT		
Subtotal \$1,100.00 + est Tax \$55.00		\$1,155.00

RO Fees		
Fee:	Materials and Consumables	\$132.75
Subtotal		\$132.75

Warranty: From the date of delivery for a period of 36 months or 40,000 kilometers, whichever comes first*, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. Neglect/abuse of vehicle will immediately void any and all warranties. Warranty does not transfer to subsequent vehicle owner(s). *Some limitations apply. This does not include wearable items including but not limited to brakes, belts, tires, hose, etc. Ask advisor for details on the specific part being installed. GST#: 744 546 516

Wheel nuts (bolts) tightness (torque) must be rechecked by AUTOGERMANY after 80 kilometers.