



Mechanical

Whitecloud Mechanical

58030 RR100
 PO Box 1098
 Saint Paul, AB T0A 3A0
 (780) 227-6202
 whitecloudmechanical@outlook.com

Invoice for RO #10034

Service Advisor: Glen Plaska

Date Created: 10/14/25 at 08:34 AM MDT

Client: [REDACTED]

Vehicle: 2000 Mack CH CH600

2000 Mack CH CH600 11.9L 6Cyl DIESEL E7
 VIN: 1M1AA13YXYW121359
 License: N/A
 Color: N/A
 Odometer In: 278377 / Out: 278377

RO # 10034

PO # -

Time-In: 10/14/25 at 08:34 AM MDT

Save Parts: No

Client concerns:

- Change front steer hub fluid
- Check all fluid levels/condition
- Check brakes.
- Give truck full inspection

1 - Intake Inspection

Tech AS

Labor: Tech to fill out inspection form for units coming into shop, perform prescan on every vehicle

✓ Approved on 10/14/25 at 08:34 AM MDT

0 0

2 - Change front steer hub fluid

Tech: AS

Labor: Remove hub caps. Drain oil oil. Remove old gasket and clean surfaces. Install hub caps back on with new gaskets. Fill with oil. Clean up from job.

Parts: Hub Cap Gasket 2
75W90 DIFF OIL - Sold By Litre. Pail is in parts room 2

✓ Approved on 10/14/25 at 08:34 AM MDT

Subtotal \$205.30 + est. Tax \$10.27 \$215.57

3 - Check all fluid levels/condition

Tech: AS

Labor: Checked fluid levels and conditions. No levels are low and fluids look in good condition still.

✓ Approved on 10/14/25 at 08:34 AM MDT

Subtotal \$41.25 + est. Tax \$2.06 \$43.31

4 - Check brakes.

Tech: AS

Labor: Inspected brakes. All shoes are around 18mm which is almost the same as new. Checked for any air leaks on brake system. Rest of brake components are in good condition.

✓ Approved on 10/14/25 at 08:34 AM MDT

Subtotal \$82.50 + est. Tax \$4.13 \$86.63

5 - Give truck full inspection

Tech: AS

Labor: Checked over truck. Found a few concerns which were noted but nothing major.

✓ Approved on 10/14/25 at 08:34 AM MDT

Subtotal \$165.00 + est. Tax \$8.25 \$173.25

6 - QC Inspection

Tech GR

Labor: A technician who is not working on the vehicle must go through unit to inspect for any leaks or other repairs that original technician may have missed. Go to inspection page and follow step procedure.

✓ Approved on 10/14/25 at 08:34 AM MDT

0 0