

Regina, SX 10 Redhead Road C4N 71 7 306.721.2666 800.667.7710

$\mathbf{v} \cup \mathbf{v}$	V	0	١	_	١
------------------------------	---	---	---	---	---

SWIFT CURRENT ESTEVAN 306.634.4788 306,773,2951 LLOYDMINSTER 306.825.3434 SASKATOON 306.934.3555 306.752.2273 HUMBOLDT 306.682.9920 NORTH BATTLEFORD KINISTINO 306.864.3667

PRINCE ALBERT 306.763.6454

For additional contact information visit redheadequipment.ca Branch ESTEVAN Date Time Page 08:53:32 03/18/25 01 Account No. Phone No. Invoice No. Ship Via Purchase Order

IN STORE PICKUP

ö Ship

ë

3

<u></u>		/ICE	DDEL	IRAIN	ADV
J	CK	VICE	PREL	LIIVIIIN	ARI

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

Salesperson

Case IH 9250 Combi

893 HAJF9N4LTNG248869

525 YNG248869

SEGMENT# 1 S 02016 NA

03/04/25 03/06/25

Repair feeder

CUSTO COMPLAINT

- -front feeder face top cover bent.
- -feeder top cover rivet nut broken, bolt missing.
- -feeder chain slats bent-USE SOME USED SLATS.
- -feeder chain needs adjust.

9250

-rocktrap right bg has play-REPLACE.

CORRECTION:

Unbolt bent front feeder face top plate. Use hydraulic press to repair bent plate. Bolt on top plate. Unbolt feeder housing top cover. Find broken rivet nut. Drill out old broken rivet nut. Install new rivet nut. Bolt on top cover.

Find old feeder chain outside. Unbolt 5 bent feeder chain slats from combine. Swap 5 feeder chain slats from used chain. Adjust feeder chain. Unbolt RH feeder rock trap bearing plate cover. Unbolt RH rock trap bearing bolt. Replace worn rock trap bearing. Install bearing bolt.

Install RH bearing metal cover.

Remove feeder gear box speed sensor. Find oil is dark but no burnt clutches. Drain feeder gear box and replace oil. Install speed sensor.

.24 EHC Oil .06 EHCOIL .48 EHC Container 4 .12 EHC1LT 64.04 Oil,1Qt 16.01 73344319

> OEM CNH-Genuine (Gear Oils) 75w90 Synthetic Hypoid Gear Oil 1 Litre

CONTINUED ON PAGE 02

the markine including remote access, for the purpose of diagnosting, repairing, or servi- updates and/or diagnostics to a modified system. RE and its employees may operate it redelivery of the machine or on terms satisfactory to RE until paid in full. Registration of understood that RE assumes no responsibility for loss or damage by their or first to any extremely. Amy society on paids returned refire 30 days will be subject to a 15% restocking.	lets. Lagree that Hednead Equipment ("NE") may access and uture any execution calls affect a sivulation of the machine or its components. RE will not be responsible for any costs incurred resulting from software above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to commercial ten is acknowledged on the above machine to secure the amount of repairs threeto. It is tachine placed with them for storage, sale, repair or while field testing. Special order and electrical parts are not charge. RE cannot except any part returns on weekends or after hours. Part returns are not accepted after one ing. Notitle passes on purchased machines until the applicable invoice is paid in full. 2½ per month will be s. Whole goods and rental payments are due on delivery.	F
CIONATUDE:	DATE	

k o	Land Description SecTwsp_ RM, I hereby certify the goods listed on this involce will be used solely in the operation of my farm.	
	Date	
	Authorized Farm Signature	ı

SIGNATURE.	
DDINT NAME:	GST #83464386



Regina, SK **Head Office** Box 32098 10 Redhead Road C/N 71 2 306.721.2666 800.667.7710

ESTEVAN 306.634,4788 **SWIFT CURRENT** 306.773.2951 LLOYDMINSTER 306.825.3434 SASKATOON 306.934.3555 MELFORT 306,752,2273 HUMBOLDT 306.682.9920 NORTH BATTLEFORD 306.445.8128 KINISTINO 306.864.3667 PRINCE ALBERT 306.763.6454

For additional contact information visit redheadequipment.ca Branch **ESTEVAN** Date Time Page 03/18/25 08:53:32 Phone No. Account No. Invoice No. Ship Via Purchase Order Salesperson

1077.98

IN STORE PICKUP

ö Ship 1

SERVICE PRELIMINARY

WARRANTY DATE HRS PIN/EIN STK#/FLEET# HAJF9N4LTNG248869 893 Case IH 9250 Combi

525 YNG248869 9250

233.22 233.22 Bearing. 92116331

> OEM CNH-Genuine (Bearings) 4 Bolt Housing With Bearing

297.98 PARTS 780.00 LABOR

SEGMENT TOTAL == 10400

SEGMENT# 2 S 02016 NA

03/04/25 03/06/25

Repair rotor and components

CUSTO COMPLAINT

- -cage left vane missing; bolt and hardware missing.
- -right concave damaged.
- -right second concave has damage.DO NOT REPLACE
- -left concaves second and third are bent.DO NOT REPLACE
- -front rotor flighting has missing chunks.
- -many rotor rub bars are damaged and missing chunks of material, recommend

to replace HALF SET.

-check rotor vibration and ADVISE after replacing half set rub bars. . 1881.

CORRECTION:

Disconnect under cab harness. Unbolt harness bracket. Remove top front cone cover. Remove old damaged front rotor flighting extensions. Install new extensions and torque bolts. Install top front cone cover. Bolt on harness bracket. Connect cab harness. Remove RH and LH damaged concaves. Repair and weld cracked concaves. Install missing RH new cage vane adjustment bolts and bushings. Install new missing LH front cage small vane, bolts and nuts. Install LH and RH rotor concaves.

CONTINUED ON PAGE 03

updates and/or diagnostics to a modified system. RE and its employees may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to redelivery of the machine or on terms satisfactory to RE until paid in ful. Registration of a commercial ten is acknowledged on the above machine to secure the amount of repairs thereto. It is understood that RE assumes no responsibility for loss or demage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts ere not neturnable. Any stocking parts returned after 30 days will be subject to a 15% restocking charge. RE cannot accopt any part returns on weekends or after hours. Part returns are not accepted after one or opinal invoice date. All part returns require the original invoice and packaging. Not like passes on purchased machines until the applicable invoice is paid in ful. 2% per month will be		Farm Customers Only Land Description SecT wsp RM, I hereby certify th goods listed on this invoice will be use solely in the operation of my farm. Date
SIGNATURE:	DATE:	Authorized Farm Signature
	GST #834643868	Authorized Latin Signature



Regina, SK Box 32098 In Redhead Boar 306.721.2666

800.667.7710

IN STORE PICKUP

ë

NORTH BATTLEFORD 306.445.8128 KINISTINO 306.864.3667 PRINCE ALBERT 306.763.6454 For additional contact information visit redheadequipment.ca Branch **ESTEVAN** Date Page 03/18/25 08:53:32 (0) Phone No. Account No. Invoice No. Ship Via Purchase Order

SWIFT CURRENT

SASKATOON

HUMBOLDT

306.773.2951

306.934.3555

306.682.9920

Salesperson

306.634.4788

306.825.3434

306.752.2273

SERVICE PRELIMINARY

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

ESTEVAN

MELFORT

LLOYDMINSTER

HRS

Case IH 9250 Combi

HAJF9N4LTNG248869 893

525 YNG248869

Find 14 damaged rotor rub bars. Remove old rub bars. Clean rotor rub bar brackets. Install new rub bars and bolts.

Inspect rotor cone and find vanes too damaged. Start combine. Move feeder housing down. Disconnect cab harness. Unbolt harness bracket.

Unbolt from cone 3 damaged vanes and nuts. Connect cab harness. Start combine and move feeder housing to all top. Unbolt nuts from 3 vanes. Remove inspection door from inside grain tank. Unbolt all top nuts from vanes. Start combine and move feeder housing down. Remove 3 damaged vanes. Install 3 new vanes. Use all new vane bolts. Install all top cone vane nuts.

Start combine move feeder

PRINT NAME:

9250

housing at top. Tight all bottom nuts for vanes. Start combine move feeder housing dawn. Disconnect cab harness. Install cone top cover. Connect cab harness. Bolt harness bracket.

-Remove LH all concaves. Inspect rotor and find rotor is not in balance. Spin rotor many times. Find rotor stops in

position all time. Install mark on rotor. Across rotor another side, use magnets and nuts all different size, assess

how much is needed to rebalance. Use scale, weigh all nuts and magnets. find weight needed. Use metal plate; cut metal from plate and put on scales how many to get good identical weight . Grind metal plate

for weight needed. Unbolt battery cover. Disconnect battery clamps. Weld metal plate on rotor. Spin rotor many times and

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of any necessary materials. I agree that Redhead Equipment ("RE") may access and utilize any electronic of the machine including remote access, for the purpose of diagnosing, repairing, or servicing the machine or its components. RE will not be responsible for any costs incurred updates endor diagnostics to a modified system. RE and its employees may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I it redelivery of the machine or on terms satisfactory to RE until paid in that. Registration of a commercial ison is acknowledged on the above machine to secure the amount of reunderstood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order returnable. Any stocking parts returned after 30 days will be subject to a 15% restocking charge. RE continued accept any part returns on weekends or after hours. Part returns year from the original invoice and packaging. No title passes on purchased machines until the applicable invoice is paid in full charged on all overdure accounts (24% per annum). Parts & Service are net 30 days. Whole goods and rental payments are due on delivery.	resulting from soward agree to pay cash prior to epairs thereto. It is goods listed on this invoice will be and electrical parts are not accepted after one seems of accepted after one.
SIGNATURE: DATE:	Authorized Farm Signature
	Authorized raini Signature

GST #834643868



Regina, SK Head Office Box 32098 10 Redhead Road 54N 7L2 306.721.2666

800.667.7710

ESTEVAN 306.634.4788 SWIFT CURRENT 306.773.2951 LLOYDMINSTER 306.825.3434 SASKATOON 306.934.3555 MELFORT 306.752.2273 HUMBOLDT 306.682.9920 NORTH BATTLEFORD 306.445.8128 KINISTINO 306.864.3667

PRINCE ALBERT 306.763.6454

For additional contact information visit redheadequipment.ca Branch ESTEVAN Date Page Time 03/18/25 Account No. 08:53:32 (O) Phone No. 04 Invoice No. Ship Via Purchase Order Salesperson

IN STORE PICKUP

Ship to:

SERVICE PRELIMINARY

		upc p	IN/EIN	WADDAN	ITY DATE	HRS	
STK#/FLEET#	T. 0050 G		IN/EIN AJF9N4LTNG2:		III DALE	nkb	
	se IH 9250 Combi		NG248869	40003			
	250						
grind plate for	or good balance. In	stall al	1 left conc	aves.			
Connect batte	ry clamps. Install	cover.	Run combine	. Find			
	new calibration. A			•			
	Run and check is ok		1	40	40.60		595.44
278821A3		ar,		12 N	49.62	7 N. 19 20 1 1 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	595.44
	OEM CNH-Genuine						
	Rotor Rasp Bar w	/o Spike	Chrome				
47841885		ane,		1	74.43	g es.	74.43
	OEM CNH-Genuine	(Crop Ha	rvesting)	**			
	Rotor Cage Vane						
47994263	В	ushing,		1	59.13		59.13
	OEM CNH-Genuine	(Bushing	s) Bushing				
47994268	B	ushing,		1	66.57		66.57
	OEM CNH-Genuine	(Bushing	rs)				
	Rubber Bushing						
48118400		it,		1	747.17		747.17
40110100	OEM CNH-Genuine	(Harvest	ing Kits)				
	Rotor Wear Plate						
84196601		lamp,	20.00-	1 N	16.59		16.59
04130001	OEM CNH-Genuine	288888 = T 19 53650	re)				
	Clamp						
86981487		olt.		14	5.05		70.70
00301407	OEM CNH-Genuine	•	re)				
	M12-1.75 x 35 10			<u> </u>			
87053359	No. 2011 (1987)	tiffene		3	186.74		560.22
8/053359	OEM CNH-Genuine		•	_			
	Stiffener	(CLOP III	it vebering,				
		Bolt,		27	9.42		254.34
87106338	OEM CNH-Genuine	•	ra) M10 v 30		J. 20		
	- · · ·	(naruwa.	re, mro v o				
	T-Bolt			COMMIT	NUED ON PAG	∓E 05	
				CONTI	MOND ON PA	.L 03	

updates and/or dagnostics to a modified system. RE and its employee medivery of the machine or on terms satisfactory to RE unit paid in ful understood that RE assumes no responsibility for loss or damage by it returnable. Any stocking parts returned after 30 days will be subject to	pairing, or servicing the machine or its components. RE with not be responsible for any costs incurred resulting from software is may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to it. Registration of a commercial ten is acknowledged on the above machine to secure the amount of repairs thereto. It is neft or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts are not a 15% restocking charge. RE cannot accept any part returns or weekernds or after hours. Part returns on reduce and packaging. No title passes on purchased machines until the applicable invoice is paid in full. 2% per month will be color and not 30 days. Whole goods and rental payments are due on delivery.
CIGNATUDE:	DATE:

5	Farm Customers Only and Description Sec Twsp M , I hereby certify the poods listed on this invoice will be used totely in the operation of my farm.
ŀ	Authorized Farm Signature

SIGNATURE:	DATE:
PRINT NAME:	GST #834643868



Regina, SK Head Office Box 32098 10 Redhead Road S4N 7L2 800.667.7710

ESTEVAN	306.634.4788	SWIFT CURRENT	306.773.295
LLOYDMINSTER	306.825.3434	SASKATOON	306.934.355
MELFORT	306.752.2273	HUMBOLDT	306.682.992
NORTH BATTLEFORD	306.445.8128	KINISTINO	306.864.366
ODINGE ALDEDT	200 702 0454		

For additional contact i	information	visit redh	eadequ	ipment.ca	
Branch					
ESTEVAN					
Date	Time			Page	
03/18/25	08:	53:32	(0)	05	
Account No.	Phone No	0.		Invoice No.	
Ship Via		Purchase	Order		
				-	
	-				
			Sale	sperson	
			1		

IN STORE PICKUP

Ship to:

Invoice to:

SERVICE PRELIMINARY

		<u> </u>			
				WWW DAME IIDA	
STK#/FLEET#		HRS PIN/EIN		NTY DATE HRS	
-	ase IH 9250 Combi	893 HAJF9N4LTNG	248869		
	9250	525 YNG248869	_	84 05	71 05
87107892		Angle,	1	71.05	71.05
		e (Crop Harvesting)			
	Angle				0515 64
				PARTS	2515.64
				LABOR	3217.50
10400			SEGMENT	rotal==>	5733.14
SEGMENT# 3 S	02016 NA	03/04/25 03/06/25			
Repair vac f	an and SAS wand		-		
CUSTO COMPLA	INT		. .		
-vac fan bel	t cracked.		e izak		
-SAS wand pl	astic seals worn.				
CORRECTION:		Sec.		\$ ^*	
		t to remove vac fan	belt &		
replace vac	fan belt with new	belt	(1) 110k		
- SAS wand r	removed, rivets rem	oved off the seal fo	or both		
SAS wand & i	installed both seal	s on, & Installed SA	AS wand		
back on.					
BK700		Blade,Set	1 0	164.00	164.00
	OEM Redekop-Ge	nuine Chopper Blade			
		0 Blades Per Set)			
FRT		Freight Charge	1	12.00	12.00
47514305		Ring,	1	61.20	61.20
2,021000	OEM CNH-Genuir	e (FPT Engines & Par	rts)		
	Ring	· •			
48155344		Belt,	1	60.20	60.20
40133311	OEM CNH-Genuir	ne (Belts) Fan Drive	V-Belt		
87472745		Ring,	1	127.78	127.78
V. 412143	OEM CNH-Genuir	ne (Crop Harvesting)			
	Ring				
			CONT	NUED ON PAGE 06	

I hereby authorize the above work to be done along with the use of any necessary materials. I agree that Redhead Equipment ("RE") may access and utilize any electronic data stored or available on the machine including remde access, for the purpose of diagnosing, repating, or servicing the machine or its components. RE will not be responsible for any costs incurred resulting from software updates and/or diagnosis to a modified system. RE end its employees may operate the above machine to its purposes of inspection, testing or delivery at my sole risk I agree to pay eash prior to redelivery of the machine or on terms satisfactory to RE until peid in full. Registration of a commercial is a acknowledged on the above machine to secure the emount of repairs thereto. It is understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or while field testing. Special order and electrical parts are not returnable. Any stocking parts returned after 30 days will be subject to a 15% restocking charge. RE cannot accept any part returns on veckends or after hours. Part returns are not accepted after one successive and the original invoice date. All part returns require the original invoice date. All part returns require the original invoice date. All part returns require the original invoice of the control of the part returns require the original invoice date. All part returns require the original invoice and packaging. No tile passes on purchased machines until the applicable invoice is paid in full. 2% per month will be charged on all overd

	rain castoners only
	Land Description Sec Twsp
ı	R , I hereby certify the
1	goods listed on this invoice will be used
t	solely in the operation of my farm.
•	osidi, in also specialistics in , in
	Date

Authorized Farm Signature

SIGNATURE:	DATE:
PRINT NAME:	GST #834643868



Regina, SK **Head Office** Box 32098 10 Redhead Road S4N 7L2 306.721.2666

IN STORE PICKUP

ö

ë

800.667.7710

MELFORT	306.75	2.2273	н	UMBOLDT		306	.682.9920
NORTH BATTLEFORD	306.44	5.8128	K	NISTINO		306	.864.3667
PRINCE ALBERT	306.76	3.6454					
For additional cor	ntact in	format	ion	visit redhe	adequ	ipmer	nt.ca
Branch							
ESTEVAN							
Date		Time					Page
03/18/25		l o	8:	53:32 ((0)		06
Account No.		Phone				Invoi	ce No.
Ship Via	_			Purchase	Order		
_							
				-	Sale	spers	on
					1		
						_	

SWIFT CURRENT

SASKATOON

306.634.4788

306.825.3434

SERVICE PRELIMINARY

STK#/FLEET#

10400

HRS PIN/EIN WARRANTY DATE

ESTEVAN

LLOYDMINSTER

HRS

Case IH 9250 Combi

893 HAJF9N4LTNG248869

9250

525 YNG248869

PARTS

LABOR

425.18 897.00

306.773.2951

306.934.3555

SEGMENT TOTAL ==>

1322.18

SEGMENT# 4 S 02016 NA

03/04/25 03/10/25

Repair cleaning system

CUSTO COMPLAINT

- -rear center cleaning frame pivot brg plate is cracked, brg has play.
- -right and left rear upper sieve shaker arms rubbing on frame.
- -rotor and sieve loss sensors need blow out.
- -inclination sensors need calibrate.
- -sieve opening and level need adjust and calibrate.

CORRECTION:
Use stand and jack, lift rear self level frame. Replace cracked rear pivot plate. Inspect center bearing and find bearing has a small amount of play. Remove stand and jack. Remove L and R rear shaker arms rubbing at frame. Inspect arms and find arm just scratched frame. Inspect arm rubber bushings, good. Adjust rubber bushings. Install arms. Check shaker arms are not rubbing, good. Clean L and R rotor loss sensors. Unbolt sieve grain loss sensor under metal cross plate. Clean plate. Disconnect loss sensor. Remove and blow out sensor. Install loss sensor and connect harness. Bolt on bottom cross plate. Repair bent upper sieves. Adjust and calibrate upper and lower sieves. Run combine and Calibrate inclination sensors. Calibrate self level clean system.

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of any necessary materials. I agree that Rechear the machine including remote access, for the purpose of diagnosing, repairing, or servicing the machine or its corruptions and/or diagnosities to a modified system. RE and its employees may operate the above machine for the redelivery of the machine or on terms satisfactory to RE until paid in tall Registration of a commercial fen is active understood that RE assumes no responsibility for loss or damage by theft or fire to any machine placed with them returnable. Any stocking petrs returned after 30 days will be subject to a 15% restocking charge. RE cannot accept year from the original invoice date. All part returns require the original invoice and packaging. No title passes on p charged on all overdue accounts (24% per annum). Parts & Service are not 30 days. Whole goods and rem	RM, I hereby certify the goods listed on this invoice will be used solely in the operation of my farm	
SIGNATURE:	DATE:	Authorized Farm Signature
PRINT NAME:	GST #834643868	



Regina, SK Head Office Box 32098 10 Redhead Road SAN 71 2 800.667.7710

ESTEVAN 306.634.4788 **SWIFT CURRENT** 306.773.2951 LLOYDMINSTER 306.825.3434 SASKATOON 306.934.3555 MELFORT HUMBOLDT 306.752.2273 306.682,9920 NORTH BATTLEFORD 306.445.8128 KINISTINO 306.864.3667

PRINCE ALBERT 306.76	3.6454	
For additional contact in	nformation visit redheadeq	uipment.ca
Branch		
ESTEVAN		
Date	Time	Page
03/18/25	08:53:32 (0)	07
Account No.	Phone No.	Invoice No.
		1
Ship Via	Purchase Orde	r
-	Sal	esperson

IN STORE PICKUP

₽

nvoice to:

SERVICE PRELIMINARY

WARRANTY DATE HRS STK#/FLEET# HRS PIN/EIN Case IH 9250 Combi 893 HAJF9N4LTNG248869 9250 525 YNG248869 ______ 1 134.38 134.38 Plate, 84457842 OEM CNH-Genuine (Hay & Forage) Wear Plate 134.38 PARTS LABOR: 1365.00 SEGMENT TOTAL ==> 1499.38 10400

SEGMENT# 5 S 02016 NA

03/04/25 03/10/25

Repair tailings processor

- CUSTO COMPLAINT -tailings processor bottom cross auger left side brg failed, may be damage to auger too.
- -tailings processor belt inline pulley brg has play.
- -tailings processor ratchet clutch worn, hub has damage. CORRECTION:

Remove shaker drive belt. Unbolt side metal cover plate behind battery housing. Remove tailing processor belt. Remove belt center tension pulley Unbolt RH tailing processor bottom auger bearing plate. Unbolt LH tailing auger pulley. Use puller pull off LH auger pulley. Slide out RH tailing auger from tailing housing. Remove failed LH cross auger bearing and flanges. Clean LH cross auger bearing shaft. Install new bearing flanges, bearing and lock. Install LH cross auger pulley. Slide in RH tailing cross auger. Bolt on RH auger bearing plate. Install belt tension pulley. Bolt on LH auger pulley. Install drive shaker belt. Bolt on battery cover plate. Inspect RH cross auger bearing and find LH bearing has play. Use puller and try to remove bottom pulley. Pulley is bent and seized.

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of any necessary materials. I agree that Redhead the machine including remote access, for the purpose of diagnosting, repairing, or servicing the machine or the computation and the computation of a computation of a computation of a computation of a computation or or terms satisfactory to RE until paid in full. Registration of a commercial ten is action understood that RE assumes no responsibility for loss or damage by their of fre to any machine placed with them returnable. Any stocking pairs returned after 30 days will be subject to a 15% restocking charge. RE cannot accept year from the original invoice date. All part returns require the original invoice and packaging, No title passes on theraged on all overdue accounts (24% per annum). Parts & Service are net 30 days. Whole goods and rent	R, I hereby certify the goods listed on this invoice will be used solely in the cognition of my farm	
SIGNATURE:	DATE:	Authorized Farm Signature
PRINT NAME:	GST #834643868	



Regina, SK Box 32098 10 Redhead Road 306.721.2666

IN STORE PICKUP

ö

800.667.7710

NORTH BATTLEFORD	306.445.8128	KINISTINO	306	5.864.3667
PRINCE ALBERT	306.763.6454			
For additional con	tact informatio	n visit redhead	lequipme	nt.ca
Branch			ĺ	
ESTEVAN Date	Time			Dogo
Date	Time			Page
03/18/25	80	:53:32 (0))	08
Account No.	Phone I			ice No.
Ship Via		Purchase O	rder	
Stilb Ala		Fulcilase O	1001	
	-	T	-	-
		Ì		
<u> </u>		'	Salespers	on
		'	Juicapera	···

SWIFT CURRENT

SASKATOON

HUMBOLDT

306,773,2951

306.934.3555

306.682.9920

306.634.4788

306.825.3434

306,752,2273

SERVICE PRELIMINARY

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

ESTEVAN

MELFORT

LICYDMINSTER

HRS

Case IH 9250 Combi

9250

893 HAJF9N4LTNG248869

YNG248869 525

Use torch and cut off siezed pulley. Use air hammer and puller to remove pulley. Clean rusty auger shaft. Use air hammer and remove stuck bearing lock. Unbolt bottom bearing metal cover. Use grinder cut off old bearing. Use air hammer remove stuck bearing. Grind rusty shaft. Install new bearing. Bolt on bearing cover. Tighten bearing lock. Install new bottom pulley.

Remove vacuum fan belt. Remove elevator drive belt. Unbolt tailing processor slip clutch spring. Remove tailing drive pulley. Inspect slip clutch and find clutch hub is cracked and damaged. Unbolt vacuum fan air chute tube. Use puller and remove tailing processor clutch hub. Unbolt elevator and vacuum fan drive pulleys from hub. Install vacuum fan and elevator drive pulley on new hub. Install new hub. Install drive tailing processor pulley and slip clutch spring. Install elevator, vacuum fan and tailing processor belts. Adjust belts. Bolt on vacuum fan chute air tube.

===============		=====		
FRT	Freight Charge	1	36.00	36.00
Q1458GRA108RRB	Bearing, Bearing,	1	41.53	41.53
-	OEM Mack/SKF-Genuine Spherical Ball			
	Bearing C/W Lock Collar			
47513699	Hub,	1 N	842.90	842.90
	OEM CNH Genuine (Crop Harvesting)			
	Hub			
86974037	Flange,	2	31.67	63.34
	OEM CNH-Genuine (Crop Harvesting)			
	Flange			
87282789	Pulley,	1	393.75	393.75
	OEM CNH-Genuine (Crop Harvesting)			
		CONTI	NUED ON PAGE 09	

I hereby authorize the above work to be done along with the use of any necessary materials. I agree that Rochead Equipment ("RE") may access and utilize any electronic data stored or available on the machine including remote access, for the purpose of diagnosing, repairing, or servicing the machine or its components. RE will not be responsible for any costs incurred resulting from software updates and/or diagnostics to a modified system. RE and its employees may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to redelivery of the machine or on terms satisfactory to RE until peals in till. Registration of a commercial len is acknowledged on the above machine to secure the amount of repairs thereto. It is understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or while field testing. Special order and electrical parts are not returnable. Any stocking parts returned after 30 days will be subject to a 15% estocking charge. RE cannot accept any part returns on weekends or after hours. Part returns are not accepted after one system from the original invoice date. All part returns require the original invoice and packaging. No title passes on purchased machines until the applicable invoice is paid in full. 2% per month will be charged on all overdue accounts (24% per annum). Parts & Service are not 30 days. Whole goods and rental payments are due on delivery.

k 8	RM, I hereby certify the goods listed on this invoice will be used solely in the operation of my farm.
	Date
	Authorized Farm Signature

SIGNATURE: _	 DATE:
PRINT NAME:	GST #834643868



Regina, SK Head Office Box 32098 10 Redhead Roa 306,721,2666 800.667.7710

SWIFT CURRENT 306.773.2951 **ESTEVAN** 306.634.4788 LLOYDMINSTER 306.825.3434 SASKATCON HUMBOLDT MELFORT 306.752.2273 NORTH BATTLEFORD 306.445.8128 KINISTINO

306.934.3555 306.682.9920 306.864.3667

IN STORE PICKUP

ë

PRINCE ALBERT 306.76	3.6454				
For additional contact in	formation	visit redhea	adequip	ment.ca	
Branch					
m CMTDL/A NI					
ESTEVAN Date	Time			Page	
03/18/25		<u>53:32 (</u>		09	
Account No.	Phone No	0.		nvoice No.	
Ship Via	!	Purchase	Order		
			Sales	person	
				•	
1					

SERVICE PRELIMINARY

WARRANTY DATE HRS HRS PIN/EIN STK#/FLEET# HAJF9N4LTNG248869 Case IH 9250 Combi 893 YNG248869 9250 Pulley Assembly 179.96 89.98 Bearing, 2 87605590 OEM CNH-Genuine (Bearings) Bearing 1557.48 PARTS LABOR 1462.50 SEGMENT TOTAL ==> 3019.98 10400

SEGMENT# 6 S 02016 NA

03/04/25 03/06/25

Repair chopper

CUSTO COMPLAINT

- -internal chopper blades bent.REPLACE FULL SET
- -internal chopper bottom concave frame has hole.REPAIR
- -internal chopper overhead sheetmetal right side has

hole.PATCH

- -RH rear and LH rear plastic shields have holes.
- -Redekop RH door handle broken.
- -Redekop RH rear deflector broken.REPAIR
- -Redekop rear bottom deflector bent.STRAIGHTEN
- -Redekop chopper blades worn out.
- -Redekop left rear hyd motor mount cracked.
- -Redekop left rear deflector bolt missing.
- -Redekop chopper stationary knife back panel has hole-PATCH

CORRECTION:

Internal chopper blades bent, replace 4 blades. Flip remaining internal chopper blades. Apply blue loctite to all bolts. Repair internal chopper bottom concave frame. Install sheet metal. Patch internal chopper overhead sheet metal.

- Redekop RH door handle broken, only one broken piece that

CONTINUED ON PAGE 10

updates and/or dagnostics to a modified system. RE and its employees may operate the above meakine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to redelivery of the machine or on terms satisfactory to RE until paid in full. Registration of a commercial fen is acknowledged on the above machine to secure the amount of repairs therefor. It is understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts are not understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts are not understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts are not understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts are not understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts are not understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field festing. Special order and electrical parts are not understood that RE assumes no responsibility for loss or damage by their or fire and control order and the special parts are not understood that RE assumes not the fire of the special parts are not an electrical parts are		R
SIGNATURE:	DATE:	Authorized Farm Signature
PRINT NAME:	GST #834643868	



Head Office Box 32098 10 Redhead Roa SAN 71 2 800 667 7710

IN STORE PICKUP

ö

ö

	6.445.8128 6.763.6454	KINISTINO	306	.864.366/
For additional contag		n visit redhea	dequipme	nt.ca
Branch				
ESTEVAN				
Date	Time			Page
03/18/25	08	:53:32 (0)	1.0
Account No.	Phone	No.	Invo	ice No.
Ship Via		Purchase 0	Order	
				
_				
			Salespers	on

SWIFT CURRENT

SASKATOON

HUMBOLDT

306,634,4788

306.825.3434

306 752 2273

306.773.2951

306.934.3555

306.682.9920

SERVICE PRELIMINARY

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

CONTINUED ON PAGE 11

ESTEVAN

MELFORT

LLOYDMINSTER

HRS

Case IH 9250 Combi

893 HAJF9N4LTNG248869

525

9250

YNG248869

was left. Welded metal to make new door handle & drill bolt hole for the door. Install door handle .

- Redekop RH rear deflector broken. Remove deflector and weld broken piece back together. Grind, paint and install deflector.
- Redekop chopper blades worn out. Replace all with new blades. Apply blue loctite on bolts.
- Redekop left rear HYD motor mount cracked. Remove, grind and weld mount. Paint mount.
- Redekop stationary blade assembly has multiple cracks and is bent. Remove assembly and plates & blades. Grind paint off cracks and weld. Grind, weld. Heat with torch to straighten knife holder as well as the plate cover for the knives. Paint and install whole assembly back.
- Patch hole in Redekop stationary knife back panel.

______ 368.00 368.00 Bushing, BK553 OEM Redekop-Genuine Bushing Kit - HA650 Straight Chopper Blade 3024.00 252.00 12 BK655C Knife, OEM Redekop-Genuine Serrated Chopper Blade Knife Kit Threadlocker, 40.77 40.77 0516624240 OEM Mack/Permatex®-Genuine Blue Removable Strength Threadlocker 306.00 306.00 Cover, 73340388 OEM CNH-Genuine (Crop Harvesting) Chopper Grate Cover Kit 3738.77 PARTS LABOR 2730.00

I hereby authorize the above work to be done along with the use of any necessary materials. I agree that Redhead Equipment ("RE") may access and utilize any electronic data stored or available on the machine including remote access, for the purpose of diagnosing, repairing, or servicing the machine or its components. RE will not be responsible for any costs incurred resulting from software updates and/or diagnostics to a modified system. RE and its employees may operate the above machine to rispection, testing or delivery at my sole risk. I agree to pay cash prior to redelivery of the machine or on terms satisfactory to RE until peld in full. Registration of a commorcial in a schrowledged on the above machine to secure the amount of repairs thereto. It is understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or white field testing. Special order and electrical parts are not returnable. Any stocking parts returned after 30 days will be subject to a 15% restocking charge. RE cannot accept any part returns on weekends or after hours. Part returns are not accepted after one superior of the common statement o

Land Description SecTwsp RM, I hereby certify the goods listed on this invoice will be used solely in the operation of my farm.
Date

SIGNATURE:	 DATE:
DDINT NAME.	GST #834643868



Regina, SK Head Office Box 32098 10 Redhead Road S4N 7L2 306.721.2666

30 Kedan Sah 306.72 800.66

IN STORE PICKUP

Ship to:

voice to:

NORTH BATTLEFORD	306.445.8128	KINISTINO	3	06.864.3667
PRINCE ALBERT	306.763.6454			
For additional cor	tact informat	ion visit redhea	adequipm	ent.ca
Branch				,, ,
ESTEVAN				
Date	Time			Page
03/18/25	o	8:53:32 (0)	11
Account No.	Phone		Inv	oice No.
Ì				
Ship Via		Purchase	Order	
'				
			Salespe	rson

SWIFT CURRENT

SASKATOON

HUMBOLDT

306.634.4788

306.825.3434

306.752.2273

SERVICE PRELIMINARY

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

SEGMENT TOTAL ==>

ESTEVAN

MELFORT

LLOYDMINSTER

HRS

Case IH 9250 Combi

893 HAJF9N4LTNG248869

nks

9250

525 YNG248869

10400

6468.77

306.773.2951

306.934.3555

306.682.9920

SEGMENT# 7 S 02016 NA

03/04/25 03/11/25

03/04/25 03/11/25

Repair rear ladder wont stay in position

CORRECTION:

Inspect engine laddder and find at top LH bottom cracked bracket. Remove LH top and side plastic panels. Disconnect exhaust DEF NOX harness. Unbolted and remove cracked bottom leader bracket. Remove all leader LH handle. Weld bracken bracket. Bend correct leader handle. Bolted leader handle on. Bolted bottom leader bracket. Connect harness,. Install LH and side plastic panels. ======

LABOR

390.00

10400

SEGMENT TOTAL ==>

SEGMENT# 8 S 02016 NA

Repair hyd leaks

CUSTO COMPLAINT

- -steering handpump hyd hose twisted under cab.
- -hyd line leaking on left side above front axle.
- -PFC pump hose sweating, need dual clamp.

CORRECTION:

Find hyd hose from steering hand pump under cab is twisted.

Loosen hyd hose and tighten correctly.

Find LH front axle hyd hose sweating oil. Check hose,

loose. Tighten hyd fitting.

Find PFC pump hyd oil hose sweating. Install dual clamps.

Q4485ET28

SIGNATURE: _

PRINT NAME:

Clamp,

1.54

OEM Mack/Fairview Fittings-Genuine Ext.

CONTINUED ON PAGE 12

1.54

I beligh stilliouse the spoke work to be done stoll design with the need of sub-lines and stoll design and stollar design and s
the machine including remote access, for the purpose of diagnosing, repairing, or servicing the machine or its components. RE will not be responsible for any costs incurred resulting from software
updates and/or diagnostics to a modified system. RE and its employees may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to
redefivery of the machine or on terms satisfactory to RE until paid in full. Registration of a commercial lien is acknowledged on the above machine to secure the amount of repairs thereto. It is
regardery of the machine or on terms substituting to the unit paid in this regarders of a contract of the machine or on terms substituting to the contract of the machine or on terms substituting the contract of the machine or on terms substituting the contract of the machine or on terms substituting the contract of t
understood that RE assumes no responsibility for loss or damage by theft or fire to any machine placed with them for storage, sale, repeir or white field testing. Special order and electrical parts are not
returnable. Any stocking parts returned after 30 days will be subject to a 15% restocking charge. RE cannot accept any part returns on weekends or after hours. Part returns are not accepted after one
year from the original invoice date. All part returns require the original invoice and packaging. No title passes on purchased machines until the applicable invoice is paid in full. 2% per month will be
year not not distinguish thouse accounts (24% per annum). Parts & Service are not 30 days. Whole goods and rental payments are due on delivery.
charged on all overdue accounts (24% per annum). Parts a Service are not 50 days. While goods and remain payments and due on dealers.

 DATE:	į
GST #834643868	_

Farm Customers Only
Land Description Sec Twsp
R , I hereby certify the
goods listed on this invoice will be used
solely in the operation of my farm.

Date
Authorized Farm Signature
Date Authorized Farm Signature



Regina, 5 K Head Office Box 32098 10 Redhead Road S4N 7L2 306.721.2666 800.667.7710

SWIFT CURRENT 306.773.2951 306.634.4788 **ESTEVAN** LLOYDMINSTER 306.825.3434 SASKATOON 306.934.3555 MELFORT HUMBOLDT 306,752,2273 NORTH BATTLEFORD 306.445.8128 KINISTINO 306.864.3667 PRINCE ALBERT 306.763.6454

PRINCE ALBERT 306.763.6454

For additional contact information visit redheadequipment.ca

Branch

ESTEVAN

Date Time Page

03/18/25 08:53:32 (0) 12

Account No. Phone No. Invoice No.

Ship Via Purchase Order

Salesperson

IN STORE PICKUP

Ship to:

nvoice to:

SERVICE PRELIMINARY

HRS PIN/EIN

WARRANTY DATE

HRS

043739

10400

Case IH 9250 Combi

893 HAJF9N4LTNG248869

525 YNG248869

1-3/4" Tongue Clamp

PARTS LABOR 1.54 117.00

9250

SEGMENT TOTAL==>

118.54

SEGMENT# 9 S 02016 NA

03/04/25 03/11/25

Repair oil leak on top of transmission-DIAGNOSIS REQUIRED CUSTO COMPLAINT

- -transmission oil low.
- -transmission oil leak on top of transmission.

CORRECTION:

Unbolt front transmission rubber cover. Blow out top of transmission housing. Remove transmission housing bottom grille. Inspect top of transmission housing oil leak. Find oil leak from speed sensor. Disconnect harness. Unbolt transmission speed sensor and find sensor o ring is cracked. Replace o ring. Install speed sensor. Connect harness. Find transmission oil is low. Top up transmission oil to correct level. Bolt on front rubber cover.

EHCOIL 4

EHCOIL EHC4LT 73344265

EHC Container Oil,1Ga 4 .06 1 .48

1

.24

41.49

OEM CNH-Genuine Hytran® Premium Hydraulic Transmission Oil 1

Gallon/3.78 Litre

PARTS

41,49

42.21

Man.

LABOR

312.00

10400

SEGMENT TOTAL ==>

354.21

CONTINUED ON PAGE 13

Thereby authorize the above work to be done along with the use of any necessary materials. I agree that recones a Equipment ("RE") may access and usize any electronic data scored to available on
the machine including remote access, for the purpose of diagnosing, repairing, or servicing the machine or its components. RE will not be responsible for any costs incurred resulting from software
updates and/or diagnostics to a modified system. RE and its employees may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to
redelivery of the machine or on terms satisfactory to RE until paid in full. Registration of a commercial lien is acknowledged on the above machine to secure the amount of repairs thereto. It is
understood that RE assumes no responsibility for loss or damage by theft or fire to any machine placed with them for storage, sale, repair or while field testing. Special order and electrical parts are not
returnable. Any stocking parts returned efter 30 days will be subject to a 15% restocking charge. RE cannot accept any part returns on weekends or after hours. Part returns are not accepted after one
year from the original invoice date. All part returns require the original invoice and packaging. No title passes on purchased machines until the applicable invoice is paid in full. 2% per month will be
charged on all overdue accounts (24% per annum), Parts & Service are net 30 days. Whole goods and rental payments are due on delivery.

od O	RM, I hereby certify the goods listed on this invoice will be used solely in the operation of my farm.
	Date
	Authorized Farm Signature

SIGNATURE:	 DATE:
PRINT NAMF:	GST #834643868



Regina, SK Head Office Box 32098 10 Redhead Road S4N 7L2 306.721.2666 800.667.7710

ESTEVAN 306.634.4788 SWIFT CURRENT 306.773.2951 LLOYDMINSTER 306.825.3434 SASKATOON 306.934.3555 HUMBOLDT 306.682.9920 MELFORT 306.752.2273 KINISTINO 306.864.3667 NORTH BATTLEFORD 306.445.8128

306.763.6454 PRINCE ALBERT

For additional contact information visit redheadequipment.ca Branch ESTEVAN Date Time Page 03/18/25 Account No. 08:53:32 (O) Phone No. 13 Invoice No. Ship Via ruichase Oluer Salesperson

IN STORE PICKUP

Ship to:

₽

				<u> </u>			
		SERVI	CE PRE	LIMINAF	RY		
STK#/FLEET:	#	HRS PI	•		TY DATE	HRS	
043739	Case IH 9250 Combi 9250		JF9N4LTNG: IG248869	248869			
	orn fuel lines	03/04/25 0	3/11/25				
-fuel line of wear a	es from high pressure t clamp.	pump to fi	lter have	lots	ok)		
CORRECTION Inspect ex	<u>N:</u> ngine fuel lines and f	ind line o	lamps wor	n.			
Install n	ew zip ties.					*	
=======	=======================================	========	:=======		LABOR	tr.	39.00
10400				SEGMENT 1	344 Sept. 1920 St. 2013 St. 20		39.00
		03/04/25)3/11/25				
Repair un				. V. 1995 1. V. 1995			
CUSTO COM	Chains loose, have lo	ts of wear	c .				
	wont go into cradle.	, ob					
CORRECTIO		35,45.					
Adjust un	load auger and grain t	ank bubble	e up auger	drive			
chains. U	nload auger chain is q	ood. Unloa	ad vertica	l auger			
drive cha	in adjusted almost to	maximum. 9	Spray with	chain			
	ove unload vertical au	ger drive	chain. In	stall new			
chain and				- Obl-			
	oad auger won't close.	. Adjust a	iger saddi	e. Check			
	ow it is closed.			========			
51436188		Chain,		1	177.43		177.43
	OEM CNH-Genuine	e (Roller (Chain & Ma	nure			
	Spreader Chain	Chain					4.55 4.5
				CONTI	PARTS NUED ON PA	GE 14	177.43

I hereby authorize the above work to be done along with the use of any necessary materials, I agree that Redhead Equipment ("RE") may access and utilize any electronic data stored or available on the machine including remote access, for the purpose of diagnosing, repairing, or servicing the machine or its components. RE will not be responsible for any costs incurred resulting from software updates and/or diagnostics to a modified system. RE and its employees may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to redelivery of the machine or on terms satisfactory to RE until peid in full. Registration of a commercial is acknowledged on the above machine to secure the amount of repairs thereto. It is understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or while field testing. Special order and electrical parts are no returnable. Any stocking perts returned after 30 days will be subject to a 15% restocking charge, RE cannot accept any part returns on weekends or after hours. Part returns are not accepted after any part returns or not excepted after any part returns or not accepted after any part returns or not accepted after hours. Part returns are not accepted after hours and part returns are not accepted after hours. Part returns are not accepted after hours are not accepted after hours. Part returns are not accepted after hours are not accepted after hours. Part returns are not accepted after hours have returned after hours and accepted after hours. Part returns are not accep

n	Farm Customers Only
,	Land Description SecTwsp R M , I hereby certify the goods listed on this invoice will be used
ne	solely in the operation of my farm.
	Date
	Authorized Farm Signature

DATE: _ SIGNATURE: GST #834643868 PRINT NAME:



Regina, SK Head Office Box 32098 10 Redhead Road S4N 7L2 306.721.2666 800.667.7710

SWIFT CURRENT 306.773.2951 **ESTEVAN** 306.634.4788 LLOYDMINSTER 306.825.3434 SASKATOON 306.934.3555 MELFORT 306.752.2273 HUMBOLDT 306.682.9920 NORTH BATTLEFORD 306.445.8128 KINISTINO 306.864.3667

| Salesperson |

Authorized Farm Signature

IN STORE PICKUP

Ship to:

Invoice to:

SIGNATURE:

PRINT NAME:

	0-01/10-00-00-		
	SERVICE PRE	LIMINARY	
STK#/FLEET# Case IH 9250 Comb 9250	HRS PIN/EIN bi 893 HAJF9N4LTNG2 525 YNG248869	WARRANTY DATE HRS 248869 LABOR	234.00
10400		SEGMENT TOTAL==>	411.43
SEGMENT#12 S 02016 NA Replace batteries CORRECTION: Unbolt battery cover. Remove clamps. Replace batteries. Cobracket and bolt on cover.	Connect clamps. Install Install two new missing	battery bolts.	
	Core-Battery Battery,P-Style ide-Genuine 925 CCA 1129 year free replacement	2- 27.00 2 129.99	54.00- 259.98
Q355131G925CC	Core-Battery	2 27.00	54.00
		PARTS LABOR	259.98 117.00
10400		SEGMENT TOTAL==>	376.98
SEGMENT#13 S 02016 NA Repair service brake pedal CORRECTION: Run combine and check service work good.	[18] (19] 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	R brakes	
		LABOR	58.50
10400		SEGMENT TOTAL ==>	58.50
SEGMENT#14 S 02016 NA Thereby authorize the above work to be done along with the use of	03/04/25 03/14/25	CONTINUED ON PAGE 15	Farm Customers Only
updates and/or diagnostics to a modified system. RE and its empt redelivery of the machine or on terms satisfactory to RE until paid understood that RE assumes no responsibility for loss or damage	cyces may operate the above machine for the purposes of insi- in full. Registration of a commercial fen is acknowledged on the by theft or fire to any machine placed with them for storage, sa ct to a 15% restocking charge. RE cannot accept any part fetur inal invoice and packaging. No little passes on purchased mach	le, repair or while field testing. Special order and electrical parts are no ns on weekends or after hours. Part returns are not accepted after on thes until the applicable invoice is paid in full. 2% per month will be	Land Description Sec Twep R M , 1 hereby certify the goods listed on this invoice will be used solely in the operation of my farm.

DATE: _

GST #834643868



IN STORE PICKUP

Box 32098 S4N 7L2 800 667 7710

ESTEVAN

MELFORT

LLOYDMINSTER

Regina, SK Head Office

NORTH BATTLEFORD	306.445.8128	KINISTINO	30	6.864.3667
PRINCE ALBERT	306.763.6454			
For additional cor	ntact informatio	n visit redhe	adequipme	nt.ca
Branch				
			ì	
ESTEVAN				
Date	Time			Page
	1			1
<u>03/18/25</u>		:53:32	(0)	115
Account No.	Phone	No.	Invo	ice No.
			i	
- AT: 17		16		
Ship Via		Purchase	Orger	
				
		1		
		1		
			Salesper	eon .
			- Calesper	3 011

SWIFT CURRENT

SASKATOON

HUMBOLDT

306.634.4788

306.825.3434

306 752 2273

306.773.2951

306.934.3555

306.682.9920

SERVICE PRELIMINARY

STK#/FLEET#

;; Ship

> PIN/EIN HRS

WARRANTY DATE

HRS

Case IH 9250 Combi

HAJF9N4LTNG248869 893

9250

525

YNG248869

Run and test operation

CORRECTION:

Run combine and test all options.

390.00 LABOR SEGMENT TOTAL ==> 390.00

SEGMENT#15 S 02016 NA

Winter Works Inspection REDHEAD LOYALTY REWARDS

Winter Works

03/04/25 03/18/25

1210.95

1210.95-

Parts And Service Promotion

PARTS

1210.95-

10400

10400

39904410

SEGMENT TOTAL ==>

1210.95-

***** WORK ORDER TOTALS ***** PARTS 7939.64 12109.50 LABOR SHOP SUPPLIES 1089.85 21138.99 SUB TOTAL ==>

GST 5% 83464 3868 1056.98 22195.97 TOTAL

I hereby authorize the above work to be done along with the use of any necessary materials. I agree that Redhead Equipment ("RE") may access and utilize any electronic data stored or available on the machine including remote access, for the purpose of diagnosting, repairing, or servicing the machine or its components. RE will not be responsible for any costs incurred resulting from software updates endor diagnostics to a modified system. RE and its employees may operate the above machine for the purposes of inspection, testing or delivery at my sole risk. I agree to pay cash prior to redelivery of the machine or on terms setistaciony to RE until pel of in till. Registration of a commercial fen is acknowledged on the above machine to secure the amount of repairs thereto. It is understood that RE assumes no responsibility for loss or damage by their or fire to any machine placed with them for storage, sale, repair or while field testing. Special order and electrical parts are not returnable. Any stocking parts returned after 30 days will be subject to a 15% reslocking charge. RE cannot accept any part returns on weekends or effer hours. Part returns or end to accepted after one year from the original invoice date. All part returns require the original invoice and peckaging. No title passes on purchased machines until the applicable invoice is paid in full. 2% per month will be charged on all overdue accounts (24% per annum). Parts & Service are net 30 days. Whole goods and rental payments are due on delivery.

Farm Customers Only
Land Description Sec Twsp
R, I hereby certify the
goods listed on this invoice will be used
solely in the operation of my farm.
Date

Authorized Farm Signature

SIGNATURE:	 DATE:
PRINT NAME:	GST #834643868