

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

Service
Invoice



SOLD TO:

TREWIN FARM CORP.
STK # 09203362
G/L# 105-00-000322
S/N # 1RW9520RLKP062315

TAX EX # NW 02-44-05 W3

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.
3200187

INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9203362

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN	
	306-223-4468	9203362	02	24SEP24		
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	9520R	1RW9520RLKP062315	9520R 52	1173		

DESCRIPTION	AMOUNT
DIAGNOSE ENGINE RUNNING ISSUE COMPLAINT: COMPLAINT OF ENGINE RUNNING ISSUE CAUSE: FAILED ECU ON UNIT. CORRECTION: 2.00H-DO VISUAL INSPECTION INCLUDING FLUID LEVELS. CHECK ACTIVE AND STORED DTC. OPEN SERVICE ADVISOR JOB. CONNECT LIVE AND SAVE SNAPSHOT DATA. CLEAR ALL DTC'S. START ENGINE, ENGINE CRANK BUT WILL NOT START. NO DTC RETURN. CLEAN ECU AND INJECTOR CIRCUIT CONNECTION POINTS, DISCONNECT BATTERY NEGATIVE CABLE, REMOVE CONNECTORS AND PERFORM ECU AND INJECTOR HARNESS CONNECTOR TEST, NO PROBLEMS FOUND. CHECK ECU POWER SUPPLY AND GROUND RESISTANCE. CHECK DTC'S STORED AND PRIORITIES DTC'S FOR DIAGNOSTICS. WITH SERVICE ADVISOR STILL CONNECTED OPEN RECORDING WITH NEEDLE AND SPILL CONTROL VALVE CURRENT DATA POINTS. HAVE THE ONE SET TRUE RIGHT AFTER THE OTHER CONCLUDING BAD ECU. 1.50H-ESTABLISH INTERNET CONNECTION, SWITCH TO SERVICE ADVISOR LIVE. CANT	

QST # 1226957240		DESCRIPTION	AMOUNT
PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50. I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. X _____ SIGNATURE _____ DATE		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES SALES TAX	
		PLEASE PAY THIS TOTAL	***CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

Service Invoice



INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9203362

SOLD TO:

TREWIN FARM CORP.
STK # 09203362
G/L# 105-00-000322
S/N # 1RW9520RLKP062315

PAGE
2
SALE TYPE
WARRANTY
CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

TAX EX # NW 02-44-05 W3

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPER	AUTHORIZED BY
	306-223-4468	9203362	02	24SEP24		
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER		
JD	9520R	1RW9520RLKP062315	9520R 52	1173		

DESCRIPTION	AMOUNT
FIND OF LINE RECORDING. RE-DO RECORDING. DOWNLOAD ECU SOFTWARE, START REPROGRAMING. SWITCH IGNITION OFF AND REMOVE BATTERY NEGATIVE AGAIN. REMOVE SHIELDS, CLEAN FUEL HOSE ENDS, REMOVE AND CAP HOSES, REPLACE FUEL COOLED ECU AND ASSEMBLE IN REVERSE ORDER. COMPLETE SOFTWARE DOWN LOAD. TEST ECU OPERATION. CHECK NO FUEL LEAKS. INSTALL SHIELDS. ACC	
EMMISSIONS CLAIM	
1 D2115243 ENGINE C	2,545.31
** TOTAL LABOR **	722.50
AG CARBON TAX SURCHG	14.45
>>--> SEG# 02 PRT 2,545.31 LAB 722.50 MSC	14.45
	3,282.26

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUUM). MINIMUM CHARGE OF \$1.50.		DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.		TOTAL PARTS	2,545.31
		TOTAL LABOR	722.50
		MISC. CHARGES	14.45
		SALES TAX	0.00
X _____ SIGNATURE		DATE	
		PLEASE PAY THIS TOTAL	3,282.26

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

Service Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9203362

SOLD TO:

TREWIN FARM CORP.
STK # 9203362
G/L# 532-00-322322
S/N # 1RW9520RLKP062315

PAGE
1
SALE TYPE
INTERNAL
CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

TAX EX # NW 02-44-05 W3

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
	306-223-4468	9203362	01	24SEP24		
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	9520R	1RW9520RLKP062315	9520R 52	1173		

DESCRIPTION	AMOUNT
TRAVEL	
CORRECTION:	
-TRAVEL TO MACHINE LOCATION IN LAIRD	
AND BACK TO ROSTHERN.	
-PLEASE PROVIDE CURRENT ENGINE HOURS	
* LABOR *	837.50
AG CARBON TAX SURCHG	16.75
>>--> SEG# 01 PRT .00 LAB 837.50 MSC 16.75	854.25

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50. I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. X _____ SIGNATURE _____ DATE	DESCRIPTION	AMOUNT
	TOTAL PARTS	0.00
	TOTAL LABOR	837.50
	MISC. CHARGES SALES TAX	16.75 0.00
PLEASE PAY THIS TOTAL ➔		854.25

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

**Service
Invoice**



SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9205532

PAGE 1 SALE TYPE
CASH CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
	306-223-4468	9205532	01	10OCT25	438	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	9520R	1RW9520RLKP062315	9520R 52	1435		

DESCRIPTION	AMOUNT
INSPECTION	
COMPLAINT: -LOOK OVER INSTRUCTIONS FOR REMOVING AXLE. SPENT TIME TRYING TO FIND BEST WAY TO JACK UP TRACTOR AND WERE TO PLACE STANDS.	
CORRECTION: -REMOVED FRONT AXLE SUSPENSION HARNESS CONNECTION, LOOKED UP PROCEDURE AND RELIEVED PRESSURE FROM HYDRAULIC LINES. REMOVED 4 LINES AND CAPPED. CLEANED UP SPILT OIL AND TABLE. SUPPORTED ACCUMULATOR ASSEMBLY AND REMOVED BRACKET HARDWARE. REMOVED ASSEMBLY FROM TRACTOR. TOOK ACCUMULATORS TO WASH BAY AND CLEANED UP. NEXT GOT ALL BLOCKS AND JACKSTANDS NEEDED. JACKED UP TRACTOR AND SET ON STANDS. COULD REMOVE ONE SET OF DRIVESHAFT YOLK BOLTS BUT COULD NOT GET OTHER SIDE OFF DUE TO SPACE. STARTED TRACTOR AND PUT TRANSMISSION IN NEUTRAL BUT STILL COULD NOT GET DRIVESHAFT TO TURN ENOUGH TO GET OUT OTHER YOLK BOLTS. CLEANED UP TOOLS TO START OTHER JOB.	
1 N AR69444 HY-GARD	153.27
1 N 3958 EHC O	3.60
* LABOR *	
	1,399.00

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUUM). MINIMUM CHARGE OF \$1.50. I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. X _____ SIGNATURE _____ DATE	DESCRIPTION	AMOUNT
	TOTAL PARTS	
	TOTAL LABOR	
	MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL ➔		**CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

Service Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9205532

SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

PAGE
2
SALE TYPE
CASH
CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
	306-223-4468	9205532	01	10OCT25	438	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	9520R	1RW9520RLKP062315	9520R 52	1435		

DESCRIPTION						AMOUNT
1	AG PARTS DISC ALLOW				209.47-	209.47-
	AG SERVICE ACCESSORI				125.91	125.91
	ENVIRONMENTAL FEE				13.99	13.99
>>--> SEG# 01 PRT 133.88 LAB 1,399.00 MSC 69.57-						1,463.31
* GST/HST *						73.17
CHANGE ALL AIR FILTER & GREASE VAR FAN AND BREATHERS						
CORRECTION:						
-REPLACED ALL AIR FILTERS AND FOLLOWED						
PROCEDURE IN SERVICE ADVISOR TO GREASE						
FAN DRIVES, MARKED DATES ON FILTERS.						
1	N TA32591	AIR FILT			120.65	108.59
2	N RE594852	AIR FILT			352.44	634.39
1	N TY25744	GREASE			26.70	24.03
1	N DZ112918	FILTER			245.52	208.69
2	N 3962	EHC F			1.25	2.50
1	N DZ130550	FILTER			241.64	217.48
1	N RE291412	AIR FILT			133.61	113.57
* LABOR *						370.00
	AG SERVICE ACCESSORI				33.30	33.30
	ENVIRONMENTAL FEE				3.70	3.70
>>--> SEG# 02 PRT 1,309.25 LAB 370.00 MSC 37.00						1,716.25
* GST/HST *						85.81
SOFTWARE UPDATE X4 (INCL DISPLAY)						
COMPLAINT:						
-LOOK UP UPDATES ON UNIT						

QST # 1226957240		DESCRIPTION	AMOUNT
PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50. I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. X _____ SIGNATURE _____ DATE		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES	
		SALES TAX	
		PLEASE PAY THIS TOTAL	**CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

**Service
Invoice**



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9205532

SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

PAGE
3
SALE TYPE
CASH
CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
I
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
	306-223-4468	9205532	03	21OCT25	438	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	9520R	1RW9520RLKP062315	9520R 52	1435		

DESCRIPTION	AMOUNT
CORRECTION: -COMPLETE SOFTWARE UPDATES FOR CAB, DISPLAY, OTHER UPDATE FROM DISPLAY AND GPS RECEIVER. * LABOR * AG SERVICE ACCESSORI 49.95 ENVIRONMENTAL FEE 5.55 >>--> SEG# 03 PRT .00 LAB 555.00 MSC 55.50 * GST/HST * 30.53 REPLACE FRT AXLE INPUT SEAL COMPLAINT: -WIPE OFF LEAK AND VERIFY LEAK CAUSE: -LEAKING INPUT SEAL CORRECTION: -LOWERED TRACTOR SUSPENSION ALL THE WAY DOWN. LOCKED OUT TRACTOR. GOT ALL STANDS, BLOCKS AND BOTTLE JACKS TO LIFT UP TRACTOR. RELIEVED SYSTEM PRESSURE FOR SUSPENSION. REMOVED AND CAPPED LINES TO FRONT SUSPENSION. REMOVED ELECTRICAL TO SUSPENSION. SUPPORTED FRONT ACCUMULATORS AND REMOVED BRACKET HARDWARE. REMOVED ACCUMULATOR ASSEMBLY, WASHED ASSEMBLY AND PUT TO THE SIDE.	555.00 49.95 5.55 610.50

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.		DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. X _____ SIGNATURE _____ DATE		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES SALES TAX	
		PLEASE PAY THIS TOTAL	**CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rossmore, SK S0K 3R0
(306) 232-4852

Service Invoice



INVOICE DATE	BRANCH	INVOICE NO.
20JUL26	322	9205532

SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

PAGE 4 SALE TYPE
CASH CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
LAIRD, SK S0K 2H0
T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	AUTHORIZED BY
	306-223-4468	9205532	04	21OCT25	438	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER		
JD	9520R	1RW9520RLKP062315	9520R 52	1435		

DESCRIPTION	AMOUNT
NEXT JACKED UP TRACTOR AND REMOVED BOTTOM REAR DRIVE SHAFT BOLTS. LOOKED UP ALL SPECIAL TOOLS NEEDED FOR JOB AND ORDERED TOOLS. REMOVED REAR SUSPENSION ARM GREASE LINES. REMOVED REAR SUSPENSION SENSOR BRACKET. REMOVED TOW CABLE. STARTED TRACTOR AND PUT IN NEUTRAL. COULD GET DRIVE SHAFT TO ONLY TURN A SMALL AMOUNT. HAD TO SET TRACTOR BACK ON GROUND AND DRIVE FORWARD TO GET OTHER DRIVESHAFT BOLTS REMOVED. JACKED TRACTOR BACK UP AND SET ON STANDS. REMOVED OUTER WHEELS, WHEEL HUBS AND INNER WHEELS. GOT BLUE CRANK AND HOOKED UP TO AXLE. SUPPORTED SUSPENSION ARM AT REAR OF DIFF. REMOVED SUSPENSION CYLINDER TO DIFF HARDWARE. REMOVED REAR SUSPENSION ARM PINS. ONE PIN WAS RUSTED IN AND TOOK A LONG TIME TO REMOVE PIN FROM THE LEFT SIDE. AFTER PINS WERE REMOVED HAD TO JACK UP TRACTOR MORE AND REMOVED DIFF FROM TRACTOR. SET DIFF ON BLOCKS REMOVED REAR DIFF ARM ASSEMBLY. CLEANED OUT GREASE AND DIRT FROM DIFF ARM BUSHINGS. REPLACED ONE SEAL THAT WAS DAMAGED ON RIGHT SIDE DUE TO REMOVAL OF HARD TO GET OUT PIN. CLEANED AND BUFFED OFF BOTH PINS AS WELL. CLEANED OUT RUST AND DEBRIS FROM PIN SUPPORTS IN FRAME WITH A WIRE WHEEL. GREASED BUSHINGS FOR INSTALLATION. TOOK	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUAL). MINIMUM CHARGE OF \$1.50.		QST # 1226957240	DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.			TOTAL PARTS	
			TOTAL LABOR	
			MISC. CHARGES SALES TAX	
			PLEASE PAY THIS TOTAL	**CONTINUED**
X _____ SIGNATURE		_____ DATE		

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

**Service
Invoice**



SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

INVOICE DATE	BRANCH	INVOICENO.
20JUL26	322	9205532

PAGE
5
SALETYPE
CASH
CUSTOMERNO.
3200187

5 TREWIN FARM CORP.
H BOX 102
I
P
LAIRD, SK S0K 2H0
T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
	306-223-4468	9205532	04	21OCT25	438	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY	
JD	9520R	1RW9520RLKP062315	9520R 52	1435		

DESCRIPTION	AMOUNT
DIFFERENTIAL TO WASH BAY AND CLEANED OFF ALL DEBRIS FROM LEAKING SEAL. GOT DIFF BACK TO BAY AND REMOVED AXLE YOLK. REMOVED SEAL AND INSTALLED NEW SEAL. -GOT TOOL MADE TO HOLD YOLK TO TORQUE INPUT YOLK. PUT IN NEW SEALS WITH YOLK AS WELL. INSTALLED SUSPENSION ARM BACK ONTO DIFF AND TIGHTENED BOLTS TO SPEC. GOT DIFF READY FOR INSTALLATION. GOT LUCAS M TO HELP INSTALL DIFFERENTIAL. TOOK QUITE A BIT OF JACKING TRACTOR AND SUSPENSION ARM TO LINE UP DIFF IN TRACTOR AND GET SUSPENSION ARM PINS INSTALLED. AFTER THAT INSTALLED ALL OTHER PREVIOUSLY REMOVED COMPONENTS TIGHTENING HARDWARE TO SPEC. NOTICED THAT PICK UP TUBE LINE TO BOTTOM OF DIFF SPINS. LUCAS M REMOVED SHIELD AND TRIED TO TIGHTEN TOP BOLTS BUT THEY WERE ALREADY TIGHT. THAT IS THE WAY THEY WERE BEFORE ANY WORK WAS STARTED AND WAS NOT LEAKING. DECIDED TO CHECK FOR ANY LEAKS FOR THAT HOSE AFTER START UP. INSTALLED INNER WHEELS, TORQUED WEDGES TO SPEC. DROVE TRACTOR IN BETWEEN AND CHECKED TORQUE AGAIN. INSTALLED OUTER WHEEL HUBS AND TIGHTENED WEDGES TO SPEC. INSTALLED WHEELS. CHECKED TORQUE AFTER DROVE TRACTOR. TOOK TRACTOR DOWN ROAD AND BACK TO CHECK FOR LEAKS. DID NOT HAVE	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.		QST # 1326957240	DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.			TOTAL PARTS	
			TOTAL LABOR	
			MISC. CHARGES	
			SALES TAX	
X _____ SIGNATURE			PLEASE PAY THIS TOTAL ➔ **CONTINUED**	
_____ DATE				

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

Service Invoice



JOHN DEERE

SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

INVOICE DATE	BRANCH	INVOICENO.
20JUL26	322	9205532

PAGE
6
SALE TYPE
CASH
CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	AUTHORIZED BY
	306-223-4468	9205532	04	21OCT25	438	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER		
JD	9520R	1RW9520RLKP062315	9520R 52	1435		

DESCRIPTION						AMOUNT
ANY LEAKS. INSTALLED SHIELDS.						
1	N	RE329255	SEAL	XY		120.88
1	N	AR69444	HY-GARD			130.28
1	N	3958	EHC	O		3.60
1	N	Y2502316	V-RING	SCY		45.19
2	N	T39414	O-RING			32.64
1	N	R568163	O-RING	CY		22.92
1	N	T102137	SEAL	CY		41.19
1	N	R72560	O-RING	XY		15.18
1	N	PM38627	LIQUID	G		78.79
1	N	RE330747	POSITION	XY		160.94
		* LABOR *				9,250.00
		AG SERVICE ACCESSORI				832.50
		ENVIRONMENTAL FEE				92.50
>>--> SEG# 04 PRT 651.61 LAB 9,250.00 MSC 925.00						10,826.61
* GST/HST *						541.33
YELLOW ITEMS						
SMV SIGN DAMAGED						
ENGINE CRANKING LONG TO START						
TOPPED UP HYD OIL						
HOOD LATCH NOT WORKING						
WHEEL TORQUE ?						
>>--> SEG# 05 PRT .00 LAB .00 MSC .00						.00
FULL WASH AND DETAIL						

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.		QST # 1226957240	DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. X _____ SIGNATURE _____ DATE			TOTAL PARTS	
			TOTAL LABOR	
			MISC. CHARGES SALES TAX	
			PLEASE PAY THIS TOTAL	**CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
911 Saskatchewan Street
Box 279
Rosthern, SK S0K 3R0
(306) 232-4852

**Service
Invoice**



JOHN DEERE

INVOICE DATE	BRANCH	INVOICENO.
20JUL26	322	9205532

SOLD TO:

TREWIN FARM CORP.
BOX 102

LAIRD, SK S0K 2H0

TAX EX # NW 02-44-05 W3

PAGE
7
SALETYPE
CASH
CUSTOMER NO.
3200187

S TREWIN FARM CORP.
H BOX 102
P
T LAIRD, SK S0K 2H0
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	AUTHORIZED BY
	306-223-4468	9205532	06	21OCT25	438	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER		
JD	9520R	1RW9520RLKP062315	9520R 52	1435		

DESCRIPTION	AMOUNT
CUSTOMER DECLINED	
>>--> SEG# 06 PRT .00 LAB .00 MSC .00	.00
* TOTAL GST/HST * - GST No. 899544779	730.84

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	2,094.74
TOTAL LABOR	11,574.00
MISC. CHARGES	947.93
SALES TAX	0.00
PLEASE PAY THIS TOTAL	15,347.51

CUSTOMER COPY