

# FOUNTAIN TIRE (NORTH BATTLEFORD) LTD.



AIR MILES

# Fountain Tire

11101 110 ST  
NORTH BATTLEFORD SK S9A 3S8

## INVOICE COPY

Order Number: 207SWO00180092  
Service Contact: STUART RODGERS

Phone: 306.445.2323  
Fax: 306.445.3236  
F207@fountaintire.com  
861423184RT0001  
0372912

Date: 04/11/2025  
Invoice: 2071163621  
PO#: \*\*\*\*\*80000754142  
AirMiles # :  
Terms of payment Net\_30

Bill to Customer 207C0000052 Ship to Customer: 207C0000052

RON BUZIAK  
BOX 14 RR 1  
MAYFAIR SK S0M 1S0

RON BUZIAK  
BOX 14 RR 1  
MAYFAIR SK S0M 1S0

Year: 2025 Unit:  
Make: MISCELLANEOUS  
Model: LOOSE SALES  
Design:  
Engine:  
License: Colour:  
Vin:  
Mileage: 0 Hours: 0

Item number	Item description	Qty	Unit price	Total
<b>Commercial Truck Tires, Retreads, Wheels and Service</b>				
3032018	11R22.5 (74447) LR H 146/143L Roadmaster RM832+ EM	2.00	\$564.99	\$1,129.98
30531	11R22.5 IRONHEAD IDR311 H16 146/143M	5.00	\$393.99	\$1,969.95
3C031	Change-Over Commercial Truck (Over 19.5")	5.00	\$43.00	\$215.00
3B033	Commercial Truck Powder / Liquid Balance	2.00	\$25.00	\$50.00
3S034	Commercial Wheel R&R	7.00	\$9.50	\$66.50
3C031	Change-Over Commercial Truck (Over 19.5")	2.00	\$43.00	\$86.00
<b>Tire and Wheel Parts / Hardware</b>				
3033	Commercial Truck Aluminum Valve Stem (TR545)	5.00	\$15.00	\$75.00
3032	Commercial Truck Valve Stem	2.00	\$11.00	\$22.00
<b>Other Miscellaneous Items</b>				
30P	Shop Supplies	1.00	\$10.00	\$10.00
	Thank you for choosing Fountain Tire, we appreciate your business	1.00	\$0.00	\$0.00
	Thank you for choosing Fountain Tire, we appreciate your business	1.00	\$0.00	\$0.00

Air Miles: 25

### Invoice comment

5x new drive tires - 4x on Driver Side, 1x passenger rear outside

2x new steer tires + powder balance

We acknowledge: (1) receipt of goods and services, and (2) Fountain Tire may conduct a registry search to verify the VIN on my vehicle if required for collection purposes on unpaid invoices related to my vehicle.

The customer is to ensure all wheel lugs are re torqued by a qualified technician before the vehicle has travelled 100 kilometers.

Parts: \$3,196.93  
Services: \$427.50  
Tire Fee: \$98.00  
Sub Total: \$3,722.43  
GST: \$186.12  
PST: \$217.47  
Total: (CAD) \$4,126.02

Pay type: AR \$4,126.02

X \_\_\_\_\_

**Torq'd Up Mechanical Ltd**  
**Box 700**  
**Battleford, SK**  
**S0M 0E0**  
**(306) 446-2022**

**Page 1 of 2**  
**2025-11-03**  
**Invoice 9485**

Sold to:

**Customer Acct # 00-000657**

**Ron Buziak**  
**RR1 Box 4**  
**Mayfair SK S0M 0E0**

1M1AE07Y02W012084

Part Number	Description	Quantity	Unit Cost	Total
<b>Labour</b>	<b>Labour</b>	<b>2.00</b>	<b>190.00</b>	<b>380.00</b>
	Inspection check over made a list of repairs			
<b>Labour</b>	<b>Labour</b>	<b>0.40</b>	<b>190.00</b>	<b>76.00</b>
	Gauge cluster not working pulled panel was unplugged plugged in tested			
<b>Labour</b>	<b>Labour</b>	<b>5.00</b>	<b>190.00</b>	<b>950.00</b>
	Replaced RH front and Rh rear drive wheels seals, brakes, drums one set of wheel bearings on RH rear, torqued wheel nuts checked diff oil level			
<b>Labour</b>	<b>Labour</b>	<b>1.00</b>	<b>190.00</b>	<b>190.00</b>
	Replaced steering gear box input seal, topped up fluid			
<b>Labour</b>	<b>Labour</b>	<b>1.00</b>	<b>190.00</b>	<b>190.00</b>
	Replaced ignition switch put steering column back together			
<b>Labour</b>	<b>Labour</b>	<b>2.50</b>	<b>190.00</b>	<b>475.00</b>
	Changed engine oil, filter, fuel filters, air filter checked levels greased			
<b>Labour</b>	<b>Labour</b>	<b>1.00</b>	<b>190.00</b>	<b>190.00</b>
	Air leak for splitter found broken line at slave valve ran new line tested			
<b>Labour</b>	<b>Labour</b>	<b>2.00</b>	<b>190.00</b>	<b>380.00</b>
	Replaced battery box, wired in disconnect switch customer supplied battery box, installed convex mirror on RH front of hood			
<b>Labour</b>	<b>Labour</b>	<b>0.50</b>	<b>190.00</b>	<b>95.00</b>
	Repaired two cab light, LH front signal, replaced license plate light and rear centre marker, tightened coolant clamps on fittings behind compressor			
<b>Labour</b>	<b>Labour</b>	<b>0.70</b>	<b>190.00</b>	<b>133.00</b>
	Adjusted clutch			

**CONTINUED NEXT PAGE**

Part Number	Description	Quantity	Unit Cost	Total	
Labour	Labour	1.00	190.00	190.00	
Replaced exhaust flex pipe and clamps under cab					
3157NA	Amber bulb	1.00	2.78	2.78	
194	BULB	2.00	0.90	1.80	
G1032	LED, 2.5" HIGH COUNT RED	1.00	11.62	11.62	
XSS714515QK	ex 16.5X7 meritor Q shoe	2.00	64.14	128.28	
39BD22BW	16.5X7 DRUM 10 hole	2.00	115.14	230.28	
TAS000001	SEAL KIT, STEERING	1.00	65.10	65.10	
3303106	AXLE GASKET 5/8HOLE	2.00	3.85	7.70	
392-9131	WHEEL SET, DRIVE, OIL SEAL, GRIT GUARD	2.00	79.25	158.50	
SET401	BEARING SET, 580/572	1.00	71.40	71.40	
SET403	BEARING SET, 594A/592A	1.00	83.94	83.94	
8622	union 1/8	1.00	1.85	1.85	
8682A	CONNECTOR 5/32TX1/8P	1.00	2.40	2.40	
49035	5" stainless flexpipe	1.50	23.22	34.83	
EC50PLS	CLAMP-EXH	2.00	18.97	37.94	
14814	INSERT,1/4" SYNDFLEX	1.00	0.38	0.38	
TRSY759P20	Traxon synthetic 75W-90	2.00	12.31	24.62	
	EHC 3	Enviro per L	2.00	0.18	0.36
7630001N	batter cable axxy 2/0 17" neg	1.00	37.22	37.22	
Q23656743	tumbler kit	1.00	230.83	230.83	
3588	HD fuel filter	1.00	39.40	39.40	
	EHC1	FILTER 8 IN OR MORE	1.00	1.25	1.25
3587	HD fuel filter	1.00	48.04	48.04	
	EHC1	FILTER 8 IN OR MORE	1.00	1.25	1.25
60151	LICENSE LAMP 12V	1.00	9.03	9.03	
RS3936	air filter	1.00	85.06	85.06	
500010131D	Rotella T3 fleet 15W-40 CK4	35.00	5.94	207.90	
	EHC 3	Enviro per L	35.00	0.18	6.30
B76	Oil filter	2.00	14.00	28.00	
	EHC1	FILTER 8 IN OR MORE	2.00	1.25	2.50
610551	MIRROR, CONVEX, 8" OFFSET, SS	1.00	23.88	23.88	

Retorque wheel nuts at 100 km

Thank You!  
We appreciate your business!

<b>Sub Total</b>	<b>\$4,833.44</b>
<b>Shop Supplies</b>	<b>\$162.45</b>
<b>PST 6%</b>	<b>\$299.75</b>
<b>GST 5%</b>	<b>\$249.79</b>
<b>Total</b>	<b>\$5,545.43</b>
<b>Paid</b>	<b>\$0.00</b>
<b>Balance</b>	<b>\$5,545.43</b>

Sold to:

Customer Acct # 00-000657

Ron Buziak  
RR1 Box 4  
Mayfair SK S0M 0E0

Part Number	Description	Quantity	Unit Cost	Total
Labour	Labour	1.00	190.00	190.00
Alternator not charging replaced alternator tested, bolted up grill				
8600310	alternator	1.00	415.32	415.32

Retorque wheel nuts at 100 km

Thank You!  
We appreciate your business!

Sub Total	\$605.32
Shop Supplies	\$10.00
PST 6%	\$36.92
GST 5%	\$30.77
Total	\$683.01
Paid	\$0.00
Balance	\$683.01