

Motion Mechanical
233016 Hwy 519
Box 510
Nobleford, AB T0L 1S0, CA
accounting@motionmech.ca
587-800-0829



Invoice: 123557
Date: 5/13/2025

Bill To

Truckin Bell Transport Ltd

P: (587) 220-2339

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
739517	COD	5/13/2025	Jamie		Neudorf, Abe	

Item	Description	Quantity	Rate	Amount
Complaint: HD Oil Change/Service, Full Package				
Cause: Customer request				
Labor	Correction: Chassis / Chassis / HD Service: Drain engine oil, change oil and fuel filters. Fill with 15W40 engine oil. Grease truck and 5th wheel, inspect truck and top up fluids. - Completed: 5/13/2025	2.54167	\$120.00	\$305.00
Parts	Detroit Diesel - Fuel Filter Insert Kit	1.00000	\$123.64178	\$123.64
Parts	Environmental Fee	1.00000	\$1.25	\$1.25
Parts	Detroit Diesel - Oil Filter Kit	1.00000	\$46.31475	\$46.31
Parts	Environmental Fee	1.00000	\$1.25	\$1.25
Parts	5W40 Rotella T6 - Bulk	36.00000	\$10.346	\$372.46
Parts	Environmental Fee, Oil	36.00000	\$0.05	\$1.80
Parts	50/50 Extended Life Red Coolant, Premix	1.50000	\$4.14589	\$6.22
Subtotal				\$857.93


Complaint: Diff blown? Inspect and Advise

Cause: Customer request

(Inspection)

100-100000

100-100000



100-100000

[REDACTED]

[REDACTED]

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

Item	Description	Quantity	Rate	Amount
Labor	Correction: Chassis / Chassis / -Found lots of metal shavings on the magnet when checking oil level. -Drained oil and found glittery oil. -Removed wheels and brake drum and removed the wheel hubs to check if a wheel bearing was failing but found no issue. -Installed new dust shields on axle #2. -Cleaned wheel hub assemblies and spindle. -Re-installed the wheel hubs with oil and torqued them to spec. -Checked for the proper end play and filled hubs with 75w90 gear oil. -Removed the drive shaft and un-bolted the differential from the diff housing and removed the diff. -Cleaned out the diff housing and removed any gasket material. -Removed drive shaft from the output shaft side of the diff. -Removed the yoke nut and pulled out the yoke. -Removed the housing holding the bearings inside. -Removed the shaft and pressed the bearings off the shaft and removed the seals. -Cleaned surfaces and pressed on the new bearing and installed new bearing races. -Installed the new seals and re-installed the output shaft assembly onto the diff. -Re-installed the yoke and installed the drive shaft with new bolts (old ones were partially stripped) -Installed the new diff and used silicone as necessary. -Tightened down the diff and connected air lines and wiring, used new fittings as necessary. -Removed yoke off the old diff and replaced the yoke seal and installed the yoke onto the new diff. -Re-installed the drive shaft. -Re-installed the axle shafts with new gaskets and re-installed brake drums and wheels. -Filled diff with 75w90 gear oil. -Checked functions of the diff locks. -Took unit for a test drive and found no obvious leaks. -Re-checked diff fluid and installed a new level plug. -Torqued wheels to 500 ft lbs. - Completed: 5/13/2025	15.00000	\$120.00	\$1,800.00
Parts	1/4" NPT x 1/4" Tube 90 NPT Connector	1.00000	\$4.67001	\$4.67
Parts	Scot Seal Plus	2.00000	\$72.65	\$145.30
Parts	Axle Flange Gasket 5/8	2.00000	\$4.42695	\$8.85
Parts	Dust Shield	2.00000	\$60.385	\$120.77
Parts	Forward Diff 342 - No pump	1.00000	\$4,365.00	\$4,365.00
Parts	Inherent Core for Forward Diff 342 - No pump	1.00000	\$2,160.00	\$2,160.00
Parts	Dirty Core for Forward Diff 342 - No pump	-1.00000	\$2,160.00	-\$2,160.00
Parts	1/4" NPT x 1/4" Tube 90 NPT Connector	1.00000	\$4.67001	\$4.67
Parts	75W90 Spirax S6 - 18.9L Pail	1.00000	\$280.788	\$280.79
Parts	Enviro Fee - 20L Pail	1.00000	\$3.60	\$3.60
Parts	Magnetic Fill Plug	1.00000	\$8.022	\$8.02
Parts	Sockethead 12pt Screw	8.00000	\$4.242	\$33.94

Item	Description	Quantity	Rate	Amount
Parts	Misc. Bolt/Fasteners	6.00000	\$0.89	\$5.34
Parts	Misc. Cable Ties/Fasteners	4.00000	\$0.58	\$2.32
Parts	Freight, Lyles Courier	2.00000	\$23.00	\$46.00
Subtotal				\$6,829.27

Unit: VIN: 3AKJGNDV5GDHD8453
2016 Freightliner SD122
Chassis: 1,617,635 Kilometres

Labor	\$2,105.00
Parts	\$5,582.20
Shop Supplies	\$126.30
Pre-Charge Subtotal	\$7,813.50
GST (5% of \$7,813.50)	\$390.68
Total	\$8,204.18
Payments & Credits	\$8,204.18
Balance Due	\$0.00

Payment Information

Date Created	Date Applied	Payment #	Method	Reference #	Amount
5/14/2025	5/14/2025				\$8,204.18

Any wheels removed for work must be re-torqued within 150 kms.

GST#755125291-RT0001

TERMS: NET 30 DAYS FOLLOWING DATE OF INVOICE UNLESS OTHERWISE SHOWN. A SERVICE CHARGE OF 1.5% PER MONTH WILL BE CHARGED ON OVERDUE ACCOUNTS. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE EQUIPMENT DESCRIBED ON THIS ORDER TO SECURE THE FULL AMOUNT OF SERVICES THERETO.

Customer Signature: _____



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture