



310 MARQUIS DRIVE
 SASKATOON, SK S7R 1B5
 Phone: (306) 242-4911
 FAX: (306) 242-3171

Invoice No.	R101091386:01
Invoice Date	08/28/2025
P.O. Number	
Terms:	MC
Customer No	14158
Customer Unit:	
GST No.	120053855 RT0001

Service Invoice

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 65,516 KM	In Service Date: 11/08/2019
Advisor: DARREN	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

JOB#1 TRK-100 RET ENGINE REPAIRS				
CONDITION	ENGINE REPAIRS - CUSTOMERS CONCERN CHECK ENGINE LIGHT ON. UNIT KEEPS WANTING TO SHUTTING DOWN.			
CAUSE	poor duty cycle.			
CORRECTION	Brought unit into shop. Checked DDEC reports. unit has high idle time at 45%. Checked daily usage in the past week, lots of idle time and not enough driving time. Checked auto elevate, it is enabled. Checked software levels, ACM had update, updated software. After going through troubleshooting for code 3250/31 found no issues aside high idle time. Performed low temp regen for 25 minutes to verify all temp sensors within suitable range. All temp sensors were within 45°F of each other. Proceeded to perform regen. Monitored temps during regen, all temps were within spec, DOC outlet did not spike. DOC inlet pressure was slightly high but not high enough to be of concern. Nox efficiency was good at 95%+. code 3250/31 was due to poor duty cycle with too much idle time causing DOC to build up with hydrocarbons causing temp spikes. Advised customer.			
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	C	*****WARRANTY REPAIRS REQUIRE PRINT OUT F	0.00	0.00
	TRK-100-25	LABOR		378.10
JOB#1 TRK-100 ---- PARTS: 0.00 -- LABOR: 378.10 -- TOTAL 378.10				

JOB#2 TRK-EA RET EXPRESS ASSESSMENT				
CONDITION	EXPRESS ASSESSMENT			
CORRECTION				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
JOB#2 TRK-EA ---- PARTS: -- LABOR: -- TOTAL				

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Invoice No.	R101091386:01
Invoice Date	08/28/2025
P.O. Number	
Terms:	MC
Customer No	14158
GST No.	120053855 RT0001

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 65,516 KM	In Service Date: 11/08/2019
Advisor: DARREN	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

INVOICE REPRINT

Please Remit Payment to:
 FRONTLINE TRUCK & TRAILER
 310 MARQUIS DRIVE
 SASKATOON, SK S7R 1B5

MISC CHARGES	0.00
PARTS	0.00
LABOR	378.10
BODY SHOP SUPPLIES	0.00
SUBLET	0.00
MISC SUPPLIES	37.81
SUBTOTAL	415.91
GST	20.80
PST	24.95
TOTAL	461.66

Disclaimer of Warranty:

Any warranties on the products sold hereby are those made by the manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty or merchantability or fitness for a particular purpose, and Frontline Truck & Trailer neither assumes nor authorizes any other person to assume any liability in connection with the sale of the said products.

Frontline Truck & Trailer shall not be liable for special, indirect or consequential damages, e.g. articles left in vehicles, theft, down time, loss of revenue, loss of vehicle, towing charges, driver's expenses, loss of perishable cargo, etc. Failed parts return requests must be made when the unit is checked in.

I/We hereby acknowledge the above repair order and an express Commercial Lien thereon to secure the full amount of the indebtedness. I/We agree to pay interest at the rate of 2% per month (24% per annum), if the balance due is not paid within the credit terms of Frontline Truck & Trailer. I/We also agree to pay storage fees of fifteen dollars (\$15.00) per day, both before and after judgment plus all costs incurred in the collection of the balance owing; including legal fees and disbursements on a solicitor/client basis.

Authorized by: _____

Printed Name: _____



310 MARQUIS DRIVE
 SASKATOON, SK S7R 1B5
 Phone: (306) 242-4911
 FAX: (306) 242-3171

Invoice No.	R101089519:01
Invoice Date	03/22/2025
P.O. Number	
Terms:	MC
Customer No	14158
Customer Unit:	
GST No.	120053855 RT0001

Service Invoice

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 62,886 KM	In Service Date: 11/08/2019
Advisor: DARREN	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

JOB#1 TRK-2100 RET TRUCK SAFETY INSPECTION ..PST EXEMPT				
CONDITION TRUCK SAFETY INSPECTION ..PST EXEMPT				
CORRECTION Completed safety inspection				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	DECAL	SFI SAFETY STICKER	20.00	20.00
	TRK-2100-1	LABOR		312.00
JOB#1 TRK-2100 ---- PARTS: 20.00 -- LABOR: 312.00 -- TOTAL 332.00				

JOB#2 TRK-9999 RET SERVICE SPECIAL				
CONDITION SERVICE SPECIAL ESSO 10/30 GREASE UNIT REPLACE FUEL FILTERS F/L INSPECTION.				
CORRECTION Complated engine service with Esso 10/30 oil. Changed oil. fuel 7 cabin air filters. Greased unit, changed washer nozzles & completed checklist.				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	101D/DDE A4700903151	FUEL FILTER KIT	113.45	113.45
1	101D/DDE A4731800909	TS OIL FILTER KIT (A4731800109	39.23	39.23
1	101V/ABP N10G 36000006	CABIN AIR FILTER	12.05	12.05
2	101V/TRI 88171 757	NOZZLE	9.45	18.90
40	101X/OIL ESSO 10W30BULK	10W-30 CK-4 BULK (105420)	5.86	234.40
40	ENV05	ENVIRO HANDLE CHARGE .05	0.05	2.00
2	ENV100	ENVIRO HANDLE CHARGE 1.00	1.00	2.00
	TRK-9999-1	LABOR		316.00
JOB#2 TRK-9999 ---- PARTS: 422.03 -- LABOR: 316.00 -- TOTAL 738.03				

JOB#3 TRK-3500 RET REAR AXLE				
CONDITION REAR AXLE - CUSTOMER REQUEST TO REPLACE FRONT DIFF FILTER				
CORRECTION replaced diff oil filter as requested.				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	101S/DN P552518	OIL FILTER	8.76	8.76
	C	*****WARRANTY REPAIR MUST BE CALLED IN (PI	0.00	0.00
1	ENV50	ENVIRO HANDLE CHARGE .50	0.50	0.50
	TRK-3500-11	LABOR		59.70
JOB#3 TRK-3500 ---- PARTS: 9.26 -- LABOR: 59.70 -- TOTAL 68.96				

JOB#4 TRK-3500 RET REAR AXLE				
------------------------------	--	--	--	--

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Invoice No.	R101089519:01
Invoice Date	03/22/2025
P.O. Number	
Terms:	MC
Customer No	14158
GST No.	120053855 RT0001

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 62,886 KM	In Service Date: 11/08/2019
Advisor: DARREN	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

JOB#4 TRK-3500 RET REAR AXLE				
CORRECTION The repair operation involved replacing the right rear wheel seal due to leaking. The technician removed the wheels and hub, inspected the bearings, replaced the brake shoes due to oil contamination, cleaned the brake spider, and installed new seal and bearings. The axle nut was torqued to 500ft/lb, and the wheels were torqued to 450ft/lb. The differential oil level was checked and found to be good.				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	101F/11-14418-000	GASKET-AXLE SHAFT,7.00, 8,.66,	4.15	4.15
1	101V/ABP 10045887	SEAL SERVICE KIT R DRIVE	45.21	45.21
1	101V/ABP MK4711Q 23PREM	16.5 x 8-5/8 BRAKE KIT- Reman	145.66	145.66
	101V/ABP MK4711Q	BRAKE CORE	72.80	0.00
	23PREM-CORE			
1	101X/OIL 1L 75W90	Delvac 75W90 SYN 1L (104361)	22.76	22.76
1	ENV05	ENVIRO HANDLE CHARGE .05	0.05	0.05
	TRK-3500-1	LABOR		696.50
JOB#4 TRK-3500 ---- PARTS: 217.83 -- LABOR: 696.50 -- TOTAL 914.33				

JOB#5 TRK-6000 RET CAB				
CONDITION CAB - REPLACE CAB REFLECTORS LOOSE.				
CORRECTION Removed plastic reflectors and cleaned around area with soap and water to not scrape dirt/dust into the paint. Scraped old glue off with a plastic blade and brake clean. Installed reflective tape.				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
4	101X/TKL98105	REFLECTOR	5.74	22.96
	TRK-6000-2	LABOR		159.20
JOB#5 TRK-6000 ---- PARTS: 22.96 -- LABOR: 159.20 -- TOTAL 182.16				

JOB#6 TRK-8800 RET HOOD, GRILLE, CAB FENDERS				
CONDITION HOOD, GRILLE, CAB FENDERS - PASSENGER SIDE HOOD STRAP TORN.				
CORRECTION The repair operation involved replacing the passenger side hood strap due to it being torn. However, the new strap was longer than the one on the left side, necessitating the replacement of both straps to properly secure the hood. The repair was successfully completed, ensuring that both straps are now holding the hood in place.				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
2	101F/A17-20380-001	STRAP-RESTRAINT,HOOD	58.69	117.38
	TRK-8800-1	LABOR		119.40
JOB#6 TRK-8800 ---- PARTS: 117.38 -- LABOR: 119.40 -- TOTAL 236.78				

JOB#7 TRK-8300 RET HEATER / AIR CONDITIONING				
CONDITION HEATER / AIR CONDITIONING REPLACE ESPAR EXHAUST CLAMP BROKEN				
CORRECTION The vehicle repair involved replacing a broken exhaust clamp in the heater/air conditioning system. The technician used a smaller clamp without rubber due to concerns about melting.				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	101F/23-09528-047	CLAMP	3.74	3.74
1	101X/WUR 074.14.1	1/4X 1NC GR8 BOLT	0.17	0.17

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Invoice No.	R101089519:01
Invoice Date	03/22/2025
P.O. Number	
Terms:	MC
Customer No	14158
GST No.	120053855 RT0001

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 62,886 KM	In Service Date: 11/08/2019
Advisor: DARREN	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
JOB#7 TRK-8300 RET HEATER / AIR CONDITIONING				
1	101X/WUR 335.14	1/4 NC STOVER LOCKNUT	0.12	0.12
2	101X/WUR 410.14	1/4 FLAT WASHER	0.07	0.14
	TRK-8300-5	LABOR		79.60
JOB#7 TRK-8300 ---- PARTS: 4.17 -- LABOR: 79.60 -- TOTAL 83.77				

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
JOB#8 TRK-8300 RET HEATER / AIR CONDITIONING				
CONDITION HEATER / AIR CONDITIONING RE-SEAL FITTING AT ESPAR COOLANT LEAKING				
CORRECTION The vehicle repair involved fixing a coolant leak in the heater/air conditioning system caused by pinched coolant hoses and melted shrink hose clamps. The damaged hoses were repaired by cutting off the damaged parts and installing new hose clamps. Additionally, the brass fittings were cleaned and re-installed with thread sealant, and the heater box was cleaned of old coolant residue.				
2	101V/BRZ 62012H C	CLAMP-HOSE,11/16-1 1/4IN, 1/2	0.96	1.92
	TRK-8300-5	LABOR		258.70
JOB#8 TRK-8300 ---- PARTS: 1.92 -- LABOR: 258.70 -- TOTAL 260.62				

INVOICE REPRINT

Please Remit Payment to:
 FRONTLINE TRUCK & TRAILER
 310 MARQUIS DRIVE
 SASKATOON, SK S7R 1B5

MISC CHARGES	24.55
PARTS	791.00
LABOR	2,001.10
BODY SHOP SUPPLIES	0.00
SUBLET	0.00
MISC SUPPLIES	200.11
SUBTOTAL	3,016.76
GST	150.84
PST	162.29
TOTAL	3,329.89

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Invoice No.	R101089519:01
Invoice Date	03/22/2025
P.O. Number	
Terms:	MC
Customer No	14158
GST No.	120053855 RT0001

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 62,886 KM	In Service Date: 11/08/2019
Advisor: DARREN	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

Disclaimer of Warranty:

Any warranties on the products sold hereby are those made by the manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty or merchantability or fitness for a particular purpose, and Frontline Truck & Trailer neither assumes nor authorizes any other person to assume any liability in connection with the sale of the said products.

Frontline Truck & Trailer shall not be liable for special, indirect or consequential damages, e.g. articles left in vehicles, theft, down time, loss of revenue, loss of vehicle, towing charges, driver's expenses, loss of perishable cargo, etc. Failed parts return requests must be made when the unit is checked in.

I/We hereby acknowledge the above repair order and an express Commercial Lien thereon to secure the full amount of the indebtedness. I/We agree to pay interest at the rate of 2% per month (24% per annum), if the balance due is not paid within the credit terms of Frontline Truck & Trailer. I/We also agree to pay storage fees of fifteen dollars (\$15.00) per day, both before and after judgment plus all costs incurred in the collection of the balance owing; including legal fees and disbursements on a solicitor/client basis.

Authorized by: _____

Printed Name: _____



310 MARQUIS DRIVE
 SASKATOON, SK S7R 1B5
 Phone: (306) 242-4911
 FAX: (306) 242-3171

Invoice No.	R101085702:01
Invoice Date	04/05/2024
P.O. Number	
Terms:	MC
Customer No	14158
Customer Unit:	
GST No.	120053855 RT0001

Service Invoice

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 52,825 KM	In Service Date: 11/08/2019
Advisor: HOWARD	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

JOB#1 TRK-2100 RET TRUCK SAFETY INSPECTION ..PST EXEMPT				
CONDITION TRUCK SAFETY INSPECTION ..PST EXEMPT				
CORRECTION Completed inspection.				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	DECAL	S&I SAFETY STICKER	20.00	20.00
	TRK-2100-1	LABOR		286.00
JOB#1 TRK-2100 ---- PARTS: 20.00 -- LABOR: 286.00 -- TOTAL 306.00				

JOB#2 TRK-9999 RET SERVICE SPECIAL				
CONDITION SERVICE SPECIAL				
PERFORM ENGINE SERVICE WITH SHELL 15W40. CHANGE OIL FILTER, GREASE UNIT & PERFORM FL CHECKLIST. *****DO NOT CHANGE FUEL FILTERS*****				
CORRECTION Completed engine service with Shell 15W40 oil. changed oil & cabin air filters. Greased unit, topped up coolant & completed FL checklist				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	101D/DDE A4731800909	TS Oil Filter Kit (A4731800109)	43.28	43.28
1	101S/OWI 23539617	OAT Coolant 50/50	14.43	14.43
1	101V/ABP N10G 36000006	Cabin Air Filter	11.68	11.68
2	101X/OIL 1T GREASE	MOBILGREASE (121928) 40X.4KG	5.44	10.88
2	101X/OIL SHELL 20L	15W40 Oil 19L Pail (550045128)	107.68	215.36
1	101X/OIL SHELL 5L	15W40 5L Jug (550045135)	30.62	30.62
2	ENV100	ENVIRO HANDLE CHARGE 1.00	1.00	2.00
2	ENV300	ENVIRO HANDLE CHARGE 3.00	3.00	6.00
1	ENV75	ENVIRO HANDLE CHARGE .75	0.75	0.75
	TRK-9999-2	LABOR		219.00
JOB#2 TRK-9999 ---- PARTS: 335.00 -- LABOR: 219.00 -- TOTAL 554.00				

Bill To:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Owner:
 TREWIN FARM CORP
 BOX 102
 LAIRD, SK S0K 2H0

Invoice No.	R101085702:01
Invoice Date	04/05/2024
P.O. Number	
Terms:	MC
Customer No	14158
GST No.	120053855 RT0001

Year: 2020	Make: FREIGHTLINER	Model: 122SD	Vin: 3AKJGND11LDKV5826
Colour: BLACK ELITE EY	License: 898 LNJ	Odometer In: 52,825 KM	In Service Date: 11/08/2019
Advisor: HOWARD	Contact: TREVOR JANZEN	Tax Exempt No.:	Pinnacle No.:

INVOICE REPRINT

Please Remit Payment to:
 FRONTLINE TRUCK & TRAILER
 310 MARQUIS DRIVE
 SASKATOON, SK S7R 1B5

MISC CHARGES	28.75
PARTS	326.25
LABOR	505.00
BODY SHOP SUPPLIES	0.00
SUBLET	0.00
MISC SUPPLIES	50.50
SUBTOTAL	910.50
GST	45.52
PST	54.63
TOTAL	1,010.65

Disclaimer of Warranty:

Any warranties on the products sold hereby are those made by the manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty or merchantability or fitness for a particular purpose, and Frontline Truck & Trailer neither assumes nor authorizes any other person to assume any liability in connection with the sale of the said products.

Frontline Truck & Trailer shall not be liable for special, indirect or consequential damages, e.g. articles left in vehicles, theft, down time, loss of revenue, loss of vehicle, towing charges, driver's expenses, loss of perishable cargo, etc. Failed parts return requests must be made when the unit is checked in.

I/We hereby acknowledge the above repair order and an express Commercial Lien thereon to secure the full amount of the indebtedness. I/We agree to pay interest at the rate of 2% per month (24% per annum), if the balance due is not paid within the credit terms of Frontline Truck & Trailer. I/We also agree to pay storage fees of fifteen dollars (\$15.00) per day, both before and after judgment plus all costs incurred in the collection of the balance owing; including legal fees and disbursements on a solicitor/client basis.

Authorized by: _____

Printed Name: _____